

Work Order	Description	Start Date
021336	LOCATE FAULT WITH PTO NOT OPERATING, FOUND MAIN PTO SWITCH	04/23/2020
020550	LOCATE FAULT WITH PTO NOT OPERATING, FOUND MAIN PTO SWITCH	05/15/2020
020572	PTO NOT WORKING, FOUND SWITCH ON PANEL FAULTY, REPLACED	05/15/2020
020573	LOCATE FAULT WITH ELECT WIRING SHORTING, FOUND PLUG WITH	05/15/2020
020578	REPLACED RIGHT ANGLE AIR FITTING COMING OUT OF VALVE	05/15/2020
019111	N133540-4X BATTERIES	05/21/2020
021034	REPLACE FRONT AND REAR AXLE DRIVE TYRES	05/23/2020
019363	C-(A) 250HR SERVICE @ 287 (250) HR TKP KENWORTH T659	05/29/2020
022284	MURPHY TRUCK AND TRAILERS TO SERVICE TRAILERS ONLY	06/04/2020
019795	C-(B) 500HR SERVICE @ 599 (500) HR TKP KENWORTH T659	06/05/2020
023943	REPLACED BEACON LIGHT	06/07/2020
020983	N133281-DRIVE TYRES	06/24/2020
021144	C-(A) 250HR SERVICE @ 802 (750) HR TKP KENWORTH T659	06/25/2020
024168	FITTED RUNOUT MSD DRIVE TYRE	06/25/2020
021495	N133308-PTO CHANGE OUTS	07/01/2020
021497	N133308-PTO CHANGE OUTS	07/01/2020
024289	FIT NEW STEER TYRES AND SET OF DRIVE TYRES	07/02/2020
024290	FIT BANGO TO REAR GREASE BLOCK	07/02/2020
021908	C-(C) 1000HR SERVICE @ 1,048 (1,000) HR TKP KENWORTH T659	07/04/2020
022155	N133366-FLASHING LIGHT	07/05/2020
022897	C-(A) 250HR SERVICE @ 1,319 (1,250) HR TKP KENWORTH T659	07/17/2020
026019	REPLACED BOTH WIPER BLADES	07/26/2020
023716	C-(B) 500HR SERVICE @ 1,637 (1,500) HR TKP KENWORTH T659	07/30/2020
024047	N132919-TARP ISSUE	08/01/2020
024074	N132923-STEER & DRIVE TYRES	08/01/2020
024604	C-(A) 250HR SERVICE @ 1,898 (1,750) HR TKP KENWORTH T659	08/07/2020
025094	C-(C) 1000HR SERVICE @ 2,107 (2,000) HR TKP KENWORTH C509	08/12/2020
026807	C-(B) 500HR SERVICE @ 2,517 (2,500) HR TKP KENWORTH T659	08/13/2020
027621	INSPECT WASTE GATE TRAVEL AND ADJUSTED	08/16/2020
027622	FIT NEW SET OF DRIVE TYRES AND NEW LH BEACON LIGHT	08/16/2020
027442	C-(A) 250HR SERVICE @ 2,831 (2,750) HR TKP KENWORTH T659	08/22/2020
028905	REPLACED LHR DRIVE TYRES WITH NEW	08/29/2020
028226	C-(C) 1000HR SERVICE @ 3,016 (3,000) HR TKP KENWORTH T659	08/30/2020
028600	2ND TRAILER - 2ND AXLE RHM REPLACED INSIDE TYRE WITH RUNOUT	09/01/2020

029355	5 X NEW TYRES ANS 2 X NEW BRAKES	09/05/2020
029356	REPLACED BOTH STEER TYRES	09/05/2020
026687	C-(A) 250HR SERVICE @ 2,274 (2,250) HR TKP KENWORTH T659	09/06/2020
029267	C-(A) 250HR SERVICE @ 3,257 (3,250) HR TKP KENWORTH T659	09/12/2020
030013	RETIGHTEN HYDR FITTING	09/13/2020
027199	N117402-DRIVE TYRES	09/16/2020
030494	REPLACED WORN TYRES ON 1ST TRAILER FRONT AXLE WITH NEW	09/28/2020
030780	REPLACE RHS WINDSCREEN	10/01/2020
030781	REPLACED INTAKE PRESSURE TEMP SENSOR AND HUMP HOSE AND CLAMP	10/01/2020
030809	C-(B) 500HR SERVICE @ 3,572 (3,500) HR TKP KENWORTH T659	10/05/2020
031057	REPAIR WIRING TO AUTO GREASER	10/06/2020
029234	N100636-SUPA SINGLE STEERS & BALANCE BAGS	10/09/2020
031080	C-(A) 250HR SERVICE @ 3,804 (3,750) HR TKP KENWORTH T659	10/09/2020
030363	NPR 100724; 8 X DRIVE TYRES 11R 22.5	10/24/2020
032364	C-(D) 2000HR SERVICE @ 4,042 (4,000) HR TKP KENWORTH T659	11/01/2020
034477	RH AND LH FRONT WHEEL BEARINGS LOOSE, ADJUSTED AND TESTED	11/05/2020
034468	REMOVED THE DRIVELINE AXLES AND HUB ASSEMBLIES, CLEANED BOLT	11/14/2020
031630	NPR 115601, 4 X N7022 BATTERIES. 2 X FANBELTS	11/19/2020
033688	C-(A) 250HR SERVICE @ 4,230 (4,250) HR TKP KENWORTH T659	11/21/2020
034609	REPLACED RYCO SEALS	11/23/2020
034611	REPLACED THE BEARINGS IN THE A/C TENSIONER/ IDLER	11/23/2020
034612	REPLACED THE ALTERNATOR BELT	11/23/2020
034613	REPLACED THE DRIVE TYRES	11/23/2020
034615	REPLACED STEER TYRES	11/23/2020
032794	N115618-WHEEL BEARINGS	12/05/2020
034691	C-(B) 500HR SERVICE @ 4,523 (4,500) HR TKP KENWORTH T659	12/07/2020
035362	C-(A) 250HR SERVICE @ 4,805 (4,750) HR TKP KENWORTH T659	12/17/2020
035988	C-(A) 250HR SERVICE @ 5,025 (5,000) HR TKP KENWORTH T659	01/08/2021
038422	UNI JOINT U/S	01/22/2021
038312	C-(A) 250HR SERVICE @ 5,283 (5,250) HR TKP KENWORTH T659	02/04/2021
041440	C-(A) 250HR SERVICE @ 5,540 (5,500) HR TKP KENWORTH T659	03/20/2021
045441	Change out dryer as blocked	04/07/2021
042497	C-(A) 250HR SERVICE @ 5,785 (5,750) HR TKP KENWORTH T659	04/10/2021
041477	npr129637 Enzed to supply 4 x a frame hydr pipes	04/16/2021
042016	NPR129700 Wrights to fabricate mudguards	04/24/2021

046646	Removed the old style solenoid. Fitted the new relay and	05/06/2021
044893	C-(C) 1000HR SERVICE @ 5,964 (6,000) HR TKP KENWORTH T659	05/20/2021
046073	C-(A) 250HR SERVICE @ 6,250 (6,250) HR TKP KENWORTH T659	06/05/2021
046297	C-(A) 250HR SERVICE @ 6,500 (6,500) HR TKP KENWORTH T659	06/06/2021
044427	Repair speedo, check faults, valve set	06/09/2021
047655	Supply of parts as per Cummins quote	06/21/2021
045973	Cummins to quote on engine repairs	07/02/2021
045974	Transport of PM by Mansells to Darwin	07/02/2021
049683	C-(A) 250HR SERVICE @ 6,750 (6,750) HR TKP KENWORTH T659	07/29/2021
050021	@ 352282 klms B&H supply front diff centre for breakdown	07/30/2021
051852	Supply front diff	08/27/2021
052652	C-(A) 250HR SERVICE @ 7,334 (7,250) HR TKP KENWORTH T659	09/11/2021
054566	C-(A) 250HR SERVICE @ 7,589 (7,500) HR TKP KENWORTH T659	10/11/2021
054883	C-(C) 1000HR SERVICE @ 7,142 (7,000) HR TKP KENWORTH T659	10/15/2021
056223	C-(C) 1000HR SERVICE @ 8,080 (8,000) HR TKP KENWORTH T659	11/06/2021
056529	C-(A) 250HR SERVICE @ 8,264 (8,250) HR TKP KENWORTH T659	11/08/2021
056682	C-(A) 250HR SERVICE @ 8,786 (8,750) HR TKP KENWORTH T659	11/12/2021
057599	Bears Mech supply Roadworthy certificate	11/23/2021
058849	Lift road speed to 92km/h as per A.Hopper	12/13/2021
058897	Beaurepairs supply 7 x drive tyres @ 499313 klms	12/13/2021
058881	Retractable Tarps supply parts as per quote @ 4991hrs	12/13/2021
058970	Ashdowns supply parts for tarps	12/14/2021
059076	replace RHS steer wheel seal	12/15/2021
059077	replace steer uni joints u/s	12/15/2021
059078	replace alternator	12/15/2021
059079	reseal front diff and output shaft seal	12/15/2021
059080	replace steer wheel backing plates	12/15/2021
059083	repair crack in rear diff	12/15/2021
059349	Bears mech to do RW for Mine pass outs	12/17/2021
059095	C-(C) 1000HR SERVICE @ 9,009 (9,000) HR TKP KENWORTH T659	12/18/2021
060411	Replace injector and ad blue filter, purge and clean codes.	12/19/2021
060464	Replaced A/C blower motor.	12/25/2021
062322	LH windscreen cracked.	01/03/2022
062323	PBR fitting leak on tank.	01/03/2022
062324	Belt squealing.	01/03/2022

059792	Beaurepairs supply 2 x new steer tyres	01/10/2022
059823	Cummins supply recon turbo & access @ 6644 hrs	01/10/2022
059092	Replace bonnet mounts	01/14/2022
061113	Fan belt/tensioner/	01/17/2022
061119	Repairs to rose joints and clutch bearing.	01/27/2022
062108	Cab air bags leaking.	01/28/2022
061643	B&H 30.12.2021 : ESTDIFREB Strip down, inspect, rebuild if	02/03/2022
061525	(A) 250HR SERVICE @ 9,342 (9,250) HR TKP KENWORTH T659	02/05/2022
061712	(A) 250HR SERVICE @ 9,640 (9,500) HR TKP KENWORTH T659	02/07/2022
062070	(A) 250HR SERVICE @ 9,790 (9,750) HR TKP KENWORTH T659	02/11/2022
062670	Cummins supply fan belt @ 10149hrs	02/14/2022
062669	Cummins to supply parts for Midlife Repairs @ 10149hrs quote	02/17/2022
063016	B&H: 07.10.2021 ESTDIFREB Strip down, inspect, rebuild if	02/18/2022
060794	Fan Belt/tensioner	02/19/2022
062791	(C) 1000HR SERVICE @ 10,149 (10,000) HR TKP KENWORTH T659	02/19/2022
063147	Cummins repair SCR fault, call out 19.02.2022 @ 10229 hrs	02/21/2022
064545	Replace Nox sensor, rose joints, gear box mounts.	02/25/2022
065448	Replaced brakes, drums and s-cam.	03/04/2022
065449	Put 4x new tyres on 1st axle, RHS.	03/04/2022
065450	Changed R12 valve, 2nd tank LHS.	03/04/2022
065985	(A) 250HR SERVICE @ 10,491 (10,250) HR TKP KENWORTH T659	04/27/2022
069512	Re-kit turntable, new foot pins and bushes.	04/29/2022
067984	(A) 250HR SERVICE @ 11,357 (11,250) HR TKP KENWORTH T659	05/03/2022
071226	CHANGED HUB BEARINGS AND SEAL	05/03/2022
066532	MISSED(A) 250HR SERVICE @ (10,500) HR TKP KENWORTH T659	05/04/2022
066539	(A) 250HR SERVICE @ 10,913 (10,750) HR TKP KENWORTH T659	05/04/2022
066546	(C) 1000HR SERVICE @ 11,000 (11,000) HR TKP KENWORTH T659	05/04/2022
071249	COMBINATIONS LIGHTS NOT WORKING	05/08/2022
071170	TYRES AND RINGO	05/10/2022
071195	TYRES AND RINGO	05/10/2022
071728	TYRES AND RINGS	05/10/2022
069141	Drive tyres and steer tyres.	05/11/2022
069150	Strip and flip steer tyres and balance bags	05/12/2022
069162	Horton fan 11' blade	05/12/2022
071737	BELT AND TENSIONER	05/12/2022

071738	COOLANT	05/12/2022
071739	ROSE JOINTS	05/12/2022
069986	AFTER TREAT FAULT AND LIGHTS	05/15/2022
069992	DOLLY 829	05/16/2022
071665	1000HR SERVICE AND REPAIRS	05/27/2022
071669	SERVICE AND REPAIRS	05/28/2022
071671	REPLACE RH SPRING DRIVE	05/28/2022
070653	(A) 250HR SERVICE @ 11,627 (11,500) HR TKP KENWORTH T659	06/03/2022
072449	TRUCK WON'T START	06/07/2022
071085	(A) 250HR SERVICE @ 11,892 (11,750) HR TKP KENWORTH T659	06/10/2022
071958	(C) 1000HR SERVICE @ 12,209 (12,000) HR TKP KENWORTH T659	06/16/2022
071965	(A) 250HR SERVICE @ 12,209 (12,250) HR TKP KENWORTH T659	06/16/2022
074057	ad blue fault	06/16/2022
074033	drive tyres	06/18/2022
074035	service and repairs	06/18/2022
072172	Beaurepairs supply 8 x drive tyres + 4 rims @ 644140 klms	06/21/2022
072179	Cummins replace water pump @ 12540hrs	06/21/2022
072181	Cummins replaced O ring @ 11892hrs	06/21/2022
072188	B&H supply adblue tank pickup @ 12690hrs	06/21/2022
074108	SERVICE REPAIRS	06/26/2022
074158	SERVICE REAPIRS	06/26/2022
072786	Supply 100 amp relays	07/04/2022
073158	Cummins replace adblue doser pump @ 13018hrs	07/08/2022
073355	(A) 250HR SERVICE @ 12,629 (12,500) HR TKP KENWORTH T659	07/11/2022
075117	Service Repairs	07/16/2022
075109	A/greaser wiring, steering column and battery charger	07/17/2022
075125	Windscreen replace.	07/17/2022
073866	B&H supply steering wheel adjustment shockie @ 13212hrs	07/18/2022
073868	Ashdowns supply red arc smart start battery isolator @	07/18/2022
073973	(A) 250HR SERVICE @ 12,805 (12,750) HR TKP KENWORTH T659	07/20/2022
074481	FIRST TARP NOT WORKING	07/24/2022
078091	SERVICE REPAIRS	08/04/2022
078094	REMOVE AND REPLACE FRONT UNI AND CENTRE BEARING	08/05/2022
078271	FITTED 8X NEW DRIVE TYRES TO PRIME MOVER	08/12/2022
075747	NPR047455 Beaurepairs supply 8 x drive tyres @ 699412 klms	08/15/2022

075752	NPR047463 B&H supply reverse light switch & torque rod	08/15/2022
075756	NPR047467 Cummins repair gear housing cracked & leaking &	08/15/2022
076021	(C) 1000HR SERVICE @ 13,190 (13,000) HR TKP KENWORTH T659	08/17/2022
076032	(A) 250HR SERVICE @ 13,190 (13,250) HR TKP KENWORTH T659	08/17/2022
078553	NO AUTO GREASERS WORKING	08/27/2022
078614	REPLACE 1ST TRAILER TARP SWITCH	08/29/2022
078434	Repair cracked diff housing	09/06/2022
078783	REPAIR TRAILER PLUG WIRE	09/16/2022
078807	SERVICE REPAIR	09/17/2022
081576	(A) 250HR SERVICE @ 14,361 (14,250) HR TKP KENWORTH T659	09/17/2022
078808	2ND DOLLY RIGHT HAND SIDE REPLACEMENT LEAKING FRONT HOSE	09/18/2022
078894	R+R FLEP PIPE CLEANED EXHAUST OUT 2 NEW GASKETS ON ALSO 2X	09/22/2022
077847	(A) 250HR SERVICE @ 13,604 (13,500) HR TKP KENWORTH T659	09/23/2022
078944	REPLACED FLEP PIPE AT GEAR OF EXHAUST PUT 2ND EXHAUST CLAMPS	09/24/2022
078995	BOOSTER REPLACE	09/26/2022
078251	NPR157262 Enzed replace damaged hoses @ 14550hrs	09/27/2022
079041	REPLACE DRIVERS SIDE WINDSCRREN	09/29/2022
082553	(A) 250HR SERVICE @ 14,657 (14,500) HR TKP KENWORTH T659	10/03/2022
079101	Replace cruise control dash bulb	10/04/2022
079197	NPR157309 B&H supply Adblue components to suit @ 14675hrs	10/06/2022
079769	REPLACE POWER DIVIDER HOSE	10/08/2022
079654	2ND TRAILER TARP ISSUE, PULLED PLUG OFF CLEAN PUT ELEC	10/11/2022
080203	REPLACED BRAKES ON 2ND AXLE & DRUMS	10/15/2022
082899	(A) 250HR SERVICE @ 14,888 (14,750) HR TKP KENWORTH T659	10/15/2022
080081	750,000 KM SERVICE (756,252KM)	10/17/2022
080045	(A) 250HR SERVICE @ 13,769 (13,750) HR TKP KENWORTH T659	10/18/2022
080197	REMOVED & REPAIRED STEER TYRES WITH X2 NEW STEER TYRES	10/18/2022
080460	Replace electrical connector	10/21/2022
080489	Replace Sbicodisp 12v100a battery isolator	10/21/2022
080602	Replaced redarch isolator on truck	10/21/2022
080771	Replace Ac compressor	10/26/2022
080949	Replace rear diff assy	10/28/2022
081095	Reline drive brakes	10/31/2022
084855	(C) 1000HR SERVICE @ 15,176 (15,000) HR TKP KENWORTH T659	11/02/2022
081302	(C) 1000HR SERVICE @ 14,121 (14,000) HR TKP KENWORTH T659	11/02/2022

081351	Replace high/low headlights	11/02/2022
081811	Replace A/C blower fan	11/03/2022
081835	Replace unis on second half of tail shaft	11/05/2022
081937	Topped up hydraulic tank with 60 litres of hydraulic oil	11/05/2022
081596	Replace uni joints	11/06/2022
081702	Replace main ryco hose from dolly to 2nd trailer	11/06/2022
081836	Replace drive tyres RH rear	11/06/2022
082251	Air leak on QR valve replaced 1/2 inch airline fitting	11/09/2022
085176	MISSED(A) 250HR SERVICE @ (15,250) HR TKP KENWORTH T659	11/10/2022
082271	Replaced broken wind screen wiper on driver's side with new	11/12/2022
082345	SUPPLY SPEED SENSOR AND HARNESS	11/14/2022
083782	Replace gear box harness - part number P92-4313	11/15/2022
083786	REPLACE CRANK SENSOR - PART NUMBER 5594275	11/15/2022
082619	REPLACE SPEED SENSOR AND HARNESS	11/16/2022
082623	REPLACE CRANK SENSsor AND CONNECTOR	11/16/2022
083784	REPAIR WIRING TO FRONT RH LIGHTS "INDICATOR"	11/16/2022
085177	(A) 250HR SERVICE @ 15,474 (15,500) HR TKP KENWORTH T659	11/17/2022
083768	3 x dash wedge lights	11/18/2022
083834	Replace hyd hose dkt 20303	12/01/2022
084468	8 X NEW DRIVE TYRES	12/01/2022
084047	Replace bunk window	12/06/2022
084070	Replace steering box	12/06/2022
084366	Clutch adjustment, will require new clutch soon	12/06/2022
085428	Remove and replace steering box	12/08/2022
085503	Replace drive tyre	12/14/2022
085563	Steering column shock x 1 #13CS0002	12/14/2022
087195	(A) 250HR SERVICE @ 15,838 (15,750) HR TKP KENWORTH T659	12/19/2022
086524	Strip and assess front diff 5258226	12/22/2022
086633	Replace clutch	12/23/2022
086663	Replace CLUTCH HOUSING ASSY	12/28/2022
086664	Replace batteries	12/28/2022
087013	Remove gearbox	01/03/2023
086910	Rebuild engine quote 6636009	01/05/2023
087444	Steer wheel alignment	01/09/2023
087458	Replace tie rod assy	01/10/2023

091297	CB no signal	01/10/2023
089310	Remove & replace LH steer spring	01/15/2023
087196	(C) 1000HR SERVICE @ 16,138 (16,000) HR TKP KENWORTH T659	01/16/2023
089273	Flushed Adblue system, cleared codes	01/16/2023
088714	Replace steer tyres	01/18/2023
089049	Exhaust Flex broken	01/22/2023
091564	(A) 250HR SERVICE @ 16,572 (16,250) HR TKP KENWORTH T659	01/31/2023
091572	(A) 250HR SERVICE @ 16,572 (16,500) HR TKP KENWORTH T659	01/31/2023
090216	Replace indicator switch	02/01/2023
090531	AC Cover	02/01/2023
090558	Finish fitting brake hose to RH front drive	02/01/2023
091577	Replace clock spring	02/14/2023
091584	Steer wheel alignment	02/14/2023
091643	Replace drive brakes	02/14/2023
091843	Replaced steer tyres and retorqued	02/14/2023
091893	Replaced driver's side, drive brakes, scam, tube and hubseal	02/14/2023
091771	Replace drive tyres	02/15/2023
091916	Replace quick release valves	02/16/2023
092379	Air Leak	02/16/2023
092479	RH H/Lights u/s	02/19/2023
092491	RH Low Beam	02/19/2023
092530	Oil/Fuel Leaks	02/22/2023
092668	Replace hyd hose dkt 18921	02/27/2023
095025	(A) 250HR SERVICE @ 17,146 (16,750) HR TKP KENWORTH T659	03/02/2023
095026	(C) 1000HR SERVICE @ 17,146 (17,000) HR TKP KENWORTH T659	03/02/2023
093551	G/B fill plug x 1 RHS Wiper Blade	03/03/2023
093552	Replaced bearings, brakes, drum and bearings, plus scam on	03/04/2023
095027	(A) 250HR SERVICE @ (17,250) HR TKP KENWORTH T659	03/13/2023
096659	Air con not cold - found leak in system, rectified +	03/24/2023
096687	Replace Horton + Fan Belt	04/07/2023
095028	(A) 250HR SERVICE @ 17,750 (17,500) HR TKP KENWORTH T659	04/13/2023
095029	(A) 250HR SERVICE @ 17,750 (17,750) HR TKP KENWORTH T659	04/13/2023
097434	Replaced leaking govenor valve	04/13/2023
096864	Replace spring pack	04/14/2023
098812	Replaced all drive tyres with 8 new tyres due to being worn	04/26/2023

097601	Replace gearbox	04/27/2023
097705	Replace drive tyres	04/28/2023
097731	Replace drive tyres	05/01/2023
097842	Asst parts for minor repairs	05/03/2023
097847	Replace front springs	05/03/2023
097883	Replace pto assy	05/04/2023
099064	Replaced both steer springs with parabolic springs	05/05/2023
098043	Repair Ac fault	05/08/2023
098121	Repairs to Ac fault parts supplied	05/09/2023
098126	Repairs to Ac fault	05/09/2023
099054	Aftertreat	05/09/2023
095031	(A) 250HR SERVICE @ (18,250) HR TKP KENWORTH T659	05/12/2023
099296	Replaced Alternator	05/12/2023
095030	(C) 1000HR SERVICE @ 18,118 (18,000) HR TKP KENWORTH T659	05/13/2023
101280	(A) 250HR SERVICE @ 18,118 (18,250) HR TKP KENWORTH T659	05/13/2023
099297	Replace F.Diff LH Hub seal & brakes	05/14/2023
099298	Clutch Adjustment	05/14/2023
099300	Changed LH Windscreen	05/14/2023
099941	Replace Crank Pulley	05/18/2023
098878	Replace drive tyres	05/21/2023
098966	Replace axle gaskets drive	05/22/2023
095032	(A) 250HR SERVICE @ 18,430 (18,500) HR TKP KENWORTH T659	05/29/2023
100045	Replace batteries	06/04/2023
095033	(A) 250HR SERVICE @ 18,729 (18,750) HR TKP KENWORTH T659	06/13/2023
100828	Replace add blue harness	06/14/2023
100832	Replace diff sensor	06/14/2023
100833	Repairs to trunnion	06/14/2023
101105	Crack spring and wear pads u/s	06/15/2023
103268	Top bonnet mount replaced	06/15/2023
095034	(C) 1000HR SERVICE @ 19,051 (19,000) HR TKP KENWORTH T659	06/29/2023
102234	Removed and replaced the right side windscreen due to chips	06/29/2023
102261	Repairs to diff 5258226	06/30/2023
102489	Replace wipers and side lights	07/04/2023
102719	Exhaust Leak	07/06/2023
095035	(A) 250HR SERVICE @ 19,307 (19,250) HR TKP KENWORTH T659	07/14/2023

103277	Drive Brakes U/S	07/15/2023
103130	Replace drive tyres	07/16/2023
103271	R/H Drive Springs	07/16/2023
103153	Replace drive springs and brakes	07/17/2023
103154	Replace axle gaskets	07/17/2023
103619	Replace LH headlight bucket, rewire headlight	07/20/2023
102604	Bears Mech conduct Certificate of Inspection/NHVAS	07/28/2023
103954	Repair Surging, misfire	07/31/2023
104186	Recover truck to Cummins	08/04/2023
104194	Replace engine assy	08/04/2023
104236	Replace turbo dump pipe	08/07/2023
104237	parts for clutch install and minor repairs	08/07/2023
104932	Topped up engine oil with 6 Litres	08/07/2023
095036	(A) 250HR SERVICE @ 19,735 (19,500) HR TKP KENWORTH T659	08/11/2023
105142	Replace roof lights	08/11/2023
105528	(A) 250HR SERVICE @ 19,753 (19,750) HR TKP KENWORTH T659	08/11/2023
105220	Replace nox sensor	08/14/2023
105629	Aftertreat Fault	08/15/2023
105916	Replace alternator assy	08/22/2023
105978	(C) 1000HR SERVICE @ 19,989 (20,000) HR TKP KENWORTH T659	08/23/2023
106216	Replace steer tyres	08/28/2023
107296	Removed jack shaft	08/28/2023
106334	Replace batteries	08/29/2023
106534	Replace Pinion seal	09/04/2023
107617	(A) 250HR SERVICE @ 20,259 (20,250) HR TKP KENWORTH T659	09/06/2023
107618	(A) 250HR SERVICE @ 20,591 (20,500) HR TKP KENWORTH T659	09/24/2023
108495	Replace x 8 drive tyres	09/24/2023
108814	Replace cab air bags	10/03/2023
109510	Replace front drive diff head	10/05/2023
110156	Re-wired coolant temperature sensor wiring from sender to	10/09/2023
109515	Replace Adblue dose injector - injector line	10/11/2023
109823	Starting issues	10/15/2023
107619	(A) 250HR SERVICE @ 20,988 (20,750) HR TKP KENWORTH T659	10/16/2023
107620	(C) 1000HR SERVICE @ 20,988 (21,000) HR TKP KENWORTH T659	10/16/2023
109490	Replace alternator	10/16/2023

109844	Replace addblue injector	10/18/2023
109970	Stop engine light	10/18/2023
110188	Headlight Fault	10/23/2023
107621	(A) 250HR SERVICE @ 21,391 (21,250) HR TKP KENWORTH T659	11/06/2023
111656	Install MT Data system	11/07/2023
111566	FIT NEW TYRES TKP768	11/08/2023
111947	Tested if engine would rev to 1500 with PTO engaged	11/11/2023
112888	Filled hydraulic oil, 60L	11/19/2023
112887	Replaced QR Valve	11/21/2023
115890	Aftertreatment light	11/21/2023
115891	Not pumping adblue	11/21/2023
112766	Replace 2 x steering tyres	11/26/2023
107622	(A) 250HR SERVICE @ 21,852 (21,500) HR TKP KENWORTH T659	11/29/2023
107623	(A) 250HR SERVICE @ 21,852 (21,750) HR TKP KENWORTH T659	11/29/2023
113713	Worn Uni joint	12/06/2023
113422	Replace uni joints	12/07/2023
114220	Replace drive tyres	12/15/2023
115102	Replace 8 x drive tyres	12/15/2023
114479	Replace alternator and belts	12/20/2023
115104	Replace exhaust flex joint	12/20/2023
114139	TMA Higher Mass Fees for all *2024	12/22/2023
115105	Air leak under cab	12/25/2023
115091	Failed downshaft centre bearing	12/26/2023
114698	Exhaust repairs	12/27/2023
114701	Replace steering shaft	12/27/2023
107624	(C) 1000HR SERVICE @ 22,412 (22,000) HR TKP KENWORTH T659	12/29/2023
115389	(A) 250HR SERVICE @ 22,412 (22,250) HR TKP KENWORTH T659	12/29/2023
112434	TMA Higher Mass Fees *2023	12/30/2023
114784	Rekit air dryer	01/08/2024
115592	Installed new relay housing for AC blower	01/11/2024
115584	Changed AC blower motor	01/13/2024
115622	Replace fan blower assy	01/15/2024
116358	Replaced drivers side windscreen due to being cracked	01/17/2024
117802	(A) 250HR SERVICE @ 22,744 (22,500) HR TKP KENWORTH T659	01/17/2024
117803	(A) 250HR SERVICE @ 22,744 (22,750) HR TKP KENWORTH T659	01/17/2024

121249	Driveline Vibration	01/17/2024
116600	Replace 4 x Anderson plugs, 6 x 10amp fuses, clean + grease	01/21/2024
116330	REFURBISH ISRI DRIVERS SEAT	01/22/2024
116773	Aftertreatment light on	01/25/2024
116795	refurb Isri seat	01/30/2024
117563	8 x drive tyres	01/31/2024
118161	Flush adblue system	02/04/2024
118166	Adblue fault	02/10/2024
117804	(C) 1000HR SERVICE @ 23,172 (23,000) HR TKP KENWORTH T659	02/11/2024
117805	(A) 250HR SERVICE @ 23,172 (23,250) HR TKP KENWORTH T659	02/11/2024
118176	Replace steering box	02/12/2024
118530	Replace output shaft and replace brakes	02/15/2024
120907	Removed & fitted a new fan belt	03/01/2024
119880	TRANSMISSION, CLUTCH & ACCESSORIES TKP768	03/04/2024
119937	OPTIMAX BEACON TKP768	03/04/2024
119984	Recover truck back to Ilm	03/05/2024
121020	Remove and replace gearbox and clutch	03/10/2024
120406	Replace gearbox	03/11/2024
120440	Replace batteries	03/11/2024
120441	Replace pitman arm	03/11/2024
121019	Remove + replace gearstick isolator	03/11/2024
120813	Supply ADBLUE pickup o'ring kits – part; HHW0116	03/18/2024
121694	2 x steer tyres	03/21/2024
117806	(A) 250HR SERVICE @ 23,774 (23500) HR TKP KENWORTH T659	03/24/2024
117807	(A) 250HR SERVICE @ 23,774 (23,750) HR TKP KENWORTH T659	03/24/2024
121657	Replace starter motor	03/25/2024
121843	Replace drive shaft and uni joints	03/26/2024
122005	Install new front half of driveline with centre bearing, due	03/27/2024
122041	Machine flywheel	03/28/2024
122049	Replace multifunction switch	03/28/2024
128442	Reported won't engage splitter or range while moving, have	03/28/2024
122394	Starting issues	03/29/2024
122164	8 x 11R22.5 roadway drive tyres	03/30/2024
122255	Refit indicator stalk	03/30/2024
122308	Repair Ac fault	04/04/2024

122309	Replace cab blower motor	04/04/2024
122695	Fix broken drive wheel fender/mudguard bracket	04/06/2024
122718	Repair Starting Issues	04/09/2024
123587	No head lights	04/16/2024
123443	NPR032378 SPOTLIGHTS U/S	04/19/2024
123588	Engine Derated	04/21/2024
117808	(C) 1000HR SERVICE @ 24,297 (24,000) HR TKP KENWORTH T659	04/25/2024
124445	(A) 250HR SERVICE @ 24,297 (24,250) HR TKP KENWORTH T659	04/25/2024
125571	Replaced headlight mount	05/02/2024
125570	Low engine oil & power steering oil	05/03/2024
126634	Driver reported "pop" sound behind dash and brief burning	05/04/2024
125948	Breakdown, rekitted LHS airdryer	05/09/2024
125950	Breakdown, air dryer gasket blown out, all bolts loose,	05/09/2024
125697	Remove and replace red dot relay 12v	05/15/2024
125131	(A) 250HR SERVICE @ 24,739 (24,500) HR TKP KENWORTH T659	05/19/2024
125132	(A) 250HR SERVICE @ 24,739 (24,750) HR TKP KENWORTH T659	05/19/2024
126129	Remove and repair radiator shroud + refit	05/19/2024
126131	Replace brake booster LHRD	05/19/2024
126632	RHS steer hub oil milky	05/19/2024
125897	Replace drive spring pack	05/20/2024
125898	Repairs to Ac fault	05/20/2024
127250	Aftertreat light on dash	05/29/2024
126987	Replace Add blue doser unit	05/30/2024
128738	Throwout bearing grease line	06/07/2024
117220	2023-2024 ** NHVAS INSPECTION - Passed 07.06.2024	06/07/2024
125133	(C) 1000HR SERVICE @ 25,048 (25,000) HR TKP KENWORTH T659	06/07/2024
128497	Alternator belt damaged	06/07/2024
128546	Front diff pinion seal leaking	06/07/2024
128564	2nd drive LHS + RHS axle gasket leaking	06/07/2024
128704	Repair bull bar pivot mounts, replace nuts & bolts	06/08/2024
128443	Replace air dryer kits	06/14/2024
129244	Travelled to call point 4 on McNamara road & replaced	06/19/2024
129259	Replace exhaust flex	06/23/2024
129263	Replace Alternator and belt	06/23/2024
125134	(A) 250HR SERVICE @ 25,507 (25,250) HR TKP KENWORTH T659	07/03/2024

125135	(A) 250HR SERVICE @ 25,507 (25,500) HR TKP KENWORTH T659	07/03/2024
130757	Replace LH drive springs + wear plates x 2	07/06/2024
131244	Repair derating fault	07/18/2024
130941	(A) 250HR SERVICE @ 25,831 (25,750) HR TKP KENWORTH T659	07/24/2024
131948	Repaired front bonnet & bull bar indicator	07/25/2024
132578	Coolant over temp/de-rated	08/02/2024
132579	Carry out brake adjustment	08/05/2024
132432	Replace fire extinguishers	08/07/2024
132588	Quote to repair diff 299715	08/08/2024
130942	(C) 1000HR SERVICE @ 26,277 (26,000) HR TKP KENWORTH T659	08/19/2024
130943	(A) 250HR SERVICE @ 26,277 (26,250) HR TKP KENWORTH T659	08/19/2024
133716	Tightened fuel lines on tanks	08/21/2024
133666	Replace horton fan	08/22/2024
134105	Truck leaking air	08/24/2024
135784	Engine light on	08/27/2024
130944	(A) 250HR SERVICE @ 26,627 (26,500) HR TKP KENWORTH T659	09/10/2024
134994	Critical Works Rekit Turntable 11.09.2024	09/11/2024
135282	8 x 11r22.5 roadway drive tyres	09/11/2024
135167	Quote to repair diff 260579	09/12/2024
135468	Repaired RH bonnet indicator and tidy up wiring to prevent	09/13/2024
135731	Driver's windscreen cracked	09/19/2024
135597	Replace starter motor	09/22/2024
135970	Replace radiator and shroud	09/29/2024
137174	No tail lights on trailers	10/03/2024
136843	Replace leaking axle gasket LHRD	10/05/2024
130945	(A) 250HR SERVICE @ 26,998 (26,750) HR TKP KENWORTH T659	10/11/2024
130946	(C) 1000HR SERVICE @ 26,998 (27,000) HR TKP KENWORTH T659	10/11/2024
137701	Replace pto assy	10/18/2024
137793	Replace uni joints and yoke	10/21/2024
137983	Repairs to rear light harness	10/23/2024
138000	Replace Tie rod and draglink	10/23/2024
138220	Replace 2 x cab airbag + fittings, as leaking	10/23/2024
138148	Replace clock spring	10/25/2024
139053	Breakdown, won't start	11/03/2024
130947	(A) 250HR SERVICE @ 27,389 (27,250) HR TKP KENWORTH T659	11/08/2024

130948	(A) 250HR SERVICE @ 27,389 (27,500) HR TKP KENWORTH T659	11/08/2024
138960	TKP768 Ignition barrel & key	11/08/2024
139318	Truck won't start	11/08/2024
139288	RH windscreen cracked	11/09/2024
139291	Axle oil temp lights n/w	11/09/2024
139230	Replace starting motor	11/11/2024
140834	Breakdown	11/20/2024
140293	Fibreglass repairs to quarter guard	11/28/2024
140811	8 x 11r22.5 roadway drive tyres	11/30/2024
140370	Replace front rhs fuel tank	12/02/2024
139179	(A) 250HR SERVICE @ 27,821 (27,750) HR TKP KENWORTH T659	12/10/2024
141239	Compressor head leaking	12/10/2024
141429	REPAIRS TO AIR TEMP SENSOR	12/12/2024
141471	Repairs to exhaust flex	12/16/2024
142317	AIR LEAK ON LHS ON TANK WAS A FITTING RUBBED THROUGH SO	12/28/2024
142326	AIR DRYER LEAKING, REPLACED RH AIR DRYER, REWIRING RH AND LH	12/29/2024
139180	(C) 1000HR SERVICE @ 28,182 (28,000) HR TKP KENWORTH T659	01/01/2025
139181	(A) 250HR SERVICE @ 28,182 (28,250) HR TKP KENWORTH T659	01/01/2025
140208	TMA Higher Mass Fees for all *2025	01/01/2025
140542	MT data - Monthly Service & Licence Fees for all *2025	01/01/2025
142018	Critical Works Ring Feeder 01.01.2025	01/01/2025
142020	Critical Works Tow Eye 01.01.2025	01/01/2025
142871	REPLACE FRONT RHS/ DS FUEL TANK	01/03/2025
144407	REPLACED 2 X BY 385/65R 22.5 ROADWAY STEERS TYRES	01/05/2025
114191	MT data - Monthly Service & Licence Fees for all *2024	01/09/2025
129336	TMA Higher Mass Fees for all *2024	01/09/2025
143437	Blown motor inop. Diagnosed blown fuse in dash due to high	01/14/2025
143496	Replace throttle position sensor & pin & roller as required	01/14/2025
143593	Guardian monitoring Monthly Fees for all *2025	01/17/2025
137792	Replace turbo and coolant	01/20/2025
139182	(A) 250HR SERVICE @ 28,595 (28,500) HR TKP KENWORTH T659	01/25/2025
144020	TKP768 Spring worn out	01/28/2025
144254	Welding repairs to fuel tank	01/30/2025
145144	8 x drive tyres	02/05/2025
145148	Down on power (no operate)	02/07/2025

145149	Road relay not working	02/07/2025
145392	Alternator not Charging	02/11/2025
145430	No Air build up	02/12/2025
145653	Replaced Air filters, cabin filter, fuel filter, coolant	02/15/2025
136444	2024-2025 ** NHVAS INSPECTION - Passed 15.02.2025	02/15/2025
139183	(A) 250HR SERVICE @ 28,965 (28,750) HR TKP KENWORTH T659	02/15/2025
139184	(C) 1000HR SERVICE @ 28,965 (29,000) HR TKP KENWORTH T659	02/15/2025
145880	Replace engine oil+filter, replaced gearbox oil+filter,	02/16/2025
145934	Replace 1 X Anderson plug on back of the truck due to	02/22/2025
145960	Rooved & replaced harness with new one and truck has been	02/22/2025
145724	Replace engine harness	02/24/2025
146384	Replace Charge Air Cooler	03/04/2025
146616	Repairs to hump hoses and intercooler	03/07/2025
146640	Replace fan blade	03/07/2025
146964	Repairs to Ac fault	03/12/2025
147382	Replaced 1 x by 11r/22.5 roadway drive tyres rear LHS	03/13/2025
147701	WELDING REPAIRS TO SCR PIPE	03/21/2025
147097	In chassis engine rebuild	03/27/2025
148321	Going from samples & inspection engine heads rebuild ,pull	03/27/2025
148856	Replaced smashed L/H windscreen	03/28/2025
148771	Set boost pressure plugs	04/04/2025
149484	Replaced both HD UHF microphone GME , Part No MC553B + No	04/04/2025
149480	Top up power steering flowed, Replace + peace for air blower	04/09/2025
139185	(A) 250HR SERVICE @ 29,393 (29,250) HR TKP KENWORTH T659	04/12/2025
139186	(A) 250HR SERVICE @ 29,393 (29,500) HR TKP KENWORTH T659	04/12/2025
149505	REPLACE HYD HOSES DKT 24990	04/14/2025
149777	Replace Steer spring packs	04/17/2025
150084	Critical Works Steering Components 18.04.2025	04/18/2025
150262	Replaced horton fan	04/22/2025
150688	REPAIRS TO AC FAULT	05/06/2025
149539	(A) 250HR SERVICE @ 29,802 (29,750) HR TKP KENWORTH T659	05/11/2025
151784	Check drag link + tie rod ends add to report	05/17/2025
152035	Repair LH fuel pick up line in tank, Tracking unit MT Data	05/20/2025
151411	Replace front diff	05/21/2025
152583	Replace with 2 X 385/65/225.5 Roadways steers	05/28/2025

149540	(C) 1000HR SERVICE @ 30,250 (30,000) HR TKP KENWORTH T659	06/10/2025
149541	(A) 250HR SERVICE @ 30,250 (30,250) HR TKP KENWORTH T659	06/10/2025
153408	Replaced hydraulic hose in birds nest LH side	06/16/2025
149542	(A) 250HR SERVICE @ 30,600 (30,500) HR TKP KENWORTH T659	06/27/2025
149543	(A) 250HR SERVICE @ 30,600 (30,750) HR TKP KENWORTH T659	06/27/2025
149709	SUPPLY MT DATA SPARES	06/30/2025
154804	Dash display & rod relay dropping in out send over to sos	07/08/2025
153494	REPLACE DOSER INJECTOR	07/15/2025
154331	REPAIRS TO DASH DISPLAY FAULT	07/18/2025
155378	(C) 1000HR SERVICE @ 30,942 (31,000) HR TKP KENWORTH T659	07/19/2025
155909	Replaced 8 X 11R 22.5 Roadway drivers tyres	07/19/2025
151138	REPLACE DRIVE SPRING PACKS	07/22/2025
155635	REPLACE AMBIENT AIR TEMP SENSOR	07/25/2025
155676	Supply Hose and Fittings dkt 1299330	07/27/2025
156942	Replaced hot hose	07/30/2025
157320	Replaced leaking RH rear drive booster with new unit	08/03/2025
156317	REPAIR STARTING FAULT	08/04/2025
155421	(A) 250HR SERVICE @ 31,274 (31,250) HR TKP KENWORTH T659	08/07/2025
160443	Replaced 4 worn rose joints and clutch adjuster	08/08/2025
159513	FUEL TAPS ON R/H/S WERENT TURNED ON ALL THE WAY SO FUEL	08/15/2025
157191	REPLACE CLUTCH AND BELL HOUSING	08/18/2025
159480	NO LIGHTS WORKING ON TRAILERS, TESTED AND REPLACED LIGHT	08/21/2025
159485	REPAIRED R/H HEADLIGHT, LOW BEAM WAS N/W, FOUND BROKEN WIRE	08/21/2025
157826	REPLACE BULLBAR BACKING PLATE	08/26/2025
159511	REPLACE AIRCON BELT DUE TO WEAR	08/26/2025
155422	(A) 250HR SERVICE @ 31,608 (31,500) HR TKP KENWORTH T659	09/03/2025
161293	Replaced hose clamp on Turbo Intake	09/04/2025
159074	REPAIRS TO SHORT IN HARNESS	09/09/2025
159079	REPLACE ENGINE HARNESS ECM	09/10/2025
158785	2025-2026 ** NHVAS INSPECTION	09/15/2025
160129	REPAIRED REVERSE LIGHT WIRING	09/23/2025
160130	REPLACED BOTH RYCOS AS THEY WERE LEAKING	09/23/2025
155423	(A) 250HR SERVICE @ 31,889 (31,750) HR TKP KENWORTH T659	09/27/2025
160869	2 X NEW ROADWAY 385.65.22.5 STEERS	10/01/2025
155424	(C) 1000HR SERVICE @ 31,996 (32,000) HR TKP KENWORTH T659	10/04/2025

162278	Removed & refitted gear box	10/06/2025
163588	RESEALED BELL HOUSING & G-BOX INPUT SEAL	10/06/2025
163589	REPLACED DUMP PIPE FLEX PIPE	10/06/2025
163590	REPLACED 3 X EXHAUST CLAMPS & 3 X EXHAUST GASKETS	10/06/2025
163591	REPLACED RH FUEL LINES	10/06/2025
162276	REPLACED ENGINE FAN	10/07/2025
160960	CRITICAL WORKS SAFETY ITEMS 08.10.2025	10/08/2025
162277	AXLE GASKET LEAKING	10/08/2025
162315	8 X NEW 11R 22.5 ROADWAY DRIVES	10/11/2025
160764	REPLACE REAR MAIN SEAL	10/16/2025
161728	BOLTS FOR TRUNION REPLACEMENT	10/17/2025
161790	TRUNNION REPAIRS	10/17/2025
161840	TRUNNION REPAIR	10/17/2025
155425	(A) 250HR SERVICE @ 32,301 (32,250) HR TKP KENWORTH T659	10/22/2025
155426	(A) 250HR SERVICE @ 32,491 (32,500) HR TKP KENWORTH T659	11/03/2025
163840	CRITICAL WORKS TOW EYE 09.11.2025	11/09/2025
164328	REPLACE S-CAM & BUSH & SLACK ADJUSTER	11/13/2025
164330	REPLACE BRAKE LINING	11/13/2025
164331	REPLACE HUB SEAL	11/13/2025
164332	REPLACE ALL WHEEL STUD BOLTS	11/13/2025
164333	REPLACE HUB GASKET	11/13/2025
164334	REPLACE TAP	11/13/2025
155427	(A) 250HR SERVICE @ 32,797 (32,750) HR TKP KENWORTH T659	11/19/2025
165335	REPLACED CRACKED DRIVER'S SIDE WINDSCREEN	11/19/2025
165336	REPLACED WORN CRANK PULLEY & FAN BELT	11/19/2025
165337	REPLACED DAMAGED ENGINE FAN	11/19/2025
165233	REPAIRED HEADLIGHT WIRING	11/20/2025
165338	REPLACE HIGH BEAM HEADLIGHT LEFT & RIGHT	11/22/2025
165444	REPLACE HEADLIGHTS	11/26/2025
165474	BLOWN RETURN LINE HYD HOSE PM TO TRAILERS	11/26/2025
165475	REPLACE RH REAR DRIVE BRAKE	11/26/2025
165476	8 X NEW DRIVE TYRES	11/26/2025
165477	JUMPED S-CAM	11/26/2025
165852	FUEL TANK	11/29/2025
166058	REPLACE 2 X SPEED SENSORS	12/04/2025

166278	REPAIRS TO FAULTY FUEL PUMP HEAD CHECK VALVES	12/08/2025
166429	REPLACED BOTH STEER TYRES WITH NEW	12/09/2025
165413	(C) 1000HR SERVICE @ 33,167 (33,000) HR TKP KENWORTH T659	12/10/2025
165414	(A) 250HR SERVICE @ 33,167 (33,250) HR TKP KENWORTH T659	12/10/2025
165415	(A) 250HR SERVICE @ (33,500) HR TKP KENWORTH T659	12/10/2025
166417	REPLACE DRIVE BRAKES AND DRUMS	12/10/2025
165416	(A) 250HR SERVICE @ (33,750) HR TKP KENWORTH T659	12/17/2025
166657	TMA HIGHER MASS FEES FOR ALL *2026	12/20/2025
165417	(C) 1000HR SERVICE @ (34,000) HR TKP KENWORTH T659	12/23/2025
165418	(A) 250HR SERVICE @ (34,250) HR TKP KENWORTH T659	12/30/2025
165419	(A) 250HR SERVICE @ (34,500) HR TKP KENWORTH T659	01/06/2026
165420	(A) 250HR SERVICE @ (34,750) HR TKP KENWORTH T659	01/13/2026
165421	(C) 1000HR SERVICE @ (35,000) HR TKP KENWORTH T659	01/19/2026
165422	(A) 250HR SERVICE @ (35,250) HR TKP KENWORTH T659	01/26/2026
165423	(A) 250HR SERVICE @ (35,500) HR TKP KENWORTH T659	02/02/2026
165424	(A) 250HR SERVICE @ (35,750) HR TKP KENWORTH T659	02/08/2026
165425	(C) 1000HR SERVICE @ (36,000) HR TKP KENWORTH T659	02/15/2026
165426	(A) 250HR SERVICE @ (36,250) HR TKP KENWORTH T659	02/22/2026
165427	(A) 250HR SERVICE @ (36,500) HR TKP KENWORTH T659	02/28/2026
165428	(A) 250HR SERVICE @ (36,750) HR TKP KENWORTH T659	03/07/2026
165429	(C) 1000HR SERVICE @ (37,000) HR TKP KENWORTH T659	03/14/2026