

QTY.	PART NO. AND DESCRIPTION	PRICE
7	$\frac{3}{8} \times 2\frac{1}{2}$ " bolts, lock fender & flat nuts, washers	6.30
3	K15145S MAXI pots	362.43
3	T1003	9.75
6	1493-8C	59.40
1	110800 VALVE	128.84
1	122D	2.68
2	121C	4.26
2	'97' wheel seals	110.50
2	litres 80W90	12.00
1	hub cap	20.98
2	hub cap gaskets	4.46
1	set brake shoes	56.25
1	long hardware kit	13.35
2	S20905 top plate	51.76
4'	$\frac{3}{16} \times 3 \times 6$ " tubing	167.74
3	sq. ft. $\frac{1}{4}$ plate	52.50
2	8709 AIRbags	367.26
2	121B	3.00
4	$\frac{3}{4}$ " NF nuts, lock & flat washers	6.32
4	11549	3.24
3	1468-6B	7.89
1	821000 Junction Box	20.31
3	10702	7.65
1	1050	9.00
4'	7 wire	12.12
4'	4 wire	7.52
8	blue butt connectors	8.00
6	yellow butt connectors	7.80
6'	$\frac{1}{4}$ " split loom	5.76
3	94902	8.37
12"	1" shrink tube	7.08
20	blue eyelids	3.00
4	848004	4.20
1	RK069731 5 th wheel bushings	137.38
1	mudflap	26.66
1	AK1471	54.65
1	1495L	8.39
1	122B	1.81
1	1469-6B	3.15

M.K.S. Trailer & Equipment Repairs Ltd.

716 Carter Crest Way
Edmonton, Alberta T6R 2N3

Shop: 780-451-3861

Cell: 780-966-2963

INVOICE **Nº 75466**

DATE: DEC 30 2022

NAME TERRA PRO INC.		
ADDRESS 53345 Range Road 232 Sherwood Park		CITY
PROVINCE AB		POSTAL CODE T8A 4V2
PURCHASE ORDER		
LICENSE NO. 5M4179	YEAR	MAKE/MODEL
SERIAL NO.	UNIT NO. 459A	

CNIP & SERVICE - Wheels off, full inspection
Straightened RHS mudflap bracket, weld crack and installed missing mudflap
Removed / Replaced: LR, RR, LC maxi pots; both haldex pins on rear axle; LC brake shoes; LR, RR wheel seals; dump valve & EMG valve
Cut out rotten tubing above rear airbags
Plated inside & outside of webs on both sides
Installed new tubing, air bag top plates and airbags
Installed new J box at rear and rewired back end
Painted repaired areas
Torqued all wheel nuts
Replaced fifth wheel bushings

34 Hrs 110 ⁰⁰	TOTAL LABOR	3740.00
	TOTAL PARTS	1783.75
	SHOP SUPPLIES	204.00
	SUB TOTAL	5727.75
	GST # 877828343	286.39
	TAX	
	TOTAL	6,014.14

