

Richy B Contracting Ltd.
 RR2, Site 4, Box 45
 Barrhead AB T7N 1N3
 780-674-7476
 richycontracting@gmail.com

Invoice 2189

235-1
 JUN



BILL TO

Dean Gordon Trucking Ltd.

DATE
 04/05/2022

APR 06/22

PLEASE PAY
 \$40,836.50

DUE DATE
 05/05/2022

DATE	DESCRIPTION	HOURS	RATE	TAX	AMOUNT
03/31/2022	Richard (9:00 am - 3:00 pm--6 hours) Unit YML 445: John Deere 2154D S#1FF2154DHA0210153 Located @ Richy B Shop I brought the John Deere reman long block out from storage. Then installed an engine oil cooler and remote filter housing. I installed the front engine cover and bell housing.	6	145.00	GST	870.00
04/02/2022	Dustin (5:00 am - 4:30 pm--11.5 hours) Unit YML 445: John Deere 2154D S#1FF2154DHA0210153 Located@(53.651131, -117.25750) ,Yellowhead Cnty, AB We set the machine in a position to work on it. Then removed the needed access covers and set them aside. We drained the engine coolant and disposed of it. Then unbolted the muffler and set it aside. We unbolted the hydraulic pumps and supported them. Then unbolted the A/C compressor from the engine and supported it. We unbolted the fan pump and supported it. Then unhooked the fuel lines and needed wire harness. We unbolted the engine from the car body and removed it with our crane. Then we set the engine in a transport stand and hauled it to our shop for repair.	11.50	120.00	GST	1,380.00
04/02/2022	Kylie (5:00 am - 4:30 pm--11.5 hours) Unit YML 445: John Deere 2154D S#1FF2154DHA0210153 I assisted Dustin with preparing and loading the unit for repair.	11.50	40.00	GST	460.00
04/02/2022	Richard (9:00 am - 6:00 pm--9 hours) Unit YML 445: John Deere 2154D S#1FF2154DHA0210153 Located @ Richy B Shop I installed new injectors and a rocker cover. Then installed a new water pump and pulley. We received the old engine, and removed the engine oil and disposed of it. Then I removed the oil pan, turbocharger, exhaust manifold, and studs. I removed the fuel injection lines and the starter from the old engine. Then removed the alternator and other needed parts from the old engine. I put some of the parts in the typhoon washer and started to clean them. Then installed a new reman injection pump on the new engine.	9	145.00	GST	1,305.00

APRIL 7/22
 CH# 13517
 \$40,836.50

Thank you for your business.

DATE	DESCRIPTION	HOURS	RATE	TAX	AMOUNT
04/03/2022	Richard (9:00 am - 6:00 pm—9 hours) Unit YML 445: John Deere 2154D S#1FF2154DHA0210153 Located @ Richy B Shop I installed a fuel injection rail from my stock, with a new rail pressure sensor and rail relief. Then I installed the cleaned fuel injection lines. I installed a new fuel rail heat shield. Then installed new front and rear crank seals. I installed a new belt tensioner and belt idler. Then installed the thermostat housing with a new thermostat. I installed the rest of the front engine parts. Then installed the cleaned oil pan and oil pump pipe. I installed oil pressure sensors and the old exhaust manifold studs. Then installed the old exhaust manifold with the old bolts. I installed a new reman turbocharger, and a new engine wire harness. Then installed the injector hold down clips and a new injector wire harness. I installed a new injector harness heat shield. Pre-lubed the engine with our lube machine with break-in oil. Then wrapped the engine up for transport to the site.	9	145.00	GST	1,305.00
04/03/2022	Parts: a) 1 - SE501791 JD Long Block - \$14,655.17 b) 1 - R516125 O-ring - \$5.09 c) 1 - R55453 O-ring - \$11.10 d) 1 - RE528609 Wire Harness, Injector - \$678.31 e) 1 - RE516335 Rail Relief Valve - \$665.35 f) 1 - RE520930 Rail Pressure Sensor - \$646.42 g) 1 - RE505939 Vibration Dampener - \$1,305.18 h) 1 - DZ102076 Block Heater - \$234.19 i) 1 - SE501609 Water Pump - \$494.84 j) 1 - 294000-0564EX Denso HP3 HPCR Injection Pump - \$1,581.31 k) 1 R520929 Dipstick Tube - \$44.82 l) 1 - R523340 Heat Shield - \$249.99 m) 1 - SE502192 Turbocharger - \$2,319.99 n) 1 - AT344143 Engine Wire Harness - \$1,827.09 o) 1 - RE33705 Thermostat - \$18.86 p) 1 - RE167207 Oil Pressure Sensor - \$174.23 q) 1 - RE55145 Oil Pressure Switch - \$244.89 r) 1 - DZ120069 Fuel Lift Pump - \$114.90 s) 1 - R522410 Heat Shield - \$316.28 t) 1 - R120467 Elbow Fitting - \$17.26 u) 1 - R521548 Seal - \$9.40 v) 1 - AT211041 Idler - \$96.99 w) 1 - RE548027 Belt Tensioner - \$222.41 x) 1 - FYB0000114 Pump Drive Coupler - \$1,262.06 y) 1 - RE504836 Engine Oil Filter - \$43.83 z) 1 - Re522878 Fuel Filter - \$66.25 aa) 1 - RE541922 Fuel Filter - \$56.86 bb) 1 - T223368 Turbo Air Hose - \$115.16 cc) 2 - TY26663 Break-in Oil Pail - \$169.64 x 2 = \$339.28 dd) 6 - SE501925 - \$634.43 x 6 = \$3,806.58 Total: \$31,624.09			GST	31,624.09

Thank you for your business.

DATE	DESCRIPTION	HOURS	RATE	TAX	AMOUNT
04/04/2022	Dustin (4:30 am - 10:00 pm--17.5 hours) Unit YML 445: John Deere 2154D S#1FF2154DHA0210153 Located@(53.651131, -117.25750) ,Yellowhead County, AB We removed the engine from my truck and unwrapped it. Then removed it from the engine stand and installed the mounts. We set the engine in the car body and bolted it in place. Then we coupled the hydraulic pumps to the engine and bolted them on. We hooked up the engine wire harness and fuel lines. Then hooked up the air lines and the coolant hoses. We changed the engine oil filter and fuel filters. Then bled the fuel system, and started the engine while checking for leaks. We installed the new engine trim codes with my laptop. Then filled it with new coolant. We ran the unit and worked the engine while checking for leaks. Then reinstalled the hoods and access panels. We stopped at the customer's shop in Edson and picked up an engine to haul to our shop for repair.	17.50	120.00	GST	2,100.00
04/04/2022	Kylie (4:30 am - 10:00 pm--17.5 hours) Unit YML 445: John Deere 2154D S#1FF2154DHA0210153 I assisted Dustin with the repair of this unit.	17.50	40.00	GST	700.00
04/04/2022	Parts: a) 30 Litres of Antifreeze \$3.34 x 30 =\$100.20 Total: \$100.20			GST	100.20
04/04/2022	Note: JD Reman S# SE6068Z006409 — Machine Hours: 24,542.0				
04/06/2022	Good Client Discount			Exempt	-1,000.00

Make all cheques payable to: Richy B Contracting Ltd.

SUBTOTAL	38,844.29
GST @ 5%	1,992.21
TOTAL	40,836.50

NOTE: DUE UPON RECEIPT

Restocking charge is 25%. No return on electrical.

TOTAL DUE	\$40,836.50
-----------	--------------------

THANK YOU.

Thank you for your business.

