

D16-5
MAY

Urban Repair Inc.
PO Box 20069, Century Crossing
Spruce Grove AB T7X 0S2
+17806994067
accounting@urbanrepair.ca
GST/HST Registration No.:
818111700RT0001



Invoice

BILL TO
BOYD VENTURES INC

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
25-0283	07/04/2025	\$9,042.36	08/30/2025	EFM	

DESCRIPTION	QTY	RATE	AMOUNT
Unit: 152 Year: 2019 Make: Kenworth Model: W900 VIN: 1XKWD40XDXJ949181 KM: 1 016 882 Hours: 18 403			
Job: Hook up Insite and perform injector cut out test. Found injector #5 no good.	0.50	145.00	72.50
Computer Connection Fee	1	135.00	135.00
Job: Remove crossover pipe and valve cover. Replace #5 injector. Run truck. Did not help with grey smoke/engine missing.	2	145.00	290.00
Job: Check valves. Found #5 exhaust valve extremely tight. Had to back off 3/4 of a turn before getting any lash. Remove rockers and valve bridges. Drain coolant and remove rad assembly. Remove fan, fan hub, and fan shroud. Remove timing cover and unload scissor gear. Remove cam gear and idler gear. Remove turbo.	8.50	135.00	1,147.50
Job: Remove EGR valve assembly and bracket. Remove exhaust manifold. Remove thermostat housing. Remove camshaft. Strip left side of cylinder head. Remove injectors. Remove cylinder head. Clean deck. Swap parts from old head to new head. Paint cylinder head.	7	145.00	1,015.00
Job: Finish scraping sanded deck. Clean out all bolt holes. Clean deck with brake clean. Install head gasket and head. Wash and wire wheel head bolts. Oil all bolts. Install bolts and torque head. Install and wedge cam shaft. Pin crank shaft.	7	145.00	1,015.00
Job: Install timing gears and set base timing. Install timing cover. Put new seals on injectors and install. Install fuel rail and fuel lines. Install rockers and torque.	6	145.00	870.00
Job: Adjust valves and jakes. Install injector harness and valve cover. Completely assemble left side of engine.	4.50	145.00	652.50
Job: Completely assemble right side of engine minus turbo actuator.	7.50	145.00	1,087.50

DESCRIPTION	QTY	RATE	AMOUNT
Job: Pick up parts at KW on customer account.	1	145.00	145.00
Job: Install and calibrate turbo actuator. Install all intake air piping. Fill coolant. Change engine oil and oil filter. Run engine and perform high pressure fuel test. #6 fuel line leaking.	4	145.00	580.00
Job: Remove batteries from battery box to access bolts for the air tank assembly. Unbolt air tank and remove tank assembly.	1.50	145.00	217.50
Job: Install new fittings in tanks. (Tank is different from the original.) Mounted tanks. Lengthened three air lines. Hook up all lines. Install batteries and cover. Install #6 injector line and run truck.	7	145.00	1,015.00
Fittings - Purchased for job	1	113.32	113.32
Fittings - From stock	1	47.01	47.01
Shop Supplies	1	208.91	208.91
Past due invoices will be subject to late charges of 2% per month (24% per annum).			
		SUBTOTAL	8,611.74
		GST @ 5%	430.62
		TOTAL	9,042.36
		BALANCE DUE	\$9,042.36

Please note that credit card payments will also be subject to a 2% service charge.
We appreciate your business and look forward to helping you in the future!

Urban Repair Inc.
 PO Box 20069, Century Crossing
 Spruce Grove AB T7X 0S2
 +17806994067
 accounting@urbanrepair.ca
 GST/HST Registration No.:
 818111700RT0001



Invoice

BILL TO
 BOYD VENTURES INC

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
25-0146	03/18/2025	\$2,183.87	04/30/2025	EFM	

DESCRIPTION	QTY	RATE	AMOUNT
Unit: 152 Year: 2019 Make: Kenworth Model: W900 VIN: 1XKWD40XDXJ949181 KM: 994 863 Hours: 18 104			
Job: Check left side of engine for leak. Found one high pressure fuel line leaking at fuel pump. Tighten line, wash, and blow dry. Perform high pressure test. Pass.	1	145.00	145.00
Job: Remove drive shaft and yoke for access to trans cooler.	1	145.00	145.00
Job: Drain coolant to replace trans cooler lines. Found trans cooler loose on transmission. Tighten cooler back up and replace cooler-coolant hose.	2.50	145.00	362.50
Job: Try to straighten headache rack. Check fifth wheel slider for excess wear (well within specs).	1	145.00	145.00
Job: Jack up truck. Put front end on frame stand. Remove right hand spring pins and shackles. Remove bottom right hand spring pin.	2	145.00	290.00
Job: Shrunk rear eye on right spring with torch so bushing would fit tightly.	0.50	145.00	72.50
Job: Clean eye for spring. Install new spring pin and bushing. Weld in the spring pin bushing. Install shackles. Grease pins. Jack up truck and remove the frame stand.	2	145.00	290.00
Job: Set valves and jakes	2.50	145.00	362.50
Job: Install yoke on transmission, install drive shaft, and grease driveline.	1	145.00	145.00
Hardware	1	30.20	30.20
Grease (no charge)	1	0.00	0.00
Shop Supplies	1	92.16	92.16

Please note that as of April 2024, credit card payments will be subject to a 2% service charge.
We appreciate your business and look forward to helping you in the future!

SUBTOTAL	2,079.86
GST @ 5%	104.01
TOTAL	2,183.87
BALANCE DUE	\$2,183.87

Urban Repair Inc.
 PO Box 20069, Century Crossing
 Spruce Grove AB T7X 0S2
 +17806994067
 accounting@urbanrepair.ca
 GST/HST Registration No.:
 818111700RT0001



Invoice

BILL TO
 BOYD VENTURES INC

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
25-0102	03/06/2025	\$2,322.99	04/30/2025	EFM	

DESCRIPTION	QTY	RATE	AMOUNT
Unit: 152 Year: 2019 Make: Kenworth Model: W900 VIN: 1XKWD40XDXJ949181 KM: 981 416 Hours: 17 918			
Job: Remove passenger side step. Unhook all electronic/DEF connections from emissions cannister. Remove emissions cannister from truck to hollow it out.	1	145.00	145.00
Job: Mark and remove/unthread sensors from emissions cannister. Remove clamps holding cannister together. Split into four sections. Air hammer out all the insides of cannister. Buff all graphite gaskets off of mating surfaces.	2.50	145.00	362.50
Job: Reassemble emissions cannister. Tie up all harnesses nice and neat on can. Install back into truck and reinstall passenger step frame and step.	2	145.00	290.00
Job: Remove ECM for reprogramming	0.50	145.00	72.50
Job: Remove exhaust from back of turbo	0.50	145.00	72.50
Job: Empty DEF tank	0.50	145.00	72.50
Job: Install block off plates at EGR bellows and at crossover pipe to intake manifold.	1	145.00	145.00
Job: Drill hole in exhaust behind turbo to stick pyro probe inside. Remove dash panels. Remove DEF gauge from dash. Install pyro gauge. Run probe through firewall to exhaust fitting. Tie into key on power for gauge. Reinstall dash panels.	2.50	145.00	362.50
Pyrometer	1	584.48	584.48
Shop Supplies	1	105.37	105.37

Please note that as of April 2024, credit card payments will be subject to a 2% service charge.
We appreciate your business and look forward to helping you in the future!

SUBTOTAL	2,212.35
GST @ 5%	110.64
TOTAL	2,322.99
BALANCE DUE	\$2,322.99

urban repair Inc.
 PO Box 20069, Century Crossing
 Spruce Grove AB T7X 0S2
 +17806994067
 accounting@urbanrepair.ca
 GST/HST Registration No.:
 818111700RT0001



Invoice

BILL TO
 BOYD VENTURES INC

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
25-0022	01/16/2025	\$479.59	03/02/2025	EFM	

DESCRIPTION	QTY	RATE	AMOUNT
Unit: 152 Year: 2019 Make: Kenworth Model: W900 VIN: 1XKWD40XDXJ949181 KM: 958 888 Hours: 17 535			
Job: Install bumper assist springs and brackets. Bumper is much easier to open/close.	1	145.00	145.00
Job: Remove crossover pipe (EGR). Remove valve cover and replace gasket. Reinstall cover and pipe. Drain coolant and replace coolant pipe on right front frame rail. Reinstall coolant.	2	145.00	290.00
Shop Supplies	1	21.75	21.75
Please note that as of April 2024, credit card payments will be subject to a 2% service charge. We appreciate your business and look forward to helping you in the future!			
		SUBTOTAL	456.75
		GST @ 5%	22.84
		TOTAL	479.59
		BALANCE DUE	\$479.59

urban repair Inc.
 PO Box 20069, Century Crossing
 Spruce Grove AB T7X 0S2
 +17806994067
 accounting@urbanrepair.ca
 GST/HST Registration No.:
 818111700RT0001



Invoice

BILL TO
 BOYD VENTURES INC

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
24-0110	01/07/2025	\$5,607.91	03/02/2025	EFM	

DESCRIPTION	QTY	RATE	AMOUNT
Unit: 152 Year: 2018 Make: Kenworth Model: W900 VIN: 1XKWD40XDXJ949181 KM:958 247 Hours: 17 518			
Commercial Vehicle Inspection - unit pass - write up and decal unit - #8261911	1	250.00	250.00
Wheels off per axle	3	100.00	300.00
Job: Go to Kenworth to pick up parts on customer account. Remove and replace all six axle shocks. Remove and replace cab air bags. Remove and replace cab bump stops.	5	145.00	725.00
Job: Remove and replace all brake shoes and drums. Readjust all brakes.	3.50	145.00	507.50
Job: Remove and replace stack bushings	2	145.00	290.00
Job: Source parts. Remove air piping and valve cover. Adjust valves and jakes.	4	145.00	580.00
Job: Replace right heated convex mirror. Tried finding wiring problem for rear diff temp sensor.	2	145.00	290.00
Job: Drain coolant to fix coolant leak. Check exhaust for leaks. Found bellow leaking.	1	145.00	145.00
Job: Fix coolant leak. Refill coolant. Install new back up alarm. Remove old exhaust bellow. Buff clean all pipes and install new bellows kit.	4	145.00	580.00
Back up alarm	1	40.36	40.36
Job: Remove SS blade bumper. Mount new herd bumper bracket on truck. Pound old bumper bushings out and install new ones.	1	145.00	145.00
Job: Drill hole for bumper pin in 4" aluminum flat bar. Weld flat bar to bumper to patch where pin previously tore through. Install new slam latch on bumper. Install bumper on truck. Order new spring assist kit.	3	145.00	435.00

We accept cheque, Visa, Mastercard, EFT and email money transfer. Please call for more information.

DESCRIPTION	QTY	RATE	AMOUNT
Flat bar	1	15.86	15.86
Job: Grease unit. Check rear of truck for air leaks. Remove and replace purge valve. Run truck and soap test rear for air leaks.	2	145.00	290.00
Grease	1	10.00	10.00
Windshield	1	504.00	504.00
Shop Supplies	1	233.14	233.14
Please note that as of April 2024, credit card payments will be subject to a 2% service charge. We appreciate your business and look forward to helping you in the future!			
SUBTOTAL			5,340.86
GST @ 5%			267.05
TOTAL			5,607.91
BALANCE DUE			\$5,607.91

We accept cheque, Visa, Mastercard, EFT and email money transfer. Please call for more information.



ROJ ENTERPRISES INC.
 670 ATHABASCA ST. WEST
 KAMLOOPS, B.C.. V2H1C4
 Phone: 250-319-1505 Fax: 250-377-7785
 TAKING CARE OF BUSINESS

INVOICE

49297

897758322

INVOICE

Printed Date: 06/06/2025

Work Completed: 06/05/2025

BOYD VENTURES INC.

2019 Kenworth - W900 - Cummins X15 CM2350 X116B 6 CYL

Lic # : A73649

Odometer In : 0

Unit # : 152

VIN # : 1XKWD40X0 KJ949181

Home
 Office
 Driver :

Part Description	Number	Qty	Sale	Ext	Labor Description	Hours	Ext
AFTER HOURS CALL OUT AHC		1.00	200.00	200.00	***Vehicle Memo*** Cab Card #AB8134-1		
EGR Step Boot 3687223 Shop Supplies		1.00	186.08	186.08	After hours service on June 5 call to Petro Pass at Kokanee Way Kamloops BC for blown EGR	1.00	175.00
				17.50	Arrived at location, confirmed blown EGR step boot. Removed blown boot and replaced with new. Got driver to start unit and ensure no exhaust leaks.		

Org. Estimate 0.00 Revisions 0.00 Current Estimate 0.00

Labor:	175.00
Parts:	403.58
SubTotal:	578.58
Tax:	28.93
Total:	607.51
Bal Due:	\$607.51

[Payments -]

WARRANTY : 90 DAYS LABOUR 1 YEAR PARTS

Vehicle Received: 6/5/2025

Customer Number : 3555

I hereby authorize the above repair work to be done along with the necessary materials, under the terms and conditions here on. All labour and materials supplied in the above vehicle remain the property of ROJ Enterprises Ltd. until full payment is received for same. Terms are 30 days from the date of invoice and overdue accounts will be subject to a 19% per month late fee. Vehicles not picked up within 7 days of the work completed will be subject to a \$80/day storage fee. Any disputes against an invoice must be made within 14 days of the invoice print date.

IF WHEELS REMOVED FOR REPAIRS PLEASE RETORQUE WITHIN 150KMS

Signature _____ Date _____

Visit us on the web: www.WWW.ROJTRUCKANDTRAILER.CA

Email Address: Jcdhalliwal@rojtruckandtrailer.ca

Urban Repair Inc.
 PO Box 20069
 Spruce Grove AB T7X 0S2
 +1 7806994067
 accounting@urbanrepair.ca
 GST/HST Registration No.:
 818111700RT0001



Invoice

BILL TO
 BOYD VENTURES INC

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
597	03/15/2024	\$12,703.93	04/14/2024	Net 30	

DESCRIPTION	QTY	RATE	AMOUNT
Unit #: 152 Year: 2019 Make: Kenworth Model: W-900 VIN: 1XKDW40XDXJ959181 LP: A73649 KM: 834 716 Hours: 15 760			
Job: Disassembled entire engine for in-frame	12	135.00	1,620.00
Job: Scraped deck. Removed pistons from rod and stamped them. Disassembled pump and inspected (Good). Reassembled.	2	135.00	270.00
Job: Finished scraping deck.. Buff deck and liner boxes.. Chase all head bolt holes and blow out.	3	135.00	405.00
Job: Go to Edmonton Kenworth. Pick up parts on customer account. Stop to wash oil pan and all other parts to be painted at truck wash.	1.50	135.00	202.50
Power wash unit - Per Minute	15	1.75	26.25
Job: Remove water pump to inspect. OK. Reinstalled. Remove EGR cooler and oil cooler. Replaced oil cooler thermostat and oil cooler element. Cleaned up all surfaces and reassembled.	8	135.00	1,080.00
Job: Installed shims and liners. Assembled pistons in liners. Torqued all rod caps. Replaced and torqued all main bearings. Install piston cooling nozzles.	8	135.00	1,080.00
Job: Installed oil pump. Replaced thermostat. Cleaned up and painted parts off engine.	5	135.00	675.00
Job: Parts run (drive from Urban to Prime Engine to pick up cylinder head. Load. Drive back to Urban.	1.75	135.00	236.25
Job: Set head on truck and torque down. Try to remove timing pin plug. Stripped it out, welded nut to it (after removing neg battery terminals.) Installed cam and timing pin and wedge.	2.50	135.00	337.50
Job: Painted rest of engine parts. Installed parts on head. Put valve cover on head and painted head and cover.	6.50	135.00	877.50

We accept cheque, Visa, Mastercard, EFT and email money transfer, Please call for more information.

DESCRIPTION	QTY	RATE	AMOUNT
Job: Installed head and torqued. Installed cam and timing gears. Set base timing. Installed timing cover. Installed bridges and rockers. Set valves. Install manifold, turbo, AC comp, alternator and fan hub.	12.50	135.00	1,687.50
Job: Remove and replace all silicone heater lines on PS of engine. Fill engine with water and pressure test.	4	135.00	540.00
3/4" Silicone heater hose (by the foot)	9	10.27	92.43
5/8" Silicone heater hose (by the foot)	6	9.65	57.90
5/8 constant tension clamps	5	3.50	17.50
Job: Installed intake manifold. Installed fuel rail. Cleaned injectors. Replaced tip seals and O-rings. Installed injectors and connecting tubes. Installed all injector lines and supply lines. Installed injector wiring harness.	7	135.00	945.00
Job: Go to EKW to pick up timing pin plug on customer account and AC bolt (included in shop supplies). Install stiffener plate and pick up tube and pil pan and torque to spec.	2	135.00	270.00
Job: Installed valve cover. Crankcase filter BRK and filter assy. Install charge air piping. Ran truck up with water and restore for 90 minutes. Drained cooling system and ran up again. Drained again and removed reservoir and filled with cold parts cleaner. Soaked for 1 hour. Drained and flushed with water. Reinstalled and filled with coolant. Ran up and checked over. All good.	5	135.00	675.00
Valve cover gasket	1	118.70	118.70
Job: Installed last AC line plus leak tested and charged AC system. Hooked up hood springs and cables. Changed coolant line from thermostat housing to EGR valve. Greased unit.	2.50	135.00	337.50
A/C machine connection fee	1	135.00	135.00
R134A - Refrigerant per pound	4	28.34	113.36
Grease	1	10.00	10.00
Shop Supplies	1	289.06	289.06
We appreciate your business and look forward to helping you in the future!			
		SUBTOTAL	12,098.95
		GST @ 5%	604.98
		TOTAL	12,703.93
		BALANCE DUE	\$12,703.93

We accept cheque, Visa, Mastercard, EFT and email money transfer. Please call for more information.

Urban Repair Inc.
 PO Box 20069, Century Crossing
 Spruce Grove AB T7X 0S2
 +17806994067
 accounting@urbanrepair.ca
 GST/HST Registration No.:
 818111700RT0001



Invoice

BILL TO
 BOYD VENTURES INC

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
25-0099	03/19/2025	\$294.00	04/30/2025	EFM	

DESCRIPTION	QTY	RATE	AMOUNT
Unit: 152 Year: 2019 Make: Kenworth Model: W900 VIN: 1XKWD40XDXJ949181			
Job: Scan engine ECM to find why check engine light is on. Found EGR valve no good. Customer notified.	1	145.00	145.00
Computer Connection Fee	1	135.00	135.00
SUBTOTAL			280.00
GST @ 5%			14.00
TOTAL			294.00
BALANCE DUE			\$294.00

Please note that as of April 2024, credit card payments will be subject to a 2% service charge.
 We appreciate your business and look forward to helping you in the future!

urban repair Inc.
 PO Box 20069, Century Crossing
 Spruce Grove AB T7X 0S2
 +17806994067
 accounting@urbanrepair.ca
 GST/HST Registration No.:
 818111700RT0001



Invoice

BILL TO
 BOYD VENTURES INC

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
24-0009	11/06/2024	\$796.69	12/30/2024	EFM	

DESCRIPTION	QTY	RATE	AMOUNT
Unit #: 152 Year: 2019 Make: Kenworth Model: W900 VIN: 1XKWD40XDXJ949181 LP: A73649 KM: 931 962 Hours: 17 115			
Job: Remove herd bumper and mounting bracket. Call FGI for replacement herd bracket. Supplier said it would be a day or two to be able to price it out. Decided to temporarily install factory bumper.	2	145.00	290.00
Job: Travel to Boyd shop. Measure bumper, load up, and bring to Urban shop.	1	145.00	145.00
Job: Install replacement temporary bumper with stainless hardware. Remove LP bracket and modify to mount plate above bumper so that it doesn't get ripped off.	1	145.00	145.00
Stainless hardware	1	146.08	146.08
Shop Supplies	1	32.68	32.68
SUBTOTAL			758.76
GST @ 5%			37.93
TOTAL			796.69
BALANCE DUE			\$796.69

Please note that as of April 2024, credit card payments will be subject to a 2% service charge.
 We appreciate your business and look forward to helping you in the future!

Remit To: Edmonton Kenworth Ltd.

17335 118 Avenue
Edmonton, AB
T5S 2P5

Tel: 780-453-3431 Fax: 780-454-6124

Purchased From:
Edmonton Kenworth (West)
17335 - 118 Avenue
Edmonton, Alberta T5S 2P5
Phone: 780-453-3431

Invoice: 28M0812672
Date / Hour: 12/9/2024 11:01:43AM
Repair Order: 12672
Customer:
Branch: M08
Total Invoice: 919.79
Charge
Page 1 of 1

Bill To: BOYD VENTURES INC.

Ship To: BOYD VENTURES INC.

Office Phone:
Shop Phone:

Email:

Work:

Shop:

Fax:

Customer P/O:	Open Date: 11/24/2024	Completion Date: 11/28/2024
Add User: Ltassier	Salesperson: Vcoulter	
Unit Number: 152	Model Year: 2019	Make/Model: KENWORTH W900L
Type: Class 8	VIN: 1XKWD40X0KJ949181	Meter: 943544 Kilometers

Task: 1 31-000010 Charging System - Battery - Diagnose Department: ServTruck

Complaint: Customer complaint of the batteries going dead.

Cause: Inspected the batteries pulled the connections load tested the batteries all tested good. Cleaned the terminals hooked back up started unit it starts and runs OK. The problem persisted looked over the battery cables, alternator cables, mega fuses and common rub points. Found a damaged wire on the DEF power supply connector under the battery box. Repaired the wire tied up so it won't rub wrapped in protective hose tied up loose wires. Hooked up to the ECM's checked for faults there wasn't any. Ran unit turned the electrical load up as high as possible. Checked the alternator output it was good checked the battery cables and other wire for amperage running and off found the engine heater drawing power with the key off. Disconnected the heater informed the customer they are going to send it in for a rebuild.

Correction: Made RO charged out parts restocked and invoiced.

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
P0100	54001403	TERMINAL	EA	1.0	\$0.76	\$0.76
P0100	CT05512	TIE-CABLE 120LB, 15.25" BLK	EA	8.0	\$1.04	\$8.32
P0100	D1030-2585	HOSE-RADIATOR #36 J20R1-A ET RR SIL	FT	1.0	\$44.06	\$44.06
	STSSE	ENV/MISC SUPPLIES		1.0	\$60.95	\$60.95

Customer Tax ID: 853752756RT0001

Detail Tax Info:

GST REGISTRATION NUMBER: R101577278
Total: \$43.80

3.33	Total Parts:	\$53.14
	Total Labor:	\$761.90
	Total Miscellaneous:	\$60.95
	Invoice Subtotal:	\$875.99
	Total Tax:	\$43.80
	Total Invoice:	\$919.79

Payment Method: ***Charge***
Terms: Net 15th of month
Due Date: 1/15/2025

I/WE HEREBY ACKNOWLEDGE INDEBTEDNESS IN THE AMOUNT OF \$ _____ FOR THE PARTS AND LABOUR ON THIS WORK ORDER AND IT IS ACKNOWLEDGED THAT THE SAID AMOUNT MAY BE ADJUSTED ON FINAL PRICING. IF THE BALANCE DUE ISN'T PAID WITHIN EDMONTON KENWORTH'S CREDIT TERMS. I AGREE TO PAY INTEREST AT THE RATE OF 2% PER MONTH (24% ANNUUM) PLUS \$30.00 PER DAY STORAGE FEE.

SIGNATURE _____ DATE/TIME _____

PRINT NAME: _____

Urban Repair Inc.
 PO Box 20069
 Spruce Grove AB T7X 0S2
 +1 7806994067
 accounting@urbanrepair.ca
 GST/HST Registration No.:
 818111700RT0001



Invoice

BILL TO
 BOYD VENTURES INC

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
646	04/05/2024	\$788.71	05/05/2024	Net 30	

DESCRIPTION	QTY	RATE	AMOUNT
Unit #: 152 Year: 2018 Make: Kenworth Model: W900 VIN: 1XKWD40XDXJ959181 KM: 835 025 Hours: 15 771			
Job: Found corroded wires at back of truck. Neither tail lights on skirt nor headache rack were working. Repaired wiring and changed one oval tail light on headache rack. Drained coolant and removed headline from oil cooler to turbo-coolant supply line.	2.50	135.00	337.50
Sig/Tail light	1	33.59	33.59
Small wiring kit	1	5.00	5.00
Job: Parts run	1	135.00	135.00
Job: Reinstalled new hard line and filled coolant. Ran truck to find air leak at air dryer. Found press in union leaking. Replaced push in union with compression union.	1.50	135.00	202.50
Compression union	1	4.99	4.99
Shop Supplies	1	32.56	32.56

We appreciate your business and look forward to helping you in the future!

SUBTOTAL	751.14
GST @ 5%	37.57
TOTAL	788.71
BALANCE DUE	\$788.71

Urban Repair Inc.
 PO Box 20069
 Spruce Grove AB T7X 0S2
 +1 7806994067
 accounting@urbanrepair.ca
 GST/HST Registration No.:
 818111700RT0001



Invoice

BILL TO
 BOYD VENTURES INC

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSURE
597	03/15/2024	\$0.00	04/14/2024	Net 30	

DESCRIPTION	QTY	RATE	AMOUNT
Unit #: 152 Year: 2019 Make: Kenworth Model: W-900 VIN: 1XKDW40XDJ959181 LP: A73649 KM: 834 716 Hours: 15 760			
Job: IN FRAME ENGINE	71	135.00	9,585.00
Job: Remove water pump to inspect. OK. Reinstalled. Remove EGR cooler and oil cooler. Replaced oil cooler thermostat and oil cooler element. Cleaned up all surfaces and reassembled.	8	135.00	1,080.00
Job: Parts run (drive from Urban to Prime Engine to pick up cylinder head. Load. Drive back to Urban.	1.75	135.00	236.25
3/4" Silicone heater hose (by the foot)	9	10.27	92.43
5/8" Silicone heater hose (by the foot)	6	9.65	57.90
5/8 constant tension clamps	5	3.50	17.50
Job: Installed last AC line plus leak tested and charged AC system. Hooked up hood springs and cables. Changed coolant line from thermostat housing to EGR valve. Greased unit.	2.50	135.00	337.50
A/C machine connection fee	1	135.00	135.00
R134A - Refrigerant per pound	4	28.34	113.36
Grease	1	10.00	10.00
Shop Supplies	1	289.06	289.06

1XKDW40XDJ959181

PAID

SUBTOTAL	11,954.00
GST @ 5%	597.71
TOTAL	12,551.71
PAYMENT	12,551.71
BALANCE DUE	\$0.00

Urban Repair Inc.
 PO Box 20069
 Spruce Grove AB T7X 0S2
 +1 7806994067
 accounting@urbanrepair.ca
 GST/HST Registration No.:
 818111700RT0001



Invoice

BILL TO
 Boyd Ventures

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
478	11/14/2023	\$380.63	12/14/2023	Net 30	

DESCRIPTION	QTY	RATE	AMOUNT
UNIT: 152 YEAR: 2019 MAKE: KENWORTH MODEL: W900 VIN: 949191 KMS: 806597 HOURS: 15373 Job: Assess/ repair coolant leak -Pressurize cooling system. Mark where 2 leaks were found. Drain coolant and remove 2 leaking hoses. Retrieve new parts for repair. Install new hose and clamps. Refill colling system. Pressurize, test for leaks, all good.	2.50	135.00	337.50
Shop Supplies	1	25.00	25.00

We appreciate your business and look forward to helping you in the future!

SUBTOTAL	362.50
GST @ 5%	18.13
TOTAL	380.63
BALANCE DUE	\$380.63

we accept cheque, Visa, Mastercard, EFT and email money transfer, Please call for more information.

Urban Repair Inc.
 PO Box 20069
 Spruce Grove AB T7X 0S2
 +1 7806994067
 accounting@urbanrepair.ca
 GST/HST Registration No.:
 818111700RT0001



Invoice

BILL TO
 Boyd Ventures

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSURE
464	10/26/2023	\$522.38	11/25/2023	Net 30	

DESCRIPTION	QTY	RATE	AMOUNT
UNIT: 152 YEAR: 2018 MAKE: KENWORTH MODEL: W900 VIN: 949181 KMS: 793975 HOURS: 15218 Job: Assess/ repair air leak on top of transmission -Listen under truck for air leaks and soap test lines on top of transmission. Find main compressor line leaking. Go to EKW and Greggs to pick up new line and reusable ends. Return to shop and continue with repairs. Fish air line through top of transmission and attach new ends. air truck up and test for leaks. all good.	3.50	135.00	472.50
Shop Supplies	1	25.00	25.00
SUBTOTAL GST @ 5% TOTAL BALANCE DUE			497.50 24.88 522.38 \$522.38

We appreciate your business and look forward to helping you in the future!

Urban Repair Inc.
 PO Box 20069
 Spruce Grove AB T7X 0S2
 +1 7806994067
 accounting@urbanrepair.ca
 GST/HST Registration No.:
 818111700RT0001



Invoice

BILL TO
 Boyd Ventures

INVOICE #	DATE	AMOUNT DUE	DUE DATE	TERMS	ENCLOSURE
421	09/19/2023	\$1,729.46	10/19/2023	Net 30	

DESCRIPTION	QTY	RATE	AMOUNT
UNIT: 152 YEAR: 2018 MAKE: KENWORTH MODEL: W-900 VIN: 949181 KMS: 769076 HOURS: 14897			
Job: Removed both rear stainless fenders. Dropped truck driver off at Acheson. Go to Fort Gary to pick up parts on customer account. Get back to sho and unload new fenders. Started lining up on truck.	2	135.00	270.00
Job: Serviced engine. Scanned ECM for wrench light on. Found crank case pressure high and engine oil temp high.	2	135.00	270.00
Computer Connection Fee	1	135.00	135.00
Job: Replaced crank case filter. Replaced oil filler neck, O-ring and oil cap	1.50	135.00	202.50
Job: Mount 2nd rear fender. Made sure they were spaced evenly on both sides	5	135.00	675.00
Bolt kit	1	16.16	16.16
Shop Supplies	1	78.44	78.44

We appreciate your business and look forward to helping you in the future!

SUBTOTAL	1,647.10
GST @ 5%	82.36
TOTAL	1,729.46
BALANCE DUE	\$1,729.46

Urban Repair Inc.
 PO Box 20069
 Spruce Grove AB T7X 0S2
 +1 7806994067
 accounting@urbanrepair.ca
 GST/HST Registration No.:
 818111700RT0001



Invoice

BILL TO
 Boyd Ventures

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
393	08/16/2023	\$818.62	09/15/2023	Net 30	

DESCRIPTION	QTY	RATE	AMOUNT
Unit: 152 VIN: 1KWD40XDKJ949181 Year/Make/Model: 2018 Kenworth W900 751,000 Kilometers 14,655 Hours			
Job: Engine fan runs constantly. Trouble shoot engine fan problem. Determined fan solenoid no good. Replaced solenoid.	1.50	135.00	202.50
Job: Take driver from SG shop to pick up different unit at truck wash in Acheson. Go to EKW and Peterbilt to pick up parts on customers' account.	1	135.00	135.00
Job: Trouble shoot bunk A/C. Found blower not working. Replaced bunk blower motor.	3	135.00	405.00
Shop Supplies	1	37.13	37.13
Unit: 152 VIN: 1KWD40XDKJ949181 Year/Make/Model: 2018 Kenworth W900 751,000 Kilometers 14,655 Hours			
		SUBTOTAL	779.63
		GST @ 5%	38.99
		TOTAL	818.62
		BALANCE DUE	\$818.62

We accept cheque, Visa, Mastercard, EFT and email money transfer. Please call for more information.

Urban Repair Inc.
 11072 - 261 Street
 Acheson T7X6C7
 +1 7806994067
 accounting@urbanrepair.ca
 GST/HST Registration No.:
 818111700RT0001



Invoice

BILL TO
 Boyd Ventures

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
373	07/25/2023	\$623.01	08/24/2023	Net 30	

DESCRIPTION	QTY	RATE	AMOUNT
Unit: 152 VIN: 1KWD40XDKJ949181 Year/Make/Model: 2018 Kenworth W900 733,745 Kilometers 14,429 Hours			
Job: Replaced diff filter. Repaired LR signal/ brake light. Evacuated A/C. Drained coolant and removed rad assembly. Removed A/C condenser and charge air cooler from rad. Washed out all three cores. Reassembled and installed assembly. Recharged and filled coolant.	4	135.00	540.00
R134A - Refrigerant per pound	1	28.34	28.34
Supplies	1	25.00	25.00
Unit: 152 VIN: 1KWD40XDKJ949181 Year/Make/Model: 2018 Kenworth W900 733,745 Kilometers 14,429 Hours			
		SUBTOTAL	593.34
		GST @ 5%	29.67
		TOTAL	623.01
		BALANCE DUE	\$623.01

Urban Repair Inc.
 11072 - 261 Street
 Acheson T7X6C7
 +1 7806994067
 accounting@urbanrepair.ca
 GST/HST Registration No.:
 818111700RT0001



Invoice

BILL TO
 Boyd Ventures

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
328	06/13/2023	\$516.36	07/13/2023	Net 30	

DESCRIPTION	QTY	RATE	AMOUNT
Unit: 152 VIN: 1KWD40XDKJ949181 Year/Make/Model: 2018 Kenworth W900 709,638 Kilometers Engine: 14,103 Hours			
Job: Air hammered out old clutch brake and installed two piece brake. Checked alternator output, 14.3 volts (Okay) Checked 5th wheel slide for back and forth movement (3/16") OOS spec 3/8"	1.50	135.00	202.50
Parts: Clutch Brake	1	61.76	61.76
Job: Straightened drivers side exhaust stack. Found 2 broken spots in rear diff temp sensor lead. Cut out broken parts, spliced back together and heat shrunked.	1.50	135.00	202.50
Supplies	1	25.00	25.00
Unit: 152 VIN: 1KWD40XDKJ949181 Year/Make/Model: 2018 Kenworth W900 709,638 Kilometers Engine: 14,103 Hours			
		SUBTOTAL	491.76
		GST @ 5%	24.60
		TOTAL	516.36
		BALANCE DUE	\$516.36

We accept cheque, Visa, Mastercard, EFT and email money transfer. Please call for more information.

Urban Repair Inc.
 11072 - 261 Street
 Acheson T7X6C7
 +1 7806994067
 accounting@urbanrepair.ca
 GST/HST Registration No.:
 818111700RT0001



Invoice

BILL TO
 Boyd Ventures

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
332	06/13/2023	\$425.25	07/13/2023	Net 30	

DESCRIPTION	QTY	RATE	AMOUNT
Unit: 152 VIN: 1KWD40XDKJ949181 Year/Make/Model: 2018 Kenworth W900 Chassis: 710,435 Kilometers Engine: 14,118 Hours			
Job: Assess/ Repair check engine light on -Scanned ECM, found code for low coolant sensor. Replaced sensor, plug and terminals. Code went inactive. Assess/ Repair Aux lights not working. Found fuse blown and one light not working. It was unplugged and pigtail to cab skirt was shorting. Plugged back in and now working. no charge for ECM connection fee	2	135.00	270.00
Job: Drive to Edmonton kenworth for parts exchange (Female/ male pins)	1	135.00	135.00
Unit: 152 VIN: 1KWD40XDKJ949181 Year/Make/Model: 2018 Kenworth W900 Chassis: 710,435 Kilometers Engine: 14,118 Hours			
		SUBTOTAL	405.00
		GST @ 5%	20.25
		TOTAL	425.25
		BALANCE DUE	\$425.25

Urban Repair Inc.
 11072 - 261 Street
 Acheson T7X6C7
 +1 7806994067
 accounting@urbanrepair.ca
 GST/HST Registration No.:
 818111700RT0001



Invoice

BILL TO
Boyd Ventures

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
272	03/30/2023	\$1,180.00	04/29/2023	Net 30	

DESCRIPTION	QTY	RATE	AMOUNT
UNIT: 152 YEAR: 2018 MAKE: KENWORTH MODEL: W960 VIN: 949181 KMS: 671326 HOURS: 13595			
Job: Assess/ repair leaking exhaust manifold -Change manifold gaskets/ manifold slip joint gaskets -Drain coolant, remove air 2 air pipes and turbo air -Remove exhaust from turbo, remove turbo -Remove manifold, split manifold and change gaskets -Reassemble manifold sections -Install and torque manifold -Install turbo, refill coolant -Reattach air 2 air pipe -Run truck up and test for leaks, all good	6.50	135.00	877.50
Job: Assess/ repair leak under DS cab door, loose fender -Remove DS rear fender -Remove 1 rear fender stud -Install new stud with red loctite -Reinstall fender -Remove and install new reducer hose of EGR valve	1.50	135.00	202.50
Shop Supplies	1	43.80	43.80

We appreciate your business and look forward to helping you in the future!

SUBTOTAL	1,123.80
GST @ 5%	56.20
TOTAL	1,180.00
BALANCE DUE	\$1,180.00

ENTERED APR 03 2023

SCANNED

Urban Repair Inc.
 11072 - 261 Street
 Acheson T7X6C7
 +1 7806994067
 accounting@urbanrepair.ca
 GST/HST Registration No.:
 818111700RT0001



Invoice

BILL TO
 Boyd Ventures

INVOICE #	DATE	TOTAL DUE	DUPLICATE	TERMS	ENCLOSURE
#242	02/02/2023	\$708.76	03/04/2023	Net 30	

DESCRIPTION	QTY	RATE	AMOUNT
UNIT: 152 YEAR: 2018 MAKE: KENWORTH MODEL: W900 VIN: 1XKWD40X0KJ949181 KMS: 646186 HOURS: 13269.7 Job: Replace fan blade -Drain coolant, discharge A/C -Removed air 2 air pipes and removed top rand hose and overflow hose -Unbolted hood spring supported hood and top rad supports - Pushed rad forward and changed fan blade -Reinstalled everything -Refilled coolant	2.50	135.00	337.50
Job: Repair power steering leaks -Drained PS reservoir -Replaced two clamps on one hose -Replaced one hose and both clamps on other hose -Refill PS reservoir -Jacked up front of truck and bled steering -Cleaned oil off bottom of front diff with brake cleaner and wire brush -Applied light bead of silicone	1	135.00	135.00
Job: Replaced wabasto coolant taps -Removed tap on side of head and rear of waterpump housing -Installed new tap and 3/4" barb in side of head and in back of water pump housing -Reattached hoses and refilled cooling system	1.50	135.00	202.50
We appreciate your business and look forward to helping you in the future!			
SUBTOTAL			675.00
GST @ 5%			33.76
TOTAL			708.76
BALANCE DUE			\$708.76

ENTERED FEB 07 2023

Urban Repair Inc.
 11072 - 261 Street
 Acheson T7X6C7
 +1 7806994067
 accounting@urbanrepair.ca
 GST/HST Registration No.:
 818111700RT0001



Invoice

BILL TO
 Boyd Ventures

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
216	01/17/2023	\$5,700.00	02/16/2023	Net 30	

Unit 152

DESCRIPTION	QTY	RATE	AMOUNT
YEAR: 2018 MAKE: KENWORTH MODEL: W900 VIN: 1KWD40XDKJ949181 KMS: 645893 HOURS: 13251			
Job: Checked over truck, made list of all parts needed -Removed fenders from rear axle -Removed rear mudflap hangers -Tested engine wabasto, not working	4	135.00	540.00
Job: Mount 2 x 14" step boxes (started) -Removed old step from one side chain hanger from other -Drilled holes in mounting plates to line up to existing frame holes -Mounted boxes to L-brackets, prepped to weld L-brackets to mounting plates -Removed walking deck and air/lights hookups -Undid PS fuel tank straps, chased threads -Moved tank forward 1.5", drilled 2 new holes in frame on P/S for step- tool box -Hung boxes and leveled -Welded out and cleaned up	5	135.00	675.00
Job: Mounted new chain hangers/ mudflap brackets fit hangers to truck, reamed out existing frame holes, marked new holes in brackets -Drilled out brackets, bolted both brackets to frame and tightened	4	135.00	540.00
Bolt kit	1	60.00	60.00
Job: Painted first coat on step box brackets -Changed both A/C and main serpentine belts -Change fuel filter and water separator -Drained air tanks and changed leaking Y-fitting at rear -Painted second coat on step box brackets	4	135.00	540.00

ENTERED FEB 21 2023

Scanned

DESCRIPTION	QTY	RATE	AMOUNT
Job: Mounted step brackets to truck, bolted boxes to brackets -Soldered extension wire harness to headache rack to splice into harness at rear -Centered headache rack and clamped to frame with U-bolts -Capped walking deck and remounted to truck -Fabbbed new air/ power cord bracket for headache rack -Mounted tractor protection valve to headache rack	5.50	135.00	742.50
Job: Tightened fender brackets on front axle fender stubs -Removed exhaust shields -Removed donkney ear exhaust tips	2	135.00	270.00
Job: Replace low beam headlights with heated LED lights -Replaced both heated convex mirrors -Replaced burnt out Aux lights on left side of truck -Connected wiring from headache rack to rear truck harness	4	135.00	540.00
Job: Hooked up trailer air lines/ electrical - Retrieved parts from supplier -Cut mudflaps to fit hangers	2	135.00	270.00
Bushings and fittings	1	32.03	32.03
Job: Removed bunk diesel heater -Unhooked fuel line and intake exhaust -Unhooked hose inside -Unbolted unit and removed lented (3 siezed nuts) -Bolted heater back down, hooked up fuel and intake exhaust hoses -Test ran unit, bunk blows heat	1.50	135.00	202.50
Job: Disconnected and removed engine wabasto -Removed wabasto coolant hoses -Removed 5/8" barbed fitting from block and installed 3/4" barbed fittings -Installed engine wabasto and new heater hoses -Tested unit but would not fire, found no fuel coming to heater -Checked fuel pump and fuel line, found fuel line disconnected at tank -Hooked line back up and tested, works well now	3	135.00	405.00
3/4" heater hose 6ft	1	57.24	57.24
3/4" punch clamps	4	9.88	39.52
Job: Remove front bumper -Remove assist springs -Unbolted front bumper from truck -Drilled existing 1/2" bushing holes out to 5/8" -Reinstalled bumper and assist springs -Tete opened and closed bumper, no more slope	3	135.00	405.00
Shop Supplies	1	109.77	109.77
We appreciate your business and look forward to helping you in the future!			
		SUBTOTAL	5,428.56
		GST @ 5%	271.44
		TOTAL	5,700.00
		BALANCE DUE	\$5,700.00

We accept cheque, Visa, Mastercard, EFT and email money transfer, Please call for more information.