

**#100 - 10609 - 79 Ave
Clairmont, Alberta T8X 5G9
Canada**

GL 5410
Unit #127

B16-1
SEP

Invoice No.: 6761
Date: 2025-11-20
Page: 1

SCOTT HYDRO-VAC
PO BOX 341
RPO SOBEYS
FORT ST JOHN, BC V1J 6W7

SCOTT HYDRO-VAC
PO BOX 341
RPO SOBEYS
FORT ST JOHN, BC V1J 6W7
UNIT #SH1273

Quantity	Unit	Description	Tax	Base Price	Disc %	Unit Price	Amount
		AS PER WORK ORDER #5927					
		LABOR	G				8,514.00
		PARTS	G				80,155.01
		SHOP SUPPLIES	G				851.40
		HAZARDOUS MATERIALS	G				340.56
		Subtotal:					89,860.97
		G - GST 5%					
		GST/HST					4,493.05
GST# 721647725RT0001						Total Amount	94,354.02
						Amount Paid	0.00
A charge of 2% per month compounded monthly (26.8 per annum) may be assessed on overdue accounts						Amount Owng	94,354.02

Anarchy Mechanical Ltd

#100 - 10609 79 Ave

CLAIRMONT, AB. T8X5G9

Phone: 780-814-8555 Fax: 780-814-8599

5927

Org. Est. # 00674

SCOTT HYDRO-VAC - JORDAN

PO BOX 341 RPO SOBEYS

FORT ST. JOHN, BC V1J6W7

Home 250-261-1705

2014 Kenworth - T800 - Cummins ISX15 CM2350 6 CYL

Lic # :

Odometer In : 304132

Unit # : SH127

VIN # : 1NKDX4TX6 ER967226

Engine Hrs In : 17944.1

Engine Hours Out : 0.0

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
ENGINE, ISX 15 DR8650RXCUM	1.00	75,555.56	75,555.56	ENGINE SWAP	7,590.00
BOLT-FLANGE M16X2X70 10.9 W34-1095-070	4.00	10.74	42.96	Unit came in for engine swap, we removed the engine and installed a drop in engine from Kenworth. After transferring all outer components, removed oil pan to swap over oil pickup tube and orientation of oil pan. Removed turbo manifold to block off due to unit being deleted. Filled engine with new oil and coolant ran up to temp checked for leaks - good.	
GASKET- CIRCULAR 5" 2866337CUM	1.00	25.66	25.66	TRANSMISSION COOLER LINE - REPAIR	198.00
KENWORTH REAR ENGINE MOUNT M17495	2.00	289.31	578.62	Found transmission cooler line leaking, removed and replaced hose.	
HOSE-RADIATOR F50-1050-0850	1.00	143.46	143.46	REAR ENGINE MOUNTS - R&I	363.00
GREASE LINE V50-6027-01525	1.00	82.63	82.63	Removed and replaced rear engine mounts.	
RADIAL SEAL OUTER AIR ELEMENT RS5288	2.00	100.90	201.80	CLUTCH INPUT SHAFT KIT - INSTALL	363.00
BELLOW - EXHAUST EBPB11861	1.00	527.56	527.56	Installed a new clutch input shaft, cross shaft bushings and clutch brake, had flywheel resurfaced.	
GASKET - PUMP HYDRAULIC 4988280CUM	1.00	8.05	8.05	Hazardous Material	340.56
CLAMP HC19-288	2.00	26.03	52.06		
3/4" HEATER HOSE Size: FT HHS1250OE	6.00	6.25	37.50		
SEAL-O RING 3033247CUM	1.00	17.54	17.54		
CLAMP-V BAND 4" 90-0012	1.00	24.34	24.34		
CLUTCH-15.5" 2050 TQ 7 SP 108925-25AM	1.00	1,517.86	1,517.86		
BEARING-RLR NDL SG 0.75B HJ122012	1.00	70.30	70.30		
RACE 1R812	1.00	42.85	42.85		
CLUTCH INSTALL KIT K3762CL	1.00	450.68	450.68		
CLUTCH BRAKE SB200	1.00	69.50	69.50		
REGORUND FLYWHEEL FLYWHEEL-HD	1.00	125.00	125.00		
CLUTCH SHAFT GW20222	1.00	55.73	55.73		
EATON - CROSS SHAFT	1.00	36.79	36.79		

Email Address: reception@anarchymechanical.ca

Phone: 780-814-8555 Fax: 780-814-8599

Org. Est. # 00674:

Engine Hours Out : 0.0

Org. Estimate	94,354.02	Revisions	0.00	Current Estimate	94,354.02
---------------	-----------	-----------	------	------------------	-----------

[Payments -]

Copyright (c) 2025 Mitchell Repair Information Company, LLC invhrs 5.1221kr