

X37-1 Sept



SMYL CHEVROLET BUICK GMC LTD.
3520 KEPLER ST.
WHITECOURT, AB T7S 0B5
PHONE: 780-778-2202
FAX: 780-778-3398
WWW.SMYLCHEV.COM

INVOICE ORIGINAL
Work Order
#240596
Terracore Rentals LTD
November 28, 2024
Svc: Adv Hoff, Blaine
Cust.Ph. (780) 980-4949
Tag#

Page 1 of 3
02/20/2025 10:16:53

To: Terracore Rentals LTD		Year: 2017 Veh Id: 57505 Unit #:
11507-272 Street		Make: Chevrolet License #:
Acheson	AB	Model: Silverado 2500 SWB 4WD Cr Odo. In: 296,549
T7X 6E9		Colour: White Odo. Out:
		V.I.N.#: 1GC1KWEYXHF195713 Next Service:
		Date In: 11/28/2024 In Service Date: 09/18/2017
		Out: 02/19/2025 14:15 Cases: 2
		Ext. War - - (mo/) - D: \$0.00 R/Lab. Rate 175.00
		Promised Time: 00/00/0000 00:00:00 AM Call When Ready: No

Case: 1 Diagnose and report for Vehicle will accelerate on its own when driving.. Vehicle was just in for same concern.---- Refer to Ro#240073

Quantity	Description/Correction	Retail	Price	Total
1.00	12731639 - Engine	12,803.79	10,500.00	10,500.00
8.00	12664576 - SEAL-COMBUSTION F/INJR	\$11.67	\$11.67	\$93.36
8.00	12686813 - SEAL-F/INJR (O RING)	\$11.81	\$11.81	\$94.48
2.00	12705094 - Gasket	\$52.13	\$52.13	\$104.26
1.00	86792094 - CONNECTOR KIT-FWD LP WRG HARN	\$84.02	\$84.02	\$84.02
16.00	12654651 - Washer	\$8.83	\$8.83	\$141.28
1.00	87839947 - Hose Asm - Chrg Air Clr	\$872.40	\$697.00	\$697.00
1.00	12611935 - Pulley	\$143.16	\$143.16	\$143.16
1.00	12656797 - BELT-FAN & W/PMP & GEN & P/S PUMP	\$145.89	\$145.89	\$145.89
1.00	12672821 - GASKET-CTLTC CONV	\$11.45	\$11.45	\$11.45
2.00	12643149 - GASKET-ENG COOL THERM HSG	\$11.73	\$11.73	\$23.46
1.00	12672822 - GASKET-EXH SYS FRT	\$6.61	\$6.61	\$6.61
2.00	12688019 - Gasket	\$55.62	\$55.62	\$111.24
1.00	12671847 - GASKET-PCV TUBE	\$6.05	\$6.05	\$6.05
1.00	12677294 - GASKET-TURBO	\$59.91	\$59.91	\$59.91
3.00	12691866 - Gasket	\$5.96	\$5.96	\$17.88
1.00	12737099 - Gasket	\$12.40	\$12.40	\$12.40
1.00	12737100 - Gasket	\$11.85	\$11.85	\$11.85
3.00	12688018 - Gasket	\$54.21	\$54.21	\$162.63
1.00	84303174 - Block	\$485.94	\$388.81	\$388.81
2.00	12662187 - GASKET-TURBO OIL FEED PIPE	\$17.49	\$17.49	\$34.98
1.00	84224661 - RADIATOR ASM-ENG	\$1,112.07	\$950.00	\$950.00
1.00	84013962 - SEAL-EXH SYS	\$35.65	\$35.65	\$35.65
6.00	11602016 - BOLT/SCREW-	\$16.01	\$16.01	\$96.06

GST Reg # 104897806



SMYL CHEVROLET BUICK GMC LTD.
3520 KEPLER ST.
WHITECOURT, AB T7S 0B5
PHONE: 780-778-2202
FAX: 780-778-3398
WWW.SMYLCHEV.COM

INVOICE ORIGINAL
Work Order
#240596
Terracore Rentals LTD
November 28, 2024
Svc. Adv. Hoff, Blaine
Cust. Ph. (780) 960-4949
Tag#

Page 2 of 3
02/20/2025 10:16:54
\$16.20 \$16.20 \$81.00
\$308.77 \$238.70 \$477.40
\$6.30 \$6.30 \$59.85
\$28.25 \$28.25 \$28.25
\$909.31 \$727.60 \$727.60
\$82.59 \$82.59 \$82.59
\$4,240.50 \$4,240.50

5.00 10953456 - COOLANT, 50/50 MIX
DEXCOOL AND DE-IONIZE
2.00 88866309 - Batw/exch
9.60 88866794 - Oil
1.00 88865654 - FLUID, DIESEL EXHAUST
(DEF) ACDELCO 9.46L
1.00 84630270 - TANK-EMIS RDCN FLUID
1.00 84113571 - Harness

- Diagnose and report for Vehicle will accelerate on its own when driving.. Vehicle was just in for same concern.--- Refer to Ro#240073.
- Tech Comments: Scanned unit for codes. 5 codes found.
- Called tag and they advised to inspect reluctor on crankshaft. Removed starter and crankshaft sensor
- Found- Reluctor has come off the crank shaft. Reassembled to move vehicle outside and priced out engine. Contacted and notified customer.
- Started engine replacement. Found under hood fuse block is corroded and charge air cooler pipe has come apart and is held together by a clamp. Recovered A/C and continued to replace engine. Found left lower corner of radiator leaking. Serpentine belt is stretched and one idler pulley bearing is rough. Finished removing engine and disassembled parts and had to transfer to new engine. Reinstalled new engine, new radiator and charge air cooler pipe. Tested batteries both failed battery tests. Installed new batteries. Filled oil and recharged A/C, filled coolant.
- Started engine, performed crankshaft relearn. Has service emissions and speed restriction codes on the DIC. Diagnosed for emissions msg. One code setting P206B- Reductant quality sensor. Drained DEF and put new fluid and retested- Code till sets. Found faulty reductant quality sensor in DEF tank.
- Replaced DEF tank and jumper harness. Cleared codes and no codes returned. Will need tamper test to get speed restriction to go away.
- Performed tamper test and all lights went out.
- Test drove- Test Good
- NEW ENGINE:
 - PART- # FGM12731639
 - DATE- 01/14/2025
 - SERIAL # 250090001

• Core Charges - 12731639 \$6,000.00 \$6,000.00
• Core Return - 12731639COR (\$6,000.00) (\$6,000.00)
• Miscellaneous \$23.54 \$23.54

Misc \$23.54 Labour \$4,240.50 Parts \$15,389.1 Prepaid Parts Amt: \$0.00 Case Total: \$19,653.16

Case: 2 Added Operation: Replace front fascia - Tech Comments: Replaced ripped off bumper fascia

Quantity	Description/Correction	Retail	Price	Total
1.00	22978557 - Deflector	\$430.55	\$344.53	\$344.53
3.00	20632 - Retainer	\$2.30	\$2.30	\$6.90



SMYL CHEVROLET BUICK GMC LTD.
3520 KEPLER ST.
WHITECOURT, AB T7S 0B5
PHONE: 780-778-2202
FAX: 780-778-3398
WWW.SMYLCHEV.COM

INVOICE ORIGINAL
Work Order
#240596
Terracore Rentals LTD
November 28, 2024
Svc. Adv Hoff, Blaine
Cust. Ph. (780) 960-4949
Tag#

Page 3 of 3
02/20/2025 10:16:54
\$2.15 \$2.15 \$6.45
\$28.25 \$28.25 \$28.25
\$262.50 \$262.50

- 3.00 17222 - Retainer
- 1.00 88865654 - FLUID, DIESEL EXHAUST
(DEF) ACDELCO 9.46L
- Added Operation: Replace front fascia
- Tech Comments: Replaced ripped off bumper fascia
- Miscellaneous

Misc	\$1.46	Labour	\$262.50	Parts	\$386.13	Prepaid Parts Amt:	\$0.00	Case Total:	\$650.09
									\$0.00

Notes
- Terry Penney
780-289-25555
Blaine Hoff - 12/03/2024 11:00:51

JESSE- 780-622-4860
Blaine Hoff - 02/18/2025 10:38:26

O U T	Indebtedness is hereby acknowledged for the "Total Charges" being bill or the balance owing to repairs, parts & accessories described in this work order		Currency	Labour:	\$4,503.00
	Warranty on parts and labour is 3 years or 60,000km's whichever occur first on OEM parts. Some OEM powertrain components may have a 5 year or 160,000km's whichever occur first. Used parts and aftermarket components do not have any labour warranty.		Payment Ref:	Parts:	\$15,775.25
	Shop supplies are based on 11% of the labour total to a maximum of \$25.00.		Expiry Date:	Misc:	\$25.00
			P/O#: TR-15616-77	Sub Total:	\$20,303.25
		G/HST Reg # 104897806	G/HST:	\$1,015.14	
			PST:	\$0.00	
			Tax Adjustment:	\$0.00	
02/19/2025		Signature	Payment Type	Total:	\$21,318.39