

KENDZE MECHANICAL
 SERVICES LTD.
 RR1 SITE 9 BOX 14
 DIDSBURY, ALBERTA.
 TOMOWO
 (403) 559-4012



*E02-5
JW*

Invoice #PS-1514
 Number: 84837 3130 RT0001

Customer	BLUEDON FARMS	Date	09/11/2024
		Comments	2012 JOHN DEERE S680 DUAL WHEEL. VIN # 1HOS680SHD0756995
		Service Writer	LUKE KENDZE
		PO #	0

Part Number	Description	Qty/Price	Net
DE31275	TRANSMISSION CASE	1 @ \$45,826.46	\$37,486.04
DE31275CORE	TRANSMISSION CASE CORE	1 @ \$4,158.00	\$4,158.00
AZ101765	ACCUMULATOR PART	1 @ \$614.15	\$502.37
H174603	ACCUMULATOR PART	1 @ \$22.37	\$18.30
T77857	O-RING	1 @ \$6.99	\$5.72
38H5003	ACCUMULATOR PART	1 @ \$33.13	\$27.10
51M7043	O-RING	1 @ \$7.58	\$6.20
DE20914	ACCUMULATOR PART	1 @ \$140.59	\$115.00
CE21547	ACCUMULATOR PARTS	1 @ \$99.57	\$81.45
19M7864	ACCUMULATOR PART	2 @ \$4.63	\$7.57

Payments Received:

09/12/2024	AuthCode 03249J -	\$41,600.00
09/13/2024	AuthCode 462199 -	\$2,928.14

Total Taxable	\$42,407.75
Total Non-Taxable	\$0.00
Subtotal	\$42,407.75
Sales Tax	\$2,120.39
Total	\$44,528.14
Total Payments	\$44,528.14
Balance	\$0.00

X
 ALL INVOICES ARE DUE ON RECEIPT Etransfers can be sent to

Date : 12/11/2024 12:38:56 PM

Kendze Mechanical Services Ltd.

RR1 SITE 9 BOX 14
 Didsbury, ALBERTA. T0M0W0
 (403) 559-4012
 Writer: CLAYTON WHITESIDE



INVOICE # 5171

kendzemechanical@HOTMAIL.COM

BAR# 84837 3130 RT0001

ANDREW BLUEDON FARMS	YEAR:	2012	TRANS/DRIVE:	HYDRO/FWD
	MAKE/MODEL:	JOHN DEERE S680 DUAL W	LICENSE/STATE:	/ALBERTA
	VIN:	1H0S680SHD0756995	LAST SERV/CURRENT M:	1979.8 HR/2176 ENG
	ENGINE BRAND:	DEERE 13.5		

In: 3/21/2024 Out: 6/19/2024 Email: ALUELLAU@GMAIL.COM

VEHICLE ISSUE #1: INSPECT COMBINE				
PART: MILEAGE	MILEAGE	100 @ \$0.85	\$85.00	NEW
PART: AH231479	BEARING	1 @ \$274.13	\$274.13	NEW
PART: 03M7193	BOLT	3 @ \$4.44	\$13.32	NEW
PART: AXE93449	LOCKING COLLAR	1 @ \$151.94	\$151.94	NEW
PART: 14M7296	FLANGE NUT	5 @ \$4.76	\$23.80	NEW
PART: H206715	HANDLE	1 @ \$86.96	\$86.96	NEW
PART: H206716	RETAINER	1 @ \$26.15	\$26.15	NEW
PART: 28316	SPRING LOCKING	1 @ \$6.98	\$6.98	NEW
PART: H220556	ISOLATOR	1 @ \$113.75	\$113.75	NEW
PART: AH219846	ARM	1 @ \$388.08	\$388.08	NEW
PART: 19M7820	SCREW	6 @ \$10.15	\$60.90	NEW
PART: H227582	BOLT	4 @ \$21.20	\$84.80	NEW
PART: 19M8486	CAP SCREW	2 @ \$24.35	\$48.70	NEW
PART: 19M7847	SCREW	2 @ \$24.01	\$48.02	NEW
PART: 14M7291	FLANGE NUT	12 @ \$7.97	\$95.64	NEW
PART: 14M7299	FLANGE NUT	22 @ \$6.45	\$141.90	NEW
PART: AH220398	ARM	6 @ \$147.64	\$885.84	NEW
PART: H154928	BOLT	8 @ \$10.42	\$83.36	NEW
PART: AXE16294	ARM	2 @ \$329.05	\$658.10	NEW
PART: H235880	BOLT	2 @ \$26.94	\$53.88	NEW
PART: H231095	BOLT	2 @ \$20.83	\$41.66	NEW
PART: AH219844	ARM	1 @ \$485.20	\$485.20	NEW
PART: AXE54619	ROLLER CHAIN	1 @ \$291.38	\$291.38	NEW
PART: AXE23133	IDLER SPROCKET	2 @ \$71.63	\$143.26	NEW
PART: H114395	SPACER	1 @ \$7.46	\$7.46	NEW
PART: H216427	SPACER	1 @ \$20.07	\$20.07	NEW

Recommended Repairs: ALL INVOICES ARE DUE UPON PICK UP OR RECEIPT From the date of delivery for a period of 30 days, Kendze Mechanical Services will repair free of charge any defects in materials or workmanship to repairs stated on the invoice. Consequential damage is not included in these warranties. All warranty work is to be done in our shop only and we will not cover any third party expenses. Warranty does not include towing charges or customer supplied parts. Neglect or operator abuse of vehicle will immediately void any and all warranties. Kendze Mechanical Services INVOICES ARE DUE UPON RECEIPT OR PICKUP. 2% interest MONTHLY will apply to late payments.	Labor/Jobs	\$7,273.00
	Parts	\$13,340.47
	Sublet	\$0.00
	Total Fees	\$15.00
	Subtotal	\$20,628.47
	GST @ 5%	\$1,031.49
	Total	\$21,659.96
	Payments	\$0.00
	Balance	\$21,659.96

I have hereby authorized and approved the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to the vehicle or articles left in the vehicle in case of fire, theft, accident or other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorneys fees and court costs. I release and forever discharge each other; myself the customer and Kendze Mechanical Services and their respective officers, employees, associates, agents and representatives of and fro

X _____ Date 6/21/2024

Kendze Mechanical Services Ltd.

RR1 SITE 9 BOX 14
 Didsbury, ALBERTA. T0M0W0
 (403) 559-4012
 Writer: CLAYTON WHITESIDE



INVOICE # 5171

kendzemechanical@HOTMAIL.COM

BAR# 84837 3130 RT0001

ANDREW BLUEDON FARMS	YEAR:	2012	TRANS/DRIVE:	HYDRO/FWD
	MAKE/MODEL:	JOHN DEERE S680 DUAL W	LICENSE/STATE:	/ALBERTA
	VIN:	1H0S680SHD0756995	LAST SERV/CURRENT M:	1979.8 HR/2176 ENG
	ENGINE BRAND:	DEERE 13.5		

PART	DESCRIPTION	QTY	UNIT PRICE	TOTAL PRICE	STATUS
PART: HXE38073	BELT	1 @	\$35.15	\$35.15	NEW
PART: H238867	V-BELT	1 @	\$46.30	\$46.30	NEW
PART: JD29980	NEEDLE BEARING	2 @	\$10.00	\$20.00	NEW
PART: Z33854	PRESSED BEARING HOUSING	2 @	\$20.16	\$40.32	NEW
PART: HXE84650	DRIVER	1 @	\$198.92	\$198.92	NEW
PART: 49M4821	SHAFT KEY	1 @	\$5.97	\$5.97	NEW
PART: 14M7589	LOCK NUT	1 @	\$8.44	\$8.44	NEW
PART: AH229100	BEARING KIT	1 @	\$327.31	\$327.31	NEW
PART: KXE10041	ROTOR FLIGHT	1 @	\$460.22	\$460.22	NEW
PART: KXE10043	REAR FEED FLIGHT KIT	1 @	\$1,370.31	\$1,370.31	NEW
PART: KXE10042	FRONT FEED FLIGHT KIT	1 @	\$765.17	\$765.17	NEW
PART: AH208966	VANE COVER	1 @	\$1,139.24	\$1,139.24	NEW
PART: 03M7192	BOLT	4 @	\$3.53	\$14.12	NEW
PART: H174755	BOLT	10 @	\$7.39	\$73.90	NEW
PART: M48583	AUGER DRIVE SHAFT KEY	4 @	\$14.18	\$56.72	NEW
PART: H206715	HANDLE	1 @	\$86.96	\$86.96	NEW
PART: H206716	RETAINER	2 @	\$26.15	\$52.30	NEW
PART: 28316	SPRING LOCKING	2 @	\$6.98	\$13.96	NEW
PART: AXE42868	BEARING WITH HOUSING	1 @	\$540.18	\$540.18	NEW
PART: AXE67415	STONE WHEEL	1 @	\$221.07	\$221.07	NEW
PART: 40M7401	SNAP RING	1 @	\$54.47	\$54.47	NEW
PART: 14M7291	FLANGE NUT	4 @	\$4.17	\$16.68	NEW
PART: 14M7328	LOCK NUT	4 @	\$3.50	\$14.00	NEW
PART: 03M7210	BOLT	4 @	\$7.09	\$28.36	NEW
PART: 19M7789	SCREW	4 @	\$1.95	\$7.80	NEW
PART: 19M7785	SCREW	2 @	\$1.85	\$3.70	NEW
PART: AH220541	CHAIN LINK	3 @	\$25.31	\$75.93	NEW
PART: AXE24984	IDLER	2 @	\$240.81	\$481.62	NEW
PART: JD10181	BALL BEARING	2 @	\$28.09	\$56.18	NEW

Recommended Repairs: ALL INVOICES ARE DUE UPON PICK UP OR RECEIPT From the date of delivery for a period of 30 days, Kendze Mechanical Services will repair free of charge any defects in materials or workmanship to repairs stated on the invoice. Consequential damage is not included in these warranties. All warranty work is to be done in our shop only and we will not cover any third party expenses. Warranty does not include towing charges or customer supplied parts. Neglect or operator abuse of vehicle will immediately void any and all warranties. Kendze Mechanical Services INVOICES ARE DUE UPON RECEIPT OR PICKUP. 2% interest MONTHLY will apply to late payments.	Labor/Jobs	\$7,273.00
	Parts	\$13,340.47
	Sublet	\$0.00
	Total Fees	\$15.00
	Subtotal	\$20,628.47
	GST @ 5%	\$1,031.49
	Total	\$21,659.96
	Payments	\$0.00
	Balance	\$21,659.96

I have hereby authorized and approved the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to the vehicle or articles left in the vehicle in case of fire, theft, accident or other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorneys fees and court costs. I release and forever discharge each other; myself the customer and Kendze Mechanical Services and their respective officers, employees, associates, agents and representatives of and fro

X _____ Date 6/21/2024

Kendze Mechanical Services Ltd.

RR1 SITE 9 BOX 14
 Didsbury, ALBERTA. T0M0W0
 (403) 559-4012
 Writer: CLAYTON WHITESIDE



INVOICE # 5171

kendzemechanical@HOTMAIL.COM

BAR# 84837 3130 RT0001

ANDREW BLUEDON FARMS	YEAR:	2012	TRANS/DRIVE:	HYDRO/FWD
	MAKE/MODEL:	JOHN DEERE S680 DUAL W	LICENSE/STATE:	/ALBERTA
	VIN:	1H0S680SHD0756995	LAST SERV/CURRENT M:	1979.8 HR/2176 ENG
	ENGINE BRAND:	DEERE 13.5		

PART: 24M7095	WASHER	8 @ \$0.40	\$3.20	NEW
PART: 19M7868	SCREW	2 @ \$1.58	\$3.16	NEW
PART: 14M7327	LOCK NUT	2 @ \$1.12	\$2.24	NEW
PART: AXE24307	ROLLER CHAIN	1 @ \$2,530.16	\$2,530.16	NEW
PART: KFL313	BRAKE KLEEN	2 @ \$6.50	\$13.00	NEW
PART: LOC 30876	RIGHT STUFF SILICONE	1.5 @ \$55.42	\$83.13	NEW
LABOR:	COMBINE INSPECTION, MAKING LIST AND ORDER PARTS.	6.5 @ \$140.00	\$910.00	LABOR
LABOR:	GO OVER COMBINES AND DOUBLE CHECK EVERYTHING AND INSTALL GUARD/COVERS. CHECKED ALL GEAR BOX OIL LEVELS, MADE SURE ALL FLUID LEVEL ARE GOOD ON COMBINE, TENSION ON ALL BELTS, CHAINS LEFT ETC AND TEST RAN UNIT.	3 @ \$140.00	\$420.00	LABOR

Total for "INSPECT COMBINE ": \$14,500.47

VEHICLE ISSUE #2: REPLACE CHAFFER AND SIEVE SHAKER ARMS

PART: MILEAGE	MILEAGE	100 @ \$0.85	\$85.00	NEW
LABOR:	GOT CHOPPER AND SPREADER ALL DISCONNECTED, HARNESSSES, HYDRAULIC LINES, CYLINDER/SHOCKS, MISC BRACKETS, ETC., REMOVED CHOPPER AND SPREADER FROM COMBINE. UNBOLT CHAFFER AND PULL IT OUT, REPLACE SHOE SHAKER ARMS AND HARDWARE. COMPLETED WELDING UP FRONT CHAFFER MOUNT THAT WAS CRACKED. RE INSTALL CHAFFER FRAME AND ELEMENTS. RE INSTALL CHOPPER AND SPREADER. MADE SURE ALL HARDWARE WAS TORQUED AND AND REPLACED AS NEEDED. WENT OVER AFTER FINAL TEST RUN.	12.5 @ \$140.00	(Discount: \$175.00) \$1,575.00	LABOR

Total for "REPLACE CHAFFER AND SIEVE SHAKER ARMS ": \$1,660.00

VEHICLE ISSUE #3: RH BEARING ON FEEDER HOUSE DRIVE SHAFT

LABOR:	REMOVE TENSION FROM CHAIN, REMOVE SPROCKET AND BEARING. REMOVE 1 LINK FROM CHAIN. INSTALL NEW BEARING, REINSTALL SPROCKET, INSTALL CHAIN IN PLACE AND SET TENSION	0.5 @ \$140.00	\$70.00	LABOR
--------	---	----------------	---------	-------

Total for "RH BEARING ON FEEDER HOUSE DRIVE SHAFT ": \$70.00

VEHICLE ISSUE #4: REPLACE FEEDER CHAIN

LABOR:	REMOVE OLD FEEDER CHAIN AND INSTALL AND TENSION NEW CHAIN.	2 @ \$140.00	\$280.00	LABOR
--------	--	--------------	----------	-------

Total for "REPLACE FEEDER CHAIN": \$280.00

VEHICLE ISSUE #5: REPLACE RUBBER SEAL ON TOP OF FEEDER HOUSE

Recommended Repairs: ALL INVOICES ARE DUE UPON PICK UP OR RECEIPT From the date of delivery for a period of 30 days, Kendze Mechanical Services will repair free of charge any defects in materials or workmanship to repairs stated on the invoice. Consequential damage is not included in these warranties. All warranty work is to be done in our shop only and we will not cover any third party expenses. Warranty does not include towing charges or customer supplied parts. Neglect or operator abuse of vehicle will immediately void any and all warranties. Kendze Mechanical Services INVOICES ARE DUE UPON RECEIPT OR PICKUP. 2% interest MONTHLY will apply to late payments.	Labor/Jobs	\$7,273.00
	Parts	\$13,340.47
	Sublet	\$0.00
	Total Fees	\$15.00
	Subtotal	\$20,628.47
	GST @ 5%	\$1,031.49
	Total	\$21,659.96
	Payments	\$0.00
	Balance	\$21,659.96

I have hereby authorized and approved the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to the vehicle or articles left in the vehicle in case of fire, theft, accident or other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorneys fees and court costs. I release and forever discharge each other; myself the customer and Kendze Mechanical Services and their respective officers, employees, associates, agents and representatives of and fro

X _____ Date 6/21/2024

Kendze Mechanical Services Ltd.



INVOICE # 5171

RR1 SITE 9 BOX 14
Didsbury, ALBERTA. T0M0W0
(403) 559-4012
Writer: CLAYTON WHITESIDE

kendzemechanical@HOTMAIL.COM

BAR# 84837 3130 RT0001

ANDREW BLUEDON FARMS	YEAR:	2012	TRANS/DRIVE:	HYDRO/FWD
	MAKE/MODEL:	JOHN DEERE S680 DUAL W	LICENSE/STATE:	/ALBERTA
	VIN:	1H0S680SHD0756995	LAST SERV/CURRENT M:	1979.8 HR/2176 ENG
	ENGINE BRAND:	DEERE 13.5		

LABOR:	REMOVE OLD RUBBER SEAL AND INSTALL NEW ONE.	0.5 @ \$140.00	\$70.00	LABOR
Total for "REPLACE RUBBER SEAL ON TOP OF FEEDER HOUSE ": \$70.00				
VEHICLE ISSUE #6: REPLACE RE THRASH DRIVE CHAIN				
LABOR:	REMOVE OLD CHAIN, INSTALL NEW CHAIN AND TENSION	0.5 @ \$140.00	\$70.00	LABOR
Total for "REPLACE RE THRASH DRIVE CHAIN ": \$70.00				
VEHICLE ISSUE #7: REPLACE BLOWER DRIVE BELT AND IDLER				
LABOR:	PULLED DRIVE BELT OFF AND CHECKED IDLERS. IDLER NEEDS REPLACING WILL HAVE TO ORDER	0.5 @ \$140.00	\$70.00	LABOR
LABOR:	REMOVE INTAKE PIPING AND COVERS TO GET AT IDLER AND REPLACE IDLER AND RE INSTALL COVERS	2 @ \$140.00	\$280.00	LABOR
Total for "REPLACE BLOWER DRIVE BELT AND IDLER ": \$350.00				
VEHICLE ISSUE #8: REPLACE ROTARY SCREEN JACKSHAFT DRIVE BELT				
LABOR:	REPLACE ROTARY SCREEN JACK SHAFT DRIVE BELT	1 @ \$140.00	\$140.00	LABOR
Total for "REPLACE ROTARY SCREEN JACKSHAFT DRIVE BELT ": \$140.00				
VEHICLE ISSUE #9: REPLACE BUBBLE UP AUGER DRIVE				
LABOR:	CHANGE OUT BUBBLE UP AUGER DRIVE	0.5 @ \$140.00	\$70.00	LABOR
Total for "REPLACE BUBBLE UP AUGER DRIVE ": \$70.00				
VEHICLE ISSUE #10: REPLACE TOP FRONT COVER ON ROTOR AND ROTOR BEARING				
PART: MILEAGE	MILEAGE	100 @ \$0.85	\$85.00	NEW
LABOR:	REMOVE FRONT ROTOR PLASTIC COVER. REMOVE HARNESSSES. REMOVE FRONT PLATE AND ROTOR BEARING TO GET THE FRONT TOP ROTO COVER OUT. (BEARING IS SHOT) ONCE COVER WAS REMOVED CLEANED ALL SEALING SURFACES AND APPLIED SILICONE AND INSTALLED NEW COVER. TORQUED AND INSTALLED NEW HARDWARE AS NEEDED. INSTALLED NEW ROTOR BEARING AND PLATE. APPLIED SILICONE TO PLACES AFTER COVER INSTALL. AFTER TEST RUN INSTALLED FRONT PLASTIC COVER AND HARNESSSES AND METAL GUARDS AND PLATES.	12 @ \$140.00	(Discount: \$168.00) \$1,512.00	LABOR
Total for "REPLACE TOP FRONT COVER ON ROTOR AND ROTOR BEARING ": \$1,597.00				
VEHICLE ISSUE #11: CHANGE FEED FLIGHTING ON ROTOR				
LABOR:	CHANGE OUT FRONT AND REAR FEED FLIGHTS ON ROTOR. INSTALLED WEIGHTS BACK ON ROTOR. ROTOR DID SEEM TO RUN SMOOTH ON TEST RUN. MAY NEED BALANCE IF SHAKES BUT SEEMS	6 @ \$140.00	(Discount: \$84.00) \$756.00	LABOR

<p>Recommended Repairs:</p> <hr/> <p>ALL INVOICES ARE DUE UPON PICK UP OR RECEIPT From the date of delivery for a period of 30 days, Kendze Mechanical Services will repair free of charge any defects in materials or workmanship to repairs stated on the invoice. Consequential damage is not included in these warranties. All warranty work is to be done in our shop only and we will not cover any third party expenses. Warranty does not include towing charges or customer supplied parts. Neglect or operator abuse of vehicle will immediately void any and all warranties. Kendze Mechanical Services INVOICES ARE DUE UPON RECEIPT OR PICKUP. 2% interest MONTHLY will apply to late payments.</p>	Labor/Jobs	\$7,273.00
	Parts	\$13,340.47
	Sublet	\$0.00
	Total Fees	\$15.00
	Subtotal	\$20,628.47
	GST @ 5%	\$1,031.49
	Total	\$21,659.96
	Payments	\$0.00
	Balance	\$21,659.96

I have hereby authorized and approved the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to the vehicle or articles left in the vehicle in case of fire, theft, accident or other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorneys fees and court costs. I release and forever discharge each other; myself the customer and Kendze Mechanical Services and their respective officers, employees, associates, agents and representatives of and fro

X _____ Date 6/21/2024

Kendze Mechanical Services Ltd.

RR1 SITE 9 BOX 14
 Didsbury, ALBERTA. T0M0W0
 (403) 559-4012
 Writer: CLAYTON WHITESIDE



INVOICE # 5171

kendzemechanical@HOTMAIL.COM

BAR# 84837 3130 RT0001

ANDREW BLUEDON FARMS	YEAR:	2012	TRANS/DRIVE:	HYDRO/FWD
	MAKE/MODEL:	JOHN DEERE S680 DUAL W	LICENSE/STATE:	/ALBERTA
	VIN:	1H0S680SHD0756995	LAST SERV/CURRENT M:	1979.8 HR/2176 ENG
	ENGINE BRAND:	DEERE 13.5		

TO RUN SMOOTH.				
				Total for "CHANGE FEED FLIGHTING ON ROTOR ": \$756.00
VEHICLE ISSUE #12: REPAIR SPREADER WAG				
LABOR:	REMOVE OLD BEARINGS AND INSTALL NEW BEARING AND HARDWARE AND RE ASSEMBLE	1 @ \$140.00	\$140.00	LABOR
				Total for "REPAIR SPREADER WAG": \$140.00
VEHICLE ISSUE #13: TENSION BELTS AND CHAINS				
LABOR:	INSTALLING CHOPPER BELTS AND TENSION. ADJUST ELEVATOR CHAIN TENSION. REINSTALL ELEVATOR BELT AND TENSION. INSTALL TOP INSPECTION PLATE OF REAR ELEVATOR.	1.5 @ \$140.00	\$210.00	LABOR
LABOR:	REMOVE FRONT DRIVESHAFT TO GET ACCESS TO SHOW AUGERS. SETTING SHOE AUGER BACKLASH AND REINSTALL DRIVESHAFT.	2 @ \$140.00	\$280.00	LABOR
				Total for "TENSION BELTS AND CHAINS ": \$490.00
VEHICLE ISSUE #14: REPLACE DRIVE SHAFT STEADY BEARING				
LABOR:	REMOVE DRIVESHAFT FROM COMBINE. MARKING WHERE SPLINES LINE UP. REINSTALLING DRIVESHAFT AND TORQUE U-JOINT STRAPS AFTER REPLACED STEADY BEARING.	1.5 @ \$140.00	\$210.00	LABOR
LABOR:	REMOVE OLD STEADY BEARING AND INSTALL NEW BEARING ON THE SHAFT	0.5 @ \$140.00	\$70.00	LABOR
				Total for "REPLACE DRIVE SHAFT STEADY BEARING ": \$280.00
VEHICLE ISSUE #15: HEADER REPAIRS				
LABOR:	REMOVE INSPECTION PLATES ON HEADER BARREL. REMOVE OLD FINGERS/BROKEN PIECES AND INSTALL NEW PARTS. MADE SURE DRIVE CHAIN TENSION WAS CORRECT.	1 @ \$140.00	\$140.00	LABOR
				Total for "HEADER REPAIRS": \$140.00

<p>Recommended Repairs:</p> <hr/> <p>ALL INVOICES ARE DUE UPON PICK UP OR RECEIPT From the date of delivery for a period of 30 days, Kendze Mechanical Services will repair free of charge any defects in materials or workmanship to repairs stated on the invoice. Consequential damage is not included in these warranties. All warranty work is to be done in our shop only and we will not cover any third party expenses. Warranty does not include towing charges or customer supplied parts. Neglect or operator abuse of vehicle will immediately void any and all warranties. Kendze Mechanical Services INVOICES ARE DUE UPON RECEIPT OR PICKUP. 2% interest MONTHLY will apply to late payments.</p>	Labor/Jobs	\$7,273.00
	Parts	\$13,340.47
	Sublet	\$0.00
	Total Fees	\$15.00
	Subtotal	\$20,628.47
	GST @ 5%	\$1,031.49
	Total	\$21,659.96
	Payments	\$0.00
	Balance	\$21,659.96

I have hereby authorized and approved the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to the vehicle or articles left in the vehicle in case of fire, theft, accident or other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorneys fees and court costs. I release and forever discharge each other; myself the customer and Kendze Mechanical Services and their respective officers, employees, associates, agents and representatives of and fro

X _____ Date 6/21/2024