JBS Mechanical Inc Box 353

Whitecourt, AB T7S 1N5

jbsmechanical.service@gmail.com

GST/HST No.

828463240



Invoice # Date 30428 5/11/2023

K20-4

| 1011 | | | | | |
|----------|--------|--|--|--|--|
| P.O. No. | Terms | | | | |
| | Net 30 | | | | |

Invoice To NEWGEN ENERGY SERVICES

| Location | Work Order# | Make/Model | Unit Number |
|----------|-------------|------------|-------------|
| ST-13 | 6568 | | TL-01 |

| Item | Description of Item | Bin | Qty | Rate | Area | Amount |
|--------------------|--|---------|-----|----------------|------|-----------------|
| CVIP Trailer | CVIP - 3 Axle | | 1 | 210.00 | | 210.00 |
| Regular Time | Inspection and repair | | 15 | 150.00 | | 2,250.00 |
| 1500 | ABS light on find left-hand ABS speed sensor | | 1 | | | |
| | damaged remove and replace speed sensor test | | | | | |
| | system after repair all systems working as they should. remove and replace left hand rear tail | | | | | |
| | light that was damaged, remove and replace left | | | | | |
| | hand rear corner marker that was damaged, repair | | | 1 1 | | |
| | corroded wiring to rear tail lights and corner | | | | | |
| | markers. Remove wiring to rear trailer plug that | | | | | |
| | was causing cross feeding on lights and ABS | | | | | |
| | power. Remove and replace right hand rear | | | | | |
| | mudflap, install new reflective tape on the rear of | | | | | |
| | Beavertail remove and replace axle three, axle two right hand and axle one left hand slack adjusters | | | | | |
| | that were seized Adjust push rod length | 1 | | | | |
| | according to new slacks install gauge so that auto | | | | | |
| | Slack functions properly remove and replace axle | | | | | |
| | 3 S cam tubes remove and replace axle three right | | | | | |
| | hand brake drum to do wear. adjust all tire | | | | | |
| | pressures. Grease unit, torque on wheels once | | | | | |
| | reinstalled set all brakes. | | | | | |
| 3600AX | 16.5X7 DRUM STANDARD TRUCK AND | PR 8 A | 1 | 179.40 | | 179.40 |
| | TRAILER | | | 1,21,10 | | 175.10 |
| 41160 | CONSPICUITY TAPE RED/WHITE PER FOOT | Bin 1 K | 8 | 0.90 | | 7.20 |
| 24X24 | 24X24 RUBBER MUD FLAP 3/8" | PR 1 FL | 1 | 32.35 | | 32.35 |
| 46300 | TRAILER WHEEL SEAL | S 10 D | 3 | 52.95 | | 158.85 |
| 330-3009 AS1141 | OIL HUB CAP GASKET 3009 SLACK ADJUSTER 1.5 28 SPL. 6" | End 1 | 3 | 2.85 | | 8.55 |
| AS3016 | ASA COLLAR CLEVIS 5/8 | | 4 | 139.53 | | 558.12 |
| LED4000-24 | 4' RED STT 24 DIODE | S 6 B | 1 | 27.26 19.50 | | 109.04 19.50 |
| LED2500-13 | LED 2.5' RD MARKER LAMP RED | S 6 D | i | 6.80 | | 6.80 |

Subtotal

GST/HST

Total

Payment

Balance Due

JBS Mechanical Inc

Box 353

Whitecourt, AB T7S 1N5

JBS Mechanical Inc. 1-780-779-6759

Invoice

Invoice # Date 30428 5/11/2023

jbsmechanical.service@gmail.com

GST/HST No.

828463240

Invoice To

| P.O. No. | Terms |
|----------|--------|
| | Net 30 |

| NEWGEN ENERGY SERVICES | | | | |
|------------------------|----------|----------------------------------|--|-------------|
| | Location | Location Work Order # Make/Model | | Unit Number |
| | ST-13 | 6568 | | TL-01 |
| | | | | |

| Item | | Description of Item | Bin | Qty | Rate | Area | Amount |
|---------------|----|--------------------------|-----------|-----|-------|------|--------|
| S-35322-9 | C | AM TUBE KIT 28/ 23.75" | S 11 E | 2 | 95.22 | | 190.44 |
| AR0172L | C | S 1.62 X 28 X 23.50 LH | S 11 E | 1 | 53.25 | | 53.25 |
| AR0173R | C | S 1.62 X 28 X 23.50 RH | S 11 E | 1 | 53.25 | | 53.25 |
| 75W901LJ | 75 | W90 SYNTHETIC OIL 1L JUG | PR 6 FL | 2 2 | 19.80 | | 39.60 |
| S28501-500 | IN | TRAAX D/S CLAMP KIT 5" | PR 4 A | 2 | 13.75 | | 27.50 |
| 955336 | A | BS SENSOR 90 DEGREE 36 " | End 3 | 1 | 37.95 | | 37.95 |
| 94924 | 2 | WIRE PIGTAIL | END 6 | 1 | 3.55 | | 3.55 |
| 94993 | R | A S/T PIGTAIL | END 6 | 1 | 3.05 | | 3.05 |
| 3-653 | 21 | V ARCTIC FLEX 2/14 | Hose Rack | 4 | 1.45 | | 5.80 |
| Shop Supplies | 89 | % of Base Labour | | 16 | 12.00 | | 192.00 |
| Freight | Fr | eight Parts | | 1 | 45.00 | | 45.00 |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | Ш | | | | | | |
| | П | | | | | | |
| | П | | | | | | |
| | П | | | | | | |
| | П | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | * |
| | | | | | | | |
| | Ц | | | | | | |

If we have had your wheels off re-tourque within 100 km's. Flat rate charges may be subjected to a 75% increase for siezed or aftermarket parts. Subtotal \$4,191.20 A 25% increase in flat rate labor charge may occur due to excessive mud or snow on GST/HST \$209.56 units. Parts warranty subject to manufactures approval. **Total** If customer does not request old parts back they will be disposed of by JBS \$4,400.76 Mechanical. **Payment** \$0.00 No return on electrical components or special order parts. UNAUTHORIZED ENGINE MODIFICATIONS OR DPF DELETES DO NOT **QUALIFY FOR WARRANTY** \$4,400.76 **Balance Due**

JBS Mechanical Inc 3469 - 33 Street Whitecourt, AB T7\$ 1N5

jbsmechanical.service@gmail.com

3ST/HST No. 828463240

Invoice To

NEWGEN ENERGY SERVICES





26708

| Date | Due Date |
|------------|-----------|
| 12/13/2022 | 1/12/2023 |

| P.O. No. | Terms |
|----------|--------|
| | Net 30 |

| Unit Make/Model/Vin# | Unit Number |
|----------------------|-------------|
| | T2-01 |

| Item | | Description of Item | Qty | Rate | Area | Amount |
|-----------------------------|---------------------------------------|---|-----|-------------------------|------|------------------------|
| Mobile Time | Find : Repla | ose no air suspension spring brake priority valve not opening fully ce and SBPV ystem ood | 3 | 150.00 | j | 450.00 |
| Shop Supplies | 8% o | Base Labour | 3 | 10.80 | = | 32.40 |
| SE110800N 92801 241-B | AIR I GRO DOEI SN 22 VIN: | /ICE RESIVOIR PRIORITY VALVE BRAKE ANTIFREEZE IL UND KEY PLUG TYPE 1/4" MPT PKER 2340-S 2DESNSP38K3039029 METER: 143841 | | 93.94 7.35 14.858 | | 93.94 7.35 14.86 |
| <u></u> | | | | | | |

If we have had your wheels off re-tourque within 100 km's. Flat rate charges may be subjected to a 75% increase for siezed or aftermarket parts. A 25% increase in flat rate labor charge may occur due to excessive mud or snow on units. Parts warranty subject to manufactures approval. If customer does not request old parts back they will be disposed of by JBS Mechanical. No return on electrical components or special order parts. UNAUTHORIZED ENGINE MODIFICATIONS OR DPF DELETES DO NOT QUALIFY FOR WARRANTY

Subtotal \$598.55

GST/HST \$29.93

Total \$628.48

Payment \$0.00

Balance Due \$628.48