

LAKEY DIESEL & AUTO

5 - 9 Atlantic Crescent

Devon, AB. T9G 0M6

Phone: 780-987-2505 Fax: 000- -

INVOICE

8845

GST# 81712 5701

INVOICE

Printed Date: 01/23/2024

Work Completed: 01/23/2024

Rosger, tyrell

2012 Ford - F550 Super Duty - 6.7L, V8 (406CI) VIN(T)

Lic # :

Odometer In : 145183

Home
Office

VIN # : 1FD0W5HT3 CEA00197

Engine Hrs In : 5048.0

Engine Hours Out : 0.0

Part Description	I Number	Qty	Sale	Ext	Labor Description	Ext
Engine JC3Z6006B		1.00	18,816.94	18,816.94	ENGINE ASSEMBLY - Removal & Installation - [Includes: R&I only those components necessary for the removal of the complete Engine Assembly. DOES NOT include transfer components or tune Engine.]	2,739.20
COOLANT - EXTENDED LIFE UNIVERSAL 16-104X52		4.00	32.58	130.32	Completed replacement of engine - returned back to stock, replaced 2 injectors and completed programming. Road tested and reported back transmission shift issue with 5-6 upshift and 3-1, 3-2 downshift.	
Oil Filter (Gold) - Master Pack 7151MP		1.00	0.00	n/c	OIL CHANGE AND INSPECTION - DIESEL - Up to 15 L of oil	169.95
Mobil Delvac 1 ESP 5W40 Synthetic 122264		15.00	0.00	n/c	Cylinder 2 FDDE659030 Cylinder 3 0BF0898028	
tune tune		1.00	586.32	586.32	P007C - CAC connector damaged - used egr valve control connector	
Starter - Remfd - Power 2444899		1.00	424.98	424.98	P0113 - MAF - clean terminals P2138 - TPP has jumper harness in line - no dtc when unplugged P2138 - VGT connector corroded - cleaned	
Starter - Remfd - Power <CORE> 2444899		1.00	0.00	n/c	Extra time fro removing and re-installing running boards. Extra time to fix ECM faults (re-format before changing programming)	374.50
REMAN TURBOCHARGER R8671101T		1.00	2,538.79	2,538.79		
REMAN TURBOCHARGER <CORE> R8671101T		1.00	0.00	n/c		
FUEL FILTER 600737		1.00	250.05	250.05		
REMAN INJECTOR/Fuel Injector 0986435415		2.00	488.41	976.82		
REMAN INJECTOR/Fuel Injector <CORE> 0986435415		2.00	0.00	n/c		
TUBE ASSEMBLY- OIL FEED BC3Z 6B689 A		1.00	53.92	53.92		
TUBE - WATER OUTLET BC3Z 9U469 A		1.00	68.46	68.46		
Shop Supplies				100.00		
ENVIRO FEE				100.00		

Email Address: LAKEYDNA@GMAIL.COM

LAKEY DIESEL & AUTO
5 - 9 Atlantic Crescent
Devon, AB. T9G 0M6
Phone: 780-987-2505 Fax: 000- -

INVOICE

8845

GST# 81712 5701

INVOICE

Printed Date: 01/23/2024

Work Completed: 01/23/2024

Rosger, tyrell

2012 Ford - F550 Super Duty - 6.7L, V8 (406CI) VIN(T)

Lic # :

Odometer In : 145183

Home
Office

VIN # : 1FD0W5HT3 CEA00197

Engine Hrs In : 5048.0

Engine Hours Out : 0.0

Part Description	I Number	Qty	Sale	Ext	Labor Description	Ext
------------------	----------	-----	------	-----	-------------------	-----

Org. Estimate	0.00	Revisions	52,147.20	Current Estimate	52,147.20
---------------	------	-----------	-----------	------------------	-----------

Revision # 1, Previous Estimate Amount: 0.00, Additional Cost: 4702.47, Revised Estimate: 4702.47, Parts: \$4378.54 Labor: \$0.00 Sublet: \$0.00
Taxes & Fees: \$323.93 Authorized by - Rosger, tyrell, Date - 1/22/2024, Time - 11:34 AM, Initiated By - Shop

Revision # 2, Previous Estimate Amount: 0.00, Additional Cost: 23774.87, Revised Estimate: 23774.87, Parts: \$19533.58 Labor: \$2909.15 Sublet:
\$0.00 Taxes & Fees: \$1332.14 Authorized by - Rosger, tyrell, Date - 12/5/2023, Time - 10:24 AM, Initiated By - Shop

Revision # 3, Previous Estimate Amount: 4702.47, Additional Cost: 23669.86, Revised Estimate: 28372.33, Parts: \$19533.58 Labor: \$2909.15 Sublet:
\$0.00 Taxes & Fees: \$1227.13 Authorized by - Rosger, tyrell, Date - 1/22/2024, Time - 11:34 AM, Initiated By - Shop

[Payments -]

Labor:	3,283.65
Parts:	23,946.60
HazMat:	100.00
SubTotal:	27,330.25
Tax:	1,366.51
Total:	28,696.76
Bal Due:	\$28,696.76

Vehicle Received: 2023-12-05

Customer Number : 2061

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Balances past 30 days are subject to late fees at 24% APR. Warranty on parts and labor is one year or 20,000 km whichever comes first, used parts have limited coverage for 90 days, customer supplied parts are not covered by any warranty. Aftermarket modification to vehicles is the sole responsibility of the customer and not covered under any warranty. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. TIRES NEED TO BE RETORQUED AFTER 100 KM.

Signature _____ Date _____

Email Address: LAKEYDNA@GMAIL.COM

SALE

APPENDIX 1

Trace 15
MASTERCARD

APPROVED:

VERIFIED BY FBI

Mastercard
AID: A00000000400
TVR: 00 00 00 00 00
TSI: EB 00

CARROLLTON ACCOUNTING SERVICE OF CARROLL
AND OF SERVICES IN THE AMOUNT OF THE
TOTAL DUES LISTED

THANK YOU / MERO

MERCHANT COPY

Description	PERFORM 2 AXLE ALIGNMENT
-------------	--------------------------

Description	Frequency	Severity	Impact	Mitigation
1. Low - Minor issues that do not significantly impact the project. 2. Medium - Moderate issues that may impact the project if not addressed. 3. High - Major issues that could significantly impact the project. 4. Critical - Issues that are severe and require immediate attention.	1. Low - Issues occurring less than once per month. 2. Medium - Issues occurring once per month. 3. High - Issues occurring more than once per month. 4. Critical - Issues occurring frequently or continuously.	1. Low - Issues with a severity score of 1-3. 2. Medium - Issues with a severity score of 4-6. 3. High - Issues with a severity score of 7-9. 4. Critical - Issues with a severity score of 10.	1. Low - Issues that have a minimal impact on the project. 2. Medium - Issues that have a moderate impact on the project. 3. High - Issues that have a significant impact on the project. 4. Critical - Issues that have a severe impact on the project.	1. Low - Issues that are easily resolved. 2. Medium - Issues that require some effort to resolve. 3. High - Issues that require significant effort to resolve. 4. Critical - Issues that require immediate action to resolve.

ALIGN/ STRAIGHTEN STEERING WHEEL
Technician 1130 -

Cause

Carpet

Copyright © 2004
by Humana Press
www.humanapress.com

WHEELS MUST BE RE-TORQUED BETWEEN 80 TO 100 KMS CUSTOMER INITIAL

Retorque? Stay in your car! Call: 780-491-7460 Our Techs will come to you!

"Quality Parts, Expert Service, Peace of Mind"

Labour	384.25
Parts	45.00
Supplies	70.74
Sub-Total	1,000.84
GST	50.03
Total Invoice	1,050.67

ern
RAILER
RE
given.

18353 - 118 Avenue
Edmonton, AB T5S 1M8
Phone: 780-481-7400
Fax: 780-481-7725
service@westernintl.com
www.westernintl.com

#8-1807 2nd Street
Nisku, AB T9E 0W8
Phone: 780-955-2594
Fax: 780-955-7781
www.westernint.com

SERVICE ORDER
CLOSING COPY

User 1479 Page

35081	Advisor	Jordan Parier	Promised	07/22/2024 5:00 PM	Tag#
	Shop	51	Opened	07/22/2024 8:03 AM	Location
	Priority	10	Cashiered		PO #

License	Odem In	Odem Out	In Service Date	Stock No
	154250	154252		
Year	Make	Model	Model Number	Colour
2012	FORD	SUPER DUTY F-350 DRW WSH		
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FD0WJHT3CEA00197				
Engine	F7L 24-VALVE V8 DIESEL ENGINE			

Job				CSR	Status
1				1413	Original
R SUPPLIED STEERING BOX					
Type				Tech	Hours
CH				1330	3.00
R SUPPLIED STEERING BOX:					
Description	Shp	Bin	Type	Retail	Price
ATF SUPER PHILLIPS 88	5	FFRONT	CS72	10.84	8.03
PCOL LEVY CAT 4 6 10, 14		5 COUNTER	CS72	0.10	0.10
				Paris Total	45.63
Steering box to be replaced.				Labour Total	569.25
Supplied steering box, cleaned old box and placed inside truck.				Request Total	614.88
Page 7, Checkbook 4330					

Job 2 Parts Tech 1330				
ALIGNMENT		Job 2	CSR 1413	Status Original
ALIGNMENT	Type	Tech	Hours	Amount
COA	COA	1330	2.00	270.00
CRG WHEEL	COA	1330	0.30	45.00
	Parts Total			0.00
	Labour Total			315.00
	Request Total			315.00
Request straightened steering wheel, tech 1330				

Labour	384.25
Parts	45.00
Supplies	70.74
Sub-Total	1,000.84
GST	50.03
Total Invoice	1,050.67



Hart Transmission Repair Ltd.
110 Ordze Ave
Sherwood Park, AB T8B 1M6
Phone: 780-467-1424 Fax: 780-464-1230
GST # 865174643RC0001

INVOICE

RMS LAND CLEARING
21722 17ST NW
EDMONTON, AB
Home 587-897-3545

INVOICE

122182

Org. Est. # 019565

Printed Date: 1/05/2024

Work Completed: 10/18/2024

2012 Ford - F550 Super Duty - 6.7L V8 (406CI) VIN(T)

Lic #: CRX83601

Odometer In: 161026

Odometer Out: 161055

VIN #: 1FD0W5HT3 CEA00197

Engine Hrs In: 5514.0

Engine Hours Out: 0.0

Part Description

Qty	Sale	Ext	Labor Description	Ext
			R&R FRONT AND REAR SHOCK ABSORBERS	330.00
			TRANSMISSION SERVICE	325.00
			REMOVE TRANSMISSION PAN REPLACE FILTER AND FILL WITH OEM SPEC FLUID	
			SERVICE COMES WITH 6LTS OF FLUID	
			T-CASE SERVICE	99.99
			TRANSFER CASE SERVICE. DRAIN AND FILL	
			REMOVE COWLING AND REATTACH WASHER LINE HOSES TO NEW NOZZLES (THIS IS AN ESTIMATE, MORE PARTS OR LABOUR MAY BE REQUIRED ONCE WE SEE HOW THE SYSTEM WAS MODIFIED)	247.50
			REMOVE REAR BRAKE COMPONENTS AND REQUIRED PARK BRAKE COMPONENTS TO REPAIR FOR PARK BRAKE NOT HOLDING	825.00
			NOTE: FURTHER PARTS MAY BE REQUIRED ON TEAR DOWN	
			INSTALL NEW BACK UP ALARM	123.75
			19.5 CHANGE OVER	212.84
			customer supplied wheels - old wheels returned in unit	
			FUEL	
			DIESEL FUEL	100.00
			Hazardous Materials	100.00

Org. Estimate 987.53 Revisions 6,934.43 Current Estimate 7,921.96

Revision # 1, Previous Estimate Amount: 987.53, Additional Cost: 2904.17, Revised Estimate: 3891.70, Parts: \$623.05 Labor: \$1868.74 Sublet: \$0.00 Taxes & Fees: \$412.38 Authorized by: Date: 10/22/2024, Time: 7:57 AM, Initiated By: Shop

Revision # 2, Previous Estimate Amount: 3891.70, Additional Cost: 4030.26, Revised Estimate: 7921.96, Parts: \$2300.43 Labor: \$1527.50 Sublet: \$0.00 Taxes & Fees: \$202.33 Authorized by: Date: 10/22/2024, Time: 7:57 AM, Initiated By: Shop

Labor: 3,768.73
Parts: 4,041.04
Sublet: 602.84
HazMat: 100.00

SubTotal: 8,512.61
Tax: 425.63
Total: 8,938.24
Bal Due: \$0.00

[Payments - MasterCard - \$8,938.24]

Vehicle Received: 2024-10-17

Customer Number: 19618

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

HART TRANSMISSION REPAIR LTD will not be held responsible for loss or damage to vehicle or items left in it. Labor & Parts are guaranteed for 1 year or 20,000kms or NAPA AUTOPRO warranty of 2 year or 40000km, whichever occurs first. Used parts hold no labour warranty and 90day warranty subject to change depending on situation. All other guarantees are made by the manufacturer. NO WARRANTY FOR DAMAGE DUE TO MISUSE, ABUSE, OVERHEATING OR VEHICLE MODIFICATIONS. WARRANTY IS NON TRANSFERABLE. ***WHEELS MUST BE RETORQUED WITHIN 200KM IF REMOVED*** ALL WARRANTY CLAIMS MUST BE REPAIRED IN HOUSE, TOWING CHARGES ARE NOT COVERED.

** ALL INVOICES OVER THE AMOUNT OF \$3000 WILL HAVE A 3% PROCESSING FEE IF PAID BY MAJOR CREDIT CARD **

Signature

Date

Email Address: info@harttransmission.ca

Visit us on the web: www.harttransmission.ca

Page 2 of 2

Copyright (c) 2024 Mitchell Repair Information Company, LLC invhrs 5.12.24r

Service Advisor: R. HANNAH Tech: M. C. GILL P

ALBERTA DRIVELINE REBUILDERS
5152 YELLOWHEAD TRAIL
EDMONTON AB

Purchase

REV 03 2026 15:52:43
MASTERCARD *****
TO: 10541008 EASY 1 REP (C)
SEQUENCE: 136 004
AUTHOR: 002437
DATE: 136
Amount \$ 1 771.18
Total \$ 1 771.18

AB000000041010 Mastercard
TVR 0000000000 TSI 000

Approved

Important: Retain this copy for your record.

Cardholder copy

Shop Supplies

Alberta Driveline Rebuilders
5152 Yellowhead Trail
Edmonton, AB T5B 1G2
Phone: 780-479-8744 Fax: 780-477-6463

INVOICE

1364

Orig Est #001560

Ref #: 39005

Printed Date: 04/03/2024

Work Completed: 04/03/2024

ATTENTION

2012 Ford - F 550 Super Duty - 6.7L V8 (406CI) VIN(T)
Lic #

Odometer In: 154993

Odometer Out: 154995

VIN #: 1FD0WSHT3CEA00197

Qty	Rate	Ext	Labor Description	Ext
10.00	30.19	301.90	CUSTOMER WOULD LIKE TO SERVICE BOTH DIFFS	
			CHECK FOR VIBRATION ON TAKE OFF. GOES AWAY	n/c
3.00	45.28	135.84	AT HIGHER SPEEDS	n/c
			REAR U-JOINT @ DIFF YOKES HAS PLAY	
2.00	154.75	309.50	CLUNK FROM 3RD 2ND. ANYTIME/EVERYTIME	69.50
			FOUND: BAD U-JOINTS & BAD STEADY BEARING ON REAR	
			DRIVESHAFT	
			ENGINE HAS MASSIVE OIL LEAK, ENGINE THROWING CODES	
			FOR REDUCED ENGINE POWER; WE CANNOT CONTINUE	
			DIAGNOSIS ON TRANSMISSION UNTIL THAT IS RESOLVED.	
			IF ISSUE PERSISTS AFTER ENGINE REPAIRS, PLEASE BRING	
			BACK AND WE WILL FINISH DIAGNOSIS ON TRANS	
			REAR DIFFERENTIAL FLUID - DRAIN & FILL	83.40
			FRONT AXLE HOUSING COVER - Remove & Replace	111.20
			- w/o Skid Plate	
			PROPELLER SHAFT - Remove & Install or Remove &	152.90
			Replace - Rear, Three Piece Driveline, w/Skid Plate	
			MOST REAR U-JOINT IS NFG, 2ND STEADY BEARING NFG	
			UNIVERSAL JOINT - Remove & Replace - Three Piece	55.60
			Driveline, Each Additional	
			UNIVERSAL JOINT - Remove & Replace - Three Piece	55.60
			Driveline, Each Additional	
			2PC BALANCE (REAR 2PC OF 3PC SHAFT)	189.00
			(Combination) - CENTER SUPPORT BEARING -	69.50
			Remove & Replace One	
			BALANCE 1PC (FRONT OF 3PC)	95.00
			Hazardous Materials	5.00

Estimate: 760.19 Revisions: 0.00 Current Estimate: 760.19

Labor:	881.70
Parts:	800.14
HazMat:	5.00
SubTotal:	1,686.84
Tax:	84.34
Total:	1,771.18
Bal Due:	\$0.00

Card - MasterCard - \$1,771.18

Customer Number: 991

Received: 2024-03-27

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck hereon
ribed on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car or truck to secure the
cost of repairs thereto. Warranty on parts and labor is one year or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the
cost of repair. IT IS THE SOLE RESPONSIBILITY OF THE CUSTOMER TO HAVE THE WHEELS RE-TORQUED WITHIN 100 KM OF THE MILEAGE REPORTED ON THIS
INVOICE AFTER ANY AND ALL REPAIRS.

Date

Signature

Email Address: info@albertadriveline.com

on the web: www.albertadriveline.com

Copyright © 2024 Mitchell Repair Information Company, LLC. Invoiced 12.2.4