

CUSTOMER #:
UNIT# 103
TSA OIL TOOLS LTD

902807N

INVOICE

CALMONT

Calmont Truck Centre Nisku

2712-5th Street

Nisku, AB T9E 0H1

Phone: 587-906-1810

Toll Free: 1-800-252-7902

www.calmont.ca

X41-1

PAGE 1

HOME:

CONT:

BUS:

CELL:

SERVICE ADVISOR: 1104 LAWRENCE CALKINS

UNIT #	YEAR	MAKE/MODEL			VIN	LICENSE	ODOMETER IN/ OUT		TAG
RED	19	VOLVO VNL64T740			4V4NC9EJXKN900997		992604/992604		900997
DEL DATE	PROD	DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	
31JAN19 DD				00:00 22JUL25	UNIT 103	180.00	CHG	28JUL25	
R.O. OPENED		READY		OPTIONS: STK:24521 DLR:2720K 1)CONTACT: JASON					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CHECK AND ADVISE SLACK ADJUSTERS OPERATION

2720K-00-000-0009 CHECK AND ADVISE SLACK

ADJUSTERS OPERATION

14124 CL 0.94

14056 CL 0.56

1.50

2 GDX40010140 SLACK ADJUSTER, AUTOMATIC

157.52 270.00

270.00

PARTS: 220.52 LABOR: 270.00 OTHER: 0.00 TOTAL LINE A: 490.52

992604

14124- Customer complaints about slack adjuster operation on the unit. Did inspected all driver axle slack, brake pods & brakes. Found that 2nd axle both side adjusting nuts were loose, did adjust the 2nd axle brakes & tighten up the adjusting nuts. On 3rd drive axle both sides slack adjuster needs to be replaced as they are not adjusting the brakes properly, also recommend to remove 3rd axle tires, drums to inspect for brakes as they are too low.

14124- Customer approved replacement of 3rd axle both side slack adjuster. Did remove the slack adjuster on both sides 3rd axle.

14056- Installed the axle 3 both side slacks and adjust the brakes.

Job completed.

B CHECK AND ADVISE FAULT CODES

2720K-00-000-0009 CHECK AND ADVISE FAULT CODES

101228 CL 1.00

180.00

180.00

PARTS: 0.00 LABOR: 180.00 OTHER: 0.00 TOTAL LINE B: 180.00

992604

101228- Customer complaint for CEL, did scanned fault codes.

Unit had P26047F, P26067F, P260900 Intake heater faults.

P11013 Intake air temp sensor circuit open.

Diagnosed for P26047F, P26067F and P260900. Followed CBR-15

VERSION-15, CBR suggested software update, Checked and found software update available for EMS. Performed software update and verified

repairs, no issue any more, software update fixed this issue.

Job completed

Terms: Net 10th of month following.

Interest of 2% (26.4% per annum) if overdue.

DESCRIPTION

TOTALS

LABOUR AMOUNT

PARTS AMOUNT

GAS, OIL, LUBE

SUBLET AMOUNT

MISC. CHARGES

TOTAL CHARGES

LESS INSURANCE

SALES TAX

PLEASE PAY
THIS AMOUNT

CUSTOMER SIGNATURE

GST No. R121090518

CUSTOMER #:
UNIT# 103
TSA OIL TOOLS LTD

902807N

CALMONT

Calmont Truck Centre Nisku
2712-5th Street
Nisku, AB T9E 0H1
Phone: 587-906-1810
Toll Free: 1-800-252-7902
www.calmont.ca

INVOICE

PAGE 2

HOME: CONT:
BUS: CELL: SERVICE ADVISOR: 1104 LAWRENCE CALKINS

UNIT #	YEAR	MAKE/MODEL			VIN		LICENSE	ODOMETER IN/ OUT		TAG
RED	19	VOLVO VNL64T740			4V4NC9EJXKN900997			992604/992604		900997
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT		INV. DATE	
31JAN19 DD			00:00 22JUL25		UNIT 103	180.00	CHG		28JUL25	
R.O. OPENED		READY		OPTIONS: STK:24521 DLR:2720K 1)CONTACT: JASON						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

C PLEASE ROAD TEST FOR TICKING NOISE AND ADVISE

2720K-00-000-0009 PLEASE ROAD TEST FOR TICKING

NOISE AND ADVISE

101228 CL 1.00

180.00

180.00

PARTS: 0.00 LABOR: 180.00 OTHER: 0.00 TOTAL LINE C: 180.00

992604

101228- Diagnosed for customer complaint about ticking noise, While starting unit, noticed that starter making wired noise, we recommend starter replacement for this issue.

Road tested unit and noticed that noise was coming from under the cab area, checked and found clutch brake dowels were broken which rattling on input shaft and found rear drive shaft dust boot loose. Removed and replaced clutch brake on separate job code and fixed dust boot on drive shaft, road tested unit and confirmed no issue anymore. Job completed

D** INSPECTION - AXLE 3 BRAKES LOW

2720K-00-000-0009 INSPECTION - AXLE 3 BRAKES LOW

14124 CL 0.66

14056 CL 1.34

2.00

360.00

360.00

2 CAL4709ES2 4709 ES2 SHOE KIT C/W HARDWARE

74.99

69.99

139.98

2 DBC16792X 16.5X7 LIGHTWEIGHT VALU

153.78

99.99

199.98

PARTS: 339.96 LABOR: 360.00 OTHER: 0.00 TOTAL LINE D: 699.96

992604

14124- Upon inspection did found that brakes were too low, did remove the 3rd axle tire, drums & took measurement, both sides drum & brakes failed the inspection as they have uneven wear & brakes too low. 14056- Upon customer approval, replace axle 3 both side brake and drum. Put the wheels back on and torqued it. Job completed.

E** INSPECTION - INTAKE TEMP SENSOR FAULT

2720K-00-000-0009 INSPECTION - INTAKE TEMP SENSOR

FAULT

Terms: Net 10th of month following.

Interest of 2% (26.4% per annum) if overdue.

CUSTOMER SIGNATURE	DESCRIPTION	TOTALS
	LABOUR AMOUNT	
	PARTS AMOUNT	
	GAS, OIL, LUBE	
	SUBLET AMOUNT	
	MISC. CHARGES	
	TOTAL CHARGES	
	LESS INSURANCE	
	SALES TAX	
	PLEASE PAY THIS AMOUNT	

GST No. R121090518

CUSTOMER #:
UNIT# 103
TSA OIL TOOLS LTD

902807N

CALMONT

Calmont Truck Centre Nisku

2712-5th Street

Nisku, AB T9E 0H1

Phone: 587-906-1810

Toll Free: 1-800-252-7902

www.calmont.ca

INVOICE

PAGE 3

HOME: CONT:
BUS: CELL: SERVICE ADVISOR: 1104 LAWRENCE CALKINS

UNIT #	YEAR	MAKE/MODEL			VIN		LICENSE	ODOMETER IN/ OUT		TAG
RED	19	VOLVO VNL64T740			4V4NC9EJXKN900997			992604/992604		900997
DEL DATE	PROD	DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE	
31JAN19 DD				00:00 22JUL25		UNIT 103	180.00	CHG	28JUL25	
R.O. OPENED		READY			OPTIONS: STK:24521 DLR:2720K 1)CONTACT: JASON					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
	101228	CL		0.15		27.00	27.00
1	21164792	TEMPERATURE SENSOR			197.31	197.31	197.31
PARTS:	197.31	LABOR:	27.00	OTHER:	0.00	TOTAL LINE E:	224.31

992604
101228- Diagnosed for P011013, No CBR found, Followed GD, checked input to sensor, found good, checked and found open circuit in Intake air temp sensor, sensor need replacement.
Removed and replaced intake air temp sensor & fault become in-active. Job completed.

F** ADJUST CLUTCH

2720K-00-000-0009 ADJUST CLUTCH

101228	CL	0.15				27.00	27.00
0.00	LABOR:	27.00	OTHER:	0.00	TOTAL LINE F:		27.00

992604 101228- Clutch adjustment was out of specs. Adjusted the clutch and checked operation, all good. Job completed

G** INSPECTION - CLUTCH BRAKE

2720K-00-000-0009 INSPECTION - CLUTCH BRAKE

101228	CL	1.00			180.00	180.00
SP-SB200	CLUTCH BRAKE	2.00			49.70	31.06
31.06	LABOR:	180.00	OTHER:	0.00	TOTAL LINE G:	211.06

992604
101228- Took off inspection plate and found that clutch brake dowels were broken, Clutch brake need replacement.
Removed and replaced clutch brake, checked operation. Job completed

ESTIMATE: 758.88 21JUL25 16:00 SA: 1104

CONTACT:

CUSTOMER SIGNATURE	DESCRIPTION	TOTALS
	LABOUR AMOUNT	
	PARTS AMOUNT	
	GAS, OIL, LUBE	
	SUBLET AMOUNT	
	MISC. CHARGES	
	TOTAL CHARGES	
	LESS INSURANCE	
	SALES TAX	
	PLEASE PAY THIS AMOUNT	
Terms: Net 10th of month following. Interest of 2% (26.4% per annum) if overdue.		

GST No. R121090518

CUSTOMER #:
UNIT# 103
TSA OIL TOOLS LTD

902807N

INVOICE

CALMONT

Calmont Truck Centre Nisku

2712-5th Street

Nisku, AB T9E 0H1

Phone: 587-906-1810

Toll Free: 1-800-252-7902

www.calmont.ca

PAGE 4

HOME:

CONT:

BUS:

CELL:

SERVICE ADVISOR: 1104 LAWRENCE CALKINS

UNIT #	YEAR	MAKE/MODEL		VIN		LICENSE	ODOMETER IN/ OUT		TAG
RED	19	VOLVO VNL64T740		4V4NC9EJXKN900997			992604/992604		900997
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE	
31JAN19 DD			00:00 22JUL25		UNIT 103	180.00	CHG	28JUL25	
R.O. OPENED		READY		OPTIONS: STK:24521 DLR:2720K 1)CONTACT: JASON					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

ESTIMATE: 569.16 21JUL25 13:14 SA: 1104

CONTACT:

CUSTOMER PAY SHOP CHARGE FOR REPAIR ORDER
AWAITING PO#

97.92

AMEX () DEBIT () CHEQUE ()

MC () VISA ()

Terms: Net 10th of month following.
Interest of 2% (26.4% per annum) if overdue.

		105.54
DESCRIPTION	TOTALS	
LABOUR AMOUNT	1224.00	
PARTS AMOUNT	788.85	
GAS, OIL, LUBE	0.00	
SUBLET AMOUNT	0.00	
MISC. CHARGES	97.92	
TOTAL CHARGES	2110.77	
LESS INSURANCE	0.00	
SALES TAX	105.54	
PLEASE PAY THIS AMOUNT	2216.31	

CUSTOMER SIGNATURE

GST No. R121090518