

Parsons Auto Services LTD.
2903 Parsons rd NW
Edmonton, AB. T6N-1A3
Phone: 780-395-0647

INVOICE

32408

Org. Est. # 036730
GST # 77382 0873 RT0001
AMVIC- B2029831

Printed Date: 10/07/2025

Work Completed: 09/29/2025

INVOICE

2013 Chevrolet - Silverado 3500 HD WT - 6L, V8 (364CI) VIN(G)
Lic # :
Odometer In : 141053
Odometer Out : 141053

EDMONTON, AB

VIN # : 1GB3KZCG8 DF222426

Part Description	Qty	Sale	Ext	Labor Description	Ext
				BRAKE SHOES &/OR PADS - Remove & Replace - Front or Rear - [Includes: Clean, lube and/or replace Brake Hardware as necessary. Adjust Brakes (where applicable). Includes: Repack Wheel Bearings (where applicable). DOES NOT include refinishing.]	175.00
CNTRL ARM&B;BALL JOINT ASSY/Suspension Control Arm and Ball Joint Assembly	2.00	274.42	548.84		
CONTROL ARM&B;BALL JNT ASSY/Suspension Control Arm and Ball Joint Assembly	1.00	512.40	512.40		
CONTROL ARM&B;BALL JNT ASSY/Suspension Control Arm and Ball Joint Assembly	1.00	512.40	512.40	BRAKE SHOES &/OR PADS - Remove & Replace - Front or Rear - [Includes: Clean, lube and/or replace Brake Hardware as necessary. Adjust Brakes (where applicable). Includes: Repack Wheel Bearings (where applicable). DOES NOT include refinishing.]	175.00
SXD1565 PS XD/Disc Brake Pad Set (Front)	1.00	151.18	151.18		
C80441 BRK ROTOR/Disc Brake Rotor (Front)	2.00	246.98	493.96	Ball Joint - Remove and Replace Front; 4WD;Lower,One Side;DOES NOT include alignment; LT; WT; LTZ	250.00
SXD1411 PS XD/Disc Brake Pad Set (Rear)	1.00	151.18	151.18		
C07619 BRK ROTOR/Disc Brake Rotor (Rear)	2.00	272.98	545.96	Ball Joint - Remove and Replace Front; 4WD;Lower,One Side;DOES NOT include alignment; LT; WT; LTZ	250.00
TIRE TAX	6.00	5.00	30.00		
Toyo Open Country WLT1 (Studless) - 10PR	6.00	349.80	2,098.80	Ball Joint - Remove and Replace Front; 4WD;Upper,One Side;Serviced with Control Arm.;DOES NOT include alignment; LT; WT; LTZ Fluid Capacity: Differential Gear Oil - Volume: 3.17 QTS. (2.99L) - SAE 75W-90 Synthetic Gear Oil; Rear Axle 11.5"	125.00
SL91055RD STAB LINK/Suspension Stabilizer Bar Link Kit	2.00	95.20	190.40		
SL90515XL STABLNNKIT/Suspension Stabilizer Bar Link Kit	2.00	97.92	195.84		
RS5000X SHOCK/Suspension Shock Absorber	2.00	215.98	431.96	Ball Joint - Remove and Replace Front; 4WD;Upper,One Side;Serviced with Control Arm.;DOES NOT include alignment; LT; WT; LTZ	150.00
SUSPENSION SHOCK ABSORBER/Suspension Shock Absorber	2.00	293.86	587.72		
55350 AXLCVR GSK/Drive Axle Shaft Flange Gasket	2.00	9.94	19.88	SHOCK &/OR STRUT ASSEMBLY - Remove & Install or Remove & Replace - One Side - [DOES NOT include disassemble or alignment (where applicable).]	100.00
75W90 GR 946 ** price includes Eco Fee of \$0.100/Differential Oil	2.00	61.00	122.00	SHOCK &/OR STRUT ASSEMBLY - Remove & Install or Remove & Replace - One Side - [DOES NOT include disassemble or alignment (where applicable).]	100.00
AXEL SHAFT GASKET/Drive Axle Shaft Flange Gasket	2.00	18.70	37.40	SHOCK ABSORBER - Remove & Replace - One Side	100.00
MGC825 GAS CAP/Fuel Tank Cap	1.00	24.46	24.46	SHOCK ABSORBER - Remove & Replace - One Side	100.00
Shop Supplies			82.00	STABILIZER BAR CONTROL LINK - Remove & Replace - At Control Arm,Link Kit,One Side	50.00
				STABILIZER BAR CONTROL LINK - Remove & Replace - At Control Arm,Link Kit,One Side	50.00
				STABILIZER BAR LINK KIT - Remove & Replace - Dual Rear Wheels,One Side	50.00
				STABILIZER BAR LINK KIT - Remove & Replace - Dual Rear Wheels,One Side Fluid Capacity: Differential Gear Oil - Volume: 3.17 QTS. (2.99L) - SAE 75W-90 Synthetic Gear Oil; Rear Axle 11.5"	50.00
				INSTALL AND BALANCE 6 TIRES	150.00
				WHEEL ALIGNMENT	175.00

Visit us on the web: www.WWW.PARSONSAUTOSERVICES.CA

Email Address: Parsonsaautoservices@gmail.com

Service Advisor : SULTAN, MUNEEB, Tech :

Page 1 of 2

Copyright (c) 2025 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

Parsons Auto Services LTD.
2903 Parsons rd NW
Edmonton, AB. T6N-1A3
Phone: 780-395-0647

INVOICE

32408

Org. Est. # 036730
GST # 77382 0873 RT0001
AMVIC- B2029831

INVOICE

Printed Date: 10/07/2025

Work Completed: 09/29/2025

2013 Chevrolet - Silverado 3500 HD WT - 6L V8 (364CI) VIN(G)
Lic # :
Odometer In : 141053
Odometer Out : 141053

EDMONTON, AB

VIN # : 1GB3KZCG8 DF222426

Home: -- Office

Part Description	Qty	Sale	Ext	Labor Description	Ext
------------------	-----	------	-----	-------------------	-----

Org. Estimate 9,500.32 Revisions 0.00 Current Estimate 9,500.32

Labor:	2,050.00
Parts:	6,736.38
SubTotal:	8,786.38
Tax:	439.32
Total:	9,225.70
Bal Due:	\$1,225.70

[Payments - Visa - \$8,000.00]

Vehicle Received: 2025-09-29

Customer Number : 188

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 30,000 km whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. Invoice must be presented to claim warranty. This warranty does not cover parts or accessories that fail due to abuse, misuse, neglect, alteration, accident. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. PARSONS AUTO IS NOT LIABLE FOR LOSS OR DAMAGE TO VEHICLE BEFORE, DURING OR AFTER VEHICLE REPAIR. Vehicles that have had there tires removed and re-installed are subject to a re-torque after 100 - 200 km. It is the customers responsibility to bring vehicle back to the shop to re-torque the wheels. Parsons Auto Services is not responsible for lost or stolen items from the vehicle.

Signature _____ Date _____

Visit us on the web: www.WWW.PARSONSAUTOSERVICES.CA

Email Address: Parsonsaautoservices@gmail.com

Service Advisor : SULTAN, MUNEEB, Tech :