## Westside Heavy Duty Repair

Unit 130, 7420 108 Ave Se CALGARY AB T2C 5C8 westsideheavydutyrepair@gmail.com GST/HST Registration No.: 749008504



# INVOICE

**BILL TO** 

Das hauling corp

DATE		DESCRIPTION	TAX	QTY	RATE	AMOUNT	
21/05/2025	Services	Remove trailer buggy, sublet for weld rear cross- member. Run new air lines, make new connections, Repaired abs burnt harness. Reinstall buggy with new hardware and new springs.	GST 14		100.00	1,400.00	
21/05/2025	Services	Sublet weld for rear crossmember and 7 channels at front for deck at bottom.	GST	1	2,550.00	2,550.00	
21/05/2025	Parts	1/2 brass Push connect	GST	13	11.99	155.87	
21/05/2025	Parts	1/2 15 feet brake air line	GST	15	4.95	74.25	
21/05/2025	Parts	Spring loaded air line fittings	GST	2	16.75	33.50	
21/05/2025	Parts	Hardware and slider springs	GST	1	50.00	50.00	
21/05/2025	Services	Shop Supplies	GST	1	170.00	170.00	
2004 TRAILE	 ≣R	SUBTOTA	 AL		•••••••	4,433.62	
VIN- 242011		GST @ 5				221.68	
UNIT- 85423 PLATE- 6UD		TOTAL				4,655.30	
PLATE- 60D	7433	BALANCE DUE		\$4.655.30			

## TAX SUMMARY

RATE	TAX	NET
GST @ 5%	221.68	4,433.62

### Disclaimer/Consent

Westside HD Repair is not responsible for damage caused by theft, fire or acts of nature, by accepting quote and/or paying invoice I authorize the repairs and I consent to the following and aforementioned, along with any materials necessary for repair. An express mechanics lien is hereby acknowledged on the vehicle being booked to secure the amount of the repairs thereto.

## Westside Heavy Duty Repair

Unit 130, 7420 108 Ave Se CALGARY AB T2C 5C8 westsideheavydutyrepair@gmail.com GST/HST Registration No.: 749008504



# INVOICE

**BILL TO** 

Das hauling corp

DATE		DESCRIPTION	TAX	QTY	RATE	AMOUN <sup>-</sup>
13/04/2025	Services	Replace axle 2 both side chassis bushings	GST	6	100.00	600.00
13/04/2025	Parts	Bushings	GST	2	225.17	450.3
14/04/2025	Services	Wheel off inspection	GST	1	350.00	350.0
14/04/2025	Services	Replaced axle 1 rhs leaking wheel seal	GST	2	100.00	200.0
14/04/2025	Parts	Wheel seal	GST	2	62.00	124.0
14/04/2025	Parts	Hub Cap gasket	GST	2	2.95	5.9
23/05/2025	Services	Replace axle 1 lhs leaking wheel seal. Replaced brake shoes as well-was soaked in oil	GST	2.50	100.00	250.0
23/05/2025	Services	Replaced axle 1 rhs seized wheel speed sensor	GST	1	100.00	100.0
23/05/2025	Services	Replace axle 1 lhs leaking piggy back	GST	1	100.00	100.0
23/05/2025	Parts	Piggy back	GST	1	72.00	72.0
23/05/2025	Parts	Brake Shoes	GST	1	68.00	68.0
23/05/2025	Parts	Abs Sensor	GST	1	45.00	45.0
26/05/2025	Services	Replaced leaking air relay valve at air tank	GST	2.50	100.00	250.0
26/05/2025	Parts	Relay valve	GST	1	105.00	105.0
26/05/2025	Services	Shop Supplies	GST	1	136.00	136.0
2004 TRAILE		SUBTOT	SUBTOTAL			2,856.2
VIN- 242011 UNIT- 85423	N- 24201 154 GST @ 5		%			142.8
	Ti.	TOTAL				2,999.0

### Disclaimer/Consent

Westside HD Repair is not responsible for damage caused by theft, fire or acts of nature, by accepting quote and/or paying invoice I authorize the repairs and I consent to the following and aforementioned, along with any materials necessary for repair. An express mechanics lien is hereby acknowledged on the vehicle being booked to secure the amount of the repairs thereto.

PLATE- 6UD499 BALANCE DUE **\$2,999.06** 

NOTE- RETORQUE ALL WHEEL LG NUTS AFTER 150KM.

TAX SUMMARY

RATE	TAX	N	ET
GST @ 5%	142.82	2,856.	24

#### Disclaimer/Consent

Westside HD Repair is not responsible for damage caused by theft, fire or acts of nature, by accepting quote and/or paying invoice I authorize the repairs and I consent to the following and aforementioned, along with any materials necessary for repair. An express mechanics lien is hereby acknowledged on the vehicle being booked to secure the amount of the repairs thereto.