



DART MECHANICAL INC
 715043 Rge Rd 50
 County of Grande Prairie No.1, AB T8X 4E7
 Canada Ph: 587-818-5100

Invoice #: 2548

Date: 11-25-25

Sold to:

Robert Nysted

RR1
 Sexsmith, AB T0H 3C0

UNIT#: LEAD LIC#: 6AE756 AB
 VIN: 2DEHBFZ3131015594
 2003 DOEPKER SUPER B

Business No.: 743158917

Item No.	Qty	Description	Unit Price	Amount
UC		Unit Complaint - Perform CVI		
CI	1.00	CVI - "A" Inspection	300.00	300.00
L	3.75	Labour - R+R wheels and drums for inspection. Torque wheels to 475 ft-lbs.	150.00	562.50
L	11.25	Labour - Split trailers, assemble repair list. Diagnose ABS issues. Clean dirt/gravel from frame to get access to ABS wiring. Get ABS module to power up, found axle #3 RH ABS sensor code. Check sensor, it has failed. Axle #1 RH sensor is damaged as well. Replace 5x wheel seals (axle #1 both, axle #2 RH, and axle #3 both). Repalce all 6x hub covers.	150.00	1,687.50
L	9.75	Labour - Free up 5th wheel jaws. R+R axle #2 LH slack adjuster. Replace axle #2 RH brake pot clevis. Replace failed ABS sensors, top off hub fluid levels. Replace axle #3 s-cams, tubes, and slack adjusters. Weld up damaged cross members. Repair ABS light wiring, replace ABS indicator light. Replace license plate light. Secure wiring and hoses above axles. Retest all lights, move unit outside. Clean up.	150.00	1,462.50
P	1.00	Parts - ABS light, 2x ABS sensor, 5x Wheel seal, 6x Hub cover, Brake pot clevis, LH and RH s-cam, 3x Slack adjuster, 2x HD S-cam repair tube, 3x 1/2" clevis pin, 2" red marker light, 2x 2-prong pigtail.	1,013.17	1,013.17
P	1.00	Parts - 4x Used tire, Rim replacement due to cracked.	1,214.70	1,214.70
SS	1.00	Shop Supplies - 8% of Labour.	321.00	321.00
SS	1.00	Shop Supplies - 50% Discount	-160.50	-160.50
		Subtotal:		6,400.87
		G - GST 5% GST/HST		320.06

I HEREBY ACKNOWLEDGE MY INDEBTEDNESS IN THE AMOUNT OF \$ _____
 BEING THE TOTAL AMOUNT OWING OR BALANCE OWING AS SHOWN HEREON.

CUSTOMER SIGNATURE _____ DATE _____

Sold By:

**Invoice
 Total**

6,720.93