

P23-1
BLUE-MAR

Brandt Tractor Ltd.
P.O. Box 3856
Regina, SK
S4P 3R8
(306) 791-7777

Service
Invoice



JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
29OCT24	101	1101154

SOLD TO:

DENNY FORBES CONSTRUCTION
STK # 01101154
G/L# 105-00-000101
S/N # 1DW410ETLKF697640

PAGE
1
SALE TYPE
WARRANTY
CUSTOMER NO.

S
H
I
P

T
O
D
ENNY FORBES CONSTRUCTIO

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALES PRN
		1101154	01	18OCT24	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	410E	1DW410ETLKF697640	Cab, a/c	5492	GRAHAM

DESCRIPTION	AMOUNT
-------------	--------

<p>DIAGNOSE AND REPAIR TRANSMISSION ISSUES</p> <p>COMPLAINT: diagnose and repair transmission issues</p> <p>CAUSE: Internal clutch failure in transmission</p> <p>CORRECTION: Confirmed customers complaint. Transmission stuck in limp mode and will not shift properly. Active TCU code 523235.0 Clutch E slip very high. Perfrom steps for trans diagnosis from solution 216919. Could not complete due to trans failing calibration constantly. reported issue to d tac awaiting instruction. Cut filters open and take pictures as per d tacs request. They have given to go ahead to replace the trans. d tac as requested cooler lines to be cleaned and cooler and thermostatic valve to be replaced. Due to system being contaminated with metal filings and debris. Started on trans removal drained coolant recovered air condition unhooked lines and wiring off the cab to remove cab.-removed cab plastic roof, installed lifting device on cab and support with crane then</p>	
---	--

<p>PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM), MINIMUM CHARGE OF \$1.50.</p> <p>I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.</p> <p>X _____ SIGNATURE</p> <p>_____ DATE</p>	QST # 1226957240	DESCRIPTION	AMOUNT
	TOTAL PARTS		
	TOTAL LABOR		
	MISC. CHARGES SALES TAX		
RELEASE PAY		THIS TOTAL	**CONTINUED**

CUSTOMER COPY

Brandt Tractor Ltd.
P.O. Box 3856
Regina, SK
S4P 3R8
(306) 791-7777

**Service
Invoice**



JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
29OCT24	101	1101154

SOLD TO:

DENNY FORBES CONSTRUCTION
STK # 01101154
G/L# 105-00-000101
S/N # 1DW410ETLKF697640

PAGE
2
SALE TYPE
WARRANTY
CUSTOMER NO.

S DENNY FORBES CONSTRUCTIO
H
I
P
T
O

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN
		1101154	01	18OCT24	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	410E	1DW410ETLKF697640	Cab, a/c	5492	GRAHAM

DESCRIPTION	AMOUNT
secure, removed bac r/h front mounting bolt, carefully removed cab from machine and put on jack stand, removed exhaust chrome pipe and set aside, installed lifting device on exhaust top cover and secure, loosen and removed exhaust cover mounting bolts and carefully removed cover, rigged exhaust assembly and secure, removed exhaust filter frame front mounting bracket, removed exhaust filter harness securing clamps and disconnected harness from DEF dosing unit, removed DEF dosing unit assembly with the coolant hose lines and cover opening, lift up exhaust filter assembly and carefully removed from machine, disconnected harness from hyd tank, and unmounted harness securing clamp then removed harness and set aside, unmounted harness securing clamp from the bracket at the top of assembly and set aside harness, disconnected hyd oil pipe line from hyd oil filter housing on top of hyd tank and cover opening. Removed hyd oil pipe line securing clamp and moved pipe line out of way for tranny removal, disconnected hyd oil lines from bottom of hyd tank and support opening, unmounted lifting device on hyd tank and secure, loosen	

PAST DUE IN FULL WITH PERMITS TO REPAIR. MINIMUM CHARGE OF \$1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine and to be the amount for repairs thereto. It is understood that this company is not responsible for loss or damage by theft or fire to machine placed with them for storage, repair, or other work being done.

X _____
SIGNATURE

DATE

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES	
SALES TAX	
PLEASE PAY THIS TOTAL	**CONTINUED**

CUSTOMER COPY

Brandt Tractor Ltd.
P.O. Box 3856
Regina, SK
S4P 3R8
(306) 791-7777

**Service
Invoice**



INVOICE DATE	BRANCH	INVOICE NO.
29OCT24	101	1101154

SOLD TO:

DENNY FORBES CONSTRUCTION
STK # 01101154
G/L# 105-00-000101
S/N # 1DW410ETLKF697640

PAGE
3
SALE TYPE
WARRANTY
CUSTOMER NO.

S DENNY FORBES CONSTRUCTIO
H
I
P
T
O

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALES PRN
		1101154	01	18OCT24	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	410E	1DW410ETLKF697640	Cab, a/c	5492	GRAHAM

DESCRIPTION	AMOUNT
and removed r/h hyd tank mounting bolts, carefully removed hyd tank from machine, disconnected hyd oil lines from hyd pump and capped opening, disconnected hyd oil lines from secondary steering pump B32 and capped opening. Loosen and removed rear tranny output drive shaft mounting bolts and disconnected drive shaft from tranny., B31. -removed cab plastic roof, installed lifting device on cab and support with crane then secure, removed bac r/h front mounting bolt, carefully removed cab from machine and put on jack stand, removed exhaust chrome pipe and set aside, installed lifting device on exhaust top cover and secure, loosen and removed exhaust cover mounting bolts and carefully removed cover, rigged exhaust assembly and secure, removed exhaust filter frame front mounting bracket, removed exhaust filter harness securing clamps and disconnected harness from DEF dosing unit, removed DEF dosing unit assembly with the coolant hose lines and cover opening, lift up exhaust filter assembly and carefully removed from machine, disconnected harness from hyd tank, and unmounted harness securing	

<p>PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM), MINIMUM CHARGE OF \$1.50.</p> <p>I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.</p> <p>X _____ SIGNATURE</p> <p>_____ DATE</p>	QST # 1226957240	DESCRIPTION	AMOUNT
	TOTAL PARTS		
	TOTAL LABOR		
	MISC. CHARGES SALES TAX		
PLEASE PAY THIS TOTAL		**CONTINUED**	

CUSTOMER COPY

Brandt Tractor Ltd.
P.O. Box 3856
Regina, SK
S4P 3R8
(306) 791-7777

**Service
Invoice**



JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
29OCT24	101	1101154

SOLD TO:

DENNY FORBES CONSTRUCTION
STK # 01101154
G/L# 105-00-000101
S/N # 1DW410ETLKF697640

PAGE
4
SALE TYPE
WARRANTY
CUSTOMER NO.

S
H
I
P
T
O
D
ENNY FORBES CONSTRUCTIO

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPAN
		1101154	01	18OCT24	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	410E	1DW410ETLKF697640	Cab, a/c	5492	GRAHAM

DESCRIPTION	AMOUNT
clamps then removed harness and set aside, unmounted harness securing clamps from the bracket at the top of tranny and set aside harness, disconnected hyd oil pipe line from hyd oil filter housing on top of hyd tank and cover opening. Removed hyd oil pipe line securing clamps and moved pipe line out of way for tranny removal. Disconnected hyd oil lines from bottom of hyd tank and capped opening, installed lifting device on hyd tank and secure, loosen and removed r/h hyd tank mounting bolts, carefully removed hyd tank from machine, disconnected hyd ctoc drive shaft from tranny, 331isconne	
2 HOSE FIT	
1 BULK HOS	
1 PLUNGER	
TO HAVE CUSTOMER BUY	
1 ELBOW FI	
1 TRANSMISCY	
SUB FOR AT4-0891 TO 11R 1E	
1 OIL COOLCY	
1 O-RING	
1 THERMOSTXY	
1 OIL FILT	
1 O-RING	
1 C-RING	
1 C-RENG	

<p>PAST DUE INTEREST AND PENALTIES ON THIS ACCOUNT ARE IN FULL CHARGE OF \$1.50.</p> <p>I hereby authorize the above repair work to be completed with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine for the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, repair, or testing.</p> <p>X _____ SIGNATURE</p> <p>_____ DATE</p>	<p>QST # 1226957260</p>	<p>DESCRIPTION</p> <p>TOTAL PARTS</p> <p>TOTAL LABOR</p> <p>MISC. CHARGES</p> <p>SALES TAX</p>	<p>AMOUNT</p>

PLEASE PAY THIS TOTAL ****CONTINUED****

CUSTOMER COPY

Brandt Tractor Ltd.
P.O. Box 3856
Regina, SK
S4P 3R8
(306) 791-7777

Service
Invoice



INVOICE DATE	BRANCH	INVOICE NO.
29OCT24	101	1101154

SOLD TO:

DENNY FORBES CONSTRUCTION
STK # 01101154
G/L# 105-00-000101
S/N # 1DW410ETLKF697640

PAGE
5
SALE TYPE
WARRANTY
CUSTOMER NO.

S
H
I
P
T
O
DENNY FORBES CONSTRUCTIO

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALES PRN
		1101154	01	18OCT24	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	410E	1DW410ETLKF697640	Cab, a/c	5492	GRAHAM

DESCRIPTION	AMOUNT
6 N T78612 O-RING	
1 N T72570 O-RING	
7 N T286130 O-RING	
2 N T223688 O-RING CY	
1 N R22459 O-RING	
1 N R71596 O-RING	
2 N T77358 O-RING	
1 N T77613 O-RING	
1 N T77613 PLUNGER	
1 N T77613 OIL X	
100 WASTE DI	
1 N ATB48594 FLUID KI	
1 N ATB48531 TEST/MEA	
1 N T77628 HYDRAULI	
** TOTAL LABOR **	
HOSE MAKING	
CARBON TAX SURCHARGE	

>>>> SEG# 01 PRT LAB MSC

<p>PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUAL), MINIMUM CHARGE OF \$1.50.</p> <p>I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.</p> <p>X _____ SIGNATURE DATE</p>	DESCRIPTION	AMOUNT
	TOTAL PARTS	
	TOTAL LABOR	
	MISC. CHARGES SALES TAX	
PLEASE PAY THIS TOTAL		

CUSTOMER COPY

Brandt Tractor Ltd.
P.O. Box 3856
Regina, SK
S4P 3R8
(306) 791-7777

Service
Invoice



JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
31OCT24	101	1101284

SOLD TO:

DENNY FORBES CONSTRUCTION
STK # 01101284
G/L# 105-00-000101
S/N # 1DW410ETLKF697640

PAGE 1
SALE TYPE
WARRANTY
CUSTOMER NO.

S DENNY FORBES CONSTRUCTIO
H
I
P
T
O

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN
		1101284	03	31OCT24	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	410E	1DW410ETLKF697640	Cab, a/c	5495	GRAHAM

DESCRIPTION	AMOUNT
REPAIR HYDRAULIC OIL LEAK AT HYDRAULIC TANK COMPLAINT: REPAIR HYDRAULIC OIL LEAK AT HYDRAULIC TANK CAUSE: CAUSED BY FAILED O-RING_ CORRECTION: Drain oil and put onto drum. Order parts. Disconnect hydraulic lines. Check fittings flange surface for any damage. None. Remove, replace and install new seal o ring. Install and and tighten hose. Refill hydraulic oil onto specific level. Start engine and run hydraulic. No leaks on the hose and fittings area. Clean and remove oil spill on the machine. Clean tools. Do Tech report. 1 N 278784 O-RING ** TOTAL LABOR ** CARBON TAX SURCHARGE >>--> SEG# 03 PART LAB MSC	

PAST DUE INTEREST 1 1/2% PER MONTH (13% ANNUUM). MINIMUM CHARGE OF \$1.50. I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing. y _____ SIGNATURE DATE	QST 61226957240	DESCRIPTION	AMOUNT
		TOTAL PARTS	
		TOTAL LABOR	
		MISC. CHARGES SALES TAX	
		PLEASE PAY THIS TOTAL	

CUSTOMER COPY