

STRAIGHTLINE HEAVY EQUIPMENT

jeremy@straightlinemech.ca
www.straightlinemech.ca
GST:838540649RT0001

TRANS/DRIVE: 6-SPEED AUTOM
LICENSE/PROVIN /AB
KMS IN/KMS OUT 370840/370840

VEHICLE ISSUE #1: FRONT END INSPECTION

LABOR: STRUIK, INSPECTION	0.5 @ 125.00	\$62.50	LABOR
---------------------------	--------------	---------	-------

VEHICLE IN USE FOR PERSONAL PURPOSES

TECH REPORT: MAKE SECTION OF PIPE TO EXTEND EXHAUST OUT FROM UNDERNEATH BODY.

PART: 90356B	4" STEP CLAMP	1 @ \$24.76	\$24.76	NEW
--------------	---------------	-------------	---------	-----

PART: 33285	3.5 BAND CLAMP	1 @ \$32.65	\$32.65	NEW
-------------	----------------	-------------	---------	-----

DATE: 12/04/20	NELSON	12/04/20	12/04/20	NEW
----------------	--------	----------	----------	-----

LABOR: HILLING, EXTEND EXHAUST	1.5 @ 125.00	\$187.50	LABOR
--------------------------------	--------------	----------	-------

VEHICLE ISSUE #3: REPLACE FRONT END SUSPENSION AND STEERING COMPONENTS

[illegible]

PART: FT-7652A-F	NAPA FLEET FRONT BRAKE PADS	1 @ \$171.40	\$171.40	NEW
------------------	-----------------------------	--------------	----------	-----

PART: 515059	FRONT HUB ASSEMBLIES	2 @ \$296.47	\$592.94	NEW
--------------	----------------------	--------------	----------	-----

[illegible]

PART: MCGOWEN	2 @ \$74.32	\$148.64	NEW
---------------	-------------	----------	-----

PART: MK6659	MK6659 IDLER WITH REMOTE GREASE LINE	1 @ \$111.23	\$111.23	NEW
--------------	--------------------------------------	--------------	----------	-----

PART: MS50188	FRONT UPPER CONTROL ARM ASSEMBLY	1 @ \$147.23	\$147.23	NEW
---------------	----------------------------------	--------------	----------	-----

PART: MS50180	FRONT UPPER CONTROL ARM ASSEMBLY	1 @ \$147.23	\$147.23	NEW
---------------	----------------------------------	--------------	----------	-----

2

PART: 349009	GAS SHOCK	2 @ \$69.66	\$139.32	NEW
--------------	-----------	-------------	----------	-----

PART: 349046	GAS SHOCK	2 @ \$79.22	\$158.44	NEW
--------------	-----------	-------------	----------	-----

PART: 213-4688	ENGINE COOLANT TEMP SENSOR	1 @ \$48.55	\$48.55	NEW
----------------	----------------------------	-------------	---------	-----

[illegible]

PART: 905-142	SHIFT CABLE	1 @ \$67.43	\$67.43	NEW
---------------	-------------	-------------	---------	-----

	Parts	\$3,311.51
	Sublet	\$0.00
	Total Fees	\$0.00
	Subtotal	\$6,749.01
	Total	\$7,086.47
	Payments	\$0.00
	Balance	\$7,086.47

All work is performed upon a continuous basis. The work is performed in a continuous manner.

Payment by E-Transfer to office@straightlinemech.ca
Cheques can be issued to Straightline Heavy Equipment & Auto Ltd
Payment by Visa/MC/Amex/Debit at an additional 3%
GST#: 838540649RT0001

We thank you for your business!

Straightline Heavy Equipment
58
Jersey, AB. T0I0a0
(403) 852-2352



STRAIGHTLINE HEAVY EQUIPMENT

INVOICE #2105

jeremy@straightlinemech.ca
www.straightlinemech.ca
GST:838540649RT0001

CUSTOMER: HIGH COUNTRY VAC SERVICES

YEAR: 2011
MAKE/MODEL: CHEVROLET EXPRESS G3500
VIN: 1GB3G3CG7B1106739
ENGINE: 6.0L V8 OHV 16V

TRANS/DRIVE: 6-SPEED AUTOM
LICENSE/PROVIN /AB
MILES IN/OUT: 370840 370840

PART: 5W30	SYNTHETIC 5W30 MOBIL1 1LTR	7 @ \$12.32	\$86.24	NEW
PART: 7060MP	NAPA GOLD OIL FILTER	1 @ \$15.34	\$15.34	NEW
PART: 3" EXHAUST PIPE	NELSON	1 @ \$70.13	\$70.13	NEW
LABOR: COCKLE,	FRONT END REPAIRS	17 @ 125.00	\$2,125.00	LABOR
VEHICLE ISSUE #4: DIAG EXHAUST CAT CODES				
TECH REPORT: CHECK IF CAT'S HAD BEEN CLEARED OUT, FOUND TO BE STILL INTACT, CUT OUT CAT'S. WELD IN NEW SECTION OF EXHAUST PIPING. TUNE AND CAT DELETE CHEAPER THAN REPLACING CATS AND ELIMINATES PROBLEMS. FLASH UNIT TO REGULAR 87 OCTANE PUMP GAS TUNE, ENABLE FUEL ENRICHMENT, TURN OFF POST 02'S, TURN OFF EVAP AND EMISSIONS.				
PART: HPTUNERS GM GAS	ENGINE TUNE	1 @ \$449.99	\$449.99	NEW
LABOR: HILLING,	REMOVE AND REPLACE CATALYTIC CONVERTORS	3 @ 125.00	\$375.00	LABOR
VEHICLE ISSUE #5: VEHICLE NOT CHARGING				
TECH REPORT: PERFORM ELECTRICAL DIAGNOSIS ON AMBULANCE FOR CHARGING SYSTEM. FOUND LARGE BATTERY ISOLATOR TO BE FAULTY. REPLACE BATTERY ISOLATOR. PUT CABINET COVERS BACK ON. REPAIR BATTERY TRAY.				
PART: SP2403	BATTERY ISOLATOR	1 @ \$497.99	\$497.99	NEW
LABOR: HILLING,	REPLACE BATTERY ISOLATOR	1.5 @ 125.00	\$187.50	LABOR
LABOR: HILLING,	CHARGING SYSTEM DIAGNOSIS	2.5 @ 125.00	\$312.50	LABOR
LABOR: COCKLE,	REPAIR BATTERY TRAY AND HOLD DOWN	1.5 @ 125.00	\$187.50	LABOR

Recommended Repairs:	Labor/Jobs	\$3,437.50
	Parts	\$3,311.51
	Sublet	\$0.00
	Total Fees	\$0.00
	Subtotal	\$6,749.01
	GST @ 5%	\$337.46
	Total	\$7,086.47
	Payments	\$0.00
	Balance	\$7,086.47

All work is performed upon customer request/specifications.

Payment by E-Transfer to office@straightlinemech.ca
Cheques can be issued to Straightline Heavy Equipment & Auto Ltd
Payment by Visa/MC/Amex/Debit at an additional 3%
GST#: 838540649RT0001

We thank you for your business!