

Excell Transmission

5034 ROSS STREET
RED DEER, AB, T4N 1Y3
(403) 358-5589 Fax: (403) 346-9225



13-2.

INVOICE # 5022

excelltransmission@telus.net

BAR# 878135912RT0001

| | | |
|--------------|-----------------------------|---------------------------------|
| TR TRANSPORT | YEAR: 2016 | TRANS/DRIVE: 6 SPD AUTOMATIC A/ |
| | MAKE/MODEL: RAM 3500 SLT | LICENSE/PROVINCE: CHH-3179/AB |
| | VIN: 3C63RRHL6GG276962 | KMS IN/KMS OUT: 366164/ |
| | ENGINE: 6.7L L6 DIR OHV 24V | FLEET NUMBER PT-23 |

In: 9/10/2025 Out: 9/16/2025 Email: a

VEHICLE ISSUE #1: CHECK AND ADVISE NO MOVE AND IS MAKING NOISE.

TECH REPORT: P0219 ENGINE OVERSPEED, P238D WATER IN FUEL, P0933 HYDRAULIC PRESSURE SENSOR RANGE/PERFORMANCE, P0740 TCC OUT OF RANGE, P0935 HYDRAULIC PRESSURE SENSOR RANGE/PERFORMANCE, P0944 LOSS OF PRIME, P0868 LINE PRESSURE LOW. BACKING PLATE IS CRACKED.

| | | | | |
|--------|---|----------------|------------|-------|
| PART | 68RFE GASKET AND SEAL KIT | 1 @ \$368.80 | \$368.80 | NEW |
| PART | 68RFE TORQUE CONVERTER MULTI DISC HD | 1 @ \$1,449.50 | \$1,449.50 | NEW |
| PART | 68RFE FILTER 4X4 | 1 @ \$54.99 | \$54.99 | NEW |
| PART | 68RFE SPIN ON FILTER | 1 @ \$77.27 | \$77.27 | NEW |
| PART | 68RFE INPUT SHAFT | 1 @ \$100.00 | \$100.00 | NEW |
| PART | 68RFE PUMP BODY WITH GEARS AND COMPLETE STATOR ASSEMBLY | 1 @ \$647.69 | \$647.69 | USED |
| PART | 68RFE UD FRICTION | 6 @ \$16.83 | \$100.98 | NEW |
| PART | 45RFE UD/ REVERSE STEEL | 6 @ \$11.82 | \$70.92 | NEW |
| PART | SYNTHETIC ATF | 16 @ \$16.95 | \$271.20 | NEW |
| PART | FREIGHT | 1 @ \$64.30 | \$64.30 | NEW |
| PART | BW 4446 REAR OUTPUT SEAL | 1 @ \$36.67 | \$36.67 | NEW |
| PART | 68RFE FLEXPLATE USED | 1 @ \$300.00 | \$300.00 | NEW |
| LABOR: | LABOUR TIME TO REMOVE TRANSMISSION, REPLACE FLEXPLATE, AND REINSTALL TRANSMISSION | | \$1,112.00 | LABOR |
| LABOR: | BENCH LABOUR TIME TO INSTALL PARTS LISTED INTO 68RFE TRANSMISSION | | \$973.00 | LABOR |
| LABOR: | HOT FLUSH COOLER AND LINES | | \$139.00 | LABOR |

SHOP SUPPLIES : \$95.00

| | | | |
|---------------|------|------------------|------------|
| Payment Rec'd | Visa | Date : 9/16/2025 | \$6,154.39 |
|---------------|------|------------------|------------|

EXCELL TRANSMISSION LTD.
5034 ROSS ST
RED DEER, AB T4N1Y3
4033585589

SALE

MID: 6562590 REF#: 00000003
TID: 002 RRN: 00000003
Batch #: 259001 09/04/24
09/16/25 APPR CODE: 02751G

AMOUNT \$6,154.39

APPROVED

TS: 68 00

BY ENTERING A VERIFIED PIN
CARDHOLDER AGREES TO PAY ISSUER
SUCH TOTAL IN
ACCORDANCE WITH ISSUER'S
AGREEMENT
WITH CARDHOLDER

THANK YOU / MERCI!

CUSTOMER COPY

RED

| | |
|------------|------------|
| Labor/Jobs | \$2,224.00 |
| Parts | \$3,542.32 |
| Sublet | \$0.00 |
| Total Fees | \$95.00 |
| Subtotal | \$5,861.32 |
| GST @ 5% | \$293.07 |
| Total | \$6,154.39 |
| Payments | \$6,154.39 |
| Balance | \$0.00 |

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X

Date 9/16/2025

SO # 169475

Printed 10/28/2022 12:27:39 PM

**SERVICE ORDER
CUSTOMER COPY**

DP



User

9404

Page 1

| | | | | | |
|-----------------------|-------------------|-------------------------------|-------------------|---------------------|----------|
| Customer No | Advisor | Gilles Beaulieu | Promised | 10/31/2022 5:00 PM | Tag |
| Tr Transport | Shop | S1 | Opened | 10/26/2022 12:27 PM | Location |
| | Priority | 10 | Cashiered | | PO # |
| | | | | | PT-23 |
| Home Cell Email | License No | Odometer In | Odometer Out | InServ Date | Stock No |
| | PT-23 | 193079 | 193113 | | |
| Bus Today | Year | Make | Model | Model No | Colour |
| | 2016 | RAM | 3500 | D28H92 | |
| Term CASH | Vehicle ID No | Selling Dealer | Extended Warranty | Delivery Date | |
| | 3C63RRHL6GG276962 | | | | |
| | Engine Size | 6.7L CUMMINS I-6 TURBO DIESEL | Fleet # | | |

| Request | Description | Job | CSR | Status |
|------------|---|-----|-------------------|----------|
| 2100 | CUSTOMER STATES EXCELL TRANSMISSION JUST OVERHAULED THE TRANSMISSION AND THERE IS A LACK OF POWER AND EXCELL STATES THAT SENSORS WERE SPIKING PLEASE ADVISE IF YOU NEED MORE INFO CALL MEL SWEET AND EXCELL TRANSMISSION AT 403-358-5589 | 1 | 9404_C | Original |
| Labour | Description | | Type | Amount |
| 2100 | CUSTOMER STATES EXCELL TRANSMISSION JUST OVERHAULED THE TRANSMISSION AND THERE IS A LACK OF POWER AND EXCELL STATES THAT SENSORS WERE SPIKING PLEASE ADVISE IF YOU NEED MORE INFO CALL MEL SWEET AND EXCELL TRANSMISSION AT 403-358-5589 | | CPD | 139.96 |
| Rate | 174.95 | | Parts Total | 0.00 |
| Technician | 9136_C - | | Labour Total | 139.96 |
| Cause | low fuel pressure | | Request Sub-total | 139.96 |
| Correction | TECH 9136 - INITIAL INSPECTION FOUND NO C.E. LIGHT ON. SCAN FOUND NO CODES. I CHECKED THE TRANSMISSION FLUID LEVEL & CONDITION - OK. I CHECKED TRANSMISSION CVI DATA, FOUND ALL CVI'S ARE WITHIN RANGE. I ROAD TESTED & FOUND ENGINE POWER IS LOW UNDER LOAD. FOUND FUEL RAIL PRESSURE LIS LOW UNDER LOAD. FUEL FILTER LIFE IS AT 0%. RECOMMEND TO START WITH FUEL FILTERS & RE-TEST. FUEL LEVEL IS SHOWING 1/8 OF A TANK. FUEL PUMP INLET SCREEN MAY ALSO BE RESTRICTED AND/OR WEAK LIFT PUMP. IF FUEL FILTERS DO NOT CORRECT THE PROBLEM IT MAY NEED A FUEL PUMP. QUOTE TO FOLLOW.DIAGS & INSPECT .8 HR | | | |
| Request | Description | Job | CSR | Status |
| Y26 | 2012-21 D TRUCK M14 WHEEL STUDS | 2 | 9404_C | Original |
| Labour | Description | | Type | Amount |
| Y26 | 2012-21 D TRUCK M14 WHEEL STUDS | | W | W |
| 22Y26181 | Safety Recall Y26 - Wheel Studs-Inspect Wheel Studs | | | |
| Technician | 9136_C - | | Parts Total | 0.00 |
| Cause | RECALL | | Labour Total | 0.00 |
| Correction | TECH 9136 - CHECKED & PERFORMED Y26 RECALL --- INSPECTION FOUND ALL THE WHEEL STUDS PASSED. LOP 22-Y2-61-81 0.6 HR | | Request Sub-total | 0.00 |

SIGN UP AND SAVE
ONE EMAIL PER MONTH SAVES MONEY ALL YEAR
GO TO MOPAR.CA TO SAVE NOW

DID YOU KNOW?
YOU CAN PURCHASE EXTENDED WARRANTY UNTIL YOUR WARRANTY EXPIRES. (ASK YOUR ADVISOR FOR INFO)

I HEREBY AUTHORIZE THE REPAIR WORK HERIN SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND AGREE THAT TO THE EXTENT PERMITTED BY LAW, YOU ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND YOUR CONTROL, OR FOR ANY DELA'S CAUSED BY HERIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND OR INSPECTION, UNTIL PAYMENT IN FULL OF THE WITHIN ACCOUNT. I HEREBY ACKNOWLEDGE THE EXISTENCE OF A MECHANIC'S LIEN IN FAVOUR OF THE WITHIN DEALER ON THE VEHICLE DESCRIBED HEREIN IN RESPECT OF THE MATERIAL SUPPLIED AND SERVICES RENDERED UNDER THIS WORK ORDER FOR THE FULL AMOUNT CHARGED THEREFOR. IF FURTHER ACKNOWLEDGE THAT THE SAID LIEN SHALL CONTINUE IN FORCE AT ALL TIMES WHETHER THE VEHICLE IS IN MY POSSESSION OR POSSESSION OF THE DEALER, UNTIL THE WITHIN ACCOUNT IS PAID IN FULL WHILE THE VEHICLE IS IN MY POSSESSION, IT SHALL AT ALL TIMES BE SUBJECT TO REPOSSESSION ON DEMAND BY THE DEALER UNTIL THE WITHIN ACCOUNT IS PAID IN FULL.

IS A WRITTEN ESTIMATE REQUIRED? ARE USED PARTS TO BE KEPT FOR 48 HOURS?

YES = INITIAL NO = INITIAL DATE CUSTOMER SIGNATURE

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS WORK ORDER

DATE CUSTOMER SIGNATURE

G.S.T. # 79781-9125 RT0001

SO # 169475

Printed 10/28/2022 12:27:39 PM

**SERVICE ORDER
CUSTOMER COPY**

User 9404

Page 2

| | | | | | | |
|--------------------|-------|-------------------|-------------------------------|--------------|---------------------|---------------|
| Customer No | | Advisor | Gilles Beaulieu | Promised | 10/31/2022 5:00 PM | Tag |
| Tr Transport | | Shop | S1 | Opened | 10/26/2022 12:27 PM | Location |
| | | Priority | 10 | Cashiered | | PO # |
| Home | Bus | License No | Odometer In | Odometer Out | InServ Date | Stock No |
| Cell | Today | PT-23 | 193079 | 193113 | | |
| Email | | Year | Make | Model | Model No | Colour |
| | | 2016 | RAM | 3500 | D28H92 | |
| | | Vehicle ID No | Selling Dealer | | Extended Warranty | Delivery Date |
| | | 3C63RRHL6GG276962 | | | | |
| | | Engine Size | 6.7L CUMMINS I-6 TURBO DIESEL | | Fleet # | |
| Term CASH | | | | | | |

| | | | | |
|------------|--|-------------------|--------|----------|
| Request | Description | Job | CSR | Status |
| INSP | COMPLETED GARY MOE CHRYSLER COURTESY INSPECTION- NO CHARGE TO THE CUSTOMER | 3 | 9404_C | Original |
| Labour | Description | | | |
| INSP | COMPLETED GARY MOE CHRYSLER COURTESY INSPECTION- NO CHARGE TO THE CUSTOMER | | | |
| Technician | 9136_C - | Parts Total | | 0.00 |
| | | Labour Total | | 0.00 |
| | | Request Sub-total | | 0.00 |
| Request | Description | Job | CSR | Status |
| FFC | REPLACE BOTH FUEL FILTERS & RE-TEST SPOKE TO DARRYL OCT 26 AT 4:12 PM AUTH WORK | 4 | 9404_C | Approved |
| Labour | Description | | | |
| FFC | REPLACE BOTH FUEL FILTERS & RE-TEST | | | |
| Part | Description | Shp | Bin | Type |
| 68157291AA | FUEL FILTER | 1 | 1C3 | CRO |
| STK | | | | Price |
| | | | | Amount |
| EHC50 | ENVIRO FEE | 1 | SHOP | CRO |
| 68197867AB | FUEL FILTER | 1 | 1C3 | CRO |
| EHC50 | ENVIRO FEE | 1 | SHOP | CRO |
| Rate | 159.95 | | | 0.50 |
| Technician | 9136_C - | Parts Total | | 0.50 |
| Cause | FFD | Labour Total | | 125.49 |
| Correction | TECH 9136 - CHECKED & REPLACED THE DUAL FUEL FILTERS. .7 HR ROAD TESTED & FOUND NO IMPROVEMENT. NEXT STEP WOULD BE TO DROP THE TANK & INSPECT/REPLACE TEH FUEL PUMP. | Request Sub-total | | 125.49 |
| | | | | 0.50 |
| | | | | 223.27 |
| | | | | 139.95 |
| | | | | 363.22 |
| Request | Description | Job | CSR | Status |
| 1400 | REPLACE FUEL PUMP & CLEAN TANK IF NEEDED SPOKE TO DARRYL OCT 27 AT 8:54 AM AUTH WORK | 5 | 9404_C | Approved |
| Labour | Description | | | |

SIGN UP AND SAVE
 ONE EMAIL PER MONTH SAVES MONEY ALL YEAR
GO TO MOPAR.CA TO SAVE NOW

DID YOU KNOW?
 YOU CAN PURCHASE EXTENDED WARRANTY UNTIL YOUR
 WARRANTY EXPIRES. (ASK YOUR ADVISOR FOR INFO)

| | |
|---|--|
| I HEREBY AUTHORIZE THE REPAIR WORK HEREIN SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND AGREE THAT TO THE EXTENT PERMITTED BY LAW, YOU ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND YOUR CONTROL, OR FOR ANY DELAYS CAUSED BY HERIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSES RESPECT OF THE MATERIAL SUPPLIED AND SERVICES RENDERED UNDER THIS WORK ORDER FOR THE FULL AMOUNT CHARGED THEREFOR. IF FURTHER ACKNOWLEDGE THAT THE SAID LIEN SHALL CONTINUE IN FULL AT ALL TIMES WHETHER THE VEHICLE IS IN MY POSSESSION, OR POSSESSION OF THE DEALER, UNTIL THE WITHIN ACCOUNT IS PAID IN FULL. WHEN ON DEMAND BY THE DEALER UNTIL THE WITHIN ACCOUNT IS PAID IN FULL. | |
| I N | IS A WRITTEN ESTIMATE REQUIRED? <input type="checkbox"/> ARE USED PARTS TO BE KEPT FOR 48 HOURS? YES <input type="checkbox"/> NO <input type="checkbox"/> INITIAL DATE <input type="checkbox"/> CUSTOMER SIGNATURE |
| O U | INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ <input type="checkbox"/> BEING PAID OR THE BALANCE OWING FOR REPAIRS PARTS & ACCESSORIES DESCRIBED IN THIS WORK ORDER DATE <input type="checkbox"/> CUSTOMER SIGNATURE |
| G.S.T. # 79781-9125 RT0001 | |

SO # 169475

SERVICE ORDER CUSTOMER COPY

Printed 10/28/2022 12:27:39 PM

User 9404

Page 3

| | | | | | | | | |
|--------------|---|-------------------|-----------------|---|---------------------|--------------|----------|--|
| Customer No | | Advisor | Gilles Beaulieu | Promised | 10/31/2022 5:00 PM | Tag | | |
| Tr Transport | | Shop | S1 | Opened | 10/26/2022 12:27 PM | Location | | |
| | | Priority | 10 | Cashiered | PO # | | | |
| Home | | License No | Odometer In | Odometer Out | InServ Date | Stock No | | |
| Cell | | PT-23 | 193079 | 193113 | | | | |
| Email | | Year | Make | Model | Model No | Colour | | |
| Bus | | 2016 | RAM | 3500 | D28H92 | | | |
| Today | | Vehicle ID No | Selling Dealer | Extended Warranty | Delivery Date | | | |
| | | 3C63RRHL6GG276962 | | Engine Size 6.7L CUMMINS I-6 TURBO DIESEL | | | | |
| Term CASH | | | | | | | | |
| 1400 | REPLACE FUEL PUMP & CLEAN TANK IF NEEDED | | | | | CP 479.85 | | |
| Part | Description | | | Shp | Bin | Type | | |
| 5145571AA | MODULE | | | 1 | 5A2 | CRO | | |
| RD | | | | | | Price 644.00 | | |
| Rate | 159.95 | Parts Total | | | | | 644.00 | |
| Technician | 9136_C - | Labour Total | | | | | 479.85 | |
| Cause | Request Sub-total | | | | | | 1,123.85 | |
| Correction | TECH 9136 - CHECKED & REPLACED THE IN TANK FUEL PUMP. I CONFIRMED THE INLET SCREEN IN THE PUMP WAS CLOGGED. THE FUEL PUMP ASSEMBLY HAD PARTIALLY FALLEN APART IN THE TANK. I REMOVED ALL OF THE PIECES OF IT FROM THE TANK. ROAD TEST AFTER REPAIRS FOUND ENGINE STILL LACKS POWER & IS NOT ACHIEVING PROPER FUEL RAIL PRESSURE. SUSPECT FUEL RAIL PRESSURE RELIEF VALVE HAS FAILED DUE TO THE LOW PRESSURE FUEL SYSTEM SUPPLY FAULT. RECOMMEND TO REPLACE THE RELIEF VALVE & RE-TEST. QUOTE TO FOLLOW. FUEL PUMP R&R 3.0 HRS | | | | | | | |
| Request | Description | | | | | Job | CSR | |
| 1400 | REPLACE FUEL RAIL PRESSURE RELIEF VALVE & RE-TEST SPOKE TO DARRYL OCT 28 AT 9:20 AM AUTH WORK | | | | | 6 | 9404_C | |
| Labour | | | | | | Type | Amount | |
| 1400 | REPLACE FUEL RAIL PRESSURE RELIEF VALVE & RE-TEST | | | | | CP | 399.88 | |
| Part | Description | | | Shp | Bin | Type | Amount | |
| 68005441AA | VALVE | | | 1 | CAB3-1 | CRO | 911.60 | |
| RD | | | | | | Price | 911.60 | |
| 68024672AB | GASKET | | | | | 1 | 4D3 | |
| STK | | | | | | CRO | 26.35 | |
| Rate | 159.95 | Parts Total | | | | | 937.95 | |
| Technician | 9136_C - | Labour Total | | | | | 399.88 | |
| Cause | Request Sub-total | | | | | | 1,337.83 | |

SIGN UP AND SAVE
ONE EMAIL PER MONTH SAVES MONEY ALL YEAR
GO TO MOPAR.CA TO SAVE NOW

DID YOU KNOW?
YOU CAN PURCHASE EXTENDED WARRANTY UNTIL YOUR
WARRANTY EXPIRES. (ASK YOUR ADVISOR FOR INFO)

I HEREBY AUTHORIZE THE REPAIR WORK HEREIN SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND AGREE THAT TO THE EXTENT PERMITTED BY LAW, YOU ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND YOUR CONTROL OR FOR ANY DELAY OR DAMAGE CAUSED BY HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. UNTIL PAYMENT IN FULL OF THE WITHIN ACCOUNT, I HEREBY ACKNOWLEDGE THE EXISTENCE OF A MECHANIC'S LIEN IN FAVOUR OF THE WITHIN DEALER ON THE VEHICLE DESCRIBED HEREIN IN RESPECT OF THE MATERIAL SUPPLIED AND SERVICES RENDERED UNDER THIS WORK ORDER FOR THE FULL AMOUNT CHARGED THEREFOR. IF FURTHER ACKNOWLEDGE THAT THE SAID LIEN SHALL CONTINUE IN FORCE AT ALL TIMES, WHETHER THE VEHICLE IS IN MY POSSESSION OR IN POSSESSION OF THE DEALER, UNTIL THE WITHIN ACCOUNT IS PAID IN FULL. WHILE THE VEHICLE IS IN MY POSSESSION IT SHALL AT ALL TIMES BE SUBJECT TO REPOSSESSION ON DEMAND BY THE DEALER UNTIL THE WITHIN ACCOUNT IS PAID IN FULL.

IN IS A WRITTEN ESTIMATE REQUIRED? ARE USED PARTS TO BE KEPT FOR 48 HOURS?
YES = NO = INITIAL YES = NO = INITIAL DATE _____ CUSTOMER SIGNATURE _____

OUT INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS WORK ORDER
DATE _____ CUSTOMER SIGNATURE _____ G.S.T. # 79781-9125 RT0001



GARY MOE
CHRYSLER | DODGE | JEEP | RAM

4450 – Highway 12 East,
Lacombe, Alberta, T4L 1A4
Phone: 403-782-2277
Fax: 403-782-3360
www.garymoe.com



SO # 169475

Printed 10/28/2022 12:27:39 PM

**SERVICE ORDER
CUSTOMER COPY**

User 9404 Page 4

| | | | | | |
|--------------------|----------------------|-------------------------------|-----------------------|--------------------------|----------------------|
| Customer No | Advisor | Gilles Beaulieu | Promised | 10/31/2022 5:00 PM | Tag |
| Tr Transport | Shop | S1 | Opened | 10/26/2022 12:27 PM | Location |
| | Priority | 10 | Cashiered | | PO # |
| | License No | PT-23 | Odometer In | 193079 | Odometer Out |
| | | | | 193113 | InServ Date |
| Home | Year | 2016 | Make | RAM | Model |
| Cell | | | | 3500 | Model No |
| Email | Vehicle ID No | 3C63RRHL6GG276962 | Selling Dealer | | Colour |
| | Engine Size | 6.7L CUMMINS I-6 TURBO DIESEL | | Extended Warranty | Delivery Date |
| Term CASH | | | | | |

Correction TECH 9136 - CHECKED & REPLACED THE FUEL RAIL PRESSURE RELIEF VALVE. ROAD TESTED & FOUND ENGINE IS MAKING PROPER POWER NOW. 2.5 HRS

ANY REMOVED WHEELS HAVE BEEN RETORQUED TO SPECIFICATIONS.

NOTE - TORQUE MUST BE RECHECKED WITHIN 100 KMS. Initial _____

VISIT www.mopar.ca/signupandsave TO SIGN UP AND SAVE\$

| | |
|----------------------|-----------------|
| Labour | 1,159.64 |
| Parts | 1,805.22 |
| Supplies | 97.85 |
| SUB-TOTAL | 3,062.71 |
| GST | 153.14 |
| TOTAL INVOICE | 3,215.85 |

SIGN UP AND SAVE
ONE EMAIL PER MONTH SAVES MONEY ALL YEAR
GO TO MOPAR.CA TO SAVE NOW

DID YOU KNOW?
YOU CAN PURCHASE EXTENDED WARRANTY UNTIL YOUR WARRANTY EXPIRES. (ASK YOUR ADVISOR FOR INFO)

| | | | | | |
|------------|--|--|--|--|--|
| I | <p>I HEREBY AUTHORIZE THE REPAIR WORK HEREIN SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND AGREE THAT TO THE EXTENT PERMITTED BY LAW, YOU ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND YOUR CONTROL OR FOR ANY DELAYS CAUSED BY HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. UNTIL PAYMENT IN FULL OF THE WITHIN ACCOUNT, I HEREBY ACKNOWLEDGE THE EXISTENCE OF A MECHANIC'S LIEN IN FAVOUR OF THE WITHIN DEALER ON THE VEHICLE DESCRIBED HEREIN IN RESPECT OF THE MATERIAL SUPPLIED AND SERVICES RENDERED UNDER THIS WORK ORDER FOR THE FULL AMOUNT CHARGED THEREFOR. IF FURTHER ACKNOWLEDGE THAT THE SAID LIEN SHALL CONTINUE IN FORCE AT ALL TIMES, WHETHER THE VEHICLE IS IN MY POSSESSION OR POSSESSION OF THE DEALER. UNTIL THE WITHIN ACCOUNT IS PAID IN FULL WHILE THE VEHICLE IS IN MY POSSESSION IT SHALL AT ALL TIMES BE SUBJECT TO REPOSSESSION ON DEMAND BY THE DEALER UNTIL THE WITHIN ACCOUNT IS PAID IN FULL.</p> <p>IS A WRITTEN ESTIMATE REQUIRED? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO INITIAL <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO INITIAL DATE _____ CUSTOMER SIGNATURE _____</p> <p>INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS WORK ORDER</p> <p>DATE _____ CUSTOMER SIGNATURE _____ G.S.T. # 79781-9125 RT0001</p> | | | | |
| OUT | | | | | |

CUSTOMER: TR TRANSPORT

YEAR: 2016
MAKE/MODEL: RAM 3500 SLT
VIN: 3C63RRHL6GG276962
ENGINE: 6.7L L6 DIR OHVTRANS/DRIVE: 6 SPD AUTOMATIC
LICENSE/PROVIN 91-M741/AB
KMS IN/KMS OUT 158587/
Fleet Number PT-23

In: 10/19/2022 Out: 10/26/2022 Email:

VEHICLE ISSUE #1: CHECK AND ADVISE LOST FORWARD STILL GOES INTO REVERSE

TECH REPORT: CODES PRESENT:

P0087 FUEL RAIL PRESSURE TOO LOW-BANK 1
P0868 LINE PRESSURE LOW
P0218 TRANS HIGH TEMP ACTIVATED
P0731 GEAR RATIO ERROR IN 1ST

POSSIBLE APP SENSOR ISSUE NEEDS TO BE ADDRESSED ASAP

ADV NOTES: 2 YEAR OR 60,000KM WARRANTY ON TRANSMISSION

| | | | | |
|--------|--|----------------|------------|-------|
| PART | 68RFE BANNER KIT | 1 @ \$585.50 | \$585.50 | NEW |
| PART | 68RFE MOLDED PISTON KIT | 1 @ \$284.54 | \$284.54 | NEW |
| PART | 68RFE TORQUE CONVERTER | 1 @ \$1,526.25 | \$1,526.25 | NEW |
| PART | 68RFE SOLENOID BLOCK | 1 @ \$602.75 | \$602.75 | NEW |
| PART | 68RFE LOW SPRAG | 1 @ \$262.98 | \$262.98 | NEW |
| PART | 68RFE FILTER 4X4 | 1 @ \$38.63 | \$38.63 | NEW |
| PART | 68RFE SPIN ON FILTER | 1 @ \$33.35 | \$33.35 | NEW |
| PART | 68RFE ACCUMULATOR PLATE | 1 @ \$64.66 | \$64.66 | NEW |
| PART | 68RFE ACCUMULATOR PISTON KIT HD | 1 @ \$191.18 | \$191.18 | NEW |
| PART | 68RFE OS SWITCH VALVE AND END PLUGS | 1 @ \$135.38 | \$135.38 | NEW |
| PART | 68RFE SMART TECH DRUM | 1 @ \$1,232.30 | \$1,232.30 | NEW |
| PART | 68RFE PRESSURE TRANSDUCER | 1 @ \$157.55 | \$157.55 | NEW |
| PART | 68RFE PUMP GEAR KIT | 1 @ \$334.36 | \$334.36 | NEW |
| PART | 68RFE REVMAX HP SEPERATOR PLATE | 1 @ \$250.78 | \$250.78 | NEW |
| PART | SYNTHETIC ATF | 17 @ \$16.95 | \$288.15 | NEW |
| PART | FREIGHT | 1 @ \$135.63 | \$135.63 | NEW |
| PART | BW 4446 REAR OUTPUT SEAL | 1 @ \$109.71 | \$109.71 | NEW |
| PART | TRANSMISSION COOLER LINE ASSEMBLY | 1 @ \$631.35 | \$631.35 | NEW |
| PART | AIR FILTER | 1 @ \$58.04 | \$58.04 | NEW |
| LABOR: | LABOR TIME TO REMOVE AND REINSTALL TRANSMISSION | | \$992.00 | LABOR |
| LABOR: | BENCH LABOR TIME TO INSTALL PARTS LISTED INTO 68RFE TRANSMISSION | | \$992.00 | LABOR |
| LABOR: | HOT FLUSH COOLER | | \$124.00 | LABOR |

Recommended Repairs:

| | |
|------------|-------------|
| Labor/Jobs | \$2,418.00 |
| Parts | \$6,923.09 |
| Sublet | \$499.50 |
| Total Fees | \$75.00 |
| Subtotal | \$9,915.59 |
| GST @ 5% | \$495.81 |
| Total | \$10,411.40 |
| Payments | \$0.00 |
| Balance | \$10,411.40 |

ALL WARRANTY WILL BE IN WRITING AND ARE NOT TRANSFERABLE. TOWING IS NOT COVERED UNDER THIS WARRANTY. WARRANTY IS VOID WHEN DAMAGE IS CAUSED BY ABUSE. EXTERNAL ELECTRICAL ISSUES CAN CAUSE TRANSMISSION FAILURE AND ARE NOT GUARANTEED OR COVERED UNDER THIS WARRANTY. ALL WHEELS MUST BE RETOURQUED AFTER 100KMS.

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

| | | |
|------------------------|--------------------------|------------------------------|
| CUSTOMER: TR TRANSPORT | YEAR: 2016 | TRANS/DRIVE: 6 SPD AUTOMATIC |
| | MAKE/MODEL: RAM 3500 SLT | LICENSE/PROVIN 91-M741/AB |
| | VIN: 3C63RRHL6GG276962 | MILES IN/OUT: 158587 |
| | ENGINE: 6.7L L6 DIR OHV | Fleet Number PT-23 |

| | | | |
|--------|---|------------------------|--------|
| LABOR: | LABOR TIME TO REPLACE TRANSMISSION COOLER LINES | \$310.00 | LABOR |
| SUBLET | FRONT DRIVESHAFT REBUILD | \$499.50 | SUBLET |
| | | SHOP SUPPLIES: \$75.00 | |

| | | |
|---|------------|-------------|
| Recommended Repairs: | Labor/Jobs | \$2,418.00 |
| | Parts | \$6,923.09 |
| | Sublet | \$499.50 |
| | Total Fees | \$75.00 |
| | Subtotal | \$9,915.59 |
| ALL WARRANTY WILL BE IN WRITING AND ARE NOT TRANSFERABLE. TOWING IS NOT COVERED UNDER THIS WARRANTY. WARRANTY IS VOID WHEN DAMAGE IS CAUSED BY ABUSE. EXTERNAL ELECTRICAL ISSUES CAN CAUSE TRANSMISSION FAILURE AND ARE NOT GUARANTEED OR COVERED UNDER THIS WARRANTY. ALL WHEELS MUST BE RETOURQUED AFTER 100KMS. | GST @ 5% | \$495.81 |
| | Total | \$10,411.40 |
| | Payments | \$0.00 |
| | Balance | \$10,411.40 |

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X_____

Date 10/26/2022

PAGE 2 OF 2