



CAM CLARK FORD RED DEER

X07-11
GR-FEB

Cam Clark Ford Sales (2012) Ltd.
417 Lantern Street, Red Deer, Alberta T4E-0A5
Phone: (403) 343-3673 Fax: (403) 341-3202
www.camclarkfordreddeer.com

SO # 697256

SERVICE ORDER CUSTOMER COPY

FordPass #

Status
Printed 11/18/2025 3:30:37 PM

User A625 Page 1

Customer No

Can - Am Auto Inc.

Home Bus
Cell Today
Email
Type
Term Charge

Advisor Adam Rodgers Promised 10/01/2025 5:30 PM Tag# 8055
Shop S1 Opened 10/01/2025 1:32 PM Location
Priority Cashiered 10/09/2025 11:56 AM PO # 25 LEE39764

License Odom In Odom Out In Service Date Stock No
238708 238708
Year Make Model Model Number Color
2020 FORD SUPER DUTY F-250 SRW W2B
Vehicle ID No Selling Dealer Extended Warranty Delivery Date
1FT7W2BT1LEE39764
Engine 6.7L 4V OHV POWER STROKE V8 Fleet #

Request Description Job CSR Status
S10 INSPECT FOR MULTIPLE WARNING MESSAGES ON THE DASH INCLUDING CHECK ENGINE 1 B100 Original
LIGHT AND VEHICLE IS DERATED TO 80KM/H

Labor Description Type Amount
1037M MULTI SYSTEM DIAGNOSIS CF 249.99
Rate 155.00 Est Parts 0.00
Technician 56 - Kelvin Agonoy Est Labor 0.00
Cause VERIFIED MULTIPLE WARNING LIGHTS PRESENT ON DASH. *** VEHICLE JUST HAD A NEW BED INSTALLED. UPON FURTHER INSPECTION, FOUND WIRING HARNESS ON THE REAR HAS BEEN CUT AND LEFT HANGING. FOUND TAIL LALMP ASSEMBLY IS THE WRONG ONE, VEHICLE IS EQUIPPED WITH BLISS REAR REVERSE CAMERA INOP. MOST OF WARNING LIGHTS PRESENT ON DASH IS RELATED TO CUT UP AND WRONG REAR WIRING HARNESS INSTALLED. FOUND GENERATOR CIRCUIT CODE AND FOUND BROKEN WIRE FOR GENERATOR CICRCUIT UNDERNEATH ENGINE, FOUND P205D PRESENT, UPON FURTHER DIAG, FOUND HARNESS FOR DEF HEATER/PUMP ASSEMBLY IS BROKEN AND WAS TRIED REPAIRING BY SILICONING HARNESS. CAUSE OF VEHICLE IN DERATE MODE IS POSSIBLY BECUASE OF DEF SYSTEM. REPAIRING DEF SYSTEM WITH NEW HEATER AND HARNESS WILL NOT CLEAR ALL OTHER WARNING LIGHT PRESENT ON DASH.
Labor Total 249.99
Request Sub-total 249.99

ALSO FOUND PARTICULATE MATTER SENSOR CIRCUIT CODE THAT IS ALSO POSSIBLY RELATED TO MULTIPLE BROKEN WIRE IN THE BACK OF THE TRUCK. WILL NEED FURTHER DIAG.

Correction 1037M 1.80

Request Description Job CSR Status
D99P MULTI POINT INSPECTION (DIESEL ENGINE) 2 B100 Original
Labor Description Type Amount
D99P FORD DIESEL MULTI-POINT VEHICLE INSPECTION IS
Technician 56 - Kelvin Agonoy Est Parts 0.00
Est Labor 0.00

Request Description Job CSR Status
INFO 24S78 POWERTRAIN CONTROL MODULE SOFTWARE UPDATE BIODIESEL DEPOSIT ACCUMULATION 3 B100 Original

Would you prefer your used parts returned after service? Please note that warranty and cores are not eligible for return to customer. YES _____ NO _____ GST # 101787604RT

I HEREBY AUTHORIZE THE REPAIR WORK HEREIN SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND AGREE THAT TO THE EXTENT PERMITTED BY LAW, YOU ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND YOUR CONTROL OR FOR DELAYS CAUSED BY UNAVAILABILITY OF PARTS, OR DELAYS IN PARTS SHIPMENTS BY THE SUPPLIER OR TRANSPORTER. I HEREBY GRANT YOU AND YOUR EMPLOYEES PERMISSION TO OPERATE THE VEHICLE HEREIN, DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. DOOR RATE \$165.00 SHOP SUPPLIES| 4% ON PARTS |14% ON LABOR. UNTIL PAYMENT IN FULL OF THE WITHIN ACCOUNT, I HEREBY ACKNOWLEDGE THE EXISTENCE OF A MECHANIC'S LIEN IN FAVOUR OF THE WITHIN DEALER ON THE VEHICLE DESCRIBED HEREIN IN RESPECT OF THE MATERIAL SUPPLIED AND SERVICES RENDERED UNDER THE WORK ORDER FOR THE FULL AMOUNT CHARGED THEREFOR. I FURTHER ACKNOWLEDGE THAT THE SAID LIEN, SHALL CONTINUE IN FORCE AT ALL TIMES, WHETHER THE VEHICLE IS IN MY POSSESSION OR THE POSSESSION OF THE DEALER, UNTIL THE WITHIN ACCOUNT IS PAID IN FULL WHILE THE VEHICLE IS IN MY POSSESSION IT SHALL AT ALL TIMES BE SUBJECT TO REPOSSESSION ON DEMAND BY THE DEALER UNTIL THE WITHIN ACCOUNT IS PAID IN FULL.

SIGNATURE: _____



CAM CLARK FORD

RED DEER

Cam Clark Ford Sales (2012) Ltd.
 417 Lantern Street, Red Deer, Alberta T4E-0A5
 Phone: (403) 343-3673 Fax: (403) 341-3202
 www.camclarkfordreddeer.com

SO # 697256
 Status
 Printed 11/18/2025 3:30:37 PM

SERVICE ORDER

CUSTOMER COPY

FordPass #
 User A625 Page 2

Customer No Can - Am Auto Inc.		Advisor Adam Rodgers	Promised 10/01/2025 5:30 PM	Tag# 8055
		Shop S1	Opened 10/01/2025 1:32 PM	Location
		Priority	Cashiered 10/09/2025 11:56 AM	PO # LEE39764
Home Cell Email	Bus Today	License	Odom In 238708	Odom Out 238708
	Type Term Charge	Year Make 2020 FORD	Model SUPER DUTY F-250 SRW W2B	In Service Date
		Vehicle ID No 1FT7W2BT1LEE39764	Selling Dealer	Model Number
		Engine 6.7L 4V OHV POWER STROKE V8	Extended Warranty	Stock No
			Fleet #	Delivery Date

25S94 STEERING COLUMN UPPER SHAFT INSPECTION REPLACEMENT
 ADVANCED NOTICE

Labor INFO	Description	Type	Amount
	24S78 POWERTRAIN CONTROL MODULE SOFTWARE UPDATE BIODIESEL DEPOSIT ACCUMULATION	IS	
	25S94 STEERING COLUMN UPPER SHAFT INSPECTION REPLACEMENT ADVANCED NOTICE		
Technician	999 - 999	Est Parts	0.00
Cause	INFO	Est Labor	0.00
Correction	THANK YOU FOR CHOOSING CAM CLARK FORD		

Request TY	Description	Job	CSR	Status
	We appreciate your business! THANK YOU!	4	B100	Original
Labor TY	Description	Type	Amount	
	We appreciate your business! THANK YOU!	IS		
Technician	999 - 999	Est Parts	0.00	
		Est Labor	0.00	

Request S10	Description	Job	CSR	Status			
	REPLACE REDUCTANT HEATER + HARNESS = BROKEN WIRES + CORRODED / RE TEST AFTER	5	B100	Approved			
Labor S10	Description	Type	Amount				
	REPLACE REDUCTANT HEATER + HARNESS = BROKEN WIRES + CORRODED / RE TEST AFTER	CF	387.50				
Part	Description	Shp	Bin	Type	Retail	Price	Amount
HC3Z 5J229 B	SENDER ASY	1	D4	CR11	1,935.00	1,644.75	1,644.75
HC3Z 14407 A	WIRE ASY - FUEL SEND	1	ETOP	CR11	359.37	305.46	305.46
CPM 27 JA	EXHAUST EMISSION CON	3	BULK	CR11	30.13	25.61	76.83
CG 807	GASKET	1	B2	CR11	88.36	75.11	75.11
Rate	155.00			Est Parts			0.00
Technician	56 - Kelvin Agonoy			Est Labor			0.00
Cause	REPLACED DEF HEATER/PUMP ASSEMBLY, AND DEF WIRING HARNESS. TOPPED UP DEF. SCANNED AND CLEARED DTC. PERFORMED SCR VISUAL LEAK TEST PASSED. VEHILCLE NO LONGER ON DERATE MORE.			Parts Total			2,102.15
				Labor Total			387.50
Correction	*** NOTE: WARNING LIGHTS STILL PRESENT ON DASH FROM CUT AND DIFFERNT WIRING HARNESS FOR THE REAR. CEL PRESENT FOR PARTICULATE MATTER SENSOR CIRCUIT IN THE BACK..			Request Sub-total			2,489.65

Would you prefer your used parts returned after service? Please note that warranty and cores are not eligible for return to customer. YES _____ NO _____ GST # 101787604RT

I HEREBY AUTHORIZE THE REPAIR WORK HEREIN SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND AGREE THAT TO THE EXTENT PERMITTED BY LAW, YOU ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND YOUR CONTROL OR FOR DELAYS CAUSED BY UNAVAILABILITY OF PARTS, OR DELAYS IN PARTS SHIPMENTS BY THE SUPPLIER OR TRANSPORTER. I HEREBY GRANT YOU AND YOUR EMPLOYEES PERMISSION TO OPERATE THE VEHICLE HEREIN, DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. DOOR RATE \$165.00 SHOP SUPPLIES] 4% ON PARTS [14% ON LABOR. UNTIL PAYMENT IN FULL OF THE WITHIN ACCOUNT, I HEREBY ACKNOWLEDGE THE EXSISTENCE OF A MECHANIC'S LIEN IN FAVOUR OF THE WITHIN DEALER ON THE VEHICLE DESCRIBED HEREIN IN RESPECT OF THE MATERIAL SUPPLIED AND SERVICES RENDERED UNDER THE WORK ORDER FOR THE FULL AMOUNT CHARGED THEREFOR. I FURTHER ACKNOWLEDGE THAT THE SAID LIEN, SHALL CONTINUE IN FORCE AT ALL TIMES, WHETHER THE VEHICLE IS IN MY POSSESSION OR THE POSSESSION OF THE DEALER, UNTIL THE WITHIN ACCOUNT IS PAID IN FULL WHILE THE VEHICLE IS IN MY POSSESSION IT SHALL AT ALL TIMES BE SUBJECT TO REPOSSESSION ON DEMAND BY THE DEALER UNTIL THE WITHIN ACCOUNT IS PAID IN FULL.

SIGNATURE: _____



CAM CLARK FORD

RED DEER

Cam Clark Ford Sales (2012) Ltd.
 417 Lantern Street, Red Deer, Alberta T4E-0A5
 Phone: (403) 343-3673 Fax: (403) 341-3202
 www.camclarkfordreddeer.com

SO # 697256
 Status
 Printed 11/18/2025 3:30:37 PM

SERVICE ORDER

CUSTOMER COPY

FordPass #
 User A625 Page 3

Customer No
 Can - Am Auto Inc.

Home **Bus**
Cell **Today**

Email

Type
Term Charge

Advisor Adam Rodgers	Promised 10/01/2025 5:30 PM	Tag# 8055
Shop S1	Opened 10/01/2025 1:32 PM	Location
Priority	Cashiered 10/09/2025 11:56 AM	PO # LEE39764

License	Odom In 238708	Odom Out 238708	In Service Date	Stock No
Year 2020	Make FORD	Model SUPER DUTY F-250 SRW	Model Number W2B	Color
Vehicle ID No 1FT7W2BT1LEE39764	Selling Dealer	Extended Warranty	Delivery Date	
Engine 6.7L 4V OHV POWER STROKE V8	Fleet #			

Request	Description	Job	CSR	Status
S10	REPAIR BROKEN WIRE FOR GENERATOR CIRCUIT AND RETEST	6	B100	Approved
Labor	Description		Type	Amount
S10	REPAIR BROKEN WIRE FOR GENERATOR CIRCUIT AND RETEST		CF	465.00
Part	Description	Shp	Bin	Type
WT 5627 A	TUBING HEAT SHRINK	1	C8	CR11
Rate	155.00			Retail 23.03
Technician	56 - Kelvin Agonoy			Price 19.58
Cause	REPAIRED GENERATOR CIRCUIT. RE ASSEMBLED. SCANNED AND CLEARED DTC. CHARGING SYSTEM FAULT NO LONGER PRESENT ON DASH.			Amount 19.58
Correction				Est Parts 0.00
				Est Labor 0.00
				Parts Total 19.58
				Labor Total 465.00
				Request Sub-total 484.58

Labor	1,102.49
Parts	2,121.73
Supplies	80.00
Sub-Total	3,304.22
GST	165.21
Total Invoice	3,469.43

Would you prefer your used parts returned after service? Please note that warranty and cores are not eligible for return to customer. YES _____ NO _____ GST # 101787604RT

I HEREBY AUTHORIZE THE REPAIR WORK HEREIN SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND AGREE THAT TO THE EXTENT PERMITTED BY LAW, YOU ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND YOUR CONTROL OR FOR DELAYS CAUSED BY UNAVAILABILITY OF PARTS, OR DELAYS IN PARTS SHIPMENTS BY THE SUPPLIER OR TRANSPORTER. I HEREBY GRANT YOU AND YOUR EMPLOYEES PERMISSION TO OPERATE THE VEHICLE HEREIN, DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. DOOR RATE \$165.00 SHOP SUPPLIES] 4% ON PARTS]14% ON LABOR. UNTIL PAYMENT IN FULL OF THE WITHIN ACCOUNT, I HEREBY ACKNOWLEDGE THE EXISTENCE OF A MECHANIC'S LIEN IN FAVOUR OF THE WITHIN DEALER ON THE VEHICLE DESCRIBED HEREIN IN RESPECT OF THE MATERIAL SUPPLIED AND SERVICES RENDERED UNDER THE WORK ORDER FOR THE FULL AMOUNT CHARGED THEREFOR. I FURTHER ACKNOWLEDGE THAT THE SAID LIEN, SHALL CONTINUE IN FORCE AT ALL TIMES, WHETHER THE VEHICLE IS IN MY POSSESSION OR THE POSSESSION OF THE DEALER, UNTIL THE WITHIN ACCOUNT IS PAID IN FULL WHILE THE VEHICLE IS IN MY POSSESSION IT SHALL AT ALL TIMES BE SUBJECT TO REPOSSESSION ON DEMAND BY THE DEALER UNTIL THE WITHIN ACCOUNT IS PAID IN FULL.

SIGNATURE: _____