



Brandt Tractor Ltd.  
101 Burnt Park Dr.  
Red Deer, AB  
T4P 0J7  
(403) 343-7557

Service  
Invoice



208-2  
BLU - 177AR

INVOICE DATE	BRANCH	INVOICE NO.
25OCT22	105	1560008

SOLD TO:

PIDHERNEY'S INC

S/N # 1DW524PAPMLZ12577

PAGE
1
SALE TYPE
WARRANTY
CUSTOMER NO.
58453072

S PIDHERNEY'S INC  
H P.O. BOX 940  
P  
T ROCKY MOUNTAIN HOUSE, AB  
O

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALES PRN
6555	403-845-3072	1560008	02	11OCT22	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	524P	1DW524PAPMLZ12577	6555	925	MARVIN/COLIN B

DESCRIPTION	AMOUNT
REPAIR FAN PUMP LEAK	
COMPLAINT: COMPLAINT OF ENGINE OIL LEAK	
CAUSE: Fan pump gasket torn	
CORRECTION: Filled out STA. Ran unit and checked for leaks - leaking at fan pump to engine mating surface. Opened engine side panels. Removed mounting hardware for fan pump. Removed fan pump from engine auxillary drive. Buffed mating surfaces, reinstalled fan pump with new gasket and torqued hardware to spec. Ran machine and reinspected for leaks, no further leaks found. SGS	
1 T350654 GASGASKET ** TOTAL LABOR ** CARBON TAX SURCHARGE	
>--> SEG# 02 PRT LAB MSC	

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50.	QST # 1226957240	DESCRIPTION	AMOUNT
I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.		TOTAL PARTS	
		TOTAL LABOR	
		MISC. CHARGES SALES TAX	
X _____ SIGNATURE	_____ DATE	PLEASE PAY THIS TOTAL	▶



Brandt Tractor Ltd.  
101 Burnt Park Dr.  
Red Deer, AB  
T4P 0J7  
(403) 343-7557

**Service  
Invoice**



INVOICE DATE	BRANCH	INVOICE NO.
26APR23	105	1561986

SOLD TO:

PIDHERNEY'S INC

S/N # 1DW524PAPMLZ12577

PAGE 1 SALE TYPE
WARRANTY CUSTOMER NO. 58453072

S PIDHERNEY'S INC  
H P.O. BOX 940  
P  
T ROCKY MOUNTAIN HOUSE, AB  
O

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN
6555	403-845-3072	1561986	04	06APR23	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	524P	1DW524PAPMLZ12577	6555	1373	MARVIN/COLIN

DESCRIPTION	AMOUNT
REPAIR TRANSMISSION LEAK	
COMPLAINT: Repair transmission oil leak	
CAUSE: WEAK MATERIAL - pinhole leak	
CORRECTION: Found transmission oil leak at lower oil cooler hose. Order parts to replace. Filled out STA Park and prepare machine for service. Open LH rear cooler door. Remove two hose clamps, remove hose for transmission cooler to bypass valve. Install new hose with two new clamps. Test drive machine to ensure no leaks. SGS	
1 AT316341 HOSE CLAXY	
1 T441464 HOSE XY	
1 N AT316341 HOSE CLAXY	
** TOTAL LABOR **	
CARBON TAX SURCHARGE	
>>--> SEG# 04 PRT LAB MSC	

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM), MINIMUM CHARGE OF \$1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X \_\_\_\_\_  
SIGNATURE DATE

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES SALES TAX	
PLEASE PAY THIS TOTAL	

CUSTOMER COPY



Brandt Tractor Ltd.  
101 Burnt Park Dr.  
Red Deer, AB  
T4P 0J7  
(403) 343-7557

Service  
Invoice



INVOICE DATE	BRANCH	INVOICE NO.
25MAY24	105	1566254

SOLD TO:

PIDHERNEY'S INC

S/N # 1DW524PAPMLZ12577

PAGE
1
SALE TYPE
WARRANTY
CUSTOMER NO.
58453072

S PIDHERNEY'S INC  
H #17 GATEWAY BLVD  
P Parts2@pidherneys.com  
T ROCKY MOUN, AB  
O

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN
6555	403-845-3072	1566254	01	16MAY24	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	524P	1DW524PAPMLZ12577	6555	2981	MARVIN

DESCRIPTION	AMOUNT
REPAIR TRANSMISSION CAN CODES 2003.09  COMPLAINT: TCU CAN Code 2003.09  CAUSE: Suspect loose connection at TCU  CORRECTION: Spoke with customer. Reviewed STA with tech. Ordered potential parts. Fill out STA. Customer complains of an Active TCU code 2003.09 and machine will not shift into forward or reverse. Turned disconnect and circuit breaker on and started machine. Codes are active and machine is not moving. Checked Fuses F12 and F28 in fuse box. Checked fuse tightness in fuse box. Checked battery voltage and battery charging: both batteries test good and machine is charging at 28V. Removed 4 bolts to access battery box and checked the tightness of the battery posts. Checked the power and ground cables at the starter. Checked ground straps from starter to frame and ground wires on cab. Checked the power and ground wires	

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50.	QST # 1226957240	DESCRIPTION	AMOUNT
I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.		TOTAL PARTS	
		TOTAL LABOR	
		MISC. CHARGES	
		SALES TAX	
X _____ SIGNATURE		PLEASE PAY THIS TOTAL → **CONTINUED**	
_____ DATE			



Brand Tractor Ltd.  
101 Burnt Park Dr.  
Red Deer, AB  
T4P 0J7  
(403) 343-7557

**Service  
Invoice**



INVOICE DATE	BRANCH	INVOICE NO.
25MAY24	105	1566254

SOLD TO:

PIDHERNEY'S INC

S/N # 1DW524PAPMLZ12577

PAGE
2
SALE TYPE
WARRANTY
CUSTOMER NO.
58453072

S PIDHERNEY'S INC  
H #17 GATEWAY BLVD  
P Parts2@pidherneys.com  
T ROCKY MOUN, AB  
O

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN
6555	403-845-3072	1566254	01	16MAY24	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	524P	1DW524PAPMLZ12577	6555	2981	MARVIN

DESCRIPTION	AMOUNT
going into the TCU. Power and ground test good. Tested can 1 Network. CAN 1 Resistance test good and high and low voltages test good. After plugging TCU connector back in and starting machine is now running. Wiggle test harness - no issues Reseated connection at TCU.UDUSYN ** TOTAL LABOR ** CARBON TAX SURCHARGE	
>>--> SEG# 01 PRT LAB MSC	

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X \_\_\_\_\_  
SIGNATURE

\_\_\_\_\_  
DATE

QST # 1224987240

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES SALES TAX	
PLEASE PAY THIS TOTAL	



Brandt Tractor Ltd.  
10630 176th St.  
Edmonton, AB  
T5S 1M2  
(780) 484-6613

Service  
Invoice



INVOICE DATE	BRANCH	INVOICE NO.
28APR22	106	1633519

SOLD TO:

PIDHERNEY'S INC

S/N # 1DW524PAPMLZ12577

PAGE
1
SALE TYPE
WARRANTY
CUSTOMER NO.
58453072

S  
H  
I  
P  
P  
I  
D  
H  
E  
R  
N  
E  
Y  
S  
I  
N  
C  
P.O. BOX 940  
ROCKY MOUNTAIN HOUSE, AB

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN
.	403-845-3072	1633519	02	21APR22	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	524P	1DW524PAPMLZ12577		113	TE

DESCRIPTION	AMOUNT
<p>DIAG/REP LOW COOLANT LEVEL FAULT</p> <p>COMPLAINT: CUSTOMER COMPLAINT OF COOLANT LEVEL VERY LOW CODE ECU 111.18 COMING UP.</p> <p>CAUSE: COOLANT LEVEL SENSOR OPEN CIRCUIT. FAILED AL201300.</p> <p>CORRECTION: ARRIVED ON SITE, WAITED FOR UNIT TO BE AVAILABLE FOR DIAGNOSTICS. VERIFIED ACTIVE CODE. CHECKED COOLANT LEVEL, AT CORRECT POSITION. DISCONNECTED SENSOR. PINS LOOK SLIGHTLY SPREAD. CHECKED FOR VOLTAGE AND PROPER ROUND AT CONNECTOR. 24VDC AND GOOD GROUND. CHECKED FOR FOREIGN MATERIALS IN TANK. NONE FOUND. USED A TEST LIGHT TO SHORT BETWEEN BOTH TERMINALS TO SEE IF CODE WENT TO INACTIVE. CODE WENT TO STORED. NEEDS COOLANT LEVEL SENSOR. ARRIVED ON SITE, WAITED FOR EQUIPMENT TO BE AVAILBLE TO BE WORKED ON. REMOVED COOLANT LEVEL SENSOR AND REPLACED WITH NEW. REPINNED CONNECTOR THEN CONNECTED TO SENSOR. CODE WENT FROM ACTIVE TO STORED. ALL GOOD. RT</p> <p>1 N AL201300 LEVEL SW</p>	

<p>PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50.</p> <p>I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.</p> <p>X _____ SIGNATURE</p> <p>_____ DATE</p>	<p>DESCRIPTION</p> <p>TOTAL PARTS</p> <p>TOTAL LABOR</p> <p>MISC. CHARGES</p> <p>SALES TAX</p> <p>PLEASE PAY THIS TOTAL</p>	<p>AMOUNT</p> <p>**CONTINUED**</p>



Brandt Tractor Ltd.  
 10630 176th St.  
 Edmonton, AB  
 T5S 1M2  
 (780) 484-6613

**Service  
 Invoice**



INVOICE DATE	BRANCH	INVOICE NO.
28APR22	106	1633519

SOLD TO:

PIDHERNEY'S INC

S/N # 1DW524PAPMLZ12577

PAGE 2
SALE TYPE
WARRANTY CUSTOMER NO. 58453072

S PIDHERNEY'S INC  
 H I P.O. BOX 940  
 P  
 T ROCKY MOUNTAIN HOUSE, AB  
 O

PURCHASE ORDER NO.	PHONE NUMBER 403-845-3072	WORK ORDER NO. 1633519	SEG. 02	DATE OPENED 21APR22	SALESPRN
MAKE JD	MODEL 524P	SERIAL NO. 1DW524PAPMLZ12577	EQUIP. NO.	METER 113	AUTHORIZED BY TE

DESCRIPTION		AMOUNT
1	N 57M7254 ELEC CO	
4	N R104846 ELEC CO	
4	N 57M7258 ELEC CO	
4	N 57M7289 ELEC CON	
** TOTAL LABOR **		
CARBON TAX SURCHARGE		
>>--> SEG# 02 PRT LAB MSC		

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X \_\_\_\_\_  
 SIGNATURE

\_\_\_\_\_  
 DATE

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES SALES TAX	
PLEASE PAY THIS TOTAL	



Brandt Tractor Ltd.  
101 Burnt Park Dr.  
Red Deer, AB  
T4P 0J7  
(403) 343-7557

Service  
Invoice



INVOICE DATE	BRANCH	INVOICE NO.
23JAN26	105	105500020

SOLD TO:

PIDHERNEY'S INC

S/N # 1DW524PAPMLZ12577

PAGE
1
SALE TYPE
WARRANTY
CUSTOMER NO.
58453072

S  
H  
P  
T  
O  
PIDHERNEY'S INC  
ap@pidherneys.com  
#17 GATEWAY BLVD  
ROCKY MOUN, AB

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN
6555	403-845-3072	105500020	01	06JAN26	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	524P	1DW524PAPMLZ12577	6555	4189	MARVIN

DESCRIPTION	AMOUNT
<p>REPAIR 4334.03 Diesel exhaust fluid supply module circuit fa</p> <p>COMPLAINT: 4334.03 DEF Supply Module circuit Fault</p> <p>CAUSE: DEF pump internal short causing circuit fault code.</p> <p>CORRECTION: Worked through diagnostics in service advisor with tech over the phone. Customer complains of active DEF code. Removed the connector from the DEF pump and checked for DEF in the connector. Connector is clean and dry. Tested for proper power and ground into the connector. Connected service advisor and performed the DEF pump test. DEF pump will not build pressure. Suspect of a failed DEF pump. Removed 3 DEF lines from the pump. Removed 3 mounting bolts and 1 connector. Installed new DEF pump into place. Tightened hardware, reinstalled DEF pump lines and connector. Test ran machine and monitored DEF pump pressure. DEF pump working correctly. MMAGTIBAY</p>	

<p>PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM), MINIMUM CHARGE OF \$1.50.</p> <p>I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.</p> <p>X _____ SIGNATURE</p> <p>_____ DATE</p>		<p>DESCRIPTION</p> <p>TOTAL PARTS</p> <p>TOTAL LABOR</p> <p>MISC. CHARGES</p> <p>SALES TAX</p> <p>PLEASE PAY THIS TOTAL</p>	<p>AMOUNT</p> <p>**CONTINUED**</p>
--	--	---	------------------------------------



Brandt Tractor Ltd.  
101 Burnt Park Dr.  
Red Deer, AB  
T4P 0J7  
(403) 343-7557

Service  
Invoice



INVOICE DATE	BRANCH	INVOICE NO.
23JAN26	105	105500020

SOLD TO:

PIDHERNEY'S INC

S/N # 1DW524PAPMLZ12577

PAGE
2
SALE TYPE
WARRANTY
CUSTOMER NO.
58453072

S PIDHERNEY'S INC  
H ap@pidherneys.com  
P #17 GATEWAY BLVD  
T ROCKY MOUN, AB  
O

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN
6555	403-845-3072	105500020	01	06JAN26	
MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	524P	1DW524PAPMLZ12577	6555	4189	MARVIN

DESCRIPTION	AMOUNT
Old DEF pump DZ121771 21082139802	
New DEF pump DZ128068 25042442206	
1 N DZ128068 DEF DOSI	
** TOTAL LABOR **	
ENVIRONMENTAL FEE	
>>--> SEG# 01 PRT LAB MSC	

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF \$1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X \_\_\_\_\_  
SIGNATURE

\_\_\_\_\_  
DATE

QST # 1224957240

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES	
SALES TAX	
PLEASE PAY THIS TOTAL	