

QTY.	PART NO. AND DESCRIPTION	PRICE
1	Trailer wash	190.00
3	24LB	40.92
2	NT3030STD-78TC	164.50
4	1492-8C	32.92
2	R810019	47.62
2	S100	248
4	19X127 clevis pins	8.60
4	19X1084 clevis pins	13.52
2	85323 Shocks	157.38
6	3/4-3/4 bolts, stove nuts	22.38
2	sets brake shoes	112.50
5	100451542 hardware	100.15
4	S353229 Cam tubes	368.16
2	E9735 S-Cams	101.88
2	E9736 S-Cams	101.88
5	tubes grease	45.95
1	3434009	20.98
1	litre 80W90	6.00
6	5/16x3/4 bolts, washers lock	1.08
1	12P46250	55.25
1	can black spray paint	19.49
1	E2237	1.70
30	torque indicators	13.50
10 1/2'	reflective tape	12.60
2	GHVS gladhands	113.32
1	GHVE	56.66
6	5/16x1" bolts, nuts, washers flat	2.46
1	12LB	1.63
1	10250R	13.69
1	15-720	14.00

M.K.S. Trailer & Equipment Repairs Ltd.

716 Carter Crest Way
Edmonton, Alberta T6R 2N3
Shop: 780-451-3861
Cell: 780-966-2963

INVOICE **Nº 76251**

DATE: **APR 09 2023**

NAME TERRA PRO INC.		
ADDRESS 53345 Range Rd 232		CITY Sherwood Park
PROVINCE AB		POSTAL CODE T8A 4V2
PURCHASE ORDER		
LICENSE NO. 5GR346	YEAR 2015	MAKE/MODEL Doepker
SERIAL NO. F1032978		UNIT NO. 455

Wash Trailer suspension
CUEP / SERVICE A
Pulled all wheels for brake measurements
Send tires for replacement
Replaced broken air tank drains
Removed / Replaced RC & RR maxis
Removed / Replaced front axle shocks & replaced worn shock bolts on RC shock
Removed / Replaced all brake drums (provided); RC, RR brake shoes and LC, RC, LR, RR cams & tube and RC wheel seal
Sand & paint beaver tail and installed reflective tape
Installed torque indicators; Replaced rear gladhands
Repaired lights & wiring; replaced 7 wire plug and freed up swing-outs
Weld cracks on aluminum fenders; straighten and weld on lock in tab on RS fender

19 lbs 110"	TOTAL LABOR	2090.00
	TOTAL PARTS	1843.20
	SHOP SUPPLIES	114.00
	SUB TOTAL	4047.20
	GST # 877828343	202.36
	TAX	
	TOTAL	4249.56

