

M12-1  
BLUE-MAR

# Bullseye Hd Ltd.

Box 1860  
Lac La Biche, Alberta T0A 2C0  
Canada

## INVOICE

Invoice No.: 4712  
Date: 07/07/2025  
Ship Date:  
Page: 1  
Re: Order No.

Sold to:

LAC LA BICHE DISTRICT NATURAL GAS CO-OP LTD

Ship to:

2006 GMC TOPKICK UNIT-212  
MILEAGE-324179

Business No.: 747013316

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
BUB AR440	EACH	1.0	ARMoured 1/4X4	G	12.69	12.69
PARTS	EACH	1.0	DOT 3 BRAKE FLUID (PER LITER)	G	14.95	14.95
LABOUR - HD	HOUR	2.0	CHECK AND REPAIR NO BRAKES; FOUND BRAKE LINE FAILED R&R BRAKE LINE AND BLEED SYSTEM; REMOVE PLUGGED BLEED SCREWS AND DRILL OUT PORTS RUN AND TEST OPERATION - GOOD TO GO	G	145.00	290.00
SHOP SUPPLIES	EACH	0.1	SHOP SUPPLIES	G	290.00	29.00
			Subtotal:			346.64
			G - GST 5%			
			GST			17.33
<div>Unit 212 Repair</div> <div>           Extension Checked By _____            P.O. Checked _____            Approved For Payment By <u>7680</u> <u>DS</u>            Code _____         </div>						
Bullseye Hd Ltd. GST: #747013316RT0001						
Shipped By: _____ Tracking Number: _____					Total Amount	363.97
Comment: Payment due upon receipt. Thank-you for your business!					Amount Paid	0.00
Sold By: _____					Amount Owing	363.97

**Bullseye Hd Ltd.**

Box 1860  
Lac La Biche, Alberta T0A 2C0  
Canada

**INVOICE**

Invoice No.: 4415  
Date: 03/24/2025  
Ship Date:  
Page: 1  
Re: Order No.

Sold to:

LAC LA BICHE DISTRICT NATURAL GAS CO-OP LTD

Ship to:

2006 GMC TOPKICK  
UNIT 212  
MILEAGE 323481  
SER#07494-8159

**COPY**

Business No.: 747013316

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
MIL S-404	EACH	1.0	SHRAEDER	G	3.95	3.95
MIL S-439	EACH	1.0	CAP VALVE STEM	G	3.15	3.15
FLM 066011A	EACH	1.0	WASHER PUMP	G	31.95	31.95
CNG BB31S	EACH	2.0	BATTERY 31S (SCREW POST) 925	G	129.99	259.98
GDY 65111	INCH	14.0	WIPER WASHER HOSE	G	0.10	1.40
PARTS	EACH	1.0	4XUBOLTS AND HARDWARE	G	150.00	150.00
PRE 74071-1L	LTR	2.0	COOLANT HD LLIFE +ENV	G	4.55	9.10
TIB 370371A	EACH	2.0	SEAL- REAR WHEEL TOPKICK/KODIAK	G	83.37	166.74
RBB BS847	EACH	1.0	BRAKE SHOES- 2.5X9.5" PARK BRAKE	G	109.63	109.63
			TOPKICK			
PARTS	EACH	1.0	NEW LIFT BLOCKS (REARX2)	G	209.95	209.95
CVIP	EACH	1.0	COMPLETE CVIP INSPECTION	G	347.50	347.50
LABOUR - HD	HOURL	26.0	BOOST TRUCK TO GET RUNNING	G	145.00	3,770.00
			AIR ALL TIRES TO 90SPI, HAD TO R+R			
			TIRE CORE ON RH #2 INSIDE TIRE,			
			WAS BROKEN, COULD NOT AIR TIRE			
			UP			
			ADJUST L AND R TOOL BOX LATCHES			
			SECURE RH MIRROR MARKER LIGHT			
			IN PLACE			
			CLEAN TERMINALS ON RH POWER			
			BLOCK ON 1/4 FENDER CHECK			
			WINDSHILD SPRAYER, GOT POWER AT			
			PLUG, REMOVE MOTOR CONNECT			
			DIRECT POWER TO MOTOR NO GO.			
			INSTALL NEW WASHER PUMP -ALL			
			OK(HAD TO CUSTOMIZE UNIVERSAL			
			PUMP OEM NOT AVAILABLE			
			MAKE BRACKET FOR TOP AIR TO AIR			
			PIPE, ZIP TIE PIPE TO BRACKET TO			
			PREVENT FUTURE RUBBING			
			JACK REAR OF TRUCK UP, REMOVE			
			SWAY BAR, CUT U BOLTS L&R, HEAT			
			AND WORK OUT UBOLTS, DRILL AND			
			TAP THREADS ON BLOCK SIDES, DIE			
			GRING CENTER PIN DOWN TO FIT ON			
			PADS. INSTALL BLOCKS, UBOLTS			
			TORQUE TO 500FT/LBS INSTALL SWAY			
			BAR, BRAKE LINE BRACKETS			
			CHECK LH MIRROR ISSUE, REMOVE			
			MIRROR TO ACCESS WIRING, FOUND			
			PLUG WAS CORRODED, HARD WIRE			
			LIGHT -ALL OK. REINSTALL MIRROR			
			REMOVE AIR CLEANER ASSEMBLY TO			
			GET TO ALTERNATOR			
Comment: Payment due upon receipt. Thank-you for your business!					Continue...	

**Bullseye Hd Ltd.**

Box 1860  
Lac La Biche, Alberta T0A 2C0  
Canada

**INVOICE**

Invoice No.: 4415  
Date: 03/24/2025  
Ship Date:  
Page: 2  
Re: Order No.

Sold to:

LAC LA BICHE DISTRICT NATURAL GAS CO-OP LTD

Ship to:

2006 GMC TOPKICK  
UNIT 212  
MILEAGE 323481  
SER#07494-8159

Extension Checked By \_\_\_\_\_

P.O. Checked \_\_\_\_\_

Approved For Payment By \_\_\_\_\_

Code 76807670

Business No.: 747013316

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
SHOP SUPPLIES	EACH	0.1	TEST ALTERNATOR PUTTING OUT 14VOLTS TEST BATTERIES BOTH TESTED AT 8.5- R+R BATTERIES RUN NEW PIECE OF AIR CLEANER INDICATOR HOSE, IT WAS BURNT INSTALL RANDOM SELF TAPPERS IN DRIVERS DOOR PANEL REMOVE CALIPERS PADS, CALIPER BRACKETS, HUBS TO CHECK PARK BRAKE ISSUEUS, EVERYTHING WAS SIEZED, LUBE AND WORK PIVOTS FREE, SO RUSTY HARD TO TAKE STUFF APRT, SET BRAKES UP, STILL NOT SETTING UP ORDER NEW BRAKE SHOES. CABLES NOT AVAILABLE REMOVE ROTARS TO ACCESS SHOES. REMOVE WHEEL SEALS, CLEAN AND BUFF PARTS INSTALL NEW WHEEL SEALS AND PARK BRAKE SHOES INSTALL HUBS, AXLES, CALIPER BRACKET, PADS AND CALIPERS TOP UP ENGINE COOLANT GREASE UNIT CHECK LEVELS INSTALL REAR WHEELS TORQUE TO 405FT/LBS SHOP SUPPLIES	G	3,770.00	377.00
			Subtotal:			5,440.35
			G - GST 5% GST			272.04
Bullseye Hd Ltd. GST: #747013316RT0001					Total Amount	5,712.39
Shipped By: _____ Tracking Number: _____					Amount Paid	0.00
Comment: Payment due upon receipt. Thank-you for your business!					Amount Owning	5,712.39
Sold By: _____						