



IGNITION AUTOWORKS 'TD.
 264003 Twp Rd 424
 Ponoka, AB T4J1R3
 (403) 704-9588
 ignitionautoworks@gmail.com

MAY 104-1

Invoice #2016
 Created: 10/10/2025
 Invoiced: 10/14/2025
 Payment Term: On Receipt
 Payment Due: 10/14/2025
 Service Writer: Collin Wassink

Tyce Kootstra
 Stradow Farm Inc
 Mobile: (403) 704-7952

2009 GMC Sierra 2500 HD SLE
 VIN: 1GTHK43KX9F109335

Suspension Control Arm R&R (Front Upper, Without Coil Spring Suspension, Both Sides)

Description	Price	QTY	HRS	Subtotal
Labor: Suspension Control Arm R&R (Front Upper, Without Coil Spring Suspension, Both Sides)			1.6	\$179.20
Labor: Stabilizer Bar Link Kit R&R (Front, Both Sides)			0.7	\$78.40
Labor: Suspension Shock or Strut Assembly R&R (Front, Both Sides)			0.5	\$56.00
Part: CONTROL ARM - UPPER	\$309.71	2		\$619.42
Part: SWAY BAR LINK	\$46.83	2		\$93.66
Part: SHOCK - FRONT Part #: 76504	\$127.73	2		\$255.46
Subcontract: WHEEL ALIGNMENT	\$120.00			\$120.00
Shop Supplies (10%): \$31.36				Total: \$1,505.18

Steering Pitman Arm R&R (With Hydraulic Brake Booster)

Description	Price	QTY	HRS	Subtotal
Labor: Steering Pitman Arm R&R (With Hydraulic Brake Booster)			0.9	\$100.80
Part: PITMAN ARM	\$90.25	1		\$90.25
Part: IDLER ARM	\$94.08	1		\$94.08
Shop Supplies (10%): \$10.08				Total: \$309.97

Axle Shaft R&R (Front Right)

CV BOOT DAMAGED. RECOMMEND REPLACEMENT OF CV AXLE DUE TO CONTAMINATION IN JOINT.

Description	Price	QTY	HRS	Subtotal
Labor: Axle Shaft R&R (Front Right)			1.9	\$212.80
Part: CV AXLE	\$247.93	1		\$247.93
Shop Supplies (10%): \$21.28				Total: \$506.11

Exhaust Manifold Gasket R&R (Right)

RIGHT SIDE EXHAUST MANIFOLD TO PIPE GASKET LEAKING.
 FOUND BROKEN EXHAUST MANIFOLD BOLTS ON BOTH SIDES.

Description	Price	QTY	HRS	Subtotal
Labor: Exhaust Manifold Gasket R&R (Right)			2.8	\$313.60
Part: EXHAUST GASKET	\$21.49	1		\$21.49
Part: EXHAUST MANIFOLD GASKET KIT Part #: MS92467	\$45.57	1		\$45.57



IGNITION AUTOWORKS LTD.
 264003 Twp Rd 424
 Ponoka, AB T4J1R3
 (403) 704-9588
 ignitionautoworks@gmail.com

Invoice #2016

Created: 10/10/2025
 Invoiced: 10/14/2025
 Payment Term: On Receipt
 Payment Due: 10/14/2025
 Service Writer: Collin Wassink

Exhaust Manifold Gasket R&R (Right)

Part: EXHAUST HARDWARE KIT Part #: 6002786	\$25.16	2		\$50.32
Shop Supplies (10%): \$31.36			Total: \$485.46	

Suspension Shock or Strut Assembly R&R

Description	Price	QTY	HRS	Subtotal
Labor: Suspension Shock or Strut Assembly R&R (Rear, Both Sides)			1	\$112.00
Part: SHOCK - REAR Part #: 76690	\$127.73	2		\$255.46
Shop Supplies (10%): \$5.92			Total: \$392.05	

Brake Pads R&R (Rear) and 1 More

Description	Price	QTY	HRS	Subtotal
Labor: Brake Pads R&R (Rear)			1.3	\$145.60
Labor: Brake Rotor R&R (Rear)			0.3	\$33.60
Part: BRAKE PAD KIT Part #: QE7653X	\$102.92	1		\$102.92
Part: ROTOR Part #: 348886828	\$119.34	2		\$238.68
Part: BRAKE CALIPER - LR Part #: 2452XA	\$148.12	1		\$148.12
Part: BRAKE CALIPER - RR Part #: 2542XB	\$148.12	1		\$148.12
Shop Supplies (10%): \$0.00			Total: \$857.89	

Brake Pads R&R (Front) and 1 More

Description	Price	QTY	HRS	Subtotal
Labor: Brake Pads R&R (Front)			1.3	\$145.60
Labor: Brake Rotor R&R (Front)			0.3	\$33.60
Part: BRAKE PAD KIT Part #: QE7652X	\$99.41	1		\$99.41
Part: BRAKE ROTOR - FRONT Part #: 18A1206A	\$174.66	2		\$349.32
Part: BRAKE CALIPER - LF Part #: 2453XB	\$163.51	1		\$163.51
Part: BRAKE CALIPER - RF Part #: 2453XA	\$163.51	1		\$163.51
Shop Supplies (10%): \$0.00			Total: \$1,002.70	



IGNITION AUTOWORKS LTD.
 264003 Twp Rd 424
 Ponoka, AB T4J1R3
 (403) 704-9588
 ignitionautoworks@gmail.com

Invoice #2016

Create: 10/10/2025
 Invoice: 10/14/2025
 Payment Term: On Receipt
 Payment Due: 10/14/2025
 Service Writer: Collin Wassink

E-Transfers can be made to ignitionautoworks@gmail.com
 Thank you for your business!
 GST # 706073749RT

This shop charges a 2% credit card processing fee.

Signature _____

Labor	\$1,411.20
Parts	\$3,187.23
Subcontracts	\$120.00
Subtotal	\$4,718.43
Shop Supplies	\$100.00
EPA	\$0.00
GST	\$240.93
Grand Total	\$5,059.36
Paid to Date	(\$0.00)

REMAINING BALANCE \$5,059.36

Handwritten signature

650 4818.43
 321 240.93

V05-1