

M10-1
MAY

HAWK HEAVY DUTY MECHANICAL LTD.

+14039739662
repairs.hawkhd@gmail.com
www.hawkhdrepairs.ca



ADDRESS
Ready Go Transport

ESTIMATE # 1034
DATE 26/03/2026

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
26/03/2026	Labor	Glad hand need to replace Axle 1 right side wheel seal need to replace Middle right side signal not working Both sides lower marker lights and top left side rear marker light not working ABS light on License plate light not working All 4 brake shoes and drums need to replace Axle 1 right side and axle 2 left side S-cam tube need to replace Axle 2 left side slack adjuster need to replace Axle 1 left side brake pot need to replace Pallet stopper missing Axle 2 left side both tires Axle 1 left side and axle 2 right side	9	95.00	855.00
	Parts	brakes X 4 84 drum X 4 108 S-cam X 2 87 Slack -119 brake pot-\$68 wheel seal-\$67	1	1,178.00	1,178.00
	Supplies	shop supplies	1	35.00	35.00
	CVIP inspection and Decal	decals charges	1	220.00	220.00

WABASH REEFER

TOTAL

\$2,288.00

VIN: 792018

Accepted By

Accepted Date