

Remit To: Edmonton Kenworth Ltd.

17335 118 Avenue

Edmonton, AB

T5S 2P5

Tel: 780-453-3431 Fax: 780-454-6124

Purchased From:
Kenworth Leduc
8202 - 42 Street
Leduc Alberta T9E 8M6
Phone: 780-612-9855

Invoice: 06AS73749
Date / Hour: 7/29/2025 11:30:08AM
Repair Order: 73749
Customer: 01322
Branch: Leduc
Total Invoice: \$0.00
Charge
Page 1

D16-10
MAY

Bill To: BOYD VENTURES INC.
RR 3 SITE 302 COMP 88
ONOWAY, AB T0E 1V0

Ship To: BOYD VENTURES INC.
RR 3 SITE 302 COMP 88
ONOWAY, AB T0E 1V0
Office Phone: (780) 405-5560
Email: boydventures2@gmail.com

Work: (780) 405-5560

Shop: 780- 405-5560

Fax: 780-967-2657

Customer P/O:

Open Date: 07/24/2025

Completion Date: 07/28/2025

Add User: Hludditt

Salesperson: Vcoulter

Unit Number: 159

Model Year: 2025

Make/Model: KENWORTH W900L

Type: Class 8

VIN: 1XKWD40X5SR999088

Meter: 2439 Kilometers

ECM Reading: 38

Task: 1 08-000001 WARRANTY RECALL

80001

Department: Service

Complaint: RECALL CAMPAIGN: [24KWL] SAFETY RECALL 24KWL: BENDIX EC80 ABS ECU INCORRECT SIGNAL PROCESSING (OPEN)
PROACTIVE

Correction: PERFORMED THE 24KWL RECALL. EC80 CALIBRATION WAS SUCCESSFUL. CONFIRMED NO FAULT CODES WERE LOGGED.

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	SHOPSUPP	ENVIRONMENT/MISC SUPPLIES		1.0	\$24.82	\$24.82
				Task 1 Subtotals	Parts:	\$0.00
					Labor:	\$0.00
				Task 1 Subtotals		\$0.00

Task: 2 08-000001 WARRANTY RECALL

80012

Department: Service

Complaint: RECALL CAMPAIGN: [7054] CUMMINS CAMPAIGN: VERIFY ELIGIBILITY THROUGH CUMMINS QUICKSERVE (OPEN)

Correction: CONFIRMED THE UNIT IS ELIGIBLE FOR CAMPAIGN C7054. CHECKED CURRENT ECM CALIBRATION AND FOUND IT IS NOT AT THE LATEST REVISION. CURRENT REVISION NN10083.06. LATEST REVISION NN10083.08. UPDATED ECM CALIBRATION.

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	SHOPSUPP	ENVIRONMENT/MISC SUPPLIES		1.0	\$7.36	\$7.36
				Task 2 Subtotals	Parts:	\$0.00
					Labor:	\$0.00
				Task 2 Subtotals		\$0.00

Task: 3 05-0000501 COMPLIMENTARY CUSTOMER INSPECTION

90501

Department: Service

Complaint: COMPLETE COMPLIMENTARY CUSTOMER INSPECTION

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
				Task 3 Subtotals	Parts:	\$0.00
					Labor:	\$0.00
				Task 3 Subtotals		\$0.00

Task: 4 15-030001 STEERING GEAR - ADJUST POPPETS & STOPS

80001

Department: Service

Complaint: CHECK AND ADVISE STEER STOPS - WHEN TURNING TO THE RIGHT, IT DOES NOT TURN SHARP.

UNIT IS 2 MONTHS IN SERVICE

** See Last Page for Invoice Total **

Remit To: Edmonton Kenworth Ltd.

17335 118 Avenue

Edmonton, AB

T5S 2P5

Tel: 780-453-3431 Fax: 780-454-6124

Purchased From:
Kenworth Leduc
8202 - 42 Street
Leduc Alberta T9E 8M6
Phone: 780-612-9855

Invoice: 06AS73749
Date / Hour: 7/29/2025 11:30:08AM
Repair Order: 73749
Customer: 01322
Branch: Leduc
Total Invoice: \$0.00
Charge
Page 2

Bill To: BOYD VENTURES INC.
RR 3 SITE 302 COMP 88
ONOWAY, AB T0E 1V0

Ship To: BOYD VENTURES INC.
RR 3 SITE 302 COMP 88
ONOWAY, AB T0E 1V0
Office Phone: (780) 405-5560
Email: boydventures2@gmail.com

Work: (780) 405-5560

Shop: 780- 405-5560

Fax: 780-967-2657

Customer P/O:

Open Date: 07/24/2025

Completion Date: 07/28/2025

Add User: Hludditt

Salesperson: Vcoulter

Correction: CUSTOMER COMPLAINT UNIT DOES NOT TURN SHARP TO THE RIGHT, ADJUSTED AXLE STOPS AND POPPETS, UNIT NOW HAS TWO TURNS OF THE STEERING WHEEL TO THE RHS AND LHS, TOOK UNIT FOR A TEST DRIVE OUT IN THE YARD, UNIT CAN MAKE SHARPER TURNS TO THE RIGHT, TASK COMPLETE

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	SHOPSUPP	ENVIRONMENT/MISC SUPPLIES		1.0	\$34.75	\$34.75
				Task 4 Subtotals	Parts:	\$0.00
					Labor:	\$0.00
				Task 4 Subtotals		\$0.00

Task: 5 02-170005 CAB DOOR - REPAIR

Department: Service

80001

Complaint: CHECK AND ADVISE - BOTH DOOR LATCHES "GRABBING" WHEN OPENING DOORS.

UNIT IS 2 MONTHS IN SERVICE

Correction: TOOK PICS OF DOOR LATCH AND CHROME TRIM, TRIM WAS PULLING AWAY FROM THE DOOR HANDLE, TRIM IS INSTALLED WITH 3M TAPE, REMOVED DOOR HANDLE TRIM FROM BOTH SIDES, FOUND THE REASON THE DOOR HANDLE WAS GRABBING ON THE CHROME TRIM WAS BECAUSE THE HANDLE HOUSING ON THE PASSENGER AND DRIVER SIDE DOORS IS RECESSED IN AND IS CAUSING THE HANDLE TO GRAB AGAINST THE CHROME TRIM. TRIMMED DOWN A BIT OF THE CHROME TRIM TO ALLOW IT TO SIT IN AGAINST THE HANDLE HOUSING BETTER, USED NEW 3M TAPE TO THE BACKS OF THE CHROME TRIM AND REINSTALLED, TESTED BOTH SIDES AND HANDLES ARE NO LONGER GRABBING AGAINST THE CHROME TRIM. TASK COMPLETE

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	SHOPSUPP	ENVIRONMENT/MISC SUPPLIES		1.0	\$25.38	\$25.38
				Task 5 Subtotals	Parts:	\$0.00
					Labor:	\$0.00
				Task 5 Subtotals		\$0.00

Task: 6 34-004149 GENERAL ACCESSORIES - AIR CLEANER LIGHT - FRT ONLY

Department: Service

80001

Complaint: CHECK AND ADVISE - AIR CLEANER LIGHTS ON P/S LOOSE

UNIT IS 2 MONTHS IN SERVICE

Correction: LOOSE AIR CLEANER LIGHT- REMOVED AIR CLEANER LIGHTS AND MOUNTED THEM SO THEY ARE TIGHT AGAINST THE AIR CLEANERS, TESTED LIGHT AFTER REMOUNTING TO CONFIRM LIGHT WILL STILL WORK, ALL LIGHTS WORK. TASK COMPLETE

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
P0100	DSWS4	SPACER-DUAL SWIVEL SADDLE	EA	2.0	\$2.14	\$4.28
	SHOPSUPP	ENVIRONMENT/MISC SUPPLIES		1.0	\$38.38	\$38.38
				Task 6 Subtotals	Parts:	\$0.00
					Labor:	\$0.00
				Task 6 Subtotals		\$0.00

** See Last Page for Invoice Total **

Remit To: Edmonton Kenworth Ltd.

17335 118 Avenue

Edmonton, AB

T5S 2P5

Tel: 780-453-3431 Fax: 780-454-6124

Invoice: 06AS73749

Date / Hour: 7/29/2025 11:30:08AM

Repair Order: 73749

Customer: 01322

Branch: Leduc

Total Invoice: \$0.00

Charge

Page 3

Purchased From:
Kenworth Leduc
8202 - 42 Street
Leduc Alberta T9E 8M6
Phone: 780-612-9855

Bill To: BOYD VENTURES INC.
RR 3 SITE 302 COMP 88
ONOWAY, AB T0E 1V0

Ship To: BOYD VENTURES INC.
RR 3 SITE 302 COMP 88
ONOWAY, AB T0E 1V0
Office Phone: (780) 405-5560
Email: boydventures2@gmail.com

Work: (780) 405-5560

Shop: 780- 405-5560

Fax: 780-967-2657

Customer P/O:

Open Date: 07/24/2025

Completion Date: 07/28/2025

Add User: Hludditt

Salesperson: Vcoulier

Task: 7 52-030006 ELECTRICAL ACCESSORIES - INVERTER DIAG/REPAIR Department: Service
90431

Complaint: CHECK AND ADVISE - LOOK INTO REPOSITIONING INVERTER AS ITS LAYING FLAT AND CUSTOMER WOULD LIKE UPRIGHT TO SAVE SPACE

UNIT IS 2 MONTHS IN SERVICE

Correction: RELOCATED TUNDRA INVERTER TO BACK PANEL UNDER BUNK, DRIVER NOW HAS A LOT OF ROOM IN THE BUNK.

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	SHOPSUPP	ENVIRONMENT/MISC SUPPLIES		1.0	\$29.73	\$29.73
				Task 7 Subtotals	Parts:	\$0.00
					Labor:	\$0.00
				Task 7 Subtotals		\$0.00

Task: 8 01-000003 HVAC-DIAGNOSE Department: Service
80001

Complaint: DIAGNOSE AND ADVISE - HVAC WATER VALVE LOCATED UNDER THE HOOD ON THE P/S NEAR THE FIREWALL IS MALFUNCTIONING (CLICKING)

UNIT IS 2 MONTHS IN SERVICE

Correction: HEARD THE WATER VALVE TICKING, CONFIRMED THAT THE WATER VALVE WAS TICKING, REMOVED AND REPLACED WATER VALVE, TAGGED PART FOR WARRANTY, CHECKED FOR VISUAL LEAKS, NO LEAKS

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
P0100	SR2000013	VALVE ASSY-WATER	EA	1.0	\$256.85	\$256.85
	SHOPSUPP	ENVIRONMENT/MISC SUPPLIES		1.0	\$22.34	\$22.34
				Task 8 Subtotals	Parts:	\$0.00
					Labor:	\$0.00
				Task 8 Subtotals		\$0.00

GST/HST Number:

Detail Tax Info:

Total Parts:	\$0.00
Total Labor:	\$0.00
Invoice Subtotal:	\$0.00
Total Tax:	\$0.00
Total Invoice:	\$0.00

Payment Method

Terms

Due Date

Charge

Net 15th of month

8/15/2025

Remit To: Edmonton Kenworth Ltd.
 17335 118 Avenue
 Edmonton, AB
 T5S 2P5
 Tel: 780-453-3431 Fax: 780-454-6124

Purchased From:
 Kenworth Leduc
 8202 - 42 Street
 Leduc Alberta T9E 8M6
 Phone: 780-612-9855

Invoice: 06AS79402
 Date / Hour: 4/15/2026 8:21:01AM
 Repair Order: 79402
 Customer: 01322
 Branch: Leduc
 Total Invoice: \$673.88
 Charge
 Page 1

Bill To: BOYD VENTURES INC.
 RR 3 SITE 302 COMP 88
 ONOWAY, AB T0E 1V0

Ship To: BOYD VENTURES INC.
 RR 3 SITE 302 COMP 88
 ONOWAY, AB T0E 1V0
 Office Phone: (780) 405-5560
 Email: boydventures2@gmail.com

Work: (780) 405-5560

Shop: 780- 405-5560

Fax: 780-967-2657

Customer P/O:

Add User: Hludditt

Open Date: 04/10/2026

Completion Date: 04/13/2026

Salesperson: Vcoulter

Unit Number: 159

Model Year: 2025

Make/Model: KENWORTH W900L

Type: Class 8

VIN: 1XKWD40X5SR999088

Meter: 2639 Kilometers

In-Service Date: 06/02/2025

ECM Reading: 43

Task: 1 05-00007 Kenworth Courtesy Inspection

Department: Service

Complaint: KENWORTH COURTESY INSPECTION

90501

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	SHOPSUPP	ENVIRONMENT/MISC SUPPLIES		1.0	\$6.28	\$6.28
				Task 1 Subtotals		
					Parts:	\$0.00
					Labor:	\$0.00
				Task 1 Subtotals		\$0.00

Task: 2 05-00202 ALBERTA CVIP - TANDEM AXLE - VISUAL INSPECT

Department: Service

Complaint: CVIP - WHEELS ON

PERFORM ALBERTA CVIP INSPECTION, WHILE COMPLETING THE ELECTRONIC RECORD OF INSPECTION - INCLUDING A LIMITED VISUAL INSPECTION OF THE BRAKE COMPONENTS, AS POSSIBLE, WITHOUT REMOVAL OF THE WHEELS OR BACKING PLATES. HAVING CONFIRMED PRIOR REPAIR HISTORY AND INSPECTIONS OF THE VEHICLES BRAKE SYSTEM, ARE WITHIN THE TIME LIMITS, WHERE FURTHER IN DEPTH INSPECTIONS ARE NOT REQUIRED.

Correction: COMPLETED CVIP. VERIFIED WHEELS OFF REQUIRED. ONLY FOUND WIPERS ARE STREAKING. SAVED CVIP ONLINE. TORQUED ALL WHEELS TO 500 FT/LBS. INSTALLED TORQUE TAG. MARKED ALL NUTS WITH TORQUE PASTE. PASSED UNIT ONLINE. PRINTED OFF 4 COPIES OF PASSED CVIP. PUT 2 COPIES ON PASSENGER SEAT, GAVE 2 COPIES TO SERVICE. REMOVED AND REPLACED CVIP DECAL.

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	SHOPSUPP	ENVIRONMENT/MISC SUPPLIES		1.0	\$47.54	\$47.54
				Task 2 Subtotals		
					Parts:	\$0.00
					Labor:	\$594.25
					Miscellaneous:	\$47.54
				Task 2 Subtotals		\$641.79

GST/HST Number:

etail Tax Info:

GST REGISTRATION NUMBER: R101677270

Total: \$32.09
 Total: \$32.09

Total Parts:	\$0.00
Total Labor:	\$594.25
Total Miscellaneous:	\$47.54
Invoice Subtotal:	\$641.79
Total Tax:	\$32.09
Total Invoice:	\$673.88