



Wild Mountain RV Ltd.
 GST # 806129631RT0001
 235188 Ryan Road
 Calgary, AB T1X 0K1
 (403) 286-3535
 info@wildmountainrv.ca
 www.wildmountainrv.ca

W17-J
MAY

Invoice #25548
 Created: 9/11/2024
 Invoiced: 10/24/2024
 Payment Term: On Receipt
 Service Writer: Kim Delisle

Ron Nichols

2005 Country Coach Intrigue

Customer Comments

coach battery is currently on as well - right inside the door on the left there is an off button to shut off the coach batteries - turn button off at end of the day.

Winterize RV - 20 - 30 Feet

There is an ice maker but it is disconnected

We aren't completing job due to aqua hot w/h. - customer winterizing himself

Description	Price	QTY	Subtotal
1 Winterize RV - Bypass and Drain Water Heater - Drain Fresh Water Tank - Remove and Set Aside Water Filters - Fill system with antifreeze through water pump - Add RV antifreeze to drain traps **Note: *Waste tanks are not emptied prior to or after winterizing			\$0.00
2 FROST-FREE RV ANTIFREEZE	\$9.70		\$0.00
			Total: \$0.00

Winterize - Add Washing Machine

Unit has an aqua hot water heater, regulator after city water and washer/dryer. Will need extra time.

Description	Price	QTY	Subtotal
1 Add Washing Machine to Winterize - Winterize Washer with RV antifreeze and drain			\$0.00
2 FROST-FREE RV ANTIFREEZE	\$9.70		\$0.00
			Total: \$0.00

Inspect 2 D/S slides

There is a slide topper/awning that ripped and it is now allowing water to get in through the slides. Customer is requesting if we replace the slide toppers, to not get the same ones that go over the windows but to get the ones that just go over the slide.

Living room/dinette slide - struggles to come out at end of travel which seems to be from the slide topper. Will further diagnose after removal of old slide topper to see if issue continues.

Bedroom slide- noticed water entry occurring when slide is open due to floor corner moulding falling off on front part of slide, rear is completely missing floor corner moulding.

Description	HRS	Subtotal
1 Inspect living room slide	1	\$180.00
2 Inspect bedroom slide	1	\$180.00



Wild Mountain RV Ltd.
 GST # 806129631RT0001
 235188 Ryan Road
 Calgary, AB T1X 0K1
 (403) 286-3535
 info@wildmountainrv.ca
 www.wildmountainrv.ca

Invoice #25548

Created: 9/11/2024
 Invoiced: 10/24/2024
 Payment Term: On Receipt
 Service Writer: Kim Delisle

Inspect 2 D/S slides			
		GST (5%): \$18.00	Total: \$378.00

Inspect front door			
Front door is very loud when customer is driving. sounds like a seal around the door needs to be replaced.			
Unable to recreate issue due to not being able to road test unit. Found slight opening at top right corner of door showing signs of water entry, also window seal at bottom P/S corner is separating. Need to add foam seal and proflex window seal back on.			
	Description	HRS	Subtotal
1	Diagnose entry door	0.3	\$54.00
		GST (5%): \$2.70	Total: \$56.70

Roof inspection			
Customer did notice a leak at the skylight and he has patched it and hasnt noticed the leak anymore. All seals are very cracked. Needs full roof reseal.			
	Description		Subtotal
1	Roof inspection		\$0.00
			Total: \$0.00

Front heat stays running (aquahot).			
Right when you walk in, it is on the floor - a little square. heat switch is on the top, when you turn the switch you will see that it stays on and doesn't put out any heat when it does come on.			
Cannot diagnose as our shop is not certified/have info on hydronic heating system. Recommended that cust contacts manufacturer for further instruction. *Noticed glycol level is low*			
	Description	HRS	Subtotal
1	Diagnose front heat issue	0.2	\$36.00
		GST (5%): \$1.80	Total: \$37.80

Front privacy door is stuck			
(1st set of 3 privacy doors). Got door unstuck and found door was pushed in too far. No damage found on rails or door. Operation now ok.			
	Description	HRS	Subtotal
1	Diagnose privacy door	0.3	\$54.00
		GST (5%): \$2.70	Total: \$56.70

Customer can't get any heat from the roof A/Cs			
As soon as it went below zero, customer couldnt get any heat from the roof units.			
Heat pumps are not designed to "heat" the unit in cold temps but take the chill off in mild temperatures. Amperage from A/C and was 26 Amps drawing from a/c, operation is ok.			



Wild Mountain RV Ltd.
 GST # 806129631RT0001
 235188 Ryan Road
 Calgary, AB T1X 0K1
 (403) 286-3535
 info@wildmountainrv.ca
 www.wildmountainrv.ca

Invoice #25548

Created: 9/11/2024
 Invoiced: 10/24/2024
 Payment Term: On Receipt
 Service Writer: Kim Delisle

Customer can't get any heat from the roof A/Cs			
Description	HRS	Subtotal	
1 Diagnose roof A/c heat issue	1	\$180.00	
		GST (5%): \$9.00	Total: \$189.00

Battery			
Customer took battery when he left			
Description	Price	QTY	Subtotal
1 INTERSTATE 12VOLT BATTERY - 31 SERIES	\$248.92	1	\$248.92
2 Battery Core Charge - Series 31 and 6 Volt	\$30.00	1	\$30.00
		GST (5%): \$13.95	Total: \$292.87

Add small foam seal to top front corner of entry door/proflex window seal				
Sealed seal and proflexed. If noise continues it may be from front into dash. Unable to diagnose.				
Description	Price	QTY	HRS	Subtotal
1 Install proflex/seal window			0.8	\$144.00
2 Shop Supplies	\$20.00	1		\$20.00
			GST (5%): \$8.20	Total: \$172.20

D/S Front complete slide Topper replace				
Complete slide topper with brackets Flange to flange: 148" Slide roof: 145 1/2" *unit will have exposed holes from old brackets with new slide topper. Need subcontract body/paint or we can just proflex the holes for no extra labour* *make sure slide operation is normal upon last leg of travel after replacement*				
Installed front slide topper and sealed brackets/anti-billow plate. Adjusted and tested awning. Found slide out is out further in rear (32") than front (31 1/2") causing fabric to sag a little when out. Fabric is tight when closed which is most crucial for travel.				
Description	Price	QTY	HRS	Subtotal
1 Install slide topper			3	\$540.00
2 Proflex over holes (no charge)			1	\$0.00
3 DOMETIC SLIDETOPPER BLK 15FT	\$1,047.24	1		\$1,047.24
4 DOMETIC SLIDE TOPPER BRACKET BLK	\$116.60	1		\$116.60
5 Shop supplies	\$20.00	1		\$20.00
			GST (5%): \$86.19	Total: \$1,810.03

D/S rear complete slide topper replace				
Complete slide topper with brackets				



Wild Mountain RV Ltd.
 GST # 806129631RT0001
 235188 Ryan Road
 Calgary, AB T1X 0K1
 (403) 286-3535
 info@wildmountainrv.ca
 www.wildmountainrv.ca

Invoice #25548

Created: 9/11/2024
 Invoiced: 10/24/2024
 Payment Term: On Receipt
 Service Writer: Kim Delisle

D/S rear complete slide topper replace					
Flange to flange: 143 1/2" Slide roof: 141" *unit will have exposed holes from old brackets with new slide topper. Need subcontract body/paint or we can just proflex the holes for no extra labour*					
Installed slide topper and sealed brackets/ anti billow plate. Adjusted awning and tested - ok.					
Description	Price	QTY	HRS	Subtotal	
1 Replace slide topper			3	\$540.00	
2 Proflex over holes (no charge)			1	\$0.00	
3 DOMETIC SLIDE TOPPER; 150"; BLACK	\$1,039.00	1		\$1,039.00	
4 DOMETIC SLIDE TOPPER BRACKET BLK	\$116.60	1		\$116.60	
5 Shop supplies	\$20.00	1		\$20.00	
			GST (5%): \$85.78	Total: \$1,801.38	

Reattach floor corner moulding and install new @ bedroom slide					
Front is coming off and rear is missing. Water entry visible due to loose moulding. Will need to order 5ft of 2"x1" ,1/8" thick aluminum angle trim.(ask Sam).					
Installed trim on both d/s slides as front was missed. Had enough aluminum and took extra 1 hour to complete. Riveted and sealed trims.					
Description	Price	QTY	HRS	Subtotal	
1 Reattach/install trims			2	\$360.00	
2 Aluminum trim (estimated parts pricing)	\$125.00	1		\$125.00	
3 Shop supplies	\$30.00	1		\$30.00	
			GST (5%): \$25.75	Total: \$540.75	

Full roof reseal					
Cleaned and resealed roof.					
Description	Price	QTY	HRS	Subtotal	
1 Full roof reseal			2.5	\$450.00	
2 DICOR- SELF LEVELING LAP SEALANT - WHITE	\$19.12	20		\$382.40	
3 Shop Supplies	\$20.00	1		\$20.00	
			GST (5%): \$42.62	Total: \$895.02	

Parts					
Description	Price	QTY	Subtotal		
1 parts	\$2.75	1	\$2.75		
2 FRESH WATER FITTING; BESTPEX; ADAPTER; 1/2 INCH HOSE	\$7.85	1	\$7.85		
3 ELKHART SUPP 1/2" STAINLESS STEEL CLAM	\$1.15	1	\$1.15		



Wild Mountain RV Ltd.
 GST # 806129631RT0001
 235188 Ryan Road
 Calgary, AB T1X 0K1
 (403) 286-3535
 info@wildmountainrv.ca
 www.wildmountainrv.ca

Invoice #25548

Created: 9/11/2024
 Invoiced: 10/24/2024
 Payment Term: On Receipt
 Service Writer: Kim Delisle

Parts	GST (5%): \$0.59	Total: \$12.34
--------------	-------------------------	-----------------------

Shut off Generator & Coach batteries	
Customer notes: coach battery is currently on as well - right inside the door on the left there is an off button to shut off the coach batteries - turn button off at end of the day.	
Description	Subtotal
1	\$0.00
	Total: \$0.00

Thank you for your business! The work is complete and your payment is due upon pickup of the vehicle. Storage fees may apply if vehicle is not picked up after 5 business days from date of invoice (unless other arrangements have been approved). Vehicles may not be picked up until invoice is paid in full. Please contact us promptly if you have any questions about this invoice. Payment options include credit, debit, cash, or bank draft. e-transfers can be sent to info@wildmountainrv.ca (please include the invoice number). No personal or business cheques.

Signature _____

Parts	\$3,227.51
Labor	\$2,718.00
Subtotal	\$5,945.51
GST	\$297.28
PST	\$0.00
HST	\$0.00
Grand Total	\$6,242.79
Paid To Date	(\$6,242.79)
REMAINING BALANCE	\$0.00

Payments			
10/25/2024	Other	E-Transfer	\$6,242.79

Past Authorizations		
In App by Ron Nichols 10/16/2024 at 9:31 AM MDT	+ Parts + Shut off Generator & Coach batteries	\$6,266.58 +\$12.34
In App by Ron Nichols 10/1/2024 at 10:40 AM MDT	+ Add small foam seal to top front corner of entry door/proflex window seal + D/S Front complete slide Topper replace + D/S rear complete slide topper replace + Reattach floor corner moulding and install new @ bedroom slide + Full roof reseal	\$11,489.10 +\$10,478.03
In App by Ron Nichols 9/24/2024 at 11:46 AM MDT	+ Battery	\$1,365.97 +\$292.87
In App by Ron Nichols 9/24/2024 at 11:46 AM MDT	+ Winterize RV - 20 - 30 Feet + Winterize - Add Washing	\$1,073.10



Wild Mountain RV Ltd.
GST # 806129631RT0001
235188 Ryan Road
Calgary, AB T1X 0K1
(403) 286-3535
info@wildmountainrv.ca
www.wildmountainrv.ca

Invoice #25548

Created: 9/11/2024
Invoiced: 10/24/2024
Payment Term: On Receipt
Service Writer: Kim Delisle

Past Authorizations

Machine
+ Inspect 2 D/S slides
+ Inspect front door
+ Roof inspection
+ Front heat stays running
(aquahot).
+ Front privacy door is stuck
+ Customer can't get any heat
from the roof A/Cs