

CG Truck And Equipment

5312 114 Avenue Southeast
 Calgary, Alberta, T2C 4T9
 (403) 279 - 6200



N25-1
 MAY

Invoice: INV-S-2364

Invoice Date: Mar 4, 2026
 Due date: Mar 11, 2026

Bill To

1573166 Alberta Ltd.
 119 Skyview Point Crescent Northeast
 Calgary, AB, T3N 1B6

Remit payment to

CG Truck And Equipment
 5312 114 Avenue Southeast
 Calgary, Alberta, T2C 4T9
 (403) 279 - 6200

Unit	VIN/Serial #	Asset	Mileage	Eng Hrs
08	1XKDD40X76J990551	2006 Kenworth T8 Series	457,595	0

Service Order	Terms	Due date	Customer PO	Authorizer
S-2364	Net 7	Mar 11, 2026		

Description	Quantity	Rate	Amount
Replace rear suspension bushings			
Worn Removed seized mounting components and fasteners. Had pieces rebushed. Replaced caps and fasteners as needed. Reinstalled suspension components.			
Labor Unit needs an alignment.	8		\$880.00
Parts AG BAR PRESS	2	\$65.00	\$130.00
Parts BUSHING 58 MM KB462	4	\$44.59	\$178.36
Parts BUSHING	4	\$73.30	\$293.20
Parts BOLT ASSEMBLY KIT M5231K	2	\$58.89	\$117.78
Parts BRACKET MK 16920	2	\$104.85	\$209.70
Parts TORQUE ROD PRESS	2	\$25.00	\$50.00
Parts BUSHING	4	\$73.30	\$293.20
Parts 5/8-11 X 12" GR8 HEX BOLT	4	\$11.20	\$44.80
Parts 5/8-11 GR8 STOVER LOCK NUT	4	\$3.54	\$14.16
		Line Total	\$2,211.20
Check air governor			
Building to 150psi			
Labor Air system is working as it should.	0.3		\$33.00
		Line Total	\$33.00
Replace cab shock			
Needed Removed air bags. Cut out seized mounting bolts. Installed new shock with antisieze. Installed new air bags. Tested.			
Labor DONE	3.8		\$418.00
Parts CABIN AIR SPRING (R81-1001)	2	\$62.32	\$124.64
Parts CAB SHOCK (W900)	1	\$56.87	\$56.87

	Description	Quantity	Rate	Amount
Parts	7/16 X 3-1/2 GR8 NC BOLT	2	\$2.73	\$5.46
Parts	7/16 GR8 WASHER	4	\$0.21	\$0.84
Parts	7/16 NC STOVER LOCK NUT	2	\$0.46	\$0.92
Parts	1/4 brass dot tube push-in X 1/8 male NPT 45 elbow	1	\$6.30	\$6.30
Parts	U-joint strap kit	1	\$19.87	\$19.87
			Line Total	\$632.90

Repair engine fan wiring

Engine light is on
 Removed intake to access fan solenoid wiring.
 Compared everything to the Cummins wiring diagram.
 Checked wiring to the fan solenoid, it is good. Checked signals to and from the ECM. The ecm is getting power all the time from the fan switch.
 Followed wiring into the cab. Found the ground side powered up. Removed the spliced in "ground wire". Added more ground to the circuit like it should have. Checked ECM inputs again. Now the switch is working and the ecm is not getting power all the time.
 Reinstalled everything, secured wiring. Cleared codes.
 Tested. DONE

Labor	DONE	11.3		\$1,243.00
			Line Total	\$1,243.00

REPLACE OUTPUT SEAL ON FIRST DIFF. AND U-JOINT

Removed rear shaft from the yoke. The caps were damaged.
 Removed yoke, it had to be heated to get the nut off.
 Removed and replaced the diff seal.
 Reinstalled yoke with a new nut. Replaced u joint. Installed drive shaft and torqued bolts.
 Topped up diff.

Labor	DONE	2.5		\$275.00
Parts	OIL SEAL (OUTPUT)	1	\$100.00	\$100.00
Parts	NUT YOKE RETAINING	1	\$37.77	\$37.77
Parts	1710 FULL ROUND U-JOINT	1	\$101.25	\$101.25
Parts	Synthetic gear oil	19	\$12.97	\$246.43
			Line Total	\$760.45

Labor	\$2,849.00
Parts	\$2,031.55
Shop supplies	\$199.43
Subtotal	\$5,079.98
GST (5%)	\$254.00
Total	\$5,333.98
Payments	
Visa	\$5,333.98
Balance	\$0.00

CG Truck And Equipment

5312 114 Avenue Southeast
 Calgary, Alberta, T2C 4T9
 (403) 279 - 6200



Invoice: INV-S-1353

Invoice Date: Aug 21, 2025
 Due date: Aug 28, 2025

Bill To

1573166 Alberta Ltd.
 119 Skyview Point Crescent Northeast
 Calgary, AB, T3N 1B6

Remit payment to

CG Truck And Equipment
 5312 114 Avenue Southeast
 Calgary, Alberta, T2C 4T9
 (403) 279 - 6200

Unit	VIN/Serial #	Asset	Mileage	Eng Hrs
	1XKDD40X76J990551	2006 Kenworth T8 Series	457,595	0
Service Order	Terms	Due date	Customer PO	Authorizer
S-1353	Net 7	Aug 28, 2025		

Description	Quantity	Rate	Amount
Adjust clutch linkage			
Too much free play			
When pressing the clutch, fork touches the bearing. Replaced			
Labor	clutch brake and backed off clutch and readjusted	1.25	\$147.50
Parts	CLUTCH BRAKE 2 PIECE	1	\$75.28
Line Total			\$222.78
Repair tailgate lock			
Broken			
Labor	Done	0	\$0.00
Parts	WELDING - FIXED RIGHT CORNER OF GRAVEL BOX	1	\$117.65
Line Total			\$117.65
			Labor \$147.50
			Parts \$192.93
			Shop supplies \$10.33
			Subtotal \$350.76
			GST (5%) \$17.54
			Total \$368.30
			Payments
			Visa \$368.30
			Balance \$0.00

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice. And further agree to pay reasonable attorney's fees and court costs in the event that legal action becomes necessary to enforce this contract.

Customer signature: _____
Printed name: _____ **Date:** _____

CG Truck And Equipment

5312 114 Avenue Southeast
 Calgary, Alberta, T2C 4T9
 (403) 279 - 6200



Invoice: INV-S-1263

Invoice Date: Aug 1, 2025
 Due date: Aug 8, 2025

Bill To

1573166 Alberta Ltd.
 119 Skyview Point Crescent Northeast
 Calgary, AB, T3N 1B6

Remit payment to

CG Truck And Equipment
 5312 114 Avenue Southeast
 Calgary, Alberta, T2C 4T9
 (403) 279 - 6200

Unit	VIN/Serial #	Asset	Mileage	Eng Hrs
	1XKDD40X76J990551	2006 Kenworth T8 Series	454,311	0
Service Order	Terms	Due date	Customer PO	Authorizer
S-1263	Net 7	Aug 8, 2025		

Description	Quantity	Rate	Amount
Repair exhaust leak - flex pipe broken Leaking.			
Labor Done.	0.75		\$82.50
Parts 5in exhaust flex pipe (10feet)	2	\$22.22	\$44.44
Parts EXHAUST BAND CLAMP 5" SS	2	\$25.87	\$51.74
		Line Total	\$178.68

Labor	\$82.50
Parts	\$96.18
Shop supplies	\$5.78
Subtotal	\$184.46
GST (5%)	\$9.23
Total	\$193.69
Payments	
Visa	\$193.69
Balance	\$0.00

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice. And further agree to pay reasonable attorney's fees and court costs in the event that legal action becomes necessary to enforce this contract.

Customer signature: _____

Printed name: _____ Date: _____

CG Truck And Equipment

5312 114 Avenue Southeast
 Calgary, Alberta, T2C 4T9
 (403) 279 - 6200



Invoice: INV-S-915

Invoice Date: Jun 17, 2025
 Due date: Jun 24, 2025

Bill To

1573166 Alberta Ltd.
 119 Skyview Point Crescent Northeast
 Calgary, AB, T3N 1B6

Remit payment to

CG Truck And Equipment
 5312 114 Avenue Southeast
 Calgary, Alberta, T2C 4T9
 (403) 279 - 6200

Unit	VIN/Serial #	Asset	Mileage	Eng Hrs
	1XKDD40X76J990551	2006 Kenworth T8 Series	450,731	0
Service Order	Terms	Due date	Customer PO	Authorizer
S-915	Net 7	Jun 24, 2025		

Description	Quantity	Rate	Amount
Replace rear diff seal Leaking Customer supplied part Removed yoke. The seal does not look to be the issue. Replaced the seal now that the yoke is off. Found a little hose in the diff housing. Cleaned up and filled with epoxy.	1.5		\$165.00
Labor			
Parts JB KWIKWELD CARD 2-1 OZ TUBES	1	\$13.71	\$13.71
Parts EMZONE BRAKE CLEAN 390g	1	\$5.83	\$5.83
		Line Total	\$184.54
Engine light on Engine light on Checked codes. Same codes for engine fan and EGR mechanism. Found the fan circuit bypassed. Checked sensor wiring to the ecm, they are good. Replaced broken coolant level sensor. Had to extract the broken plastic fitting. Will need more time to try and put the fan control circuit back to normal.	1		\$110.00
Labor			
Parts Coolant level sensor kenworth	1	\$70.70	\$70.70
Parts Radiator Cap - 15lbs	1	\$9.24	\$9.24
		Line Total	\$189.94
		Labor	\$275.00
		Parts	\$99.48
		Shop supplies	\$19.25
		Subtotal	\$393.73
		GST (5%)	\$19.69
		Total	\$413.42
		Payments	
		Visa	\$413.42
		Balance	\$0.00

CG Truck And Equipment

5312 114 Avenue Southeast
 Calgary, Alberta, T2C 4T9
 (403) 279 - 6200



Invoice: INV-S-647

Invoice Date: Jun 16, 2025
 Due date: Jun 23, 2025

Bill To

1573166 Alberta Ltd.
 119 Skyview Point Crescent Northeast
 Calgary, AB, T3N 1B6

Remit payment to

CG Truck And Equipment
 5312 114 Avenue Southeast
 Calgary, Alberta, T2C 4T9
 (403) 279 - 6200

Unit	VIN/Serial #	Asset	Mileage	Eng Hrs
	1XKDD40X76J990551	2006 Kenworth T8 Series	450,294	0
Service Order	Terms	Due date	Customer PO	Authorizer
S-647	Net 7	Jun 23, 2025		

Description	Quantity	Rate	Amount
Perform CVIP Annual Tractor Safety Labor Completed			\$250.00
		Line Total	\$250.00
Tire Removal - Three Axles Tire Removal - Three Axles Please install only outside tires on the rear. Unit is going to be painted. Labor Complete			\$240.00
		Line Total	\$240.00
Remove fifth wheel assembly. No needed. CUT OR REMOVE ALL FIFTH WHEEL MOUNT BOLTS. LIFTED FIFTH WHEEL OFF TRUCK WITH FORKLIFT. LEFT RAILS INSTALLED SHOULD CUSTOMER DESIRE TO HAVE FIFTH WHEEL AGAIN IN FUTURE. LINE COMPLETED Labor	1.25		\$137.50
		Line Total	\$137.50
Rreplace whole tie rod assembly Bent customer ordered part Labor Removed and replaced tie rod assembly. Set toe	2		\$220.00
		Line Total	\$220.00
Remove fenders Unit getting painted. Fenders not needed. REMOVED FENDERS. HAD TO CUT OFF ALL BOLTS WITH TORCH. Labor	1		\$110.00
		Line Total	\$110.00

	Description	Quantity	Rate	Amount
	Second axle left side brake pot			
	Broken spring			
	INSTALLED REPLACEMENT BRAKE POT. CUT PUSH ROD LENGTH TO MATCH ORIGINAL. TRANSFERRED FITTINGS FROM ORIGINAL POT TO NEW. HAD TO TRACK DOWN			
Labor	CORRECT KLEVIS.	1		\$110.00
Parts	SHORT STROKE BRAKE POT (2.5' STR)	1	\$74.18	\$74.18
Parts	Clevis kit	1	\$22.25	\$22.25
			Line Total	\$206.43
	Replace steering shaft u joints			
	Both are worn			
	CAM-COMPLETED INSTALL OF STEERING SHAFT U-JOINTS AND INSTALLED STEERIG COLUMN. DOUBLE CHECKED TIRE AND STEERING WHEEL STRAIGHTNESS			
Labor	BEFORE BOLTING UP	1.5		\$165.00
			Line Total	\$165.00
	Third axle right side wheel seal. Shoes and drum are oil soaked			
	Leaking			
	Customer supplied seal			
Labor	Removed and replaced wheel seal.	1.5		\$165.00
Parts	hub gasket	1	\$8.80	\$8.80
			Line Total	\$173.80
	Rear torque rods, left side.			
	Rubber squished out			
	Removed and replaced left side torque rods. Most bolts were seized.			
Labor	Customer supplied parts	3		\$330.00
			Line Total	\$330.00
	Right rear brake shoes and drum			
	Cracked.			
Labor	Replaced shoes and drum.	0.5		\$55.00
Parts	Fleetrite 4400B drums (3600A)	1	\$115.00	\$115.00
Parts	Brake shoe	1	\$78.53	\$78.53
			Line Total	\$248.53
	Second axle left side slack adjuster			
	Not working			
Labor	INSTALLED REPLACEMENT SLACK ADJUSTER	1		\$110.00
Parts	SLACK ADJUSTER	1	\$137.94	\$137.94
			Line Total	\$247.94
	Second axle right side brake shoe hardware			
	Springs are worn out.			
	Replaced shoes hardware kit. The old one did not have any			
Labor	spring return.	0.5		\$55.00
Parts	BRAKE HARDWARE KIT	1	\$25.25	\$25.25
			Line Total	\$80.25
Labor	Steer axle right side wheel seal	1.5		\$165.00

	Description	Quantity	Rate	Amount
	Leaking Removed and replaced seal, drums and shoes were not damaged.			
Parts	Hubcap gasket	1	\$5.66	\$5.66
Parts	SEAL STEER AXLE	1	\$82.58	\$82.58
Parts	Synthetic gear oil	1	\$10.41	\$10.41
			Line Total	\$263.65
	Second axle left side wheel seal. Leaking badly Change shoes and drum REPLACED WHEEL SEAL, BRAKE SHOES AND DRUM ON #2 AXLE LEFT.			
Labor	Wheel seal supplied	1.5		\$165.00
Parts	Brake shoe	1	\$78.53	\$78.53
Parts	BRAKE DRUM (4400B)(16792X)	1	\$120.53	\$120.53
Parts	Gasket 8 hole 5/8	1	\$6.28	\$6.28
Parts	Synthetic gear oil	1	\$10.21	\$10.21
			Line Total	\$380.55
	Replace rear axle shocks. Worn Had to cut off both rear shocks. Installed new shocks. DONE			
Labor	Part supplied.	1.5		\$165.00
			Line Total	\$165.00
	Replace fan clutch solenoid Not working properly Diagnosed fan clutch solenoid. Replaced solenoid. Swapped fittings over.			
Labor	Tested. DONE	1.5		\$165.00
Parts	FAN CLUTCH SOLENOID VALVE	1	\$223.96	\$223.96
			Line Total	\$388.96
	Engine light on for vehicle speed sensor Sensor issue or wiring to ECM replace speed sensor. wired old wiring harness into new			
Labor	sensor	1.5		\$165.00
Parts	SPEED SENSOR	1	\$199.68	\$199.68
			Line Total	\$364.68
	Adjust clutch Needs adjustment Checked clutch adjustment, it is out. Found clutch linkage worn and the ball sockets ready to come apart. Removed and replaced both linkages.			
Labor	Adjusted clutch and linkages. DONE	4		\$440.00
Parts	CLUTCH ROD END RH	1	\$89.48	\$89.48
Parts	CLUTCH ROD END LH	1	\$89.39	\$89.39
			Line Total	\$618.87
	Replace cross member bracket			
Labor		8		\$880.00

	Description	Quantity	Rate	Amount
	Heated and extracted all bolts using an air hammer and impact gun. Removed ABS valve bracket and torque rods. Realigned the frame and reinstalled torque rods. Job completed.			
Parts	16MM FLAT WASHER	20	\$1.37	\$27.40
Parts	16MM GR10 CRS NYL LOCKNUT	10	\$3.75	\$37.50
Parts	16 X 60MM 10.9 BLK CRS BOLT	10	\$4.18	\$41.80
			Line Total	\$986.70
	Replace fuel tank strap rubbers			
	Worn			
	Fuel tank nuts were seized and required heating for removal. The step was loosened, and a transmission jack was used to support the fuel tank. Rust was cleaned thoroughly, extending the job time. The tank was removed to replace the worn fuel tank strap rubbers. Job completed.			
Labor		2		\$220.00
			Line Total	\$220.00
	Replace air bag lines			
	All air bag fittings were seized and required heat and an air hammer to loosen. Replaced air bag lines, installed new lines with clamps, and replaced all small fittings connecting to larger lines. Job completed.			
Labor		2.5		\$275.00
Parts	1/4 Brass dot tube push-in X 1/4 male NPT run tee	1	\$12.70	\$12.70
Parts	1/4 Brass dot tube push-in union coupling	2	\$4.80	\$9.60
Parts	3/8 Brass dot tube push-in x 1/4 male NPT branch tee	1	\$8.40	\$8.40
Parts	3/8 Brass tube X 1/4 male NPT	1	\$6.14	\$6.14
Parts	34-37MM W2 BOLT CLAMP	8	\$9.35	\$74.80
			Line Total	\$386.64
	Grease			
	Truck needs grease			
	Greased unit			
	Checked fluid levels			
	Some points not taking grease, removed nipples and cleaned holes and made use nipples were good.			
Labor		0.5		\$55.00
			Line Total	\$55.00
	Check AC			
	Customer request			
	AC charge was low.			
	Recovered system. Vacuumed and leak tested. Charge system and tested.			
Labor		1.5		\$165.00
Parts	R134A Refrigerant / lbs	4	\$18.32	\$73.28
			Line Total	\$238.28

Labor	\$4,807.50
Parts	\$1,670.28
Shop supplies	\$336.53
Subtotal	\$6,814.31
GST (5%)	\$340.73
Total	\$7,155.04
Payments	
Visa	\$7,155.04
Balance	\$0.00

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice. And further agree to pay reasonable attorney's fees and court costs in the event that legal action becomes necessary to enforce this contract.

Customer signature: _____

Printed name: _____ Date: _____