

T28-3
MAY



5510 63 AVENUE
LLOYDMINSTER, AB
T9V 3T8

PH: 780-875-2596
TOLL FREE: 1-888-544-5274
MAIN FX: 780-875-2591

DATE: 10/28/2024

Page 1 of 2

GST #: 134175256

Work Order

716295

BILLED TO:
BOSS VAC
BOX 325
MACKLIN SK SOL 2C0

SHIPPED TO:

DILL PO NUMBER UNIT # SHIP VIA SOLD BY:
ADAM

Part Number	Ordered	Shipped	Price	Total	Tax
Work Completed at 18987 hrs					

PARTS						13,937.70
91200	LUBRICATOR PREMIER PUMP	2	2	449.87	899.74	0
75W90GX	75W90 MOBILUBE SEMI/SYNTHETIC GEAR OIL	45	45	11.38	512.10	0
52125459	LASH 2 1/2" 160 PSI 1/4" BM GAUGE	1	1	24.05	24.05	0
0202-4-4G	PIPE COUPLING FNPT X FNPT	1	1	1.67	1.67	0
NPL1410X	1/4" X 10" XH NIPPLE	1	1	5.05	5.05	0
50B32	3/4" STUD NUT CLASS 2H HEX NUTS	2	2	1.34	2.68	0
201TEE110	GARDNER DENVER 4X5 CAP STUD	1	1	38.97	38.97	0
25AL59	STFG.BOX/VALVE COVER GASKET (DISCHARGE MANIFOLD)	3	3	18.53	55.59	0
25C1271	G.D. SUCTION MANIFOLD GASKET	3	3	14.97	44.91	0
25R39N	GASKET	3	3	8.43	25.29	0
31PE445	4" X 5 1/4" LANTERN RING	1	1	245.84	245.84	0
28PE152	4" X 5 1/4" GLAND BUSHING	1	1	245.97	245.97	0
38PE317	4" X 5 1/4" JUNK RING	1	1	88.29	88.29	0
60BU72	4" X 5 1/4" GD PUMP PACKING (-10°F TO 180°F OR -23°C TO 82°C)	3	3	144.42	433.26	0
GDPE5HHC4000	GARDNER DENVER 4" HARDCO HOLLOW PLUNGER	3	3	1,285.92	3,857.76	0
60DD99	GD 2" POWER END PACKING	3	3	26.72	80.16	0
25AL20	STFG.BOX/VALVE COVER GASKET (3.5-4 X 5 VC/SB)	9	9	14.64	131.76	0
25BC42	GASKET (BX-153 316SS OVAL RING)	1	1	15.67	15.67	0

ALL RETURNS MAY BE SUBJECT TO A RESTOCKING FEE

Continued Next Page



10/28/2024

Page 2 of 2

Work Order
716295

BILLED TO:
BOSS VAC
BOX 325
MACKLIN SK SOL 2C0

Part Number		Ordered	Shipped	Price	Total	Tax
2118129	GARDNER DENVER TEE OIL FILTER SPIN ON	1	1	164.19	164.19	0
	EHC>8 ENVIRONMENTAL HANDLING CHARGE, 8" ELEMENT AND OVER	1	1	1.25	1.25	0
SUBLET	RE-SLEEVE FLUID END	6	6	1,175.00	7,050.00	0
VBV300GASKET	3" VIC STYLE T GASKET (OIL)	1	1	13.50	13.50	0
LABOUR					3,882.38	
LABOUR	LABOUR	26	26	145.00	3,697.50	0
<p>4x5 pressure truck not holding pressure. Valve seat surfaces in fluid end blocks are worn, check pricing to have them built up and machined back to tolerance. Pump is also leaking from plungers/packing and into crank case, change oil and inspect crank case, and replace plungers, stuffing boxes, packing etc. as needed. Customer has stated that if plungers, brass and stuffing boxes need to be replaced to notify him as he may convert to 3-1/2 x 5 instead.</p> <p>REPAIRS APPROVED, CUSTOMER WILL KEEP WITH A 4 X 5 AS STUFFING BOXES ARE GOOD</p> <p>(4.0) INSPECT POWER END, REMOVED PLUNGERS & VALVES (5.5) REMOVED STUFFING BOXES, AND FLUID END, CLEANED TRIPLEX PARTS (8.0) CLEANED STUFFING BOXES, INSTALLED NEW PACKING, VALVES, SEATS, EXTENTION ROD PACKING AND INSTALLED BACK ON UNIT (8.0) FINISHED TRIPLEX, PUMPED OUT OIL IN POWEREND, FLUSHED OUT & CHANGED FILTER</p>						
SHOP SUPP	SHOP SUPPLIES & ENVIRONMENTAL FEES	1	1	184.88	184.88	0

Sub Total	\$17,820.08	
GST 5%	\$891.00	
PST 6%	\$0.00	
Total	\$18,711.08	CAD
Paid	\$0.00	CAD
Balance	\$18,711.08	CAD