

2026150

A30/1



Kristian Electric Ltd.

4215 64th Ave SE 14236 121A Ave NW 710, 46th Street E
 Calgary, AB T2C 2C8 Edmonton, AB T5L 4L2 Saskatoon, SK S7K 0W9
 Tel: 403-292-9111 Tel: (780) 444-6116 Tel: (306) 343-9111
 Fax: 403-292-9100 Fax: (780) 483-0533 Fax: (306) 343-9114

WORK ORDER

JOB NO : 71065
 SERVICE DATE : Jul 15 22
 SCHEDULED COMPLETION: Aug 15 22

CUSTOMER: Diamond T Portable	*C.O.D*	INSTRUCTIONS: EST. SA350-CDN-D - Removed pulley from old waterpump and reinstall in on rebuilt water pump. Supply belt also.
MAIN PHONE: 403-818-6371		
LOCATION: Diamond T Portable	*C.O.D*	
Welding Ltd. (Mike) AB 403-818-6371		

CUSTOMER PO# *check # 3*

SITE CONTACT:
Mike Trotter
: 403-818-6371

REFERENCE #:

ItemCode	Description	Quantity	Unit	Price	Extl
	Equipment: Mfr: Lincoln Electric Model: SA-350-CDN-D				
	Equipment History: WO No. Date 0071065 Jul 15 22				
	Description EST. SA350-CDN-D				
	Removed pulley from old pump. Installed new pulley and glued back plate on pump. Supplied belt.				
COTM27K00601	Water pump,rebuilt TM20/TM27	1	EA	265.00	265
21118156	Belt Big40D 13Av1270	1	EA	48.80	48.80
76701	Labor	.5	EA	120.00	60
<i>plu by Mike 07/20</i>					

Foreman Notes:
Mike Trotter

Subtotal
 Taxes and Labor charges are calcu
954
\$ 392.49



Kristian Electric Ltd.

4215 64th Ave SE 14236 121A Ave NW 710, 46th Street E
 Calgary, AB T2C 2C8 Edmonton, AB T5L 4L2 Saskatoon, SK S7K 0W9
 Tel: 403-292-9111 Tel: (780) 444-6116 Tel: (306) 343-9111
 Fax: 403-292-9100 Fax: (780) 463-0533 Fax: (306) 343-9114

WORK ORDER

JOB NO : 71367

SERVICE DATE : Jul 28 22

SCHEDULED COMPLETION: Nov 30 22

CUSTOMER: Diamond T Portable	*C.O.D*	INSTRUCTIONS: Repair 350 CDN Reed switch is broken, Idler problems 11370.00 hrs
MAIN PHONE: 403-818-6371		
LOCATION: Diamond T Portable	*C.O.D*	
Welding Ltd. (Mike) AB 403-818-6371		

CUSTOMER PO#:

SITE CONTACT:
Mike Trotter
: 403-818-6371

REFERENCE #:

Item Code	Description	Quantity	Unit	Price	ExtPric
	Equipment: Mfr: Lincoln Electric Model: SA-350-CDN-D S/N: 301725 9834				
ory:	Description				
5 22	EST. SA350-CDN-D				
3 22	Repair 350 CDN				
	Removed broken reed switch, found and installed used reed switch assembly. Repaired wiring for reed switch as needed. Checked wiring, found broken wires. Checked wire connectors at idle board. Removed idle board. Tried to solder on connector onto board. Reinstalled board and wiring. Tried to start. Put battery on charger for a few hours and tried again. found smoke. Removed cables and serviced them and clamps as required. Checked glow system. Ran. Checked aux, speeds, OCV, Charge. Checked power to idle board and coming out. LB all ranges. Replaced idle board, checked operation. Replaced neg cable lug coupler assembly.				
	Labor	4	EA	120.00	480.0
	Reed Switch & Lead Assy	1	EA	95.00	95.0
	Idler Pc Bd Assy	1	EA	302.12	302.1
	Connector, Female, Tweco Style	1	EA	10.60	10.6
	Shop Supplies	1	EA	10.00	10.0
	<i>Paid by cheque 64433</i>				
	<i>X</i>				
	<i>File in Mike 12/11</i>				

Foreman Notes:

Wayne G. J. J. J.

Subtotal	897.
Taxes and Labor charges are calculated on the invoice.	44.8
	941.8
	<i>91042.78</i>

Service Writer: Wayne Gjertsen Warehouse: 01 Calgary Tech: