

537-2
MAY

Sevenwest HD Mechanics and Welding Ltd.

Box 91
Hans SK S0L1K0
newst7@cloud.com

INVOICE

Aos Ltd
Saskatoon

1312
10/06/2025
Due on receipt
10/06/2025

SERVICE	DESCRIPTION	TAX	QTY	RATE	AMOUNT
Sales	May 23 packer hinge micro -2 May 27 240 quick attach hose repair 3 May 28 get stuck side dump back to home position, diagnose 240 leak, found to be def leak, book for warranty with sms - 3 May 30 diagnose final drive leak on crawler source parts, disassemble failed t62 track idler, inspect 240 komatsu panel, inspect/repair ho70 packer leak source mirror to replace broken one, meet stranded/nonstart western star and get driving again to unload trailer for tow truck (booked by driver) 9 May 31 scan diagnose no start western star, hard surface weld idler assembly on t62 skid steer, re assemble - 5 June 2 - replace failed track on t62, replace glass on t62 - 3 June 7 - troubleshoot pump/ valve issues on Mack/ build mounting studs and weld new suction line fitting for pump. - 6 June 9 - swap pumps on Mack, re install lines weld repair on Mack mud flap bracket, install shell kit on ho 120 packer, 12.5 June 10 - remove and weld hood bracket on ho 120 packer, re install brackets re align hood, re install screen. Repair wiring for cab fan - 4	GST/PST SK	47.50	135.00	6,412.50
Sales	Service truck payment	Exempt	1	-2,000.00	-2,000.00

<i>Komatsu-240 excavator</i>	<i>-mack truck</i>	SUBTOTAL	4,412.50
<i>CL1-crawler loader</i>	<i>P101-hyundai packer-HR120C-9</i>		320.63
<i>-Bobcat skidsteer</i>		PST, SKI 6%	384.75
<i>P102-hyundai packer-HR120C</i>		TOTAL	5,117.88
<i>HT464-western star</i>		BALANCE DUE	\$5,117.88

TAX SUMMARY

RATE	TAX	NET
GST @ 5%	320.63	6,412.50

Sevenwest HD Mechanics and Welding Ltd.

Box 91
 Harris SK S0L1K0
 hewitt.r@icloud.com

INVOICE

Abs Excavating Ltd.
 Saskatoon

1017
 09/07/2025
 Due on receipt
 09/07/2025

SERVICE	DESCRIPTION	TAX	QTY	RATE	AMOUNT
Sales	<p>June 25 - Troubleshoot Mack truck not dumping, manually dump side dump load off trailer on site, troubleshoot komatsu skidsteer oil steer oil in filter. 4</p> <p>June 26 - Western star fender install and wiring 6</p> <p>June 26 - kobelco excavator bucket pin, remove old broken pin, replace with grade 8 bolt/stover nut until new part comes in. 4</p> <p>June 27 - Mack wet kit/wiring repair, Mack no signal lights diagnose repair, western star diagnose pto not operating 7</p> <p>June 30 - repair wet kit lines/fittings on western star, top up tank with mv 22, found tank empty</p> <p>Install relief valve in line for wet kit pump on Mack 7</p> <p>July 1 - repair damaged truck/trailer wiring 4</p> <p>July 4 - remove dirt, repair damaged hydraulic line in chassis of skid steer, repair hydraulic leak on hxx kit for 240 komatsu, inspect damage and advise on crusher curtain, repair tarp motor and rewind tarp on side dump - 9</p> <p>July 5 - dismantle crusher for shipping - 4</p> <p>July 7 - Mack wiring, air line repair, oil change. 9</p> <p>July 9 - service Mack unit 12 2</p>	GST/PST SK	56	135.00	7,560.00
Sales	<p>June 27 - deliver western star for steer tires, source hydraulic lines and fittings, electrical parts for Mack, 5</p> <p>July 8 - top up some oil and load crawler from micro for repair 4</p>	GST/PST SK	9	55.00	495.00
Sales	Service truck payment	Exempt	-1	2,000.00	-2,000.00

*mack truck					6,055.00
*HT464-western star					402.75
*Komatsu 240 excavator					483.30
*side dump trailer					6,941.05
*HT12-mack truck					

Sevenwest HD Mechanics and Welding Ltd.

Box 91
 Plains SK S0L 1K3
 newhr@sevenwest.ca

INVOICE

Aos Excavating Ltd
 Saskatoon

1022
 10/07/2025
 Due on receipt
 10/07/2025

SERVICE	DESCRIPTION	TAX	QTY	RATE	AMOUNT
Sales	<p>July 10 - 755c crawler diagnose and begin repairs for hydraulic leak, ordered parts</p> <p>Staple box bent into door remove and straighten tub box so door for cab can open, again 5</p> <p>Diagnose sk 30 skidsteer oil in air intake, advise Austin for cause of oil being excessive crankcase pressure pushing oil into intake. 1</p> <p>July 14 - complete repair for drive motor leak on 755c, remove bent bumper on ht 12 straighten brackets temporarily for replacement bumper while waiting on parts. Test drive ht 12 for stalling issue, test drive ht 13 for engine and traction control light complaint from driver 8</p> <p>July 13 - ht 12 roadside repair stalling out. 3</p> <p>July 14 - inspect complaint of noise on t62 skidsteer Brighton, service final drives, add hydraulic oil, level was low 3</p> <p>July 18 f350 service, 464 safety repairs, ht1 deck truck repairs 3</p> <p>July 21 - ht 11 wiring repair, crawler wiring repair 7</p> <p>July 22 - wapella 360 service, t62 service, jd tractor ad belt - 17</p> <p>July 24 - 240 komatsu, remove and replace broken fittings, repair wedge hydraulic leak, test function on thumb bucket, 3.5</p>	GST/PST SK	55.50	135.10	7,492.50
	<ul style="list-style-type: none"> • CL1 - crawler loader 755C • sk 30 skidsteer - Komatsu • HT12 - mack truck • HT13 - mack truck • Bobcat skidsteer - T62 • HT464 - Western star • HT11 - mack truck • 854 - Komatsu 360 excavator • Komatsu 240 excavator 				
Sales	<p>July 15 - service brown f350 pickup, crawler loader diagnostics for locking out 8</p> <p>July 16 - source t62 service kit, book and deliver deliver ht 12 to redhead and pick up ht 13 from sharp auto, boom crawler repairs. 5</p> <p>July 17 - order panels for 240 excavator, troubleshoot parts orders and services for wapella equipment 2</p> <p>July 21 - source 360 service kit, book/deliver flat deck for repairs at truckline, 2</p>	GST/PST SK	17	55.00	935.00
Sales	Mileage from Regina to wapella 400kms	GST/PST SK	400	0.55	220.00
Sales	Service truck payment	Exempt	-1	2,000.00	-2,000.00

Sevenwest HD Mechanics and Welding Ltd.

Box 91
 Harris SK S0L1K0
 newitt.r@icloud.com

INVOICE

Abs Excavating Ltd.
 Saskatoon

1028
 24/07/2025
 Due on receipt
 24/07/2025

SERVICE	DESCRIPTION	TAX	QTY	RATE	AMOUNT
Sales	July 24 - ht 11 diagnose side dump not dumping, toggle switch in wrong position 2 July 28 - repair bent brackets and crossmember on crusher, diagnose grapple bucket leak for komatsu 240 , remove damaged hydraulic lines. 6 July 29 - packer shell kit removal, crusher inspection for hammers and wear plates, side dump trailer tarp/tip over repairs 8 July 31 - flip crusher bars 4 Aug 5 - diagnose and repair def pump on 464 western star, install new hydraulic lines on grapple bucket, diagnose leak on 755c crawler loader 9 Aug 6 - crawler oil leak repair, grapple repair 5 Aug 7 - diagnose crusher shutting down and order parts. 4	GST/PST SK	38	135.00	5,130.00
Sales	Parts ordering for trailers , book komatsu care 1 July 30 - Run grader at floral rd site 5, hose repair for grapple bucket 1 July 31 - tire repair for service truck, deliver freightliner to truckline 4	GST/PST SK	11	55.00	605.00

• Komatsu 240 excavator	5,735.00
• HT464 - Western Star	286.75
• CL1 - Crawler loader 755C	344.10
	6,365.85
	\$6,365.85

TAX SUMMARY

RATE	TAX	NET
GST @ 5%	286.75	5,735.00
PST (SK) @ 6%	344.10	5,735.00

Sevenwest HD Mechanics and Welding Ltd

Box 91
 Hains, SK 3B0L0K0
 haw@sevenwest.com

INVOICE

Aos Excavating Ltd
 Saskatoon

1041
 25/08/2025
 Due on receipt
 10/09/2025

SERVICE	DESCRIPTION	TAX	QTY	RATE	AMOUNT
Sales	Aug 25 Call to micro for loader and end up not dumping 2 Aug 27 - crusher set up, inspect blower filter for leaks, ck 30 oil top up 7 Aug 28 - pick up, belting for crusher set up for install 2.5 Aug 29 - crusher belt install and adjustments 4 Sept 3 - inspect 140h grader for leaks, found slow sweats from multiple hydraulic lines, top up hydraulic oil and transmission oil, Mack unit 13 service oil, fuel and air 180 semi - replace ipd sensor inspect leaks for repair 7 Sept 4 freightliner 180 service engine oil and filter crack diff, change serpentine belt 4.5 Sept 6 repair side dump tarp tube inspect freightliner 180 for squeak on belt, air compressor making noise, order parts 4 Sept 8 repair unit 464 on roadside, replace pndb module and batteries, repair skidsteer leak on boom, inspect trench packer for wiring issues 7 Sept 9 freightliner no start roadside, repair broken fender and brackets on side dump unit 464 3	GST/PST SK	41	135.00	5,535.00
Sales	Aug 26 - gather crusher service kit, Mack service kit and organize crusher warranty paperwork. 6 Aug 27 ck 30 parts, pc 240 warranty booking oil sample paperwork, delivery 2 Sept 2 pick up, fill oils for 140h grader 2	GST/PST SK	10	55.00	550.00
Loan Payment	Finance Repayment	Out of Scope	1	-1,000.00	-1,000.00

• GRG1- 140H Grader	5,085.00
• HT13- mack truck	304.25
• HT15- freightliner flatdeck	365.10
• Side dump trailer	5,754.35
• HT 464 western star	\$5,754.35

Sevenwest HD Mechanics and Welding Ltd

Box 91
Hans SK S0B 1K0
sevenwest@telus.com

INVOICE

Abn Excavating Ltd
Saskatoon

1052
24/09/2025
Due on receipt
24-09/2025

SERVICE	DESCRIPTION	TAX	QTY	RATE	AMOUNT
Barrel	Sept 10 - repair remote wiring and main harness on bomag walk behind packer 7 Sept 11 - remove guards to blow out crawler and backhoe air filters. inspect gears in engine bay. 4 Sept 12 - 480 roadside wiring repair in delisle, 500hr service on 380 Hyundai ar whitecad 7 Sept 15 - ht 464 fuel and oil service, ht 11 fuel and oil service. inspect ht 12 for noise at shutdown - crankcase spinner needs replaced. 5 Sept 16 - 460 crusher bars. weld in plates for asphalt, inspect crawler loader for complaint of not driving. pick up crankcase filter for ht 12. 6 Sept 18 - remove crusher plates. repair press for crusher bars. inspect stacker, gather service kits/oil 4 Sept 19 - (lafarge site) change komatsu loader cabin and air filter. change cabin and engine air filters. change damaged side panel on 240 komatsu. 500 hour service on crusher, 500 hour service on stacker remove hydraulic lines on stacker for new ones. 9 Sept 22 - no start/no power to cab on Mack ht 13 diagnose and repair wiring issue, straighten brackets and install bumper on ht 11. install crankcase filter and vent hose on ht 11, inspect ht 11 radio not working and tires, book for new tires, send in oil samples with paperwork for crusher 7	GST/PST SK	49	135.00	6,615.00
Loan Payment	Finance Repayment	Out of Scope	1	-1,000.00	-1,000.00

- Bomag packer
 - CL1 - crawler loader
 - HT15 - freightliner
 - E52 - hyundai 380 excavator
 - HT464 western star
 - HT11 mack
 - HT12 mack
- 240 Komatsu excavator*
• HT13 Mack
 GST (SK) @ 5%
 PST (SK) @ 5%
TOTAL
- 5,615.00
 330.75
 396.90
 6,342.65
\$6,342.65

Sevenwest HD Mechanics and Welding Ltd.

Box 91
Harris SK S0L1K0
hewitt.r@icloud.com

INVOICE

Abs Excavating Ltd.
Saskatoon

492674
27/02/2026
Due on receipt
27/02/2026

SERVICE	DESCRIPTION	TAX	QTY	RATE	AMOUNT
Sales	Service ht464 western star heavy truck Oil change and filter Fuel filter Air filter Prime fuel system	GST/PST SK	3	145.00	435.00
	Load cat rock truck on step deck as requested assist driver with flat tire.				

	435.00
	21.75
	26.10
	482.85
	\$482.85

TAX SUMMARY

RATE	TAX	NET
GST @ 5%	21.75	435.00
PST (SK) @ 6%	26.10	435.00

• HT464