



**Warner Industries Saskatoon**  
**3002 FAITHFULL AVE SASKATOON, SK S7K 0B1**

TEL: (306) 931-4448  
 FAX: (306) 933-0411  
 TOLL FREE: (800) 667-6860  
 (IN SASKATCHEWAN)

*Fun Friendly People*  
 G.S.T. Registration Number 105704464RT0001  
 P.S.T. Registration Number 0898122

SERVICE INVOICE: R800016319:01

*S37-3  
MAY*

BILL TO  
 \*\*CASH ONLY\*\*ABS EXCAVATING LTD  
 4018 ARONEC AVENUE  
 SASKATOON SK S7P OE1  
 P: (306) 249-0383

DELIVER TO  
 \*\*CASH ONLY\*\*ABS EXCAVATING LTD  
 4018 ARONEC AVENUE  
 SASKATOON SK S7P OE1  
 P: (306) 249-0383

ENGINE HOURS 0

DATE PROMISED	DATE INVOICE	SALES TYPE	ADVISOR	TERMS	CUSTOMER REFERENCE			
2026-03-03 12:18:49PM	3/23/2026	SC	RJ	VISA	006			
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	CAB CARD	IN SERVICE	ODOMETER IN	ODOMETER OUT
2024	SDI	TRI SIDE DUMP	1S9DS4437RS819006				1	1

**Sold Operations**

**JOB #1 SGI-TL3 SC SGI SAFETY TRI AXLE TRAILER (12 MO)**

CONCERN SGI SAFETY TRI AXLE TRAILER (12 MO)  
 ROOT CAUSE SCHEDULED SAFETY INSPECTION  
 CORRECTION PERFORM SAFETY INSPECTION

QTY	ITEM	VMRS	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	SGID		SGI SAFETY DECAL	20.00	20.00
	LABOR SGI-TL3		SGI SAFETY TRI AXLE TRAILER (12 MO)		225.00

**TOTAL JOB #1 SGI-TL3 245.00**

**JOB #2 00-00 SC MISC REPAIR**

CONCERN DIAGNOSE AND REPAIR REASON FOR LEFT TURN SIGNAL SHORTED AND BOTH LR AND RR MARKER LIGHTS OUT  
 ROOT CAUSE CORROSION IN WIRING, CONNECTORS, AND LIGHT ASSEMBLIES.  
 CORRECTION FOUND RIGHT REAR AND LEFT REAR MARKER LIGHTS AND MIDSHIP SIGNAL LIGHT INOPERATIVE DUE TO SEVERE CORROSION IN WIRING, CONNECTORS, AND LIGHT ASSEMBLIES. LIGHT HOUSINGS CORRODED, MOUNTING GROMMETS TORN AND DETERIORATED, CAUSING POOR ELECTRICAL CONNECTIONS AND FAILED LIGHTING COMPONENTS. REMOVE DAMAGE COMPONENTS, REPLACE RIGHT REAR AND LEFT REAR MARKER LIGHT WIRING WITH NEW 2-WIRE SETUP. INSTALL NEW MARKER LIGHT ASSEMBLIES AND REPLACE DAMAGED MOUNTING GROMMETS. REPLACE MIDSHIP SIGNAL LIGHT WITH NEW 3-WIRE WIRING AND LIGHT ASSEMBLY DUE TO BROKEN HOUSING AND CORRODED CONNECTIONS. VERIFY OPERATION OF ALL LIGHTS

QTY	ITEM	VMRS	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 00-00		MISC REPAIR		412.50
1	GRO 52193		SIDE TURN LAMP ECON *D	15.35	15.35
2	GRO 67000	GRO-67000	PIGTAIL-3 WAY PLUGIN FOR FE *D	2.48	4.96
2	GRO 67050	GRO-67050	PIGTAIL-SEALED MARKER LAMP, *D	1.71	3.42
1	GRO G1502	GRO-G1502	LED MARKER LAMP RED *D	8.42	8.42
8	PHM 1 1962 100		CONNECTOR 16-14GA *D	1.05	8.40
2	TL 15702		GROMMET *D	3.68	7.36

**TOTAL JOB #2 00-00 460.41**

**JOB #3 00-00 SC MISC REPAIR**

CONCERN DIAGNOSE AND ADVISE REASON FOR #1 LEFT AND #3 RIGHT BRAKES BACKED OFF AND NOT TIGHTENING UP  
 ROOT CAUSE #3 RIGHT BRAKE CHAMBER FLUID-LOCKED, #1 LEFT NOT APPLYING OR RELEASING DUE TO BENT INNER CAM BRACKET



**Warner Industries Saskatoon**  
**3002 FAITHFULL AVE SASKATOON, SK S7K 0B1**

TEL: (306) 931-4448  
 FAX: (306) 933-0411  
 TOLL FREE: (800) 667-6860  
 (IN SASKATCHEWAN)

*Fun Friendly People*  
 G.S.T. Registration Number 105704464RT0001  
 P.S.T. Registration Number 0898122

**SERVICE INVOICE: R800016319:01**

BILL TO  
**\*\*CASH ONLY\*\*ABS EXCAVATING LTD**  
 4018 ARONEC AVENUE  
 SASKATOON SK S7P OE1  
 P: (306) 249-0383

DELIVER TO  
**\*\*CASH ONLY\*\*ABS EXCAVATING LTD**  
 4018 ARONEC AVENUE  
 SASKATOON SK S7P OE1  
 P: (306) 249-0383

ENGINE HOURS 0

DATE PROMISED	DATE INVOICE	SALES TYPE	ADVISOR	TERMS	CUSTOMER REFERENCE			
2026-03-03 12:18:49PM	3/23/2026	SC	RJ	VISA	006			
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	CAB CARD	IN SERVICE	ODOMETER IN	ODOMETER OUT
2024	SDI	TRI SIDE DUMP	1S9DS4437RS819006				1	1

**Sold Operations (Cont.)**

**CORRECTION** DIAGNOSE #3 RIGHT BRAKE CHAMBER BY ISOLATING SERVICE AND EMERGENCY AIR LINES AND CONFIRMING PUSHROD WILL NOT RETRACT. BRAKE CHAMBER IS FLUID-LOCKED DUE TO WATER CONTAMINATION INSIDE THE DIAPHRAGM, REPLACE BRAKE CHAMBER, SEIZED AUTOMATIC SLACK ADJUSTER, CLEAN CAMSHAFT SPLINES, AND INSTALL NEW COMPONENTS. ON #1 LEFT, REMOVE DAMAGED INNER CAM BRACKET FROM THE AXLE AND REWELD IN CORRECT ALIGNMENT. FREE AND LUBRICATE SEIZED CAMSHAFT. REMOVE BRAKE DRUM AND WHEELS FOR INSPECTION; DRUM SERVICEABLE BUT BRAKE SHOES ARE SEPARATED AND DAMAGED. REPLACE BRAKE SHOES AND HARDWARE AFTER REMOVING SEIZED ANCHOR BUSHINGS. REASSEMBLE BRAKE COMPONENTS, REINSTALL DRUM AND WHEELS, AND TORQUE TO SPECIFICATION. VERIFIED PROPER BRAKE OPERATION.

QTY	ITEM	VMRS	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 00-00		MISC REPAIR		1,039.50
1	ABP N42A CTS3030	ABP-N42A-33030CD	SPRINGBRK 3030 2.5IN STRK 1 *D	79.34	79.34
1	ABP N42AS R801074		SLACK MERITOR STYLE 6IN ARM 1.	80.11	80.11
1	SLL 550075629	SLL-550027558	GADUS GREASE S3 V220C 0.4KG *D	5.71	5.71
1	TDA R810019	TDA-R810019	CLEVIS-KIT,LIGHTWEIGHT,20,2 *D	23.59	23.59
2	1474-8C	1474-8C	AirBrake 45Elb;1/2x3/8 MPT	6.65	13.30
1	HD-M-4707K		4707 BRAKE SHOE,KIT CORELESS	73.67	73.67

**TOTAL JOB #3 00-00 1,315.22**

**JOB #4 00-00 SC MISC REPAIR**

**CONCERN** DIAGNOSE AND REPAIR REASON #2 FENDER DAMAGED AND #3 LEFT FENDER LOOSE  
**ROOT CAUSE** #2 RIGHT LARGE HOLE, #3 RIGHT FENDER MISSING HARDWARE  
**CORRECTION** #2 RIGHT FENDER DAMAGED WITH A LARGE HOLE. #3 RIGHT FENDER FOUND LOOSE DUE TO MISSING MOUNTING HARDWARE. INSTALL TWO NEW MOUNTING BOLTS ON THE #3 RIGHT FENDER TO PROPERLY SECURE FENDER TO THE BRACKET AND PREVENT MOVEMENT. REPLACE DAMAGED #2 RIGHT FENDER. POSITION NEW FENDER AND ALIGNED WITH EXISTING BRACKETS, VERIFY PROPER HEIGHT AND CLEARANCE BY MEASURING AGAINST ADJACENT FENDERS, AND SECURE WITH NEW MOUNTING HARDWARE. CONFIRM PROPER FITMENT AND CLEARANCE FROM TIRE.

QTY	ITEM	VMRS	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 00-00		MISC REPAIR		247.50
1	MIN-10001870		PM2261B BLACK FENDER	473.94	473.94

**TOTAL JOB #4 00-00 721.44**

**JOB #5 00-00 SC MISC REPAIR**

**CONCERN** DIAGNOSE AND REPAIR REASON FOR #3 RIGHT MUDFLAP MISSING  
**ROOT CAUSE** MISSING  
**CORRECTION** INSTALL NEW MUDFLAP WITH NEW REFLECTIVE TAPE ON BOTH SIDES.

QTY	ITEM	VMRS	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 00-00		MISC REPAIR		82.50
1	BTS RT25	BTS-RT25	STRIP-CONSPICUITY,STRAIGHT,PAI	51.39	51.39





**Warner Industries Saskatoon**  
**3002 FAITHFULL AVE SASKATOON, SK S7K 0B1**

TEL: (306) 931-4448  
 FAX: (306) 933-0411  
 TOLL FREE: (800) 667-6860  
 (IN SASKATCHEWAN)

*Fun Friendly People*  
 G.S.T. Registration Number 105704464RT0001  
 P.S.T. Registration Number 0898122

**SERVICE INVOICE: R800016319:01**

**BILL TO**  
**\*\*CASH ONLY\*\*ABS EXCAVATING LTD**  
 4018 ARONEC AVENUE  
 SASKATOON SK S7P OE1  
 P: (306) 249-0383

**DELIVER TO**  
**\*\*CASH ONLY\*\*ABS EXCAVATING LTD**  
 4018 ARONEC AVENUE  
 SASKATOON SK S7P OE1  
 P: (306) 249-0383

ENGINE HOURS 0

DATE PROMISED	DATE INVOICE	SALES TYPE	ADVISOR	TERMS	CUSTOMER REFERENCE			
2026-03-03 12:18:49PM	3/23/2026	SC	RJ	VISA	006			
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	CAB CARD	IN SERVICE	ODOMETER IN	ODOMETER OUT
2024	SDI	TRI SIDE DUMP	1S9DS4437RS819006				1	1

**Sold Operations (Cont.)**

**CONCERN** SUBLET TO REPLACE #1 LEFT TIRE /#3 RIGHT TIRE TREAD DIFF TOO LARGE NEED TO REPLACE - WORN OUT  
 FAILED ON SAFETY  
**ROOT CAUSE** WORN AND UNEVEN TREAD.  
**CORRECTION** SUBLET FOR TIRE REPLACEMENT.

QTY	ITEM	VMRS	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	PBOYZ		PRAIRIE BOYZ TIRE AND REPAIR		

**JOB #10 00-00 SC MISC REPAIR**  
**CONCERN** SUBLET TO SEND UNIT FOR ALINGMENT  
**ROOT CAUSE** SUSPENSION BUSHING REPLACEMENT.  
**CORRECTION** SUBLET FOR ALIGNMENT.

QTY	ITEM	VMRS	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	A-LINE		A-LINE FRAME & ALIGNMENT	866.20	866.20

**TOTAL JOB #10 00-00 866.20**



**Warner Industries Saskatoon**  
**3002 FAITHFULL AVE SASKATOON, SK S7K 0B1**

TEL: (306) 931-4448  
 FAX: (306) 933-0411  
 TOLL FREE: (800) 667-6860  
 (IN SASKATCHEWAN)

*Fun Friendly People*  
 G.S.T. Registration Number 105704464RT0001  
 P.S.T. Registration Number 0898122

**SERVICE INVOICE: R800016319:01**

BILL TO  
**\*\*CASH ONLY\*\*ABS EXCAVATING LTD**  
 4018 ARONEC AVENUE  
 SASKATOON SK S7P OE1  
 P: (306) 249-0383

DELIVER TO  
**\*\*CASH ONLY\*\*ABS EXCAVATING LTD**  
 4018 ARONEC AVENUE  
 SASKATOON SK S7P OE1  
 P: (306) 249-0383

DATE PROMISED		DATE INVOICE	SALES TYPE	ENGINE HOURS	ADVISOR	TERMS	CUSTOMER REFERENCE		
2026-03-03 12:18:49PM		3/23/2026	SC	0	RJ	VISA	006		
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	CAB CARD	IN SERVICE	ODOMETER IN	ODOMETER OUT	
2024	SDI	TRI SIDE DUMP	1S9DS4437RS819006				1	1	

**Estimate is valid for thirty (30) days from date of the estimate.**

At Warner Industries we are dedicated to providing elite service and products for our Customers. One of the ways we do this is by ensuring every unit has been quality inspected by a member of our service leadership team before leaving our shop -- including this one! But if the unit is not up to your standard, please ask to speak with our Service Manager. We appreciate your business and look forward to helping you in the future.

**PLEASE NOTE**

MISC CHARGES	80.00
PARTS	1,350.75
LABOR	3,690.00
SUBLET	866.20
PREPAY	0.00
SHOP SUPPLIES	369.00
DIAGNOSTICS	0.00
PST	381.36
GST	317.80
<b>TOTAL</b>	<b>7,055.11</b>

RECEIVED BY: \_\_\_\_\_

PRINT NAME OF SIGNER: \_\_\_\_\_

DATE: \_\_\_\_\_

Thank you for your business