



Warner Industries Saskatoon
3002 FAITHFULL AVE SASKATOON, SK S7K 0B1

TEL: (306) 931-4448
 FAX: (306) 933-0411
 TOLL FREE: (800) 667-6860
 (IN SASKATCHEWAN)

Fun Friendly People
 G.S.T. Registration Number 105704464RT0001
 P.S.T. Registration Number 0898122

SERVICE INVOICE: R800016501:01

*537-4
MAY*

BILL TO
****CASH ONLY**ABS EXCAVATING LTD - 35119**
 4018 ARONEC AVENUE
 SASKATOON SK S7P 0E1
 P: (306) 249-0383

DELIVER TO
****CASH ONLY**ABS EXCAVATING LTD - 35119**
 4018 ARONEC AVENUE
 SASKATOON SK S7P 0E1
 P: (306) 249-0383

ENGINE HOURS 0

DATE PROMISED	DATE INVOICE	SALES TYPE	ADVISOR	TERMS	CUSTOMER REFERENCE			
3/25/2026 8:02:04AM	3/31/2026	SC	C. DAY	VISA	SIDE DUMP			
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	CAB CARD	IN SERVICE	ODOMETER IN	ODOMETER OUT
2024	SDI	TRI SIDE DUMP	1S9DS4439RS819007				1	1

Sold Operations

JOB #1 SGI-TL3 SC SGI SAFETY TRI AXLE TRAILER (12 MO)
 CONCERN SGI SAFETY TRI AXLE TRAILER (12 MO)
 ROOT CAUSE SCHEDULED INSPECTION
 CORRECTION PERFORM TRI AXLE TRAILER SAFETY INSPECTION

QTY	ITEM	VMRS	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	SGID		SGI SAFETY DECAL	20.00	20.00
	LABOR SGI-TL3		SGI SAFETY TRI AXLE TRAILER (12 MO)		225.00
TOTAL JOB #1 SGI-TL3					245.00

JOB #4 00-00 SC MISC REPAIR
 CONCERN DIAGNOSE AND ADVISE REASON ABS LIGHT NOT WORKING
 ROOT CAUSE ABS WIRING HARNESS DISCONNECTED
 CORRECTION ABS LIGHT NOT ILLUMINATING. REMOVE LIGHT: FOUND UNPLUGGED AND NOT ENOUGH CABLE TO REACH. RELEASE HARNESS AND ADD LENGTH TO ABS WIRING. REINSTALL LIGHT AND RESECURE HARNESS. CHECKED FOR CODES. NO CODES ACTIVE.

QTY	ITEM	VMRS	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 00-00		MISC REPAIR		82.50
TOTAL JOB #4 00-00					82.50

JOB #5 00-00 SC MISC REPAIR
 CONCERN DIAGNOSE AND ADVISE REASON #1 LEFT AIR BAG NUT LOOSE
 NO CHARGE
 ROOT CAUSE AIR BAG BOLT LOOSE
 CORRECTION SECURE AIR BAG BOLT AT THE BOTTOM OF THE AIRBAG.

QTY	ITEM	VMRS	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 00-00		MISC REPAIR		0.00
TOTAL JOB #5 00-00					0.00

JOB #6 00-00 SC MISC REPAIR
 CONCERN REPLACE ALL DRUMS AND BRAKES WITH NEW DRUMS AND REMAN BRAKES AS PER CUSTOMER
 ROOT CAUSE WORN BRAKE COMPONENTS



Warner Industries Saskatoon
3002 FAITHFULL AVE SASKATOON, SK S7K 0B1

TEL: (306) 931-4448
 FAX: (306) 933-0411
 TOLL FREE: (800) 667-6860
 (IN SASKATCHEWAN)

Fun Friendly People
 G.S.T. Registration Number 105704464RT0001
 P.S.T. Registration Number 0898122

SERVICE INVOICE: R800016501:01

BILL TO
****CASH ONLY**ABS EXCAVATING LTD - 35119**
 4018 ARONEC AVENUE
 SASKATOON SK S7P 0E1
 P: (306) 249-0383

DELIVER TO
****CASH ONLY**ABS EXCAVATING LTD - 35119**
 4018 ARONEC AVENUE
 SASKATOON SK S7P 0E1
 P: (306) 249-0383

ENGINE HOURS 0

DATE PROMISED	DATE INVOICE	SALES TYPE	ADVISOR	TERMS	CUSTOMER REFERENCE			
3/25/2026 8:02:04AM	3/31/2026	SC	C. DAY	VISA	SIDE DUMP			
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	CAB CARD	IN SERVICE	ODOMETER IN	ODOMETER OUT
2024	SDI	TRI SIDE DUMP	1S9DS4439RS819007				1	1

Sold Operations (Cont.)

CORRECTION PERFORM BRAKE INSPECTION. MEASUREMENTS SHOWING UNEVEN BRAKE LINING AND DRUM WEAR ACROSS ALL SIX WHEEL POSITIONS, WITH SEVERAL COMPONENTS AT OR BEYOND SERVICE LIMITS. DURING DISASSEMBLY, FOUND MULTIPLE SEIZED COMPONENTS, FURTHER INSPECTION FOUND WORN S-CAM BUSHINGS. REMOVE AND REPLACE ALL BRAKE SHOES, DRUMS, AND ASSOCIATED HARDWARE. DURING TEARDOWN, ADDRESSED SEIZED COMPONENTS, REQUIRING ADDITIONAL TIME FOR REMOVAL AND CLEANING OF MOUNTING SURFACES TO ENSURE PROPER FITMENT OF NEW PARTS. REPLACE S-CAM BUSHINGS AT ALL LOCATIONS TO RESTORE PROPER CAMSHAFT OPERATION AND PREVENT UNEVEN BRAKE APPLICATION. REPLACE ALL WHEEL SEALS. REPACK BEARINGS AND REASSEMBLE ALL BRAKE ASSEMBLIES USING NEW COMPONENTS, ADJUST BRAKES TO SPEC AND VERIFY OPERATION.

QTY	ITEM	VMRS	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 00-00		MISC REPAIR		2,970.00
1	112.1201		Camshaft Bushing	13.86	13.86
1	23-13929-002		ELB-90,3/8 PTC X 3/8 STEM	4.98	4.98
6	ABP 10045888	ABP-10045888	SEAL SERVICE KIT TN TRAILER	52.38	314.28
6	ABP MK4707Q 23STAN		BRAKE SHOE KIT *D	97.23	583.38
-6	ABP MK4707Q 23STAN-CORE		BRAKE SHOE KIT *D	46.00	-276.00
6	ABP MK4707Q 23STAN-CORE		BRAKE SHOE KIT *D	46.00	276.00
5	SLL 550075629	SLL-550027558	GADUS GREASE S3 V220C 0.4KG *D	6.61	33.05
6	STM 330 3009	STM-330-3009	HUB CAP GASKET *D	3.72	22.32
6	STM 330 3118	STM-330-3118	GASKET-HUB CAP,6 HOLE *D	4.18	25.08
12	TDA 1205Q2123		SEAL	3.51	42.12
4	TDA 1229B1848	TDA-1229B1848	WASHER *D	0.69	2.76
14	TDA 1229R122	TDA-1229R122	WASHER	1.09	15.26
1	TDA 1229X1116	TDA-1229X1116	WASHER	0.53	0.53
6	TDA 19X1116	TDA-19X1116	CLEVIS PIN, LARGE, .50 IN. *D	2.65	15.90
6	TDA 19X127	TDA-19X127	CLEVIS PIN, SMALL, .25 IN., *D	1.45	8.70
6	TDA A2 3105G1151	TDA-A2-3105G1151	CAMSHAFT BUSHING ASSEMBLY *D	20.85	125.10
6	WID 39BD22BW		DRUM 16.5 X 7 10 HOLE *D	140.87	845.22
5	E6080		CAM BUSHING	16.87	84.35
1	FRT		FREIGHT	15.00	15.00

TOTAL JOB #6 00-00 5,121.89

JOB #7 00-00 SC MISC REPAIR

CONCERN SUBLET TO REPLACE 3 TIRES - FAILED SAFETY INSPECTION
ROOT CAUSE SUBLET TO REPLACE 3 TIRES - FAILED SAFETY INSPECTION
CORRECTION SUBLET TO REPLACE 3 TIRES - FAILED SAFETY INSPECTION

QTY	ITEM	VMRS	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 00-00		MISC REPAIR		0.00
1	PBOYZ		PRAIRIE BOYZ TIRE AND REPAIR	1,316.25	1,316.25

TOTAL JOB #7 00-00 1,316.25



Warner Industries Saskatoon
3002 FAITHFULL AVE SASKATOON, SK S7K 0B1

TEL: (306) 931-4448
 FAX: (306) 933-0411
 TOLL FREE: (800) 667-6860
 (IN SASKATCHEWAN)

Fun Friendly People
 G.S.T. Registration Number 105704464RT0001
 P.S.T. Registration Number 0898122

SERVICE INVOICE: R800016501:01

BILL TO
 CASH ONLY ABS EXCAVATING LTD - 35119
 4018 ARONEC AVENUE
 SASKATOON SK S7P 0E1
 P: (306) 249-0383

DELIVER TO
 CASH ONLY ABS EXCAVATING LTD - 35119
 4018 ARONEC AVENUE
 SASKATOON SK S7P OE1
 P: (306) 249-0383

ENGINE HOURS 0

DATE PROMISED	DATE INVOICE	SALES TYPE	ADVISOR	TERMS	CUSTOMER REFERENCE			
3/25/2026 8:02:04AM	3/31/2026	SC	C. DAY	VISA	SIDE DUMP			
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	CAB CARD	IN SERVICE	ODOMETER IN	ODOMETER OUT
2024	SDI	TRI SIDE DUMP	1S9DS4439RS819007				1	1

Sold Operations (Cont.)

JOB #8 00-00 SC MISC REPAIR

CONCERN REPAIR REASON FOR TORN MUDFLAP
 ROOT CAUSE MUDFLAP MISSING
 CORRECTION INSPECT TRAILER MUDFLAPS AND FOUND MUDFLAP MISSING. INSTALL NEW FLAP AND REFLECTOR BRACKET, MEASURED L/H SIDE FLAP, CUT NEW FLAP TO SIZE, CUT AND DRILLED HOLES IN A SECTION OF ALUMINUM FOR A BACK PLATE FOR STRENGTH, MOUNTED FLAP, BACK PLATE AND REFLECTOR, TIGHTENED DOWN HARDWEAR.

QTY	ITEM	VMRS	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 00-00		MISC REPAIR		330.00
1	BTS RT25	BTS-RT25	STRIP-CONSPICUITY,STRAIGHT,PAIR	51.39	51.39
1	PHW PLAIN24X30FLAP	RPT-242730	POMAR MUDFLAP PLAIN 24X30	26.56	26.56

TOTAL JOB #8 00-00 407.95

JOB #9 00-00 SC MISC REPAIR

CONCERN REPAIR REASON FOR #2 LEFT BRAKE POT AREA LEAKING
 ROOT CAUSE #2 LEFT BRAKE POT FITTING LEAKING
 CORRECTION FOUND #2 LEFT BRAKE POT AIR FITTING LEAKING. REMOVE OLD LEAKING PUSH CONNECT FITTING, APPLY ANTI SEIZE TO THREADS OF NEW FITTING AND INSTALL UNTIL FULLY TIGHT, CONNECT AIRLINE AND TIGHT FITTING. AIR UP UNIT TO CHECK FOR LEAKS AND CONFIRMED NO LEAKS SECURE HOSES

QTY	ITEM	VMRS	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 00-00		MISC REPAIR		148.50
1	1474-8C	1474-8C	AirBrake 45Elb;1/2x3/8 MPT	6.65	6.65

TOTAL JOB #9 00-00 155.15

JOB #10 00-00 SC MISC REPAIR

CONCERN DIAGNOSE AND ADVISE REASON FOR RIGHT REAR SIDE MARKER OUT
 DIAGNOSE AND ADVISE REASON FOR REAR CENTER MARKER 2 OF 2 NOT WORKING
 DIAGNOSE AND ADVISE REASON LICENSE PLATE OUT
 DIAGNOSE AND ADVISE REASON LEFT TURN SIGNAL MIDSHIP AND REAR NOT WORKING
 ROOT CAUSE MISC LIGHTS OUT
 CORRECTION REPLACE ALL LIGHTS: RIGHT REAR SIDE MARKER, REAR CENTER MARKER, LIC PLATE LIGHT AND LEFT TURN SIGNAL (MIDSHIP AND REAR) - ENSURE ALL LIGHTS WORKING

QTY	ITEM	VMRS	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 00-00		MISC REPAIR		198.00
2	GRO 67050	GRO-67050	PIGTAIL-SEALED MARKER LAMP, *D	1.71	3.42
8	GRO 83 3350		CONNECTOR 16-14GA *D	1.05	8.40
1	GRO G1502	GRO-G1502	LED MARKER LAMP RED *D	8.42	8.42
1	TL 15200C	TL-15200C	LAMP-MODEL 15,CLEAR 12v *D	4.91	4.91
2	TL 33050R	TL-33050R	LAMP-MARKER/CLEARANCE,LED,R *D	16.50	33.00

TOTAL JOB #10 00-00 256.15



Warner Industries Saskatoon
3002 FAITHFULL AVE SASKATOON, SK S7K 0B1

TEL: (306) 931-4448
 FAX: (306) 933-0411
 TOLL FREE: (800) 667-6860
 (IN SASKATCHEWAN)

Fun Friendly People
 G.S.T. Registration Number 105704464RT0001
 P.S.T. Registration Number 0898122

SERVICE INVOICE: R800016501:01

BILL TO
****CASH ONLY**ABS EXCAVATING LTD - 35119**
 4018 ARONEC AVENUE
 SASKATOON SK S7P 0E1
 P: (306) 249-0383

DELIVER TO
****CASH ONLY**ABS EXCAVATING LTD - 35119**
 4018 ARONEC AVENUE
 SASKATOON SK S7P 0E1
 P: (306) 249-0383

DATE PROMISED		DATE INVOICE		SALES TYPE	ENGINE HOURS	ADVISOR	TERMS	CUSTOMER REFERENCE	
3/25/2026 8:02:04AM		3/31/2026		SC	0	C. DAY	VISA	SIDE DUMP	
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	CAB CARD	IN SERVICE	ODOMETER IN	ODOMETER OUT	
2024	SDI	TRI SIDE DUMP	1S9DS4439RS819007				1	1	

Estimate is valid for thirty (30) days from date of the estimate.

At Warner Industries we are dedicated to providing elite service and products for our Customers. One of the ways we do this is by ensuring every unit has been quality inspected by a member of our service leadership team before leaving our shop -- including this one! But if the unit is not up to your standard, please ask to speak with our Service Manager. We appreciate your business and look forward to helping you in the future.

PLEASE NOTE

MISC CHARGES	35.00
PARTS	2,279.64
LABOR	3,954.00
SUBLET	1,316.25
PREPAY	0.00
SHOP SUPPLIES	395.40
DIAGNOSTICS	0.00
PST	478.82
GST	399.01
TOTAL	8,858.12

RECEIVED BY: _____

PRINT NAME OF SIGNER: _____

DATE: _____

Thank you for your business