

S37-8
MAY

Sevenwest HD Mechanics and Welding Ltd.

Box 91
Harris SK S0L1K0
hewitt.r@icloud.com

INVOICE

SP...
Abs Ltd.
Saskatoon

1005
23/05/2025
Due on receipt
23/05/2025

SERVICE	DESCRIPTION	TAX	QTY	RATE	AMOUNT
Sales	May 13 freightliner ecm repair, trench packer, 380 quick attach leaks martensville 8.5 May 14 120 packer service/hood, troubleshoot dozer codes 7 May 15 trench packer battery/wiring repair, slip tank assembly, jack hammer hose install 4 May 16 slip tank, gather service kits, oil May 20 2000hr service 380 Hyundai May 21 komatsu loader, Brandt trailer	GST/PST SK	23	135.00	3,105.00
Sales		GST/PST SK	6	55.00	330.00
Sales	Install 2 mack side dump kits on may 19 (long weekend)	GST/PST SK	2	1,500.00	3,000.00
Sales	Service truck payment	Exempt	1	-2,000.00	-2,000.00

SUBTOTAL	4,435.00
GST @ 5%	321.75
PST (SK) @ 6%	386.10
TOTAL	5,142.85

\$5,142.85

BALANCE DUE

TAX SUMMARY

RATE	TAX	NET
GST @ 5%	321.75	6,435.00
PST (SK) @ 6%	386.10	6,435.00

- HT15 - Freightliner
- Bomag trench packer
- E52 - Hyundai 380
- P101 - 120 packer
- D41 - Komatsu dozer
- L72 - Komatsu loader

Sevenwest HD Mechanics and Welding Ltd.

Box 91
 Harris SK S0L1K0
 hewitt_r@icloud.com

INVOICE

Abs Excavating Ltd.
 Saskatoon

1013
 13/06/2025
 Due on receipt
 13/06/2025

SERVICE	DESCRIPTION	TAX	QTY	RATE	AMOUNT
Sales	June 12 - deck truck hydraulic line replacement, engine oil leak, exhaust replacement. 8 June 13 - pc 240 1000hr service (3064hrs) 4 Hc 70 packer 500 hr service 2 June 14 - diagnose brakes sticking on trailer with service truck, replace and re wire faulty brake controller, repair signal wire on trailer 4 June 15 - 755c crawler, weld d rings and remove and replace bucket teeth, weld corner bits solid as requested to bucket. 5 June 16 - travel to wapella, repair main hydraulic line leak on 360 excavator stuck in swamp, 500hr service/blow out rads, diagnose 4wd tractor ac problem -15 June 18- 240 komatsu prep for drill attachment, repair cab switches, diagnose 2 way radio not working, inspect drill head, inspect flat deck freightliner broken leaf spring/ source used spring. - 7 June 19 - hr 70 packer out of fuel/no start - 2 June 20 - diagnose repair ht463 trailer would not dump, squealing noises 3 crusher adjustments and repairs 3 June 23 - packer repairs, torch out freightliner springs.4 June 24 - crusher wear plate repair, cut out stuck rebar in chamber, 755c diagnose no hydraulic oil/noise complaint - found major hydraulic leak in chassis. 6	GST/PST SK	63	135.00	8,505.00
Sales	June 14 - source d rings and teeth/pins for 755 crawler , source and pick up service kit for 450 John Deere excavator, 360 o ring kit, source jd 8630 parts and troubleshoot disassembly over the phone. June 19 - source Mack filters x3 trucks, June 23 - Mack service, freightliner leaf spring repair - 8 June 24 - re torque bolts on freightliner suspension, repair/weld crossmember on Mack, 4	GST/PST SK	20	55.00	1,100.00

- HT15 - freightliner flat deck
- Komatsu 240 excavator
- P102 - hyundai HC70 packer
- CL1 - crawler loader - 755C
- Komatsu 360 excavator
- E51 - 450 JD excavator
- mack truck

Sevenwest HD Mechanics and Welding Ltd.

Box 91
Harris SK S0L1K0
hewitt r@icloud.com

INVOICE

Abs Excavating Ltd.
Saskatoon

1034
13/08/2025
Due on receipt
24/08/2025

SERVICE	DESCRIPTION	TAX	QTY	RATE	AMOUNT
Sales	Aug 13 - Crusher welding 6 Aug 14 - Mack unit 12 hydraulic leak repair on hoses, brake loose stuck stack adjuster on side dump, grease, adjust brakes and repair air leaks 5 Aug 18- repair kobelco excavator leak, weld broke. Step back on, diagnose thumb pin retainer bolt shearing. 7 Aug 19 - kobelco oil top up, boost packer, stacker hydraulic leak repair, loader hydraulic leak repair 3 Aug 20 - flip bars on crusher, cut out welded plates from chamber 6 Aug 21 - install packer scraper, install air filters on komatsu skidsteer, install pin on Silverado rental excavator, diagnose/scan engine light on freightliner deck truck. 7 Aug 22 - trailer tarp repair, 240 komatsu hydraulic leak, repair press for crusher 8	GST/PST SK	46	135.00	6,210.00
Sales	Service Truck payment	Exempt	-1	1,000.00	-1,000.00
					279.73
					335.68
					5,210.00
					\$5,210.00

TAX SUMMARY

	RATE	TAX	NET
	GST @ 5%	279.73	5,594.59
<ul style="list-style-type: none"> • HT12 - mack truck • HT15 - freightliner • side dump trailers • 240 komatsu excavator 	PST (SK) @ 6%	335.68	5,594.59

Sevenwest HD Mechanics and Welding Ltd.

Box 91
 Harris St, S0L 1K3
 hax1117@cloud.com

INVOICE

Aos Excavating Ltd
 Saskatoon

1041
 25/08/2025
 Due on receipt
 10/09/2025

SERVICE	DESCRIPTION	TAX	QTY	RATE	AMOUNT
Sales	Aug 25 Call to micro for loader and end up not dumping 2 Aug 27 crusher belt, inspect crawler loader for leaks, oil topped up 7 Aug 28 - arrange timing for crusher, setup for install 2.5 Aug 29 - crusher belt install and adjustments 4 Sept 3 - inspect 140h grader for leaks, found slow sweats from multiple hydraulic lines, top up hydraulic oil and transmission oil, Mack unit 13 service oil, fuel and air 180 semi - replace cap sensor, inspect leaks for repair 7 Sept 4 freightliner 180 service engine oil and filter, check diffs, change serpentine belt 4.5 Sept 6 repair side dump lamp tube inspect freightliner 180 for squeak on belt, air compressor making noise, order parts 4 Sept 8 repair unit 464 on roadside, replace pnb module and batteries, repair skidsteer leak on boom, inspect trench packer for wiring issues 7 Sept 9 freightliner no start roadside, repair broken fender and brackets on side dump unit 464 3	GST/PST SK	41	135.00	5,535.00
Sales	Aug 26 - gather crusher service kit, Mack service kit and organize crusher warranty paperwork, 6 Aug 27 ck 30 parts, pd 240 warranty booking, oil sample paperwork, delivery 2 Sept 2 pick up, fill bills for 140h grader 2	GST/PST SK	10	55.00	550.00
Loan Payment	Finance Repayment	Out of Scope	1	-1,000.00	-1,000.00

- GR 61- 140H Grader 5,085.00
- HT13- mack truck 304.25
- HT15- freightliner flatdeck 365.10
- Side dump trailer 5,754.35
- HT 464 western star **\$5,754.35**

Sevenwest HD Mechanics and Welding Ltd.

Box 91
 Harris SK S0L1K0
 hewitt.r@icloud.com

INVOICE

Abs Excavating Ltd.
 Saskatoon

1052
 24/09/2025
 Due on receipt
 24/09/2025

SERVICE	DESCRIPTION	TAX	QTY	RATE	AMOUNT
Sales	Sept 10 - repair remote wiring and main harness on bomag walk behind packer. 7 Sept 11 - remove guards to blow out crawler rads, replace air filters, inspect leaks, in engine bay, 4 Sept 12 - fl80 roadside wiring repair in delisle, 500hr service on 380 Hyundai at whitecap 7 Sept 15 - ht 464 fuel and oil service, ht11 fuel and oil service, inspect ht 12 for noise at shutdown - crankcase spinner needs replaced. 5 Sept 16 - flip crusher bars, weld in plates for asphalt, inspect crawler loader for complaint of not driving, pick up crankcase filter for ht 12. 6 Sept 18 - remove crusher plates, repair press for crusher bars, inspect stacker, gather service kits/oil 4 Sept 19 - (lafarge site)change komatsu loader cabin and air filter, change cabin and engine air filters, change damaged side panel on 240 komatsu, 500 hour service on crusher, 500 hour service on stacker remove hydraulic lines on stacker for new ones. 9 Sept 22 - no start/no power to cab on Mack ht 13 diagnose and repair wiring issue, straighten brackets and install bumper on ht 11, install crankcase filter and vent hose on ht 11, inspect ht 11 radio not working and tires, book for new tires, send in oil samples with paperwork for crusher 7	GST/PST SK	49	135.00	6,615.00
Loan Payment	Finance Repayment	Out of Scope	1	-1,000.00	-1,000.00

◦ Bomag packer	◦ 240 Komatsu excavator	5,615.00
◦ CL1- crawler loader	◦ HT13 Mack	330.75
◦ HT15- freightliner	PST 396.90	396.90
◦ E52 - hyundai 380 excavator	TOTAL	6,342.65
◦ HT464 western star	BALANCE DUE	\$6,342.65
◦ HT11 mack		
◦ HT12 mack		

Sevenwest HD Mechanics and Welding Ltd.

Box 91
 Harris SK S0L1K0
 hewitt_r@icloud.com

INVOICE

Abs Excavating Ltd.
 Saskatoon

492644
 10/02/2026
 Due on receipt
 10/02/2026

SERVICE	DESCRIPTION	TAX	QTY	RATE	AMOUNT
Sales	Jan 23 - crusher repairs, t62 air seat repairs Jan 28 - 2 side dump trailer tarp and hydraulic line repair. Install new tarps repair bars, make up and install hydraulic lines for front and rear cylinders. Crusher repairs, install weld in plates in hopper for asphalt crushing, remove broken bolts from wear plates inside chamber 10.5 Feb 4 - f150 starter, wiring and battery repair, weld broken brackets and replace seized bolts on Brandt tilt deck, t62 repairs 5 Feb 5 - f350 samsara removals, clean out/wash sold f350. Diagnose Brandt trailer brakes and wiring. 4 Feb 7 - ht 11 serviced @2301hrs, replace oil, fuel and engine air filter, cabin filter. 36l 5w40, repair light, inspect tarp 3 Freightliner deck truck, diagnose and repair deck lighting. temporary fix to go to work, advise to re wire rear of truck 4.5 (7)	GST/PST SK	33.50	145.00	4,857.50
loan re payment	Service truck	Out of Scope		-2,000.00	-2,000.00

• T62 bobcat skidsteer					2,857.50
• side dump trailers					242.88
• HT11 - Mack					291.45
• HT15 - Freightliner					3,391.83
BALANCE DUE					\$3,391.83

TAX SUMMARY

RATE	TAX	NET
GST @ 5%	242.88	4,857.50
PST (SK) @ 6%	291.45	4,857.50

Sevenwest HD Mechanics and Welding Ltd.

Box 91
 Harris SK S0L1P0
 email: r@sevenwest.com
 PST SK Registration No. 7556770

INVOICE

Abs Excavating Ltd
 Saskatoon

492686
 11/03/2026
 Due on receipt
 11/03/2026

SERVICE	DESCRIPTION	TAX	QTY	RATE	AMOUNT
Sales	Mobile mechanic for side dump repairs Torch seized bearings on tarp arms. straighten brackets Driver complaint of Freightliner deck truck not charging, test alternator and batteries for working order. Faulty reading coming from ecu wiring. truck still charging.	GST/PST SK	3	145.00	435.00
Sales	Organize safety repairs, parts. Source/ Pick up parts for Mack truck front end damage Source 1000hr service kit for komatsu dozer	GST/PST SK	3	50.00	150.00
					585.00
					29.25
					35.10
					649.35
					\$649.35

TAX SUMMARY

RATE	TAX	NET
GST @ 5%	29.25	585.00
PST (SK) @ 6%	35.10	585.00

** side dump trailer
 • HT15 - Freightliner*