

# Edwards

## Garage Limited

Box 880 · Rocky Mountain House, Alberta · T4T 1A6  
 Telephone: (403)845-3328 · Fax: (403)845-4661  
 GST #101584076

SCANNED

FILE COPY

INVOICE ORIGINAL

Work Order  
 #432557

Skocdopole Construction Ltd  
 February 24, 2026  
 Svc. Adv Carswell, Karissa  
 Cust. Ph. (403) 746-5744  
 Tag# 2557

Page 1 of 2  
 03/02/2026 11:47:10

X42-1  
 MAY

<b>To: Skocdopole Construction Ltd</b>  <b>RR 4</b>  <b>Eckville AB</b> <b>TOM 0X0</b>  <i>20-01</i>	<b>Year:</b> 2020 <b>Veh Id:</b> 71978 <b>Unit #:</b> SKOC20-01 <b>Make:</b> GMC <b>License #:</b> CGR-4181 <b>Model:</b> 3500 Sierra 4WD Crew Cab <b>Odo. In:</b> 224,707 <b>Colour:</b> G7C Cardinal Red <b>Odo. Out:</b> 224,707 <b>V.I.N.#:</b> 1GT49SEY0LF310684 <b>Next Service:</b> 3/2/2026 <b>Date In:</b> 02/24/2026 <b>In Service Date:</b> 09/30/2020 <b>Out:</b> 02/24/2026 <b>Cases:</b> 1 <b>Ext. War - - ( mo/ ) - D:</b> \$0.00 <b>Promised Time:</b> 00/00/0000 00:00:00 AM <b>Call When Ready:</b> Yes
---	---

**Case: 1** HVAC vehicle has no heat in the cab, suspect blower motor issue - Remove & Replace BLOWER MOTOR ASSEMBLY

Quantity	Description/Correction	Retail	Price	Total
1.00	84861776 - Motor	\$325.88	\$325.88	\$325.88
			\$119.00	\$119.00
	• Tech Cause: blower motor			
	• Tech Comments: preformed checks found power and ground at blower motor and resistor need blower motor replaced blower motor all ok now			
	• Completed by Technician number: 6742			
	• Miscellaneous		\$13.33	\$13.33
<b>Misc</b>	\$13.33	<b>Labour</b>	\$119.00	
		<b>Parts</b>	\$325.88	
		<b>Prepaid Parts Amt:</b>	\$0.00	
		<b>Case Total:</b>		\$458.21
				\$0.00

O U T	Indebtedness is hereby acknowledged for the "Total Charges" being all or the balance owing to repairs, parts & accessories described in this work order. Interest will be charged at 2 % monthly / 24 % annually on overdue invoices.		Currency:	<b>Labour:</b>	\$119.00
	Privacy-Personal information is collected in accordance with applicable privacy legislation and is governed by EDWARDS GARAGE LIMITED Privacy Policy. Your privacy is important to us. Ask us if you would like information about EDWARDS GARAGE LIMITED Privacy Policy.			<b>Parts:</b>	\$325.88
	I agree to receive Edwards Garage newsletter containing news, updates and promotions regarding Edwards Garage products. You can withdraw your consent at anytime. I would like to unsubscribe from receiving:		<b>Payment Ref:</b> <b>Expiry Date:</b> P/O#: 20-01 G/HST Reg # R101584076	<b>Misc:</b>	\$13.33
	All messages from Edwards Garage. All promotional messages from Edwards.			<b>Sub Total:</b>	\$458.21
				<b>G/HST:</b>	\$22.91
				<b>PST:</b>	\$0.00
				<b>Tax Adjustment:</b>	\$0.00
02/24/2026 Date		Signature		<b>Payment Type Charge</b>	<b>Total:</b> \$481.12

# Edwards

## Garage Limited

Box 880 · Rocky Mountain House, Alberta · T4T 1A6  
Telephone: (403)845-3328 · Fax: (403)845-4661  
GST #101584076

INVOICE ORIGINAL  
Work Order  
#432557  
Skocdopole Construction Ltd  
February 24, 2026  
Svc.Adv Carswell, Karissa  
Cust.Ph. (403) 746-5744  
Tag# 2557  
Page 2 of 2  
03/02/2026 11:47:11

Payer	Payment Type	Reference	Date	
Skocdopole Construction Ltd	Charge		02/26/2026	\$481.12
			<b>Balance Owing:</b>	<b>\$0.00</b>

MAR - 3 2026

20-01  
50150-02

# Edwards

## Garage Limited

Box 880 · Rocky Mountain House, Alberta · T4T 1A6  
 Telephone: (403)845-3328 · Fax: (403)845-4661  
 GST #101584076

INVOICE ORIGINAL  
 Work Order  
 #429706

Skocdopole Construction Ltd  
 Dec  
 Svc. Adv Campeau, Daryl  
 Cust. Ph. (403) 746-5744  
 Tag# 9706

Page 1 of 2  
 12/31/2025 10:54:03

FILE COPY

<b>To: Skocdopole Construction Ltd</b>		Year: 2020	Veh Id: 71978	Unit #: SKOC20-01
<b>RR 4</b>		Make: GMC		License #: CGR-4181
<b>Eckville</b>	<b>AB</b>	Model: 3500 Sierra 4WD Crew Cab		Odo. In: 222,439
<b>TOM 0X0</b>		Colour: G7C Cardinal Red		Odo. Out: 222,439
		V.I.N.#: 1GT49SEY0LF310684		<b>Next Service: 12/31/2025</b>
		Date In: 12/20/2025		In Service Date: 09/30/2020
		Out: 12/30/2025		Cases: 3
		Ext. War - - ( mo/ ) - D: \$0.00		
		Promised Time: 00/00/0000 00:00:00 AM		Call When Ready: Yes

Case: 1 Check Engine Light (Check Engine Light On)

Quantity	Description/Correction	Price	Total
		\$51.00	\$51.00
	• Tech Cause: Check engine light		
	• Tech Comments: Performed code scan and found P2635 for fuel pump flow performance, checked code and found in-tank fuel pump is faulty. Quoted repairs		
	• Completed by Technician number: 6341		
	• Miscellaneous	\$5.71	\$5.71
Misc	\$5.71	Labour \$51.00	Parts \$0.00
	Prepaid Parts Amt: \$0.00	Case Total:	\$56.71

Case: 2 # N242454440 Momentary Rear Wheel Lock-Up -

Quantity	Description/Correction	Price	Total
		\$0.00	\$0.00
	• Tech Cause: Campaign		
	• Tech Comments: Warranty Claim Code: 11YN308981039, 18YN308982418. Performed transmission fast learn as per programming instructions - Warranty		
	• Completed by Technician number: 6341	\$0.00	\$0.00
Misc	\$0.00	Labour \$0.00	Parts \$0.00
	Prepaid Parts Amt: \$0.00	Case Total:	\$0.00

Case: 3 Added Operation: Remove & Replace FUEL PUMP Diesel In Tank, Fuel Pump Module, Main - Tech Cause: Fuel pump full of dirt - Tech Comments: Removed tank and replaced fuel pump, reinstalled tank. Test drove and no codes

Quantity	Description/Correction	Retail	Price	Total
1.00	86534329 - Module kit	\$506.69	\$506.69	\$506.69
			\$425.00	\$425.00
	• Tech Cause: Fuel pump full of dirt			
	• Tech Comments: Removed tank and replaced fuel pump, reinstalled tank. Test drove and no codes			

# Edwards

## Garage Limited

Box 880 · Rocky Mountain House, Alberta · T4T 1A6  
 Telephone: (403)845-3328 · Fax: (403)845-4661  
 GST #101584076

**INVOICE ORIGINAL**  
**Work Order**  
**#429706**  
 Skocdopole Construction Ltd  
 Dec:  
 Svc.Adv Campeau, Daryl  
 Cust.Ph. (403) 746-5744  
 Tag# 9706  
 Page 2 of 2  
 12/31/2025 10:54:04

- Completed by Technician number:  
6341
- Miscellaneous

Misc	\$47.60	Labour	\$425.00	Parts	\$506.69	Prepaid Parts Amt:	\$0.00	Case Total:	\$979.29
									\$0.00

O U T	<p>Indebtedness is hereby acknowledged for the "Total Charges" being all or the balance owing to repairs, parts &amp; accessories described in this work order. Interest will be charged at 2 % monthly / 24 % annually on overdue invoices.</p> <p>Privacy-Personal information is collected in accordance with applicable privacy legislation and is governed by EDWARDS GARAGE LIMITED Privacy Policy. Your privacy is important to us. Ask us if you would like information about EDWARDS GARAGE LIMITED Privacy Policy.</p> <p>_____I agree to receive Edwards Garage newsletter containing news, updates and promotions regarding Edwards Garage products. You can withdraw your consent at anytime. I would like to unsubscribe from receiving: _____</p> <p>_____All messages from Edwards Garage. _____All promotional messages from Edwards.</p>	<p>Currency:</p>	<p><b>Labour:</b> \$476.00</p> <p><b>Parts:</b> \$506.69</p> <p><b>Misc:</b> \$53.31</p> <p><b>Sub Total:</b> \$1,036.00</p> <p><b>G/HST:</b> \$51.80</p> <p><b>PST:</b> \$0.00</p> <p><b>Tax Adjustment:</b> \$0.00</p>
	<p><b>Payment Ref:</b></p> <p><b>Expiry Date:</b></p> <p><b>P/O#:</b></p> <p><b>G/HST Reg # R101584076</b></p>		
	<p>12/30/2025</p> <p>Date</p>	<p>Signature</p>	<p><b>Payment Type</b></p>
			<p><b>Total:</b> \$1,087.80</p>

Payer	Payment Type	Reference	Date	
Skocdopole Construction Ltd	Charge		12/30/2025	\$1,087.80
			<b>Balance Owing:</b>	\$0.00

# Edwards Garage Limited

Box 880 · Rocky Mountain House, Alberta · T4T 1A6  
 Telephone: (403)845-3328 · Fax: (403)845-4661  
 GST #101584076

**SCANNED**

**FILE COPY**

INVOICE ORIGINAL  
 Work Order  
**#410144**  
 Skocdopole Construction Ltd  
 November 14, 2024  
 Svc. Adv MacDougall, James  
 Cust. Ph. (403) 746-5744  
 Tag# 0144

Page 1 of 3  
 11/26/2024 09:56:49

<b>To: Skocdopole Construction Ltd</b>  <b>RR 4</b>  <b>Eckville AB</b> <b>TOM 0X0</b>	Year: 2020 Veh Id: 71978 Unit #: SKOC20-01 Make: GMC License #: Model: 3500 Sierra 4WD Crew Cab Odo. In: 186,000 Colour: G7C Cardinal Red Odo. Out: 188,802 V.I.N.#: 1GT49SEY0LF310684 <b>Next Service: 11/26/2024</b> Date In: 11/14/2024 In Service Date: 09/30/2020 Out: 11/20/2024 Cases: 4 Ext. War - - ( mo/ ) - D: \$0.00 Promised Time: 00/00/0000 00:00:00 AM Call When Ready:
---	---

**Case: 1** TOW IN, Vehicle has been setting fuel pump control module codes again, customer has been checking and clearing. This truck has had the module and pump replaced in the past, customer suspects wiring issue

Quantity	Description/Correction	Retail	Price	Total
1.00	775014 - 1/4" Black Heat Shrink	\$2.75	\$2.75	\$2.75
1.00	775038 - 3/8" Black Heat Shrink	\$3.32	\$3.32	\$3.32
4.00	5555161 - Red Shrink Connector	\$2.59	\$2.59	\$10.34
20.00	23-1413PK - Tie Strap 8" Black	\$0.12	\$0.12	\$2.42
20.00	20GGR - 20ga. Green Wire	\$0.28	\$0.28	\$5.50
20.00	PIC5140B - 1/4 Wire Loom/ft.	\$1.11	\$1.11	\$22.22
			\$501.00	\$501.00

- Tech Cause: 1st punch , towed into shop .. checked codes .. has 4 codes .. p12a6 , p129f , u0100 , p0046 .. 2 have to do with fuel pump enable - module ckts .. checked farther .. lifted truck up and removed spare tire .. removed rear module plate asmb to access fpcm .. tested powers , grounds , enable ckts ect .. 2nd punch , checked feed fuses .. all ok .. 3rd punch , load tested powers and enable ... all ok .. tested farther .. 4th punch , tested to the point of a issue with ckt 465 [ never changed to malfunction when jumpered as per si ] .. removed lh front wheel and wheel well liner .. took connector x171 apart .. tested ckt between x171 and fpcm at pins 14 and 18 ... wire is open .. 5th punch , as per don .. started to run a new wire .. opened up harness on outside on x171 and fpcm ... used jumper between and tested after .. code is passed and truck runs now .. removed jumper .. ran new wire from x171 to fpcm .. ran new wire and conduited it .. zip tied up all the way down to rear .. tapped up and mounted connectors .. reinstalled fpcm and rear module tray mount .. started and ran engine ... runs now ... ses light is still on , with only p0046 code left for tb boost performance ... will need to diag tb boost code now .. 6th punch , checked actuator arm with key off .. its free and moves the hole way .. hooked up to sps and as per si doc # 5831016 , did the actuator learn set up ... ran truck after and commanded open and closed .. started to move , then quit and flagged the p0046 code again .. needs actuator replaced ... also noted soot mass is at 91 % right now , will need a regen after work done too ..
- Tech Comments: diaged no start , fixed no start , diaged p0046 tb boost performance after ..
- Completed by Technician number: 22
- Miscellaneous \$41.80 \$41.80

<b>Misc</b>	\$41.80	<b>Labour</b>	\$501.00	<b>Parts</b>	\$46.55	<b>Prepaid Parts Amt:</b>	\$0.00	<b>Case Total:</b>	\$589.35
-------------	---------	---------------	----------	--------------	---------	---------------------------	--------	--------------------	----------

# Edwards

## Garage Limited

Box 880 · Rocky Mountain House, Alberta · T4T 1A6  
 Telephone: (403)845-3328 · Fax: (403)845-4661  
 GST #101584076

**INVOICE ORIGINAL**  
**Work Order**  
**#410144**  
 Skocdopole Construction Ltd  
 November 14, 2024  
 Svc.Adv MacDougall, James  
 Cust.Ph. (403) 746-5744  
 Tag# 0144

Page 2 of 3  
 11/26/2024 09:56:50

Case: 2 # N242454440 Momentary Rear Wheel Lock-Up -

Quantity	Description/Correction	Price	Total
		\$0.00	\$0.00
	• Tech Cause: No remedy available		
	• Tech Comments: Correction not defined. - Internal		
		\$0.00	\$0.00
Misc	\$0.00	Labour \$0.00	Parts \$0.00
		Prepaid Parts Amt: \$0.00	Case Total: \$0.00

Case: 3 Added Operation: Remove & Replace VARIABLE GEOMETRY TURBOCHARGER ACTUATOR Diesel  
 Remove & Replace VARIABLE GEOMETRY TURBOCHARGER ACTUATOR TURBOCHARGER BOOST  
 PRESSURE - Reset Diesel Turbocharger Boost Control Initial Position Learn - Tech Cause: removed and  
 replaced t.b actuator .. cleared codes after .. ses light is off now .. - Tech Comments: replaced actuator

Quantity	Description/Correction	Retail	Price	Total
1.00	12707578 - ACTUATOR ASM-VAR GEOMETRY TURBO	\$1,440.03	\$1,440.03	\$1,440.03
			\$167.00	\$167.00
	• Tech Cause: removed and replaced t.b actuator .. cleared codes after .. ses light is off now ..			
	• Tech Comments: replaced actuator			
	• Completed by Technician number: 22			
	• Miscellaneous		\$13.93	\$13.93
Misc	\$13.93	Labour \$167.00	Parts \$1,440.03	Prepaid Parts Amt: \$0.00
			Case Total: \$1,620.96	

Case: 4 Added Operation: time to do a service regen after to clean soot out , 91 % SOOT MASS right now - Tech  
 Cause: warmed up truck to op temp .. took outside and commanded a service regen .. test drove after .. no ses  
 light - Tech Comments: did regen

Quantity	Description/Correction	Price	Total
		\$217.10	\$217.10
	• Tech Cause: warmed up truck to op temp .. took outside and commanded a service regen .. test drove after .. no ses light		
	• Tech Comments: did regen		
	• Completed by Technician number: 22		
	• Miscellaneous	\$18.12	\$18.12
Misc	\$18.12	Labour \$217.10	Parts \$0.00
		Prepaid Parts Amt: \$0.00	Case Total: \$235.22

\$0.00



**Garage Limited**

Box 880 · Rocky Mountain House, Alberta · T4T 1A6  
Telephone: (403)845-3328 · Fax: (403)845-4661  
GST #101584076

**INVOICE ORIGINAL**  
**Work Order**  
**#410144**  
**Skocdopole Construction Ltd**  
**November 14, 2024**  
**Svc.Adv MacDougall, James (**  
**Cust.Ph. (403) 746-5744**  
**Tag# 0144**

Page 3 of 3  
11/26/2024 09:56:50

O U T	indebtedness is hereby acknowledged for the "Total Charges" being all or the balance owing to repairs, parts & accessories described in this work order. Interest will be charged at 2 % monthly / 24 % annually on overdue invoices.		Currency:	<b>Labour:</b>	\$885.10
	Privacy-Personal information is collected in accordance with applicable privacy legislation and is governed by EDWARDS GARAGE LIMITED Privacy Policy. Your privacy is important to us. Ask us if you would like information about EDWARDS GARAGE LIMITED Privacy Policy.		<b>Payment Ref:</b>	<b>Parts:</b>	\$1,486.58
	I agree to receive Edwards Garage newsletter containing news, updates and promotions regarding Edwards Garage products. You can withdraw your consent at anytime. I would like to unsubscribe from receiving:		<b>Expiry Date:</b>	<b>Misc:</b>	\$73.85
	___All messages from Edwards Garage. ___All promotional messages from Edwards.		<b>P/O#:</b> GARY	<b>Sub Total:</b>	\$2,445.53
		<b>G/HST Reg #</b> R101584076	<b>G/HST:</b>	\$122.28	
			<b>PST:</b>	\$0.00	
			<b>Tax Adjustment:</b>	\$0.00	
11/20/2024					
Date	Signature	Payment Type	Total:	\$2,567.81	

Payer	Payment Type	Reference	Date	
Skocdopole Construction Ltd	Charge		11/25/2024	\$2,567.81
			<b>Balance Owing:</b>	\$0.00

Vehicle Service Report

**SCANNED**

Unit #: 20-01

Date: 06/12/2023

Mileage: 142202

Hours: \_\_\_\_\_

Grease  Yes  No

Fuel Filters Changed  Yes  No

Oil Changes  Yes  No

Air Filter Changed  Yes  No

Fluids	Good	Changed	Add	Amount
Main	/			
Aux.	/			
Diff Front	/			
Diff Rear	/			
Winch				
Steering Box				
Steering Reservoir	/			
Radiator	/			

Lights Checked  Yes  No

Tire Pressure Checked  Yes  No

Brakes Set Up  Yes  No

Add Coolant Condition  Yes  No

Add Windshield Washer Fluid  Yes  No

Oil Hubs  Yes  No

Batteries Checked  Yes  No

Belts Checked  Yes  No

Glass Checked  Yes  No

Tire Tread Checked  Yes  No

Fire Extinguisher Checked  Yes  No

First Aid Kit Checked  Yes  No

Emergency Flare Kit  Yes  No

Communication Test  Yes  No

Vehicle Interior Clean  Yes  No

Exterior Washed  Yes  No

Overall Condition of Vehicle:

wires rotated and torqued to 140 ft lbs

Major or Minor Repairs:

Technician: Lucas Parsons

Reviewed by: \_\_\_\_\_

# Edwards

## Garage Limited

Box 880 · Rocky Mountain House, Alberta · T4T 1A6  
 Telephone: (403)845-3328 · Fax: (403)845-4661  
 GST #101584076

INVOICE ORIGINAL  
**SCANNED**  
**FILE COPY**  
 Work Order #400519  
 Skocdopole Construction Ltd  
 May 03, 2024  
 Svc. Adv Rosenquist, Stephan  
 Cust. Ph. (403) 746-5744  
 Tag# 0519  
 Page 1 of 2  
 05/16/2024 14:56:55

<b>To: Skocdopole Construction Ltd</b>  <b>RR 4</b>  <b>Eckville AB</b> <b>TOM OXO</b>	Year: 2020 Veh Id:71978 Unit #:SKOC20-01 Make: GMC License #: Model: 3500 Sierra 4WD Crew Cab Odo. In: 171,864 Colour: G7C Cardinal Red Odo. Out: V.I.N.#: 1GT49SEY0LF310684 <b>Next Service: 5/16/2024</b> Date In: 05/03/2024 In Service Date: 09/30/2020 Out: 05/07/2024 Cases: 2 Ext. War - - ( mo/ ) - D: \$0.00 Promised Time: 00/00/0000 00:00:00 AM Call When Ready:
---	--

**Case: 1** Truck wouldn't start, has codes for the fuel pump control module. fuel pump has been replaced twice already at another dealer. , Engine/Propulsion

Quantity Description/Correction	Price	Total
<ul style="list-style-type: none"> <li>• Tech Cause: working normally</li> <li>• Tech Comments: Towed into shop and put on charger. Vehicle was so dead that window wouldn't roll down. After charging for a bit vehicle fired right up. Watched fuel pressure, everything is reading normally right now. Actual fuel pressure is right with desired.</li> <li>• Took for road test, watched rail pressure and low pressure fuel pressure, everything is working normally. vehicle starts normally every time. Suggest replacing both batteries. Quoted repair</li> <li>• Completed by Technician number: 08</li> </ul>	\$350.70	\$350.70

Misc	\$0.00	Labour	\$350.70	Parts	\$0.00	Prepaid Parts Amt:	\$0.00	<b>Case Total:</b>	<b>\$350.70</b>
------	--------	--------	----------	-------	--------	--------------------	--------	--------------------	-----------------

**Case: 2** Tow in, Tuesday appointment , Information Only

Quantity Description/Correction	Price	Total
<ul style="list-style-type: none"> <li>• Tow in, Tuesday appointment , Information Only• - Internal</li> </ul>	\$0.00	\$0.00

Misc	\$0.00	Labour	\$0.00	Parts	\$0.00	Prepaid Parts Amt:	\$0.00	<b>Case Total:</b>	<b>\$0.00</b>
------	--------	--------	--------	-------	--------	--------------------	--------	--------------------	---------------

\$0.00

# Edwards

## Garage Limited

Box 880 · Rocky Mountain House, Alberta · T4T 1A6  
 Telephone: (403)845-3328 · Fax: (403)845-4661  
 GST #101584076

**INVOICE ORIGINAL**  
**Work Order**  
**#400519**  
**Skocdopole Construction Ltd**  
**May 03, 2024**  
**Svc.Adv Rosenquist, Stephan**  
**Cust.Ph. (403) 746-5744**  
**Tag# 0519**

Page 2 of 2  
 05/16/2024 14:56:55

<p>Indebtedness is hereby acknowledged for the "Total Charges" being all or the balance owing to repairs, parts &amp; accessories described in this work order. Interest will be charged at 2 % monthly / 24 % annually on overdue invoices.</p> <p>Privacy-Personal information is collected in accordance with applicable privacy legislation and is governed by EDWARDS GARAGE LIMITED Privacy Policy. Your privacy is important to us. Ask us if you would like information about EDWARDS GARAGE LIMITED Privacy Policy.</p> <p><input type="checkbox"/> I agree to receive Edwards Garage newsletter containing news, updates and promotions regarding Edwards Garage products. You can withdraw your consent at anytime. I would like to unsubscribe from receiving:</p> <p><input type="checkbox"/> All messages from Edwards Garage. <input type="checkbox"/> All promotional messages from Edwards.</p>	<p>Currency:</p>	<p><b>Labour:</b> \$350.70  <b>Parts:</b> \$0.00  <b>Misc:</b> \$0.00  <b>Sub Total:</b> \$350.70  <b>G/HST:</b> \$17.54  <b>PST:</b> \$0.00  <b>Tax Adjustment:</b> \$0.00</p>
<p><b>O</b></p> <p><b>U</b></p> <p><b>T</b></p>	<p><b>Payment Ref:</b>  <b>Expiry Date:</b>  <b>P/O#: SKOC20-01</b>  <b>G/HST Reg # R101584076</b></p>	
<p>05/07/2024</p>	<p>_____</p>	<p><b>Payment Type</b> <span style="float:right"><b>Total: \$368.24</b></span></p>
<p>Date</p>	<p>Signature</p>	

Payer	Payment Type	Reference	Date	
Skocdopole Construction Ltd	Charge		05/16/2024	\$368.24
			<b>Balance Owing:</b>	<b>\$0.00</b>

# Edwards Garage Limited

Box 880 · Rocky Mountain House, Alberta · T4T 1A6  
 Telephone: (403)845-3328 · Fax: (403)845-4661  
 GST #101584076

**SCANNED**

**FILE COPY**

INVOICE ORIGINAL

Work Order

#401750

Skocdopole Construction Ltd

May 29, 2024

Svc. Adv Campeau, Daryl

Cust. Ph. (403) 746-5744

Tag# 1750

Page 1 of 2

05/30/2024 09:43:07

<b>To: Skocdopole Construction Ltd</b>  <b>RR 4</b>  <b>Eckville AB</b> <b>TOM OXO</b>	<b>Year:</b> 2020 <b>Veh Id:</b> 71978 <b>Unit #:</b> SKOC20-01 <b>Make:</b> GMC <b>License #:</b> <b>Model:</b> 3500 Sierra 4WD Crew Cab <b>Odo. In:</b> 173,736 <b>Colour:</b> G7C Cardinal Red <b>Odo. Out:</b> 173,740 <b>V.I.N.#:</b> 1GT49SEY0LF310684 <b>Next Service:</b> 5/30/2024 <b>Date In:</b> 05/29/2024 <b>In Service Date:</b> 09/30/2020 <b>Out:</b> 05/29/2024 <b>Cases:</b> 1 <b>Ext. War - - ( mo/ ) - D:</b> \$0.00 <b>Promised Time:</b> 00/00/0000 00:00:00 AM <b>Call When Ready:</b>
---	---

Case: 1 Install ignition tumbler.

Quantity	Description/Correction	Retail	Price	Total
1.00	13528553 - CYLINDER ASM-IGN LK (Extra Item)	\$232.44	\$232.44	\$232.44
			\$233.80	\$233.80
	• Tech Cause: cylinder binding up			
	• Tech Comments: **Flat rate 1.4hrs***			
	• Replaced ignition lock cylinder and checked operation, key and cylinder are working normally now			
	• Completed by Technician number: 08			
	• Miscellaneous		\$26.19	\$26.19
<b>Misc</b>	\$26.19	<b>Labour</b>	\$233.80	<b>Parts</b>
			\$232.44	<b>Prepaid Parts Amt:</b>
			\$0.00	<b>Case Total:</b>
				\$492.43
				\$0.00

<b>O U T</b>	Indebtedness is hereby acknowledged for the "Total Charges" being all or the balance owing to repairs, parts & accessories described in this work order. Interest will be charged at 2 % monthly / 24 % annually on overdue invoices.		Currency:		<b>Labour:</b> \$233.80
	Privacy-Personal information is collected in accordance with applicable privacy legislation and is governed by EDWARDS GARAGE LIMITED Privacy Policy. Your privacy is important to us. Ask us if you would like information about EDWARDS GARAGE LIMITED Privacy Policy.		<b>Payment Ref:</b>		<b>Parts:</b> \$232.44
	I agree to receive Edwards Garage newsletter containing news, updates and promotions regarding Edwards Garage products. You can withdraw your consent at anytime. I would like to unsubscribe from receiving:		<b>Expiry Date:</b>		<b>Misc:</b> \$26.19
	<input type="checkbox"/> All messages from Edwards Garage. <input type="checkbox"/> All promotional messages from Edwards.		<b>P/O#:</b> SKOC20-01		<b>Sub Total:</b> \$492.43
			<b>G/HST Reg #</b> R101584076		<b>G/HST:</b> \$24.62
					<b>PST:</b> \$0.00
					<b>Tax Adjustment:</b> \$0.00
05/29/2024 Date		Signature		<b>Payment Type Charge</b>	
				<b>Total:</b> \$517.05	

# Edwards

## Garage Limited

Box 880 · Rocky Mountain House, Alberta · T4T 1A6  
Telephone: (403)845-3328 · Fax: (403)845-4661  
GST #101584076

INVOICE ORIGINAL

Work Order

#401750

Skocdopole Construction Ltd

May 29, 2024

Svc.Adv Campeau, Daryl

Cust.Ph. (403) 746-5744

Tag# 1750

Page 2 of 2

05/30/2024 09:43:07

Payer	Payment Type	Reference	Date	
Skocdopole Construction Ltd	Charge		05/29/2024	\$517.05
			<b>Balance Owing:</b>	<b>\$0.00</b>

Customer Number!

Unit Number:

Invoice No: 781077

\*INVOICE\*



SKOCDOPOLE CONSTRUCTION

RR4  
ECKVILLE, AB TOM OXO

Home: Bus:

Email:

20-01

Page 1 of 2

Cell: 403-746-5744

FILE COPY

5 Galarneau Place  
St. Albert, AB T8N 2Y3  
PHONE (780) 458-7100  
Toll Free 1-855-458-7100  
www.ronhodgson.com

SERVICE ADVISOR \$700 ANDREW MINER

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
	20	GMC SIERRA 3500	1GT49SEY0LF310684	CGR4181	150288 / 150288	T9188	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
30SEP20			16:30 30AUG23			CASH	31AUG23
R.O. OPENED	READY	OPTIONS: DLR:82243 ENG:6.6_Liter_Turbo					
16:37 28AUG23	08:12 31AUG23						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CONCERN/ADVISE- INSPECT FOR CHECK ENGINE LIGHT ON. CUSTOMER NOTICED THAT THE VEHICLE WILL NOT RUN WELL AND WILL WILL TURN OFF AFTER VEHICLE IS RUNNING/DRIVING FOR A FEW MINUTES. PLEASE ADVISE.

CAUSE: Fuel pump failed.

4028730 FUEL TANK FUEL PUMP MODULE REPLACEMENT

9 W4

(N/C)

1 85557026 MODULE KI

(N/C)

DIAG ALLOWABLE DIAGNOSIS TIME

9 W4

(N/C)

FC: 6579

PART#: 85557026

COUNT: 1

CLAIM TYPE:

AUTH CODE:

150288 Fuel pump failed. Scan test found codes P0628, P129F, P12A6, P2635. Perform diagnosis of Document ID: 5405394, Remove fuel pump connector and test circuit feeds to pump found all test ok, no fuel pump operation. Need to replace fuel pump in tank. Remove fuel tank and replace in tank fuel pump. Truck runs and fuel pressure 500kap

\*\*\*\*\*

B FREE VISUAL BASIC VEHICLE HEALTH CHECK / WHEELS ON - A \$30 VALUE

BVHC FREE VISUAL BASIC VEHICLE HEALTH CHECK /

WHEELS ON - A \$30 VALUE

9 I

(N/C)

150288 Visual inspection

\*\*\*\*\*

C\*\* TRANSMISSION SERVICE/FLUSH - DEXRON VI FLUID - up to 16 litres

(WITH FILTER)

711 TRANSMISSION SERVICE/FLUSH - DEXRON VI FLUID

- up to 16 litres (NO FILTER)

9 CG

55.40

55.40

1 10214 A/T FLUSH KIT

56.73

1 24298004 FILTER KI

74.06



Monday to Friday 7:00 AM to 6:00 PM

Saturday 8:00 AM to 3:00 PM

GM PARTS ARE WARRANTED TO ORIGINAL RETAIL PURCHASER FOR 12 MONTHS FROM DATE OF INSTALLATION

You agree by your signature below that Ron Hodgson Chevrolet Buick GMC may retain any of your personal information we presently have on file and/or any of your personal information on this form. You acknowledge and agree that (i) we collect/use such personal information in order to provide services to you and/or to communicate with you, including marketing communications and (ii) in order to carry out the foregoing purposes we may share your personal information with (a) our computing and marketing service providers, such as CDK Global LLC, (b) motor vehicle manufacturers with whom we have a franchise agreement and (c) others as may be specifically allowed by applicable law.

You may receive a customer satisfaction survey from the manufacturer in the next few weeks. If for any reason you cannot respond as "Completely Satisfied" please contact your service advisor immediately. Your satisfaction is our No. 1 concern.

Sincerely,

Ron Hodgson

CUSTOMER SIGNATURE

X

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAXES	
PLEASE PAY THIS AMOUNT	

GST #R104618632

Customer Copy



# RON HODGSON *Est. 1978*



## Certified Service

**Andrew Miner**  
*Service Consultant*

**Brad Cameron**  
*Certified Technician*

### YOUR VEHICLE

<b>Year</b> 2020	<b>Make</b> GMC	<b>Model</b> Sierra 3500 HD	<b>Engine Type</b> 6.6L V8 Y OHV (MFI)
<b>Odometer</b> 150,288	<b>License #</b> CGR4181	<b>Date</b> 8/31/2023	

## Original Customer Requests

The following is what you requested we perform or investigate regarding your vehicle:

- ✓ A. CONCERN/ADVISE- INSPECT FOR CHECK ENGINE LIGHT ON. CUSTOMER NOTICED THAT THE VEHICLE WILL NOT RUN WELL AND WILL WILL TURN OFF AFTER VEHICLE IS RUNNING/DRIVING FOR A FEW MINUTES. PLEASE ADVISE. (need to remove fuel filter and inspect for contaminants before fuel pump replace)
- ✓ Replace fuel filter
- ✓ B. FREE VISUAL BASIC VEHICLE HEALTH CHECK / WHEELS ON - A \$30 VALUE



## Package Results

### Basic Health Check

Failed Task	Observation	Recommendation	Done
Power steering fluid	Found power steering fluid to be dirty/contaminated	Replace power steering fluid	
Transmission fluid (if equipped with dipstick)	Found fluid to be dirty	Replace automatic transmission fluid and filter	✓
Tire tread depth	All tires tread depth 3/32" (2 mm) or less	Mount and balance four new tires	

Cautioned Task	Observation	Recommendation	Done
Brake fluid level and condition (moisture less than 3%)	Found brake fluid to be dirty/contaminated	Replace brake fluid	
Coolant level and condition	Found coolant to be dirty	Replace coolant	

Passed Task	Observation	Recommendation	Done
Oil level and condition	No oil or fluid leaks found		
Battery health	Battery health is good		
Operation of horn, interior lights, exterior lamps, turn signals, hazard and brake lamps	Horn, interior lights, exterior lamps, turn signals, hazard and brake lamps in good condition		
Windshield washer spray, wiper operation and wiper blades	Windshield washer spray, wiper operation, and wiper blades in good condition		
HVAC system and hoses/lines for leaks and/or damage	HVAC system and hoses/lines in good condition		

Passed Task	Observation	Recommendation	Done
Engine cooling system, radiator, hoses and clamps	Engine cooling system, radiator, hoses, and clamps in good condition		
Accessory drive belt(s)	Accessory drive belt(s) in good condition		

### Passed Tasks



- ✓ Oil level and condition
- ✓ Engine oil
- ✓ Condition of terminals
- ✓ Battery health
- ✓ Inspect body for damage, dings, and dents
- ✓ Operation of horn, interior lights, exterior lamps, turn signals, hazard and brake lamps
- ✓ Windshield washer spray, wiper operation and wiper blades
- ✓ HVAC system and hoses/lines for leaks and/or damage
- ✓ Engine cooling system, radiator, hoses and clamps
- ✓ Accessory drive belt(s)



## Recommended Services

Our technicians recommend the following services for your vehicle.

Original Customer Requests	Status	Cost	Deferred	Approved
A. CONCERN/ADVISE- INSPECT FOR CHECK ENGINE LIGHT ON. CUSTOMER NOTICED THAT THE VEHICLE WILL NOT RUN WELL AND WILL WILL TURN OFF AFTER VEHICLE IS RUNNING/DRIVING FOR A FEW MINUTES. PLEASE ADVISE.		\$179.95		X
Replace fuel filter (need to remove fuel filter and inspect for contaminats before fuel pump replace)	Fail	\$179.95		X
B. FREE VISUAL BASIC VEHICLE HEALTH CHECK / WHEELS ON - A \$30 VALUE				X
Subtotal		\$359.90		\$359.90
Inspection Recommendations	Status	Cost	Deferred	Approved
Replace power steering fluid (Found power steering fluid to be dirty/contaminated)	Fail	\$129.95	X	See AI-27
Mount and balance four new tires (All tires tread depth 3/32" (2 mm) or less)	Fail	\$1,968.56	X	See AI-31
Replace automatic transmission fluid and filter (Found fluid to be dirty)	Fail	\$459.95		X
Subtotal		\$2,558.46	\$2,098.51	\$459.95
Replace coolant (Found coolant to be dirty)	Caution	\$229.95	X	See AI-11

Inspection Recommendations	Status	Cost	Deferred	Approved
Replace brake fluid (Found brake fluid to be dirty/contaminated)	Caution	\$179.95	X	See AI-82
<b>Subtotal</b>		\$409.90	\$409.90	
Totals, Taxes and Fees		Cost	Deferred	Approved
Estimate Subtotal		\$3,328.26	\$2,508.41	\$819.85
Shop Supplies		\$150.00		\$106.58
GST		\$173.91		\$46.32
<b>Estimate Total</b>		<b>\$3,652.17</b>		<b>\$972.75</b>
For "See AI-" items  see the "Additional Information" section 				

## Additional Information

Below is information we feel would help you better understand some of the reasons for taking preventive maintenance steps -- steps that help to ensure the reliability and safety of your vehicle for you and your family.

\*\* The following section may contain instructions for servicing various components of your vehicle. These are an overview of the process that will be performed by a skilled technician in our shop. They are not intended to be a guide for a "do-it-yourself" operation.

### Coolant change

AI-11

#### Operation Description:

Remove the coolant pressure cap and open the radiator and engine coolant drain valves. Drain the coolant completely from the vehicle radiator block and heater core. Inspect all coolant hoses and connections. Close the radiator and coolant drain valves. Refill to factory-specified levels and purge air pockets from engine. Run engine to operating temperature and observe thermostat operation. Top off the coolant as necessary.



*Dirty, acidic coolant (antifreeze)*

#### Significance:

The engine's coolant pulls the heat from the engine and then dissipates the heat when it enters the radiator. The engine's cooling system is a complex system comprised of many components and materials. The most common materials used are aluminum, plastic, copper, brass, rubber, and steel. The engine coolant must be compatible with all of them. The engine coolant is designed to transfer heat, stop corrosion, and provide a lubricant for the water pump seal. Old antifreeze can become acidic. The combination of acidic fluid and the dissimilar alloys in the cooling system actually creates a crude battery. This condition can cause accelerated corrosion of these materials. Changing the coolant according to a preventative maintenance schedule will prevent this acidic condition, and help prevent corrosion, and expensive future repairs.



*New engine coolant (antifreeze)*

**Advantage:**

Replacing the engine coolant as a part of a scheduled maintenance program is essential to your vehicle's reliability and longevity. New engine coolant has a non-acidic, non-corrosive PH level that will not destroy your cooling system components. The use of proper engine coolant will help keep your engine from overheating, and can help prevent the engine from freezing during cold weather conditions.

## Power steering fluid change

AI-27

**Operation Description:**

Drain all contaminated power steering fluid from the power steering system. Replace with new manufacturer-recommended power steering fluid. Test drive vehicle and bleed air from the power steering system. Check fluid level after test drive and top off if necessary.

**Significance:**

Power steering fluid can become dirty and contaminated under normal driving conditions, and should be replaced with new fluid as part of a preventive maintenance program. Contaminated or dirty power steering fluid can cause power steering system components to fail or wear prematurely. It can also cause the check valve to stick, resulting in irritating noise and poor performance. Power steering system components can be very expensive to replace.

**Advantage:**

Replacing contaminated or dirty power steering fluid will keep you from having to replace expensive power steering components prematurely. Replacing your vehicle's power steering fluid is an easy and effective way of making sure that your power steering system functions like new for many years to come.



*Dirty, worn power steering fluid*



*New power steering fluid*

## Tire replacement

AI-31

**Operation Description:**

Raise the vehicle using an automotive lift. Remove the rim and tire assembly from the vehicle. Remove the tire from the rim. Install a new valve stem assembly. Install a new tire on the rim. Inflate the tire to recommended pressure. Balance the tire and rim assembly on a computer-aided dynamic tire balancing machine. Reinstall the tire and rim assembly onto the vehicle. Torque the wheel retaining nuts to the vehicle manufacturer's specifications.

**Significance:**

Your vehicle's tires are the only connection between your vehicle and the road. Safe vehicle operation depends on your tires being in good condition. If your tires are neglected, the tread can wear completely away, leaving the tire bald and often exposing the steel cords. Not only is this condition dangerous, it is also unlawful in many states. Tires with an abnormal tread wear pattern can cause the vehicle to shimmy and vibrate, and can adversely affect the manner in which your vehicle performs. A tire with an abnormal tread wear pattern will no longer contact the road the way that it was designed to, and this condition can be dangerous, especially during adverse road conditions.



*Signs of irregular tire wear*



*New tire*

**Advantage:**

Replacing worn tires is part of vehicle maintenance that is necessary to ensure that your driving experience is as safe as possible. Besides the obvious safety benefits, tires that are in good condition and properly inflated to the correct air pressure can increase the overall fuel economy and help provide a comfortable ride.

**Brake fluid replacement**

AI-82

**Operation Description:**


Completely purge the vehicle's brake system of all contaminated brake fluid. Clean the brake fluid reservoir of any contaminants. Replace brake fluid with new brake fluid from a sealed container.

**Significance:**


Brake fluid can become contaminated in as little as two years. This is due to the fact that brake fluid, by design absorbs the moisture that makes its way into the vehicle's hydraulic system. This moisture can greatly affect the efficiency of the brake fluid, which in turn can affect the efficiency of the braking system. Corrosion also becomes a factor and can create problems with your vehicle's anti-lock brake system (ABS) components. Corroded and damaged ABS components can be very expensive to replace.

**Advantage:**

Most vehicle manufacturers recommend replacing your brake fluid every two years or 24,000 miles. Proper brake performance is essential for the safety of you and your family. Replacing your vehicles brake fluid as part of a regular vehicle maintenance schedule and will prolong the life of brake system components and ensure that your brake system works the way that it was designed to operate.



*Dirty brake fluid*



*Contaminated (left) and clean (right) brake fluid*

# Edwards

## Garage Limited

Box 880 · Rocky Mountain House, Alberta · T4T 1A6  
Telephone: (403)845-3328 · Fax: (403)845-4661  
GST #101584076

INVOICE ORIGINAL

Work Order

#367679

Skocdopole Construction Ltd

May 02, 2022

Svc. Adv Rosenquist, Stephar

Cust.Ph. (403) 746-5744

Tag# 7679

Page 1 of 3

05/05/2022 11:48:29

SCANNED

FILE COPY

<b>To: Skocdopole Construction Ltd</b>  <b>RR 4</b>  <b>Eckville AB</b> <b>TOM OXO</b>	Year: 2020 <b>Veh Id: 71978</b> Unit #: SKOC20-01 Make: GMC License #: Model: 3500 Sierra 4WD Crew Cab Odo. In: 83,979 Colour: G7C Cardinal Red Odo. Out: 83,983 V.I.N.#: 1GT49SEY0LF310684 <b>Next Service: 5/5/2022</b> Date In: 05/02/2022 In Service Date: 09/30/2020 Out: 05/05/2022 Cases: 2 Ext. War - - ( mo/ ) - D: \$0.00 Promised Time: 05/02/2022 02:00:00 PM Call When Ready:
---	--

Case: 1 Truck locked up doing 120km's/hr down highway 2, smoking and squealling. Bringing in on a trailer. truck will drive but barely.

Quantity	Description/Correction	Retail	Price	Total
1.00	84013962 - Seal - Warranty	\$39.22	\$0.00	\$0.00
1.00	15126137 - Gasket - Warranty	\$20.68	\$0.00	\$0.00
6.00	15032594 - Nut - Warranty	\$7.72	\$0.00	\$0.00
1.00	24276422 - TRANSMISSION ASM-AUTO - Warranty	\$5,236.24	\$0.00	\$0.00
2.00	15709703 - Nut-muffl - Warranty	\$3.23	\$0.00	\$0.00
6.00	19352620 - Fluid,A/Trans.Dexron ULV ACDelco .946LX1 - Warranty	\$11.55	\$0.00	\$0.00
4.00	83-6045PK - Retainer Zip Tie-8" - Warranty	\$0.50	\$0.00	\$0.00
1.00	84526283 - CLAMP-F/AXL PROP SHF SLIP YOKE BOOT - Warranty	\$5.46	\$0.00	\$0.00
2.00	19420141 - AC Delco Dexron VI ATF Bulk - Warranty	\$7.26	\$0.00	\$0.00
1.00	84792610 - Seal - Warranty	\$36.34	\$0.00	\$0.00



Garage Limited

Box 880 · Rocky Mountain House, Alberta · T4T 1A6  
Telephone: (403)845-3328 · Fax: (403)845-4661  
GST #101584076

INVOICE ORIGINAL

Work Order

#367679

Skocdopole Construction Ltd

May 02, 2022

Svc.Adv Rosenquist, Stephar

Cust.Ph. (403) 746-5744

Tag# 7679

Page 2 of 3

05/05/2022 11:48:30

\$0.00 \$0.00

- Tech Cause: Drove vehicle into shop and found tranmission is not shifting properly. SES Light on, cheked for codes.
- P0700 - TCM Requested MIL
- P0747 - Transmission Control Soleniod Valve 1 Stuck On
- P0777 - Transmission Control Soleniod Valve 2 Stuck On
- Ran vehicle and found there is a abnormal buzzing sound coming from inside the tranmission. Checked fluid level and found transmission fluid is burnt.
- Disconnected battery's, raised vehicle, removed RH front wheel well liner, removed Catalyst pipw heat shield and RH exhaust manifold shield. Removed DEF Injector. Removed starter heat shield. Removed starter and torque converter bolts.
- Removed front and rear drive shafts, unloaded torsion bars, Removed torsion keys and torsion bar support.
- Supported tranmission, removed cross member, removed nitrogen oxides catalytic converter. Removed transfer case. Removed transmission assembly. Installed holding fixture, mounted transmission onto work bench.
- Removed torque converter. Removed tranmission pan and filter, Removed valve body, removed fluid pump. Removed Transmission Case Front Cover.
- Removed stator shaft support, Removed the 1-2-3-4-5-6 reverse clutch pack and found some of the friction plates are burnt up. Disassembled sun shell housing and found most fo tehclutched in the Triple Clutch Housing have hot spots. Disassembled Control Valve assembly and found the one valve is sticking.
- Tech Comments: Removed New tranmission From Crate. New Tranmission # Y0211470MEFX0540. Old #Y0202110MKFX0387. Flushed transmission cooler and lines.
- Installed new tranmission assembly. Reinstalled transfer case.
- Reinstballed catalyst pipe with new gaskets, reinstalled transmission cross member, reinstalled front and rear drive shafts, Reinstalled torque converter bolts, reinstaled starter and heat shields. Topped up trasfer case fluid. Reinstalled RH front wheel well liner, reinstalled front skid plates. Reprogramed TCM with new TUN, claim code 18YN110890846, Ran vehicle on hoist, set tranmission fluid to proper level. Done a transmission Fast Learn. Test drove vehicle - transmission shifting properly.
- Reassembled old tranmission for warrenty return. - Warranty
- Completed by Technician number: 18 \$0.00 \$0.00
- Core Charges - 24276422 - Warranty \$0.00 \$0.00
- Core Return - 24276422COR - Warranty \$0.00 \$0.00

Misc \$0.00	Labour \$0.00	Parts \$0.00	Prepaid Parts Amt: \$0.00	Case Total: \$0.00
-------------	---------------	--------------	---------------------------	--------------------

Case: 2 # N212354170 DPF Regeneration Temperature -

Quantity Description/Correction

Price	Total
\$0.00	\$0.00

- Tech Cause: # N212354170 DPF Regeneration Temperature -
- Tech Comments: Reprogramed ECM and TCM, done set up procedure. Claim codes 11YN110935385, 18YN110936173 and FDYN110937012 - Warranty
- Completed by Technician number: 18 \$0.00 \$0.00

Misc \$0.00	Labour \$0.00	Parts \$0.00	Prepaid Parts Amt: \$0.00	Case Total: \$0.00
-------------	---------------	--------------	---------------------------	--------------------

\$0.00



Garage Limited

Box 880 · Rocky Mountain House, Alberta · T4T 1A6  
Telephone: (403)845-3328 · Fax: (403)845-4661  
GST #101584076

INVOICE ORIGINAL

Work Order

#367679

Skocdopole Construction Ltd

May 02, 2022

Svc. Adv Rosenquist, Stephar

Cust. Ph. (403) 746-5744

Tag# 7679

Page 3 of 3

05/05/2022 11:48:30

O U T	<p>Indebtedness is hereby acknowledged for the "Total Charges" being all or the balance owing to repairs, parts &amp; accessories described in this work order. Interest will be charged at 2 % monthly / 24 % annually on overdue invoices.</p> <p>Privacy-Personal information is collected in accordance with applicable privacy legislation and is governed by EDWARDS GARAGE LIMITED Privacy Policy. Your privacy is important to us. Ask us if you would like information about EDWARDS GARAGE LIMITED Privacy Policy.</p> <p><input type="checkbox"/> I agree to receive Edwards Garage newsletter containing news, updates and promotions regarding Edwards Garage products. You can withdraw your consent at anytime.</p> <p>I would like to unsubscribe from receiving:  <input type="checkbox"/> All messages from Edwards Garage. <input type="checkbox"/> All promotional messages from Edwards.</p>		Currency:	Labour:	\$0.00
	Payment Ref:	Parts:	\$0.00		
	Expiry Date:	Misc:	\$0.00		
	P/O#:	Sub Total:	\$0.00		
G/HST Reg # R101584076	G/HST:	\$0.00	PST:	\$0.00	
	Tax Adjustment:	\$0.00			
05/05/2022	Signature	Payment Type	Total:	\$0.00	

Skocdopole Construction Ltd.

Date Rec'd MAY 11 2022 Job # \_\_\_\_\_

Chq. # \_\_\_\_\_ Unit # 20-01

Date Mailed \_\_\_\_\_ GL # 50150-02

Approved by Barry Jensen

# Let us know how we did!

How likely are you to refer Davis Chevrolet GMC Buick to your friends or family?

1 \ 2 \ 3 \ 4 \ 5 \ 6 \ 7 \ 8 \ 9 \ 10



**Davis Chevrolet GMC Buick Brooks**  
 504 2nd Street West  
 Brooks, Alberta T1R 0E9  
 Tel: (403) 362-3416 | Fax: (403) 362-3425



INVOICE ORIGINAL

Work Order

#736179

Skocdopole Construction

April 07, 2022

Svc. Adv Melnychuk, Alex

Cust. Ph. (403) 892-9320

Tag# 37027

Page 1 of 3

04/11/2022 10:34:02

<p><b>To: Skocdopole Construction</b></p> <p><b>RR#4</b></p> <p><b>Eckville AB</b></p> <p><b>TOM OXO</b></p>	<p>Year: 2020 Veh Id: 237027 Unit #:</p> <p>Make: GMC License #:</p> <p>Model: Crew CAB Pickup 4WD Odo. In: 80,926</p> <p>Colour: White Odo. Out:</p> <p>V.I.N.#: 1GT49SEY0LF310684 <b>Next Service:</b></p> <p>Date In: 04/07/2022 In Service Date: 09/30/2020</p> <p>Out: 04/08/2022 Cases: 3</p> <p>Ext. War - - ( mo/ ) - D: \$0.00</p> <p>Promised Time: 04/07/2022 03:00:00 PM Call When Ready:</p>
--	---

**Case: 1** Customer concerned of CEL - please check and advise  
 - Tech Cause: scan test 2 codes found p05ae active grille shutter 2-p2635 fuel pump flow perf - Tech  
 Comments: remove small twigs from shutters-clear code function test ok now-remove fuel tank and drain clean  
 out tank install new pump assembly and 80 dollars diesel fuel road test ok-slip tank has rust inside and has no  
 filter-contaminated diesel is getting into tank recomend to stop using slip tank or install filter on slip tank-road  
 test no code now

Quantity	Description/Correction	Retail	Price	Total					
1.00	85105758 - MODULE KIT-F/TNK F/PMP	\$368.19	\$368.19	\$368.19					
			\$489.83	\$489.83					
	• Tech Cause: scan test 2 codes found p05ae active grille shutter 2-p2635 fuel pump flow perf								
	• Tech Comments: remove small twigs from shutters-clear code function test ok now-remove fuel tank and drain clean out tank install new pump assembly and 80 dollars diesel fuel road test ok-slip tank has rust inside and has no filter-contaminated diesel is getting into tank recomend to stop using slip tank or install filter on slip tank-road test no code now								
	• Completed by Technician number: 0011								
	• S22999858 - Fuel		\$80.00	\$80.00					
	• ShopSupplies		\$63.66	\$63.66					
<b>Misc</b>	\$63.66	<b>Labour</b>	\$489.83	<b>Parts</b>	\$448.19	<b>Prepaid Parts Amt:</b>	\$0.00	<b>Case Total:</b>	\$1,001.68

**Case: 2** Fuel Filter Replace Diesel 18 (Fuel Filter - Replace) - Tech Cause: replace fuel filter - Tech Comments: replace  
 fuel filter and reset fuel life

Quantity	Description/Correction	Retail	Price	Total					
1.00	13539108 - FILTER KIT-FUEL	\$64.20	\$64.20	\$64.20					
			\$41.99	\$41.99					
	• Tech Cause: replace fuel filter								
	• Tech Comments: replace fuel filter and reset fuel life								
	• Completed by Technician number: 0011								
	• ShopSupplies		\$5.46	\$5.46					
<b>Misc</b>	\$5.46	<b>Labour</b>	\$41.99	<b>Parts</b>	\$64.20	<b>Prepaid Parts Amt:</b>	\$0.00	<b>Case Total:</b>	\$111.65

# Let us know how we did!

How likely are you to refer Davis Chevrolet GMC Buick to your friends or family?

OUR GOAL!



**Davis Chevrolet GMC Buick Brooks**  
 504 2nd Street West  
 Brooks, Alberta T1R 0E9  
 Tel: [403] 362-3416 | Fax: [403] 362-3425



INVOICE ORIGINAL

Work Order

#736179

Skocdopole Construction

April 07, 2022

Svc. Adv Melnychuk, Alex

Cust.Ph. (403) 892-9320

Tag# 37027

Page 2 of 3

04/11/2022 10:34:03

## Case: 3 4WD Service Package-Front & Rear Differentials, Transfer Case

- Includes Removal of Differential Cover \*where applicable\* & Draining of Oil; Install New GM Gear Oil
- Includes Draining of Oil & Installation of GM Approved Gear Oil.

Quantity	Description/Correction	Retail	Price	Total
6.00	89021678 - Gear lubr	\$19.19	\$0.00	\$0.00
2.00	19421424 - ATF Fluid	\$7.69	\$0.00	\$0.00
			\$409.99	\$409.99

- Tech Cause: driveline services
- Tech Comments: change frt and rear differential fluid-service transfer case all synthetic fluids
- Completed by Technician number: 0011

• Environmental Levy \$0.00 \$0.00

Misc	\$0.60	Labour	\$262.76	Parts	\$146.63	Prepaid Parts Amt:	\$0.00	Case Total:	\$409.99
									\$0.00

### Declined/MPVI Op Codes

- F007: Differential Rear Service
- 0306: MPVI: Brake Lining Green - Notation only - No Work Needed
- 0306: MPVI: Brake Lining Green - Notation only - No Work Needed
- 0411: MPVI: Tire Tread Green - Notation only - No Work Needed
- 0411: MPVI: Tire Tread Green - Notation only - No Work Needed
- 0411: MPVI: Tire Tread Green - Notation only - No Work Needed
- 0411: MPVI: Tire Tread Green - Notation only - No Work Needed

O U T	Indebtedness is hereby acknowledged for the "Total Charges" being all or the balance owing to repairs, parts & accessories described in this work order.		Currency:	Labour:	\$874.58	
			Payment Ref:	Parts:	\$579.62	
			Expiry Date:	Misc:	\$69.12	
			P/O#:	Sub Total:	\$1,523.32	
			G/HST Reg # 827263351RT0001	G/HST:	\$76.17	
				PST:	\$0.00	
				Tax Adjustment:	\$0.00	
	04/08/2022					
	Date	Signature	Payment Type	Credit Card	Total:	\$1,599.49

# Let us know how we did!

How likely are you to refer Davis Chevrolet GMC Buick to your friends or family?

OUR GOAL!



**Davis Chevrolet GMC Buick Brooks**

504 2nd Street West  
Brooks, Alberta T1R 0E9  
Tel: [403] 362-3416 | Fax: [403] 362-3425



**DAVIS**  
AUTO GROUP

INVOICE ORIGINAL

Work Order

#736179

Skocdopole Construction

April 07, 2022

Svc.Adv Melnychuk, Alex

Cust.Ph. (403) 892-9320

Tag# 37027

Page 3 of 3

04/11/2022 10:34:03

Payee	Payment Type	Reference	Date	
Skocdopole Construction	Credit Card		04/08/2022	\$1,599.49
			Balance Owing:	\$0.00



Garage Limited

Box 880 · Rocky Mountain House, Alberta · T4T 1A6  
Telephone: (403)845-3328 · Fax: (403)845-4661  
GST #101584076

SCANNED  
FILE COPY

INVOICE ORIGINAL  
Work Order  
#363637  
Skocdopole Construction Ltd  
January 21, 2022  
Svc. Adv Smith, Darcy  
Cust. Ph. (403) 746-5744  
Tag# 3637

Page 1 of 3  
01/25/2022 16:39:06

To Skocdopole Construction Ltd	Year: 2020 Veh Id: 71978 Unit #: SKOC20-01
	Make: GMC License #:
RR 4	Model: 3500 Sierra 4WD Crew Cab Odo. In: 70,026
Eckville AB	Colour: G7C Cardinal Red Odo. Out: 70,026
TOM OXO	V.I.N.#: 1GT49SEY0LF310684 Next Service: 1/25/2022
	Date In: 01/21/2022 In Service Date: 09/30/2020
	Out: 01/24/2022 Cases: 6
	Ext. War - - ( mo/ ) - D: \$0.00
	Promised Time: 01/21/2022 02:00:00 PM Call When Ready: Yes

Case: 1 diag ses light , light

Quantity Description/Correction

Price Total  
\$75.50 \$75.50

- Tech Cause: SES Light not on when driven into shop. Checked for codes.
- P018B - Fuel Pressure Sensor Performance
- P0336 - Crankshaft Position Sensor Performance
- P064C - Glow Plug Control Module Performance
- P129B - Fuel Pump Driver Control Module System Voltage Low Voltage
- P12A6 - Fuel Pump Driver Control Module Enable Circuit Performance
- P1434 - Fuel Level Sensor 1 Reference Feedback Performance
- P24B3 - Particulate Matter Sensor Heater Control Circuit
- P24B5 - Particulate Matter Sensor Heater Control Circuit Low Voltage
- P2635 - Fuel Pump Flow Performance
- All codes passed, ran vehicle and monitored engine data - all systems operating properly. Test drove vehicle - no codes rest, did notice steering wheel off center and rattle in steering column. Recommend a Long Life Inspection
- Tech Comments: No fault found
- Completed by Technician number: 18
- Miscellaneous

\$8.46 \$8.46

Misc \$8.46 Labour \$75.50 Parts \$0.00 Prepaid Parts Amt: \$0.00 Case Total: \$83.96

Case: 2 # N202308880 Rear Seat Reminder Not Activated -

Quantity Description/Correction

Price Total  
\$0.00 \$0.00

- Tech Cause: # N202308880 Rear Seat Reminder Not Activated -
- Tech Comments: Reprogrammed BCM and done set up procedure, claim codes 0SYN99638092 and FDYN99638809 - Warranty
- Completed by Technician number: 18

\$0.00 \$0.00

Misc \$0.00 Labour \$0.00 Parts \$0.00 Prepaid Parts Amt: \$0.00 Case Total: \$0.00

# Edwards

## Garage Limited

Box 880 · Rocky Mountain House, Alberta · T4T 1A6  
 Telephone: (403)845-3328 · Fax: (403)845-4661  
 GST #101584076

**INVOICE ORIGINAL**  
**Work Order**  
**#363637**  
**Skocdopole Construction Ltd**  
**January 21, 2022**  
**Svc.Adv Smith, Darcy**  
**Cust.Ph. (403) 746-5744**  
**Tag# 3637**

Page 2 of 3  
 01/25/2022 16:39:07

**Case: 3 # N212342980 Diesel Exhaust Fluid (DEF) Tank Harness Connector Terminal Overheat / Arcing - Exp. W/Base Warranty -**

Quantity	Description/Correction	Price	Total
		\$0.00	\$0.00
	• Tech Cause: # N212342980 Diesel Exhaust Fluid (DEF) Tank Harness Connector Terminal Overheat / Arcing		
	• Tech Comments: Reprogramed Reductant Control Module, claim code 14YN99637553 - Warranty		
	• Completed by Technician number: 18	\$0.00	\$0.00

**Misc \$0.00 Labour \$0.00 Parts \$0.00 Prepaid Parts Amt: \$0.00 Case Total: \$0.00**

**Case: 4 # N202314670 Front Center Seat Belt May Not Be Attached -**

Quantity	Description/Correction	Price	Total
		\$0.00	\$0.00
	• Tech Cause: # N202314670 Front Center Seat Belt May Not Be Attached		
	• Tech Comments: Inspected seat belt anchors - all seat belt anchors are installed properly. - Warranty		
	• Completed by Technician number: 18	\$0.00	\$0.00

**Misc \$0.00 Labour \$0.00 Parts \$0.00 Prepaid Parts Amt: \$0.00 Case Total: \$0.00**

**Case: 5 Wheel Alignment (2)**

Quantity	Description/Correction	Price	Total
		\$96.95	\$96.95
	• Tech Cause: customer requested wheel alignment		
	• Tech Comments: performed wheel alignment found caster camber toe out adjusted as needed		
	• Completed by Technician number: 3967		

**Misc \$0.00 Labour \$96.95 Parts \$0.00 Prepaid Parts Amt: \$0.00 Case Total: \$96.95**

**Case: 6 Front End Inspection**

Quantity	Description/Correction	Price	Total
		\$62.95	\$62.95
	• Tech Cause: Front End Inspection		
	• Tech Comments: Done a front end inspection - all suspension components are in spec.		
	• Completed by Technician number: 18		
	• Miscellaneous (Extra Item)	\$7.05	\$7.05

**Misc \$7.05 Labour \$62.95 Parts \$0.00 Prepaid Parts Amt: \$0.00 Case Total: \$70.00**

\$0.00

# Edwards

## Garage Limited

Box 880 · Rocky Mountain House, Alberta · T4T 1A6  
 Telephone: (403)845-3328 · Fax: (403)845-4661  
 GST #101584076

INVOICE ORIGINAL  
 Work Order  
 #363637  
 Skocdopole Construction Ltd  
 January 21, 2022  
 Svc.Adv Smith, Darcy  
 Cust.Ph. (403) 746-5744  
 Tag# 3637

Page 3 of 3  
 01/25/2022 16:39:07

O U T	Indebtedness is hereby acknowledged for the "Total Charges" being all or the balance owing to repairs, parts & accessories described in this work order. Interest will be charged at 2 % monthly / 24 % annually on overdue invoices.		Currency:	Labour:	\$235.40	
	Privacy-Personal information is collected in accordance with applicable privacy legislation and is governed by EDWARDS GARAGE LIMITED Privacy Policy. Your privacy is important to us. Ask us if you would like information about EDWARDS GARAGE LIMITED Privacy Policy.		Payment Ref:	Parts:	\$0.00	
	I agree to receive Edwards Garage newsletter containing news, updates and promotions regarding Edwards Garage products. You can withdraw your consent at anytime.		Expiry Date:	Misc:	\$15.51	
	I would like to unsubscribe from receiving:		P/O#: 20-01	Sub Total:	\$250.91	
	All messages from Edwards Garage. All promotional messages from Edwards.		G/HST Reg # R101584076	G/HST:	\$12.55	
				PST:	\$0.00	
				Tax Adjustment:	\$0.00	
	01/24/2022					
Date	Signature	Payment Type	Charge	Total:	\$263.46	

Payee	Payment Type	Reference	Date	
Skocdopole Construction Ltd	Charge		01/24/2022	\$263.46
			Balance Owing:	\$263.46



Box 880 · Rocky Mountain House, Alberta · T4T 1A6  
 Telephone: (403)845-3328 · Fax: (403)845-4661  
 GST #101584076

INVOICE ORIGINAL  
 Work Order  
 #363637  
 Skocdopole Construction Ltd  
 January 21, 2022  
 Svc. Adv Smith, Darcy  
 Cust.Ph. (403) 746-5744  
 Tag# 3637  
 Page 1 of 3  
 01/24/2022 14:17:49

<b>To: Skocdopole Construction Ltd</b>  <b>RR 4</b>  <b>Eckville AB</b> <b>TOM 0X0</b>	Year: 2020 Veh Id: 71978 Unit #: SKOC20-01 Make: GMC License #: Model: 3500 Sierra 4WD Crew Cab Odo. In: 70,026 Colour: G7C Cardinal Red Odo. Out: 70,026 V.I.N.#: 1GT49SEY0LF310684 Next Service: 1/24/2022 Date In: 01/21/2022 In Service Date: 09/30/2020 Out: 01/24/2022 Cases: 6 Ext. War - - ( mo/ ) - D: \$0.00 Promised Time: 01/21/2022 02:00:00 PM Call When Ready: Yes
---	---

Case: 1 diag ses light , light

Quantity Description/Correction	Price	Total
<ul style="list-style-type: none"> <li>• Tech Cause: SES Light not on when driven into shop. Checked for codes.</li> <li>• P018B - Fuel Pressure Sensor Performance</li> <li>• P0336 - Crankshaft Position Sensor Performance</li> <li>• P064C - Glow Plug Control Module Performance</li> <li>• P129B - Fuel Pump Driver Control Module System Voltage Low Voltage</li> <li>• P12A6 - Fuel Pump Driver Control Module Enable Circuit Performance</li> <li>• P1434 - Fuel Level Sensor 1 Reference Feedback Performance</li> <li>• P24B3 - Particulate Matter Sensor Heater Control Circuit</li> <li>• P24B5 - Particulate Matter Sensor Heater Control Circuit Low Voltage</li> <li>• P2635 - Fuel Pump Flow Performance</li> <li>• All codes passed, ran vehicle and moitored engine data - all systems operating proeprly. Test drove vehicle - no codes rest, did notice steering wheel off center and rattle in steering column. Recommend a Long Life Inspection</li> <li>• Tech Comments: No fault found</li> <li>• Completed by Technician number: 18</li> <li>• Miscellaneous</li> </ul>	\$8.46	\$8.46
<b>Misc \$8.46    Labour \$75.50    Parts \$0.00    Prepaid Parts Amt: \$0.00</b>	<b>Case Total:</b>	<b>\$83.96</b>

Case: 2 # N202308880 Rear Seat Reminder Not Activated -

Quantity Description/Correction	Price	Total
<ul style="list-style-type: none"> <li>• Tech Cause: # N202308880 Rear Seat Reminder Not Activated -</li> <li>• Tech Comments: Reprogramed BCM and done set up procedure, claim codes 0SYN99638092 and FDYN99638809 - Warranty</li> <li>• Completed by Technician number: 18</li> </ul>	\$0.00	\$0.00
<b>Misc \$0.00    Labour \$0.00    Parts \$0.00    Prepaid Parts Amt: \$0.00</b>	<b>Case Total:</b>	<b>\$0.00</b>

RECEIVED  
 Skocdopole Construction Ltd.  
 Date Rec'd **FEB - 1 2022** Job # \_\_\_\_\_  
 Chq. # \_\_\_\_\_ Unit # 20-01  
 Date Mailed \_\_\_\_\_ GL # 50150-02  
 Approved by Darcy Smith



Garage Limited

Box 880 · Rocky Mountain House, Alberta · T4T 1A6
Telephone: (403)845-3328 · Fax: (403)845-4661
GST #101584076

INVOICE ORIGINAL

Work Order

#363637

Skocdopole Construction Ltd

January 21, 2022

Svc.Adv Smith, Darcy

Cust.Ph. (403) 746-5744

Tag# 3637

Page 2 of 3

01/24/2022 14:17:49

Case: 3 # N212342980 Diesel Exhaust Fluid (DEF) Tank Harness Connector Terminal Overheat / Arcing - Exp. W/Base Warranty -

Quantity Description/Correction

Price Total
\$0.00 \$0.00

- Tech Cause: # N212342980 Diesel Exhaust Fluid (DEF) Tank Harness Connector Terminal Overheat / Arcing
• Tech Comments: Reprogramed Reductant Control Module, claim code 14YN99637553 - Warranty
• Completed by Technician number: 18

Misc \$0.00 Labour \$0.00 Parts \$0.00 Prepaid Parts Amt: \$0.00 Case Total: \$0.00

Case: 4 # N202314670 Front Center Seat Belt May Not Be Attached -

Quantity Description/Correction

Price Total
\$0.00 \$0.00

- Tech Cause: # N202314670 Front Center Seat Belt May Not Be Attached
• Tech Comments: Inspected seat belt anchors - all seat belt anchors are installed properly. - Warranty
• Completed by Technician number: 18

Misc \$0.00 Labour \$0.00 Parts \$0.00 Prepaid Parts Amt: \$0.00 Case Total: \$0.00

Case: 5 Wheel Alignment (2)

Quantity Description/Correction

Price Total
\$96.95 \$96.95

- Tech Cause: customer requested wheel alignment
• Tech Comments: performed wheel alignment found caster camber toe out adjusted as needed
• Completed by Technician number: 3967

Misc \$0.00 Labour \$96.95 Parts \$0.00 Prepaid Parts Amt: \$0.00 Case Total: \$96.95

Case: 6 Front End Inspection

Quantity Description/Correction

Price Total
\$62.95 \$62.95

- Tech Cause: Front End Inspection
• Tech Comments: Done a front end inspection - all suspension components are in spec.
• Completed by Technician number: 18
• Miscellaneous (Extra Item)

Misc \$7.05 Labour \$62.95 Parts \$0.00 Prepaid Parts Amt: \$0.00 Case Total: \$70.00

\$0.00





**EDWARDS GARAGE**  
**4403 - 42ND AVE**  
**ROCKY MOUNTAIN HOUSE, AB T4T 1A6**  
**PHONE 1-800-668-2438**



Work Order: R359525  
 Last Name: constrution  
 First Name: skocdopole  
 VIN: 1GT49SEY0LF310684  
 Year: 20  
 Technician: 67  
 Odometer: 70026  
 Date: 1/24/22 10:58 AM

**GMC 2020-22 Sier 4X4 3500 Crew Cab 159" Wheelbase**





REAL.  
SERIOUS.  
PROTECTION.

SCANNED

INVOICE  
FILE COPY  
NO. 47076

CENTRAL ALBERTA POLYCOATINGS LTD. Phone (403) 340-8287  
#39 Belich Crescent Fax (403) 348-0202  
Red Deer, Alberta, Canada  
T4S 2K5

DATE Oct 02, 2020

PO: \_\_\_\_\_

PAGE 1

S  
O  
L  
D  
  
T  
O

**Skocdopole Construction**  
Cliff  
R.R. #4  
Eckville, Alberta T0M 0X0  
Canada

S  
H  
I  
P  
  
T  
O  
  
Skocdopole Construction  
Red Deer, Alberta  
Canada

ITEM NO.	QUANTITY	UNIT	DESCRIPTION	GST	UNIT PRICE	AMOUNT
			2020 GMC 3500 Red/White Ser#: 1GT49SEYOLF310684 Cliff			
21	1	Each	Under-rail Boxliner	G	635.00	635.00
54	1	Each	Premium Boxliner Topcoat	G	150.00	150.00
98	1	Each	Shop Supplies/Enviromental Disposal	G	6.00	6.00
			G - GST 5%			
			GST			39.55
Skocdopole Construction Ltd.						
Date Rec'd OCT - 7 2020						Job #
Chq. #						Unit # 20-01
Date Mailed						GL # 50150-02
Approved by <i>Bary Henry</i>						
Terms: Due on Receipt DEALER GST # R136822244					TOTAL	830.55

*Thank you for allowing us to be of service !*

**WARRANTY**

CENTRAL ALBERTA POLYCOATINGS LTD. will repair the sprayed liner which if determined by the installing CENTRAL ALBERTA POLYCOATINGS LTD. Dealer to be defective in material or workmanship, and subject to any applicable service charges. Repairs must be carried out by the installing CENTRAL ALBERTA POLYCOATINGS LTD. Removal and replacement of attachments will be charged at the CENTRAL ALBERTA POLYCOATINGS LTD. Dealers prevailing labour rate at time repairs are done. Purchaser is hereby notified that colour change from original may occur in time for which no warranty applies. The foregoing is in lieu of any and all other warranty or guarantee expressed or implied and is non-transferable. This warranty only applies to pickup trucks, equipped with original equipment truck beds, sold to individuals for personal non-commercial use. The warranty applies to the original LINE-X purchaser.

**NOTICE TO VEHICLE OWNER**

Application of the CENTRAL ALBERTA POLYCOATINGS LTD. Uner involves sanding, installing, and removing masking tape and trimming on the vehicles painted surface. Purchaser warrants the paint on the vehicle against peeling during such time the above process is carried out.

**TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE**

I hereby authorize the work herein set forth and in accordance with the warranty and notice to owner set out above, to be done along with the necessary material and agree that to the extent permitted by law, you are not responsible for loss or damage to vehicles or articles left in vehicle in case of fire, theft or any other cause beyond control or for any delays caused by equipment failures, or other unforeseen circumstances. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of the work set out in this work order and delivery. Until payment in full of the within account, I hereby acknowledge the existence of a repair lien in favour of the within dealer on the vehicle described herein in respect of the material supplied and services rendered under the work order for the full amount charged therefore. I further acknowledge that the said lien shall continue in force at all times, whether the vehicle is in my possession or possession of the dealer, until the within account is paid in full. While the vehicle is in my possession it shall at all times be subject to repossession on demand by the dealer until the account is paid in full.

WORK ORDERED BY \_\_\_\_\_ DATE \_\_\_\_\_ SIGNATURE \_\_\_\_\_

CENTRAL ALBERTA POLYCOATINGS LTD. – Authorized LINE-X APPLICATOR



# Edwards

## Garage Limited

Box 880 · Rocky Mountain House, Alberta · T4T 1A6  
 Telephone: (403)845-3328 · Fax: (403)845-4661  
 GST #101584076

INVOICE ORIGINAL

Work Order

#343275

Skocdopole Construction Ltd

September 15, 2020

Svc.Adv Carswell, Donald

Cust.Ph. (403) 746-5744

Tag# 3275

Page 2 of 2

09/21/2020 08:47:20

O U T	Indebtedness is hereby acknowledged for the "Total Charges" being all or the balance owing to repairs, parts & accessories described in this work order. Interest will be charged at 2 % monthly / 24 % annually on overdue invoices.		Currency:	Labour:	\$260.00
	Privacy-Personal information is collected in accordance with applicable privacy legislation and is governed by EDWARDS GARAGE LIMITED Privacy Policy. Your privacy is important to us. Ask us if you would like information about EDWARDS GARAGE LIMITED Privacy Policy.		Payment Ref:	Parts:	\$23.32
	I agree to receive Edwards Garage newsletter containing news, updates and promotions regarding Edwards Garage products. You can withdraw your consent at anytime.		Expiry Date:	Misc:	\$29.12
	I would like to unsubscribe from receiving: <input type="checkbox"/> All messages from Edwards Garage. <input type="checkbox"/> All promotional messages from Edwards.		P/O#: 20-01	Sub Total:	\$312.44
		G/HST Reg # R101584076	G/HST:	\$15.62	
			PST:	\$0.00	
			Tax Adjustment:	\$0.00	
09/17/2020 Date _____ Signature _____		Payment Type	Charge	Total:	\$328.06

Payee	Payment Type	Reference	Date	
Skocdopole Construction Ltd	Charge		09/18/2020	\$328.06
			Balance Owing:	\$328.06

Reference: