

X48-1
MAY

Longhorn Mechanical
P.O Box 807
Carlyle SK S0C0R0
3065778669
longhornmechanical306@gmail.com
GST Registration No.: 798939674RT0001
PST (SK) Registration No.: 7309164

Invoice

BILL TO
Integrity Maintenance LTD
Po Box 725
Carlyle SK S0C0R0

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
1283	28/11/2025	\$0.00	28/12/2025	Net 30	

P.O. NUMBER
2005 KW

DATE		DESCRIPTION	TAX	QTY	RATE	AMOUNT
25/11/2025	Labour	2005 Kenworth S#1NKDXBEX16R989976 Unit 01 Fan engaged full time Test coolant temp sensor, no good Remove and replace, fan works on and off as it should Boost issue Pressure test intercooler system, found boots leaking and intercooler had a crack in the the intake pipe neck Remove and replace intercooler and all intercooler boots and clamps	S	5	130.00	650.00
	Parts	Replace heater core water valve				
	Parts	2566413 Coolant temp sensor	S	1	160.23	160.23
	Parts	6V6603 oring seal	S	1	6.20	6.20

PAID

SUBTOTAL	816.43
GST @ 5%	40.82
PST (SK) @ 6%	48.98
TOTAL	906.23
PAYMENT	906.23
BALANCE DUE	\$0.00

TAX SUMMARY

	RATE	TAX	NET
	GST @ 5%	40.82	816.43
	PST (SK) @ 6%	48.98	816.43

Longhorn Mechanical

P.O Box 807

Carlyle SK S0C0R0

3065778669

longhornmechanical306@gmail.com

GST Registration No.: 798939674RT0001

PST (SK) Registration No.: 7309164

Invoice

BILL TO

Integrity Maintenance LTD
Po Box 725
Carlyle SK S0C0R0

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
1257	17/11/2025	\$0.00	17/12/2025	Net 30	

P.O. NUMBER

2005 KW

DATE		DESCRIPTION	TAX	QTY	RATE	AMOUNT
14/11/2025	Labour	2005 KW S#1NKDXBEX16R989976 22028hrs 525860km Derate, low boost Check for codes Found code for actuator rail pressure sensor test sensor, good Found wiring to sensor was damaged, repair wiring take valve covers off, ohm test and inspect all IVAs, tested good no oil leaks at IVA inlet tubes Oil cooler leaking coolant in inlet pipe Water pump seal blown leaking engine oil from gear case Remove oil cooler and replace all gaskets and orings Remove and replace water pump Replace bearings in idler pulley Reseal thermostat housing and replace thermostat Replace 2 coolant lines test run truck, no leaks hitting 37-39psi boost empty	S	14.25	130.00	1,852.50
	Parts	247-7133 thermostat	S	1	183.99	183.99

PAID

DATE		DESCRIPTION	TAX	QTY	RATE	AMOUNT
	Parts	139-3550 Housing gasket	S	1	17.05	17.05
	Parts	456-2525 gasket kit oil cooler	S	1	650.92	650.92
	Parts	P381809 water pump	S	1	1,458.54	1,458.54
	Parts	4N1156 thermostat gasket	S	1	10.11	10.11
	Parts	6303 bearing	S	2	21.33	42.66
	Supplies	coolant	S	56	5.75	322.00
	Freight	parts freight	S	1	50.00	50.00
	Shop Supplies	sealants, cleaners shop consumables	S	1	30.00	30.00

SUBTOTAL	4,617.77
GST @ 5%	230.90
PST (SK) @ 6%	277.07
TOTAL	5,125.74
PAYMENT	5,125.74
BALANCE DUE	\$0.00

TAX SUMMARY

	RATE	TAX	NET
GST @ 5%		230.90	4,617.77
PST (SK) @ 6%		277.07	4,617.77