



REPRINT SERVICE INVOICE

L96-3
MAY

SMS EQUIPMENT INC.
16116 - 111 AVENUE
EDMONTON AB T5M 2S1
TEL: +1-780-451-2630
SMS CONTACT: TRAVIS WOLFE

INVOICE # : SSI/70443543
INVOICE DATE : 2025-Mar-24
CUSTOMER PO : E124- KF
ORDER # : WO2991497
ORDER DATE : 2024-Nov-29
SHIP DATE : Not applicable
PAYMENT TERMS : NET 30 DAYS
DELIVERY TERMS : Not applicable

BILL TO:
M.A.P. WATER AND SEWER
SERVICES LTD.
14303 - 116 AVENUE
EDMONTON AB T5N 4G2

WORK SITE:
SMS EQUIPMENT INC.
16116 - 111 AVENUE
EDMONTON AB T5M 2S1

Manufacturer : KOMATSU	Customer Unit No : E124
Model : PC350LC-8	Meter Reading : 16646.83
Serial Number : A10039	SMS Unit No : MD0004272
Service Rep : ROBERT MCGOWAN	

SEGMENT 1: SUPPLY SPROCKETS,HW

Lifted machine onto stands
Removed pad from each rail
Loosened track tension (RH side had rotated and had to be accessed from around the bottom roller)
Cut both rails with a torch
Dragged out rails
Folded tracks and placed them in Bay 8 staging

THANK YOU FOR YOUR BUSINESS!

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS	207-27-71460 SPROCKET	2	1,039.40	0.00	155.90	1,922.90
PARTS	207-27-51311 BOLT	40	6.43	0.00	19.20	238.00
LABOR						2,100.00
MISC.	SHOP SUPPLIES	1.00	147.00		0.00	147.00

SEGMENT 1 TOTAL:

PARTS 2,336.00 LABOR 2,100.00 MISC. 147.00 DISCOUNT 175.10 TOTAL 4,407.90
(EXCLUDING ENV. LEVY) ENV. LEVY 0.00

SEGMENT 3: REPLACE FRONT WINDOW ROLLERS

Changed out rollers on the front window
Confirmed positioning of rollers in the parts book

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS	20Y-54-52621 ROLLER	2	57.50	0.00	0.00	115.00
PARTS	20Y-54-52681 ROLLER	2	52.78	0.00	0.00	105.56
LABOR						525.00
MISC.	SHOP SUPPLIES	1.00	36.75		0.00	36.75
MISC.	ENVIRONMENTAL CHARGE	1.00	15.75		0.00	15.75

GST/TPS 89548 3022



REPRINT SERVICE INVOICE

SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1
 TEL: +1-780-451-2630
 SMS CONTACT: TRAVIS WOLFE

INVOICE # : SSI/70443543
 INVOICE DATE : 2025-Mar-24
 CUSTOMER PO : E124- KF
 ORDER # : WO2991497
 ORDER DATE : 2024-Nov-29
 SHIP DATE : Not applicable
 PAYMENT TERMS : NET 30 DAYS
 DELIVERY TERMS : Not applicable

SEGMENT 3 TOTAL:

PARTS 220.56 LABOR 525.00 MISC. 52.50 DISCOUNT 0.00 TOTAL 798.06
 (EXCLUDING ENV. LEVY) ENV. LEVY 0.00

SEGMENT 4: RESEAL BOTH PPC CONTROL VALVE IN CAB

Description of Services Rendered:

Resealed both PPC control valves in cab:
 Removed old seals from both PPC control valves.
 Cleaned and inspected valve surfaces to ensure proper seating of new seals.
 Installed new seals on both control valves.
 Ensured that valves were properly sealed to prevent leaks.
 Reassembled the control valves and ensured functionality.
 Tested the valves to confirm proper operation after resealing.

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS	07000-12018 O- RING	4	2.20	0.00	0.00	8.80
PARTS	07000-12015 O- RING	4	2.29	0.00	0.00	9.16
PARTS	02896-11009 O- RING	6	3.25	0.00	0.00	19.50
PARTS	07002-11423 O- RING	8	2.36	0.00	0.00	18.88
PARTS	02896-11008 O- RING	2	3.18	0.00	0.48	5.88
PARTS	702-16-71150 SEAL	4	19.31	0.00	3.88	73.36
PARTS	702-16-71160 SEAT	4	36.55	0.00	7.32	138.88
PARTS	20Y-62-53420 HOSE	1	324.25	0.00	16.21	308.04
PARTS	07000-12018 O- RING	2	2.20	0.00	0.32	4.08
LABOR						1,225.00
MISC.	SHOP SUPPLIES	1.00	85.75		0.00	85.75
MISC.	ENVIRONMENTAL CHARGE	1.00	36.75		0.00	36.75
MISC.	FREIGHT IN	1.00	102.00		0.00	102.00

SEGMENT 4 TOTAL:

PARTS 614.79 LABOR 1,225.00 MISC. 224.50 DISCOUNT 28.21 TOTAL 2,036.08
 (EXCLUDING ENV. LEVY) ENV. LEVY 0.00

SEGMENT 5: REPLACE CUTTING EDGES ON C/U BUCKET

Removed worn cutting edge from C/U bucket
 Cleaned mounting surfaces to ensure proper fitment
 Installed new cutting edge and secured with appropriate hardware
 Verified alignment and tightness of all fasteners
 Job completed and inspected for quality assurance

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS	02091-11605 PLOW BOLT 1"X4"	9	6.05	0.00	0.00	54.45

GST/TPS 89548 3022



REPRINT SERVICE INVOICE

SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1
 TEL: +1-780-451-2630
 SMS CONTACT: TRAVIS WOLFE

INVOICE # : SSI/70443543
 INVOICE DATE : 2025-Mar-24
 CUSTOMER PO : E124- KF
 ORDER # : WO2991497
 ORDER DATE : 2024-Nov-29
 SHIP DATE : Not applicable
 PAYMENT TERMS : NET 30 DAYS
 DELIVERY TERMS : Not applicable

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS	02290-11625	9	1.69	0.00	0.00	15.21
	NUT,HEX, 1"-NC					
PARTS	720074NS 1-	1	782.55	0.00	0.00	782.55
	1/8X16X74 VFDB					
	SLOPER BL (NO					
LABOR						525.00
MISC.	SHOP SUPPLIES	1.00	36.75		0.00	36.75
MISC.	ENVIRONMENTAL CHARGE	1.00	15.75		0.00	15.75

SEGMENT 5 TOTAL:

PARTS 852.21 LABOR 525.00 MISC. 52.50 DISCOUNT 0.00 TOTAL 1,429.71
 (EXCLUDING ENV. LEVY) ENV. LEVY 0.00

SEGMENT 6: WORK EQUIP.REPAIRS

Keeper bolt for h-link pin is not double nutted
 Boom lift cylinder hoses leaking under boom (REPLACE)

RESHIM BOOM BASE, BOOM TO STICK STICK TO Q/A

Gathered necessary materials (catch pan, spill pads, rags, brake cleaner) to prep for hose disconnection
 Released pressure on each flange for all four hoses
 Captured oil from hoses during pressure release
 Removed old hydraulic hoses
 Checked parts availability; new hoses were not in stock and had to be custom-made
 Installed metal caps on machine-side flanges for safe operation until new hoses arrived
 Installed blue plastic caps on cylinder piping to prevent oil leakage
 Cleaned all flanges and bolts with brake cleaner to improve visibility and ensure a clean installation
 Installed all four new hoses in the correct positions
 Sprayed flange connections with brake cleaner to remove residual oil and confirm dry, leak-free connections
 Stick to Coupler Maintenance:

Unpinned stick from coupler
 Inspected and found grease seal missing on the left-hand side and damaged on the right-hand side
 Cleaned out debris and installed new grease seals
 Installed necessary shims and O-rings
 Re-pinned coupler
 Boom Base Pin Service:

Removed boom base pin
 Installed shims for proper fitment
 Reinstalled boom base pin
 Final Inspection:

Verified proper installation and secure fitment of all components
 Ensured the machine was operational and leak-free

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS	207-70-72120 DUST	2	87.23	0.00	8.72	165.74
	SEAL					
PARTS	207-70-24190	4	69.13	0.00	13.84	262.68
	SPACER					



REPRINT SERVICE INVOICE

SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1
 TEL: +1-780-451-2630
 SMS CONTACT: TRAVIS WOLFE

INVOICE # : SSI/70443543
 INVOICE DATE : 2025-Mar-24
 CUSTOMER PO : E124- KF
 ORDER # : WO2991497
 ORDER DATE : 2024-Nov-29
 SHIP DATE : Not applicable
 PAYMENT TERMS : NET 30 DAYS
 DELIVERY TERMS : Not applicable

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS	207-70-73261 SPACER	1	59.89	0.00	2.99	56.90
PARTS	207-70-33181 O- RING	2	53.37	0.00	5.34	101.40
PARTS	207-62-52610 HOSE	2	664.06	0.00	99.60	1,228.52
PARTS	207-62-52621 HOSE	2	418.03	0.00	62.70	773.36
PARTS	FF9446-219 #16 FLANGE 90 DURO O- RING	8	3.12	0.00	1.84	23.12
PARTS	207-70-71271 SPACER	2	100.54	0.00	10.06	191.02
PARTS	207-70-72391 SPACER	2	100.28	0.00	10.02	190.54
PARTS	421-70-11410 O- RING	2	30.39	0.00	3.04	57.74
PARTS	235-46-11710 BOLT	2	26.45	0.00	2.64	50.26
PARTS	01641-20608 WASHER	4	0.92	0.00	0.28	3.40
PARTS	01596-00606 NUT	2	1.54	0.00	0.24	2.84
LABOR						1,400.00
MISC.	SHOP SUPPLIES	1.00	98.00		0.00	98.00
MISC.	ENVIRONMENTAL CHARGE	1.00	42.00		0.00	42.00
MISC.	FREIGHT IN	1.00	35.00		0.00	35.00

SEGMENT 6 TOTAL:

PARTS 3,328.83 LABOR 1,400.00 MISC. 175.00 DISCOUNT 221.31 TOTAL 4,682.52
 (EXCLUDING ENV. LEVY) ENV. LEVY 0.00

SEGMENT 7: REPLACE REMOTE FILTER HOSES FOR ENGINE

Loosened connections on both ends of the two oil hoses
 Disassembled connections on the filter side to allow excess oil to drain, placing a catch pan underneath to collect oil
 Fully drained oil from hoses before proceeding with removal
 Disconnected hose connections on the engine side and loosened the hose clamp
 Noted that the block heater cord was attached to one of the hoses, requiring removal of all zip ties to free the oil hose
 Observed that the block heater cord was not loomed, so it was removed from the block and properly loomed for protection
 Installed new oil hoses and securely tightened all connections
 Reinstalled the block heater cord and secured it neatly with zip ties along the oil hose
 Installed hose clamp to ensure proper positioning and stability of the oil hoses

Verified all connections were secure and leak-free
 Ensured proper routing and protection of the block heater cord

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS	6743-51-9942 HOSE	1	367.81	0.00	18.39	349.42
PARTS	6742-01-4540 CARTRIDGE ENVIRONMENTAL LEVY	1	102.93	0.00	5.15	97.78
						1.25

GST/TPS 89548 3022



REPRINT SERVICE INVOICE

SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1
 TEL: +1-780-451-2630
 SMS CONTACT: TRAVIS WOLFE

INVOICE # : SSI/70443543
 INVOICE DATE : 2025-Mar-24
 CUSTOMER PO : E124- KF
 ORDER # : WO2991497
 ORDER DATE : 2024-Nov-29
 SHIP DATE : Not applicable
 PAYMENT TERMS : NET 30 DAYS
 DELIVERY TERMS : Not applicable

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS	6743-51-9932	1	410.47	0.00	20.52	389.95
	HOSE					
PARTS	07000-B2050 O-	4	23.24	0.00	6.96	86.00
	RING					
PARTS	07000-B3038 O-	4	23.24	0.00	6.96	86.00
	RING					
LABOR						525.00
MISC.	SHOP SUPPLIES	1.00	36.75		0.00	36.75
MISC.	ENVIRONMENTAL CHARGE	1.00	15.75		0.00	15.75

SEGMENT 7 TOTAL:

PARTS 1,067.13 LABOR 525.00 MISC. 52.50 DISCOUNT 57.98 TOTAL 1,587.90
 (EXCLUDING ENV. LEVY) ENV. LEVY 1.25

SEGMENT 8: ADVISE ENGINE OIL LEAKS

Engine oil pan wet
 Diagnose if the oil pan is leaking or if it's caused by another leak.
 Engine oil leak at front cover behind fan
 Investigate and address the source of the oil leak in the front cover area behind the fan.

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
LABOR						525.00
MISC.	SHOP SUPPLIES	1.00	36.75		0.00	36.75
MISC.	ENVIRONMENTAL CHARGE	1.00	15.75		0.00	15.75

SEGMENT 8 TOTAL:

PARTS 0.00 LABOR 525.00 MISC. 52.50 DISCOUNT 0.00 TOTAL 577.50
 (EXCLUDING ENV. LEVY) ENV. LEVY 0.00

SEGMENT 9: ADVISE ON CONTROL LEAKING

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
LABOR						350.00
MISC.	SHOP SUPPLIES	1.00	24.50		0.00	24.50
MISC.	ENVIRONMENTAL CHARGE	1.00	10.50		0.00	10.50

SEGMENT 9 TOTAL:

PARTS 0.00 LABOR 350.00 MISC. 35.00 DISCOUNT 0.00 TOTAL 385.00
 (EXCLUDING ENV. LEVY) ENV. LEVY 0.00

SEGMENT 11: RESEAL SIDE VALVES ON PUMPS

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
--	-------------	----------	------------	-------------	----------	---------



REPRINT SERVICE INVOICE

SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1
 TEL: +1-780-451-2630
 SMS CONTACT: TRAVIS WOLFE

INVOICE # : SSI/70443543
 INVOICE DATE : 2025-Mar-24
 CUSTOMER PO : E124- KF
 ORDER # : WO2991497
 ORDER DATE : 2024-Nov-29
 SHIP DATE : Not applicable
 PAYMENT TERMS : NET 30 DAYS
 DELIVERY TERMS : Not applicable

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
LABOR	HET JM-Aft.-REG	2.00	195.00		0.00	390.00
MISC.	SHOP SUPPLIES	1.00	27.30		0.00	27.30

SEGMENT 11 TOTAL:

PARTS 0.00 **LABOR 390.00** **MISC. 27.30** **DISCOUNT 0.00** **TOTAL 417.30**
 (EXCLUDING ENV. LEVY) **ENV. LEVY 0.00**

SEGMENT 12: PAD SWAP

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS	207-32-07700 GC	1	10,262.34	0.00	769.68	9,492.66
	290/300 96L					
PARTS	207-32-05061	13	128.47	0.00	125.32	1,544.79
	SHOE BOLT KIT					
LABOR	HET APP 80%-Aft.-REG	23.50	195.00		0.00	4,582.50
LABOR	HET JM-Aft.-REG	14.50	195.00		0.00	2,827.50
MISC.	SHOP SUPPLIES	1.00	518.70		0.00	518.70

SEGMENT 12 TOTAL:

PARTS 11,932.45 **LABOR 7,410.00** **MISC. 518.70** **DISCOUNT 895.00** **TOTAL 18,966.15**
 (EXCLUDING ENV. LEVY) **ENV. LEVY 0.00**

SEGMENT 13: PM CLINIC

Service Details:

Gathered tooling and topped up hydraulic oil.
 Performed PM on PC350, following standard procedures, including pre- and post-checks.
 Observed that the machine heats hydraulic oil inefficiently and cools rapidly, leading to more frequent warm-up cycles.
 Set main relief and confirmed LS and PC valve adjustments.
 Detected a persistent leak in the LH assembly during PM.
 Disassembled the LH console and ordered replacement poppet seals and seats for the LH valve assembly.
 Replaced seals and seats, then reassembled the LH console.

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
LABOR						775.00
MISC.	SHOP SUPPLIES	1.00	54.25		0.00	54.25
MISC.	ENVIRONMENTAL CHARGE	1.00	63.00		0.00	63.00

SEGMENT 13 TOTAL:

PARTS 0.00 **LABOR 775.00** **MISC. 117.25** **DISCOUNT 0.00** **TOTAL 892.25**
 (EXCLUDING ENV. LEVY) **ENV. LEVY 0.00**

SEGMENT 14: BLOCK UP R&I RAILS

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
--	-------------	----------	------------	-------------	----------	---------

GST/TPS 89548 3022



REPRINT SERVICE INVOICE

SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1
 TEL: +1-780-451-2630
 SMS CONTACT: TRAVIS WOLFE

INVOICE # : SSI/70443543
 INVOICE DATE : 2025-Mar-24
 CUSTOMER PO : E124- KF
 ORDER # : WO2991497
 ORDER DATE : 2024-Nov-29
 SHIP DATE : Not applicable
 PAYMENT TERMS : NET 30 DAYS
 DELIVERY TERMS : Not applicable

DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
LABOR					2,340.00
MISC. SHOP SUPPLIES	1.00	163.80		0.00	163.80

SEGMENT 14 TOTAL:

PARTS 0.00 LABOR 2,340.00 MISC. 163.80 DISCOUNT 0.00 TOTAL 2,503.80
 (EXCLUDING ENV. LEVY) ENV. LEVY 0.00

SEGMENT 15: S&I LH IDLER

Service Details:

Removed LH cannon assembly.
 Removed idler from recoil.
 Installed new idler on recoil.
 Reinstalled LH assembly.
 Removed RH cannon assembly and rotated the ram to position the grease fitting correctly.
 Reinstalled RH assembly.

DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS 207-30-00164	1	1,895.20	0.00	142.14	1,753.06
IDLER ASSY					
PARTS 01010-62075 BOLT	4	26.88	0.00	8.08	99.44
LABOR					525.00
MISC. SHOP SUPPLIES	1.00	36.75		0.00	36.75
MISC. ENVIRONMENTAL CHARGE	1.00	15.75		0.00	15.75

SEGMENT 15 TOTAL:

PARTS 2,002.72 LABOR 525.00 MISC. 52.50 DISCOUNT 150.22 TOTAL 2,430.00
 (EXCLUDING ENV. LEVY) ENV. LEVY 0.00



REPRINT SERVICE INVOICE

SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1
 TEL: +1-780-451-2630
 SMS CONTACT: TRAVIS WOLFE

INVOICE # : SSI/70443543
 INVOICE DATE : 2025-Mar-24
 CUSTOMER PO : E124- KF
 ORDER # : WO2991497
 ORDER DATE : 2024-Nov-29
 SHIP DATE : Not applicable
 PAYMENT TERMS : NET 30 DAYS
 DELIVERY TERMS : Not applicable

SEGMENT 16: REPAIR ENGINE OIL LEAKS

- REPLACE LEAKING TURBO
- REPLACE ENGINE OIL PAN GASKET

Engine Oil Pan Service:
 Removed underguards below engine and pump
 Drained engine oil
 Removed oil pan
 Removed intermediate plate and oil pickup tube
 Cleaned off all old gasket and sealant residue
 Cleaned oil pan thoroughly
 Prepped new gaskets on the intermediate plate and oil pan with LG-7 for installation
 Installed intermediate plate and oil pickup tube
 Torqued pickup tube mounting hardware to 7.8NM per spec
 Installed oil pan and torqued in sequence to 24NM per spec
 Replaced engine oil filter
 Refilled engine oil to full capacity
 Reinstalled underguards
 Turbo Replacement:
 Removed turbo assembly
 Heated turbo manifold studs to facilitate extraction
 Cleaned up mating surfaces for a proper seal
 Tapped manifold holes for new stud installation
 Installed new studs, gaskets, and O-rings
 Installed new turbo
 Reassembled all intake and exhaust boots
 Tested unit to ensure proper operation

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS	R6745-82-8010 TURBO	1	2,879.07	679.66	143.95	3,414.78
PARTS	6742-01-3620 CLAMP	1	112.64	0.00	5.63	107.01
PARTS	6732-81-8830 GASKET	1	18.68	0.00	0.93	17.75
PARTS	1317956H1 GSKT,OIL PAN (R	1	11.83	0.00	0.59	11.24
PARTS	6732-81-8810 STUD	4	38.32	0.00	7.68	145.60
PARTS	6732-81-8820 NUT	4	9.97	0.00	2.00	37.88
PARTS	1307596H1 GASKET	2	573.38	0.00	57.34	1,089.42
PARTS	CR6745-82-8010 TURBO	-1	339.83	0.00	0.00	-339.83
LABOR						2,100.00
MISC.	SHOP SUPPLIES	1.00	147.00		0.00	147.00
MISC.	ENVIRONMENTAL CHARGE	1.00	63.00		0.00	63.00

SEGMENT 16 TOTAL:

PARTS 4,701.97 LABOR 2,100.00 MISC. 210.00 DISCOUNT 218.12 TOTAL 6,793.85
 (EXCLUDING ENV. LEVY) ENV. LEVY 0.00

GST/TPS 89548 3022



SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1
 TEL: +1-780-451-2630
 SMS CONTACT: TRAVIS WOLFE

REPRINT SERVICE INVOICE

INVOICE # : SSI/70443543
 INVOICE DATE : 2025-Mar-24
 CUSTOMER PO : E124-KF
 ORDER # : WO2991497
 ORDER DATE : 2024-Nov-29
 SHIP DATE : Not applicable
 PAYMENT TERMS : NET 30 DAYS
 DELIVERY TERMS : Not applicable

SEGMENT 17: RE-SEAL CONTROL VALVE (SEE NOTES)
 THIS QUOTE IS TO RE-SEAL THE TOP TWO SECTIONS OF THE CONTROL VALVE

Connected transducer for testing
 Disconnected pilot lines
 Removed cap bolts and installed guide studs for controlled disassembly
 Removed top valve section
 Removed second valve section
 Cleaned top and bottom mounting surfaces to ensure proper sealing
 Installed and lubricated new O-rings
 Reinstalled valve sections
 Reused old bolts as new ones were not available at the time
 Placed new washers in the cab for future installation
 Torqued bolts in sequence to 175NM (spec: 156.9NM - 176.5NM)
 Reinstalled panels removed for inspection
 Cleaned up parts and tools in the work area

DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS 723-11-19130 O-	4	8.62	0.00	1.72	32.76
PARTS RING 07000-13032 O-	4	5.83	0.00	0.00	23.32
PARTS RING 723-46-17510 O-	4	3.77	0.00	0.76	14.32
PARTS RING 723-46-17520 O-	4	4.23	0.00	0.84	16.08
PARTS RING 723-46-17530 O-	4	3.77	0.00	0.76	14.32
PARTS BOLT 723-46-15220	4	44.42	0.00	8.88	168.80
PARTS WASHER 01643-31445	6	2.23	0.00	0.00	13.38
LABOR SHOP SUPPLIES ENVIRONMENTAL CHARGE	1.00	73.50		0.00	1,050.00
MISC. 105.00 ENV. LEVY 0.00					73.50
DISCOUNT 12.96					13.38
TOTAL 1,437.98					31.50

SEGMENT 17 TOTAL:

PARTS 295.94 (EXCLUDING ENV. LEVY)
 LABOR 1,050.00



REPRINT SERVICE INVOICE

SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1
 TEL: +1-780-451-2630
 SMS CONTACT: TRAVIS WOLFE

INVOICE # : SSI/70443543
 INVOICE DATE : 2025-Mar-24
 CUSTOMER PO : E124- KF
 ORDER # : WO2991497
 ORDER DATE : 2024-Nov-29
 SHIP DATE : Not applicable
 PAYMENT TERMS : NET 30 DAYS
 DELIVERY TERMS : Not applicable

THANK YOU FOR YOUR BUSINESS!

REMIT PAYMENT TO:

VIA REGULAR MAIL: or

VIA COURIER:

Indicate this address on the waybill

SMS EQUIPMENT INC.
 C/O CX2572C (CAD PAYMENT)
 OR CX2572U (USD PAYMENT)
 PO BOX 2591
 CALGARY, AB T2P 0A3

SYMCOR WHOLESALE LOCKBOX
 C/O CIBC LOCKBOX -
 C/O CX2572C (CAD PAYMENT)
 OR CX2572U (USD PAYMENT)
 SMS EQUIPMENT INC.
 3663 63RD AVE NE
 CALGARY, AB T3J 0G6

PARTS (EXCLUDING ENV. LEVY):	27,352.60
LABOR:	21,765.00
MISC.:	1,986.05
DISCOUNT:	(1,758.90)
ENVIRONMENTAL LEVY:	1.25
SUBTOTAL:	49,346.00
GST/TPS	2,467.30
TOTAL (CAD)	51,813.30



SERVICE PROFORMA INVOICE

SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1
 TEL: +1-780-451-2630
 SMS CONTACT: TRAVIS WOLFE

CUSTOMER PO :
 ORDER # : WO2991497
 ORDER DATE : 2024-Nov-29
 SHIP DATE : Not applicable
 PAYMENT TERMS : NET 30 DAYS
 DELIVERY TERMS : Not applicable

BILL TO:
 M.A.P. WATER AND SEWER
 SERVICES LTD.
 14303 - 116 AVENUE
 EDMONTON AB T5N 4G2

WORK SITE:
 SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1

Manufacturer : KOMATSU	Customer Unit No : E124
Model : PC350LC-8	Meter Reading : 16646.83
Serial Number : A10039	SMS Unit No : MD0004272
Service Rep : ROBERT MCGOWAN	

SEGMENT 1: SUPPLY SPROCKETS,HW EXTERNAL CUSTOMER - SHOP

Lifted machine onto stands
 Removed pad from each rail
 Loosened track tension (RH side had rotated and had to be accessed from around the bottom roller)
 Cut both rails with a torch
 Dragged out rails
 Folded tracks and placed them in Bay 8 staging

THANK YOU FOR YOUR BUSINESS!

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS	207-27-71460 SPROCKET	2	1,039.40	0.00	155.90	1,922.90
PARTS	207-27-51311 BOLT	40	6.43	0.00	19.20	238.00
LABOR						2,100.00
MISC.	SHOP SUPPLIES	1.00	147.00		0.00	147.00

SEGMENT 1 TOTAL:

PARTS 2,336.00 LABOR 2,100.00 MISC. 147.00 DISCOUNT 175.10 TOTAL 4,407.90
 (EXCLUDING ENV. LEVY) ENV. LEVY 0.00

SEGMENT 3: REPLACE FRONT WINDOW ROLLERS EXTERNAL CUSTOMER - SHOP

Changed out rollers on the front window
 Confirmed positioning of rollers in the parts book

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS	20Y-54-52621 ROLLER	2	57.50	0.00	0.00	115.00
PARTS	20Y-54-52681 ROLLER	2	52.78	0.00	0.00	105.56
LABOR						525.00
MISC.	SHOP SUPPLIES	1.00	36.75		0.00	36.75
MISC.	ENVIRONMENTAL CHARGE	1.00	15.75		0.00	15.75

SEGMENT 3 TOTAL:

PARTS 220.56 LABOR 525.00 MISC. 52.50 DISCOUNT 0.00 TOTAL 798.06
 (EXCLUDING ENV. LEVY) ENV. LEVY 0.00

SEGMENT 4: RESEAL BOTH PPC CONTROL VALVE IN CAB EXTERNAL CUSTOMER - SHOP

GST/TPS 89548 3022



SERVICE PROFORMA INVOICE

SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1
 TEL: +1-780-451-2630
 SMS CONTACT: TRAVIS WOLFE

CUSTOMER PO :
 ORDER # : WO2991497
 ORDER DATE : 2024-Nov-29
 SHIP DATE : Not applicable
 PAYMENT TERMS : NET 30 DAYS
 DELIVERY TERMS : Not applicable

Description of Services Rendered:

Resealed both PPC control valves in cab:
 Removed old seals from both PPC control valves.
 Cleaned and inspected valve surfaces to ensure proper seating of new seals.
 Installed new seals on both control valves.
 Ensured that valves were properly sealed to prevent leaks.
 Reassembled the control valves and ensured functionality.
 Tested the valves to confirm proper operation after resealing.

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS	07000-12018 O-RING	4	2.20	0.00	0.00	8.80
PARTS	07000-12015 O-RING	4	2.29	0.00	0.00	9.16
PARTS	02896-11009 O-RING	6	3.25	0.00	0.00	19.50
PARTS	07002-11423 O-RING	8	2.36	0.00	0.00	18.88
PARTS	02896-11008 O-RING	2	3.18	0.00	0.48	5.88
PARTS	702-16-71150 SEAL	4	19.31	0.00	3.88	73.36
PARTS	702-16-71160 SEAT	4	36.55	0.00	7.32	138.88
PARTS	20Y-62-53420 HOSE	1	324.25	0.00	16.21	308.04
PARTS	07000-12018 O-RING	2	2.20	0.00	0.32	4.08
LABOR						1,225.00
MISC.	SHOP SUPPLIES	1.00	85.75		0.00	85.75
MISC.	ENVIRONMENTAL CHARGE	1.00	36.75		0.00	36.75
MISC.	FREIGHT IN	1.00	102.00		0.00	102.00

SEGMENT 4 TOTAL:

PARTS 614.79 LABOR 1,225.00 MISC. 224.50 DISCOUNT 28.21 TOTAL 2,036.08
 (EXCLUDING ENV. LEVY) ENV. LEVY 0.00

SEGMENT 5: REPLACE CUTTING EDGES ON C/U BUCKET EXTERNAL CUSTOMER - SHOP

Removed worn cutting edge from C/U bucket
 Cleaned mounting surfaces to ensure proper fitment
 Installed new cutting edge and secured with appropriate hardware
 Verified alignment and tightness of all fasteners
 Job completed and inspected for quality assurance

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS	02091-11605 PLOW	9	6.05	0.00	0.00	54.45
PARTS	BOLT 1"X4"					
PARTS	02290-11625 NUT,HEX, 1"-NC	9	1.69	0.00	0.00	15.21
PARTS	720074NS 1-1/8X16X74 VFDB SLOPER BL (NO	1	782.55	0.00	0.00	782.55
LABOR						525.00
MISC.	SHOP SUPPLIES	1.00	36.75		0.00	36.75
MISC.	ENVIRONMENTAL CHARGE	1.00	15.75		0.00	15.75

GST/TPS 89548 3022



SERVICE PROFORMA INVOICE

SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1
 TEL: +1-780-451-2630
 SMS CONTACT: TRAVIS WOLFE

CUSTOMER PO :
 ORDER # : WO2991497
 ORDER DATE : 2024-Nov-29
 SHIP DATE : Not applicable
 PAYMENT TERMS : NET 30 DAYS
 DELIVERY TERMS : Not applicable

SEGMENT 5 TOTAL:

PARTS 852.21 LABOR 525.00 MISC. 52.50 DISCOUNT 0.00 TOTAL 1,429.71
 (EXCLUDING ENV. LEVY) ENV. LEVY 0.00

SEGMENT 6: WORK EQUIP.REPAIRS EXTERNAL CUSTOMER - SHOP

Keeper bolt for h-link pin is not double nutted
 Boom lift cylinder hoses leaking under boom (REPLACE)

RESHIM BOOM BASE, BOOM TO STICK STICK TO Q/A

Gathered necessary materials (catch pan, spill pads, rags, brake cleaner) to prep for hose disconnection
 Released pressure on each flange for all four hoses
 Captured oil from hoses during pressure release
 Removed old hydraulic hoses
 Checked parts availability; new hoses were not in stock and had to be custom-made
 Installed metal caps on machine-side flanges for safe operation until new hoses arrived
 Installed blue plastic caps on cylinder piping to prevent oil leakage
 Cleaned all flanges and bolts with brake cleaner to improve visibility and ensure a clean installation
 Installed all four new hoses in the correct positions
 Sprayed flange connections with brake cleaner to remove residual oil and confirm dry, leak-free connections
 Stick to Coupler Maintenance:

Unpinned stick from coupler
 Inspected and found grease seal missing on the left-hand side and damaged on the right-hand side
 Cleaned out debris and installed new grease seals
 Installed necessary shims and O-rings
 Re-pinned coupler
 Boom Base Pin Service:

Removed boom base pin
 Installed shims for proper fitment
 Reinstalled boom base pin
 Final Inspection:

Verified proper installation and secure fitment of all components
 Ensured the machine was operational and leak-free

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS	207-70-72120 DUST SEAL	2	87.23	0.00	8.72	165.74
PARTS	207-70-24190 SPACER	4	69.13	0.00	13.84	262.68
PARTS	207-70-73261 SPACER	1	59.89	0.00	2.99	56.90
PARTS	207-70-33181 O-RING	2	53.37	0.00	5.34	101.40
PARTS	207-62-52610 HOSE	2	664.06	0.00	99.60	1,228.52
PARTS	207-62-52621 HOSE	2	418.03	0.00	62.70	773.36
PARTS	FF9446-219 #16 FLANGE 90 DURO O-RING	8	3.12	0.00	1.84	23.12
PARTS	207-70-71271 SPACER	2	100.54	0.00	10.06	191.02
PARTS	207-70-72391 SPACER	2	100.28	0.00	10.02	190.54
PARTS	421-70-11410 O-RING	2	30.39	0.00	3.04	57.74

GST/TPS 89548 3022



SERVICE PROFORMA INVOICE

SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1
 TEL: +1-780-451-2630
 SMS CONTACT: TRAVIS WOLFE

CUSTOMER PO :
 ORDER # : WO2991497
 ORDER DATE : 2024-Nov-29
 SHIP DATE : Not applicable
 PAYMENT TERMS : NET 30 DAYS
 DELIVERY TERMS : Not applicable

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS	235-46-11710 BOLT	2	26.45	0.00	2.64	50.26
PARTS	01641-20608 WASHER	4	0.92	0.00	0.28	3.40
PARTS	01596-00606 NUT	2	1.54	0.00	0.24	2.84
LABOR						1,400.00
MISC.	SHOP SUPPLIES	1.00	98.00		0.00	98.00
MISC.	ENVIRONMENTAL CHARGE	1.00	42.00		0.00	42.00
MISC.	FREIGHT IN	1.00	35.00		0.00	35.00

SEGMENT 6 TOTAL:

PARTS 3,328.83 **LABOR 1,400.00** **MISC. 175.00** **DISCOUNT 221.31** **TOTAL 4,682.52**
(EXCLUDING ENV. LEVY) **ENV. LEVY 0.00**

SEGMENT 7: REPLACE REMOTE FILTER HOSES FOR ENGINE EXTERNAL CUSTOMER - SHOP

Loosened connections on both ends of the two oil hoses
 Disassembled connections on the filter side to allow excess oil to drain, placing a catch pan underneath to collect oil
 Fully drained oil from hoses before proceeding with removal
 Disconnected hose connections on the engine side and loosened the hose clamp
 Noted that the block heater cord was attached to one of the hoses, requiring removal of all zip ties to free the oil hose
 Observed that the block heater cord was not loomed, so it was removed from the block and properly loomed for protection
 Installed new oil hoses and securely tightened all connections
 Reinstalled the block heater cord and secured it neatly with zip ties along the oil hose
 Installed hose clamp to ensure proper positioning and stability of the oil hoses

Verified all connections were secure and leak-free
 Ensured proper routing and protection of the block heater cord

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS	6743-51-9942 HOSE	1	367.81	0.00	18.39	349.42
PARTS	6742-01-4540 CARTRIDGE	1	102.93	0.00	5.15	97.78
	ENVIORNMENTAL LEVY					1.25
PARTS	6743-51-9932 HOSE	1	410.47	0.00	20.52	389.95
PARTS	07000-B2050 O-RING	4	23.24	0.00	6.96	86.00
PARTS	07000-B3038 O-RING	4	23.24	0.00	6.96	86.00
LABOR						525.00
MISC.	SHOP SUPPLIES	1.00	36.75		0.00	36.75
MISC.	ENVIRONMENTAL CHARGE	1.00	15.75		0.00	15.75

SEGMENT 7 TOTAL:

PARTS 1,067.13 **LABOR 525.00** **MISC. 52.50** **DISCOUNT 57.98** **TOTAL 1,587.90**
(EXCLUDING ENV. LEVY) **ENV. LEVY 1.25**

SEGMENT 8: ADVISE ENGINE OIL LEAKS EXTERNAL CUSTOMER - SHOP

GST/TPS 89548 3022



SERVICE PROFORMA INVOICE

SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1
 TEL: +1-780-451-2630
 SMS CONTACT: TRAVIS WOLFE

CUSTOMER PO :
 ORDER # : WO2991497
 ORDER DATE : 2024-Nov-29
 SHIP DATE : Not applicable
 PAYMENT TERMS : NET 30 DAYS
 DELIVERY TERMS : Not applicable

Engine oil pan wet
 Diagnose if the oil pan is leaking or if it's caused by another leak.
 Engine oil leak at front cover behind fan
 Investigate and address the source of the oil leak in the front cover area behind the fan.

DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
LABOR					525.00
MISC. SHOP SUPPLIES	1.00	36.75			36.75
MISC. ENVIRONMENTAL CHARGE	1.00	15.75		0.00	15.75

SEGMENT 8 TOTAL:

PARTS 0.00 (EXCLUDING ENV. LEVY) LABOR 525.00 MISC. 52.50 ENV. LEVY 0.00 DISCOUNT 0.00 TOTAL 577.50

SEGMENT 9: ADVISE ON CONTROL LEAKING EXTERNAL CUSTOMER - SHOP

DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
LABOR					350.00
MISC. SHOP SUPPLIES	1.00	24.50		0.00	24.50
MISC. ENVIRONMENTAL CHARGE	1.00	10.50		0.00	10.50

SEGMENT 9 TOTAL:

PARTS 0.00 (EXCLUDING ENV. LEVY) LABOR 350.00 MISC. 35.00 ENV. LEVY 0.00 DISCOUNT 0.00 TOTAL 385.00

SEGMENT 11: RESEAL SIDE VALVES ON PUMPS EXTERNAL CUSTOMER - SHOP

DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
LABOR HET JM-Aft.-REG	2.00	195.00		0.00	390.00
MISC. SHOP SUPPLIES	1.00	27.30		0.00	27.30

SEGMENT 11 TOTAL:

PARTS 0.00 (EXCLUDING ENV. LEVY) LABOR 390.00 MISC. 27.30 ENV. LEVY 0.00 DISCOUNT 0.00 TOTAL 417.30

SEGMENT 12: PAD SWAP EXTERNAL CUSTOMER - SHOP

DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS 207-32-07700 GC 290/300 96L	1	10,262.34	0.00	769.68	9,492.66
PARTS 207-32-05061 SHOE BOLT KIT	13	128.47	0.00	125.32	1,544.79
LABOR HET APP 80%-Aft.-REG	23.50	195.00		0.00	4,582.50
LABOR HET JM-Aft.-REG	14.50	195.00		0.00	2,827.50
MISC. SHOP SUPPLIES	1.00	518.70		0.00	518.70

GST/TPS 89548 3022



SERVICE PROFORMA INVOICE

SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1
 TEL: +1-780-451-2630
 SMS CONTACT: TRAVIS WOLFE

CUSTOMER PO :
 ORDER # : WO2991497
 ORDER DATE : 2024-Nov-29
 SHIP DATE : Not applicable
 PAYMENT TERMS : NET 30 DAYS
 DELIVERY TERMS : Not applicable

SEGMENT 12 TOTAL:

PARTS 11,932.45 LABOR 7,410.00 MISC. 518.70 DISCOUNT 895.00 TOTAL 18,966.15
 (EXCLUDING ENV. LEVY) ENV. LEVY 0.00

SEGMENT 13: PM CLINIC EXTERNAL CUSTOMER - SHOP

Service Details:

Gathered tooling and topped up hydraulic oil.
 Performed PM on PC350, following standard procedures, including pre- and post-checks.
 Observed that the machine heats hydraulic oil inefficiently and cools rapidly, leading to more frequent warm-up cycles.
 Set main relief and confirmed LS and PC valve adjustments.
 Detected a persistent leak in the LH assembly during PM.
 Disassembled the LH console and ordered replacement poppet seals and seats for the LH valve assembly.
 Replaced seals and seats, then reassembled the LH console.

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
LABOR						775.00
MISC.	SHOP SUPPLIES	1.00	54.25		0.00	54.25
MISC.	ENVIRONMENTAL CHARGE	1.00	63.00		0.00	63.00

SEGMENT 13 TOTAL:

PARTS 0.00 LABOR 775.00 MISC. 117.25 DISCOUNT 0.00 TOTAL 892.25
 (EXCLUDING ENV. LEVY) ENV. LEVY 0.00

SEGMENT 14: BLOCK UP R&I RAILS EXTERNAL CUSTOMER - SHOP

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
LABOR						2,340.00
MISC.	SHOP SUPPLIES	1.00	163.80		0.00	163.80

SEGMENT 14 TOTAL:

PARTS 0.00 LABOR 2,340.00 MISC. 163.80 DISCOUNT 0.00 TOTAL 2,503.80
 (EXCLUDING ENV. LEVY) ENV. LEVY 0.00

SEGMENT 15: S&I LH IDLER EXTERNAL CUSTOMER - SHOP

Service Details:

Removed LH cannon assembly.
 Removed idler from recoil.
 Installed new idler on recoil.
 Reinstalled LH assembly.
 Removed RH cannon assembly and rotated the ram to position the grease fitting correctly.
 Reinstalled RH assembly.

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS	207-30-00164 IDLER ASS'Y	1	1,895.20	0.00	142.14	1,753.06

GST/TPS 89548 3022



SERVICE PROFORMA INVOICE

SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1
 TEL: +1-780-451-2630
 SMS CONTACT: TRAVIS WOLFE

CUSTOMER PO :
 ORDER # : WO2991497
 ORDER DATE : 2024-Nov-29
 SHIP DATE : Not applicable
 PAYMENT TERMS : NET 30 DAYS
 DELIVERY TERMS : Not applicable

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS	01010-62075 BOLT	4	26.88	0.00	8.08	99.44
LABOR						525.00
MISC.	SHOP SUPPLIES	1.00	36.75		0.00	36.75
MISC.	ENVIRONMENTAL CHARGE	1.00	15.75		0.00	15.75

SEGMENT 15 TOTAL:

PARTS 2,002.72 LABOR 525.00 MISC. 52.50 DISCOUNT 150.22 TOTAL 2,430.00
 (EXCLUDING ENV. LEVY) ENV. LEVY 0.00

SEGMENT 16: REPAIR ENGINE OIL LEAKS EXTERNAL CUSTOMER - SHOP

- REPLACE LEAKING TURBO
- REPLACE ENGINE OIL PAN GASKET

Engine Oil Pan Service:

- Removed underguards below engine and pump
- Drained engine oil
- Removed oil pan
- Removed intermediate plate and oil pickup tube
- Cleaned off all old gasket and sealant residue
- Cleaned oil pan thoroughly
- Prepped new gaskets on the intermediate plate and oil pan with LG-7 for installation
- Installed intermediate plate and oil pickup tube
- Torqued pickup tube mounting hardware to 7.8NM per spec
- Installed oil pan and torqued in sequence to 24NM per spec
- Replaced engine oil filter
- Refilled engine oil to full capacity
- Reinstalled underguards
- Turbo Replacement:**
- Removed turbo assembly
- Heated turbo manifold studs to facilitate extraction
- Cleaned up mating surfaces for a proper seal
- Tapped manifold holes for new stud installation
- Installed new studs, gaskets, and O-rings
- Installed new turbo
- Reassembled all intake and exhaust boots
- Tested unit to ensure proper operation

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS	R6745-82-8010 TURBO	1	2,879.07	679.66	143.95	3,414.78
PARTS	6742-01-3620 CLAMP	1	112.64	0.00	5.63	107.01
PARTS	6732-81-8830 GASKET	1	18.68	0.00	0.93	17.75
PARTS	1317956H1 GSKT,OIL PAN (R	1	11.83	0.00	0.59	11.24
PARTS	6732-81-8810 STUD	4	38.32	0.00	7.68	145.60
PARTS	6732-81-8820 NUT	4	9.97	0.00	2.00	37.88
PARTS	1307596H1 GASKET	2	573.38	0.00	57.34	1,089.42
PARTS	CR6745-82-8010 TURBO	-1	-679.66	0.00	0.00	-679.66
LABOR						2,100.00

GST/TPS 89548 3022



SERVICE PROFORMA INVOICE

SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1
 TEL: +1-780-451-2630
 SMS CONTACT: TRAVIS WOLFE

CUSTOMER PO :
 ORDER # : WO2991497
 ORDER DATE : 2024-Nov-29
 SHIP DATE : Not applicable
 PAYMENT TERMS : NET 30 DAYS
 DELIVERY TERMS : Not applicable

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
MISC.	SHOP SUPPLIES	1.00	147.00		0.00	147.00
MISC.	ENVIRONMENTAL CHARGE	1.00	63.00		0.00	63.00

SEGMENT 16 TOTAL:

PARTS 4,362.14 LABOR 2,100.00 MISC. 210.00 DISCOUNT 218.12 TOTAL 6,454.02
 (EXCLUDING ENV. LEVY) ENV. LEVY 0.00

SEGMENT 17: RE-SEAL CONTROL VALVE (SEE NOTES) EXTERNAL CUSTOMER - SHOP

THIS QUOTE IS TO RE-SEAL THE TOP TWO SECTIONS OF THE CONTROL VALVE

- Connected transducer for testing
- Disconnected pilot lines
- Removed cap bolts and installed guide studs for controlled disassembly
- Removed top valve section
- Removed second valve section
- Cleaned top and bottom mounting surfaces to ensure proper sealing
- Installed and lubricated new O-rings
- Reinstalled valve sections
- Reused old bolts as new ones were not available at the time
- Placed new washers in the cab for future installation
- Torqued bolts in sequence to 175NM (spec: 156.9NM - 176.5NM)
- Reinstalled panels removed for inspection
- Cleaned up parts and tools in the work area

	DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS	723-11-19130 O-RING	4	8.62	0.00	1.72	32.76
PARTS	07000-13032 O-RING	4	5.83	0.00	0.00	23.32
PARTS	723-46-17510 O-RING	4	3.77	0.00	0.76	14.32
PARTS	723-46-17520 RING	4	4.23	0.00	0.84	16.08
PARTS	723-46-17530 O-RING	4	3.77	0.00	0.76	14.32
PARTS	723-46-15220 BOLT	4	44.42	0.00	8.88	168.80
PARTS	01643-31445 WASHER	6	2.23	0.00	0.00	13.38
LABOR						1,050.00
MISC.	SHOP SUPPLIES	1.00	73.50		0.00	73.50
MISC.	ENVIRONMENTAL CHARGE	1.00	31.50		0.00	31.50

SEGMENT 17 TOTAL:

PARTS 295.94 LABOR 1,050.00 MISC. 105.00 DISCOUNT 12.96 TOTAL 1,437.98
 (EXCLUDING ENV. LEVY) ENV. LEVY 0.00



SERVICE PROFORMA INVOICE

SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1
 TEL: +1-780-451-2630
 SMS CONTACT: TRAVIS WOLFE

CUSTOMER PO :
 ORDER # : WO2991497
 ORDER DATE : 2024-Nov-29
 SHIP DATE : Not applicable
 PAYMENT TERMS : NET 30 DAYS
 DELIVERY TERMS : Not applicable

BILL TO: C00011211
 M.A.P. WATER AND SEWER
 SERVICES LTD.
 14303 - 116 AVENUE
 EDMONTON AB T5N 4G2

WORK SITE:
 SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1

THANK YOU FOR YOUR BUSINESS!

REMIT PAYMENT TO:

VIA REGULAR MAIL: or

VIA COURIER:

Indicate this address on the waybill

SMS EQUIPMENT INC.
 C/O CX2572C (CAD PAYMENT)
 OR CX2572U (USD PAYMENT)
 PO BOX 2591
 CALGARY, AB T2P 0A3

SYMCOR WHOLESALE LOCKBOX
 C/O CIBC LOCKBOX -
 C/O CX2572C (CAD PAYMENT)
 OR CX2572U (USD PAYMENT)
 SMS EQUIPMENT INC.
 3663 63RD AVE NE
 CALGARY, AB T3J 0G6

PARTS (EXCLUDING ENV. LEVY):	27,012.77
LABOR:	21,765.00
MISC.:	1,986.05
DISCOUNT:	(1,758.90)
ENVIRONMENTAL LEVY:	1.25
SUBTOTAL:	49,006.17

GST/TPS	2,450.31
---------	----------

TOTAL (CAD): 51,456.48

WORK AUTHORIZATION

I hereby acknowledge and authorize the above described labour, materials and miscellaneous charges, plus any transportation charges and travel expenses incurred by SMS Equipment Inc.; and I agree to pay upon completion of the work, or on terms acceptable to SMS Equipment Inc.'s credit department in its discretion, the above invoice grand total, any transportation charges and travel expenses, and any other usual and customary charges of SMS EQUIPMENT Inc. in relation to the work, it being further understood and agreed that SMS Equipment Inc. is not responsible for, and is hereby released from, any liability in respect of fire or theft loss to the above described equipment or any personal property left therewith.

PRINT NAME _____ CUSTOMER'S SIGNATURE OR AUTHORIZED AGENT _____

POSITION _____ DATE SIGNED _____

ACKNOWLEDGEMENT OF DEBT

I hereby acknowledge indebtedness to SMS Equipment Inc. in the aggregate amount of the charges and expenses hereinbefore set out, and agree that the amount overdue shall bear interest compounded at a rate of 2% per month (26.8% PER ANNUM)

PRINT NAME _____ CUSTOMER'S SIGNATURE OR AUTHORIZED AGENT _____

POSITION _____ DATE SIGNED _____



SERVICE PROFORMA INVOICE

SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1
 TEL: +1-780-451-2630
 SMS CONTACT: TRAVIS WOLFE

CUSTOMER PO : REQ
 ORDER # : WO2983793
 ORDER DATE : 2023-Aug-02
 SHIP DATE : Not applicable
 PAYMENT TERMS : NET 30 DAYS
 DELIVERY TERMS : Not applicable

BILL TO:
 M.A.P. WATER AND SEWER
 SERVICES LTD.
 14303 - 116 AVENUE
 EDMONTON AB T5N 4G2

WORK SITE:
 SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1

Manufacturer : KOMATSU	Customer Unit No : E124
Model : PC350LC-8	Meter Reading : 15440.22
Serial Number : A10039	SMS Unit No : MD0004272
Service Rep : CYPYSS BADGER	

SEGMENT 1: TRAVEL EXTERNAL CUSTOMER - FIELD

DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
MISC. Segment Charges					330.00

SEGMENT 1 TOTAL:

PARTS 0.00 LABOR 0.00 MISC. 330.00 DISCOUNT 0.00 TOTAL 330.00
 (EXCLUDING ENV. LEVY) ENV. LEVY 0.00

SEGMENT 2: ADVISE ON ENGINE ERROR CODE - SPEED SENSOR EXTERNAL CUSTOMER - FIELD

Inspected wiring to speed sensor, removed sensor and found the housing to be cracked. Ordered new.
 Picked up sensor and went to unit and installed new sensor
 Ran unit and verified no errors

DESCRIPTION	QUANTITY	UNIT PRICE	CORE CHARGE	DISCOUNT	NET AMT
PARTS R6261-81-2903 SENSOR ASSY	1	141.82	14.00	0.00	155.82
LABOR					742.50
MISC. SHOP SUPPLIES	1.00	51.98		0.00	51.98
MISC. ENVIRONMENTAL CHARGE	1.00	22.28		0.00	22.28

SEGMENT 2 TOTAL:

PARTS 155.82 LABOR 742.50 MISC. 74.26 DISCOUNT 0.00 TOTAL 972.58
 (EXCLUDING ENV. LEVY) ENV. LEVY 0.00



SERVICE PROFORMA INVOICE

SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1
 TEL: +1-780-451-2630
 SMS CONTACT: TRAVIS WOLFE

CUSTOMER PO : REQ
 ORDER # : WO2983793
 ORDER DATE : 2023-Aug-02
 SHIP DATE : Not applicable
 PAYMENT TERMS : NET 30 DAYS
 DELIVERY TERMS : Not applicable

BILL TO: C00011211
 M.A.P. WATER AND SEWER
 SERVICES LTD.
 14303 - 116 AVENUE
 EDMONTON AB T5N 4G2

WORK SITE:
 SMS EQUIPMENT INC.
 16116 - 111 AVENUE
 EDMONTON AB T5M 2S1

THANK YOU FOR YOUR BUSINESS!

REMIT PAYMENT TO:

VIA REGULAR MAIL: or

VIA COURIER:

Indicate this address on the waybill

SMS EQUIPMENT INC.
 C/O CX2572C (CAD PAYMENT)
 OR CX2572U (USD PAYMENT)
 PO BOX 2591
 CALGARY, AB T2P 0A3

SYMCOR WHOLESALE LOCKBOX
 C/O CIBC LOCKBOX -
 C/O CX2572C (CAD PAYMENT)
 OR CX2572U (USD PAYMENT)
 SMS EQUIPMENT INC.
 3663 63RD AVE NE
 CALGARY, AB T3J 0G6

PARTS (EXCLUDING ENV. LEVY):	155.82
LABOR:	742.50
MISC.:	404.26
DISCOUNT:	(0.00)
ENVIRONMENTAL LEVY:	
SUBTOTAL:	1,302.58
GST/TPS	65.13

TOTAL (CAD): 1,367.71

WORK AUTHORIZATION

I hereby acknowledge and authorize the above described labour, materials and miscellaneous charges, plus any transportation charges and travel expenses incurred by SMS Equipment Inc.; and I agree to pay upon completion of the work, or on terms acceptable to SMS Equipment Inc.'s credit department in its discretion, the above invoice grand total, any transportation charges and travel expenses, and any other usual and customary charges of SMS EQUIPMENT Inc. in relation to the work, it being further understood and agreed that SMS Equipment Inc. is not responsible for, and is hereby released from, any liability in respect of fire or theft loss to the above described equipment or any personal property left therewith.

PRINT NAME _____ CUSTOMER'S SIGNATURE OR AUTHORIZED AGENT _____
 POSITION _____ DATE SIGNED _____

ACKNOWLEDGEMENT OF DEBT

I hereby acknowledge indebtedness to SMS Equipment Inc. in the aggregate amount of the charges and expenses hereinbefore set out, and agree that the amount overdue shall bear interest compounded at a rate of 2% per month (26.8% PER ANNUM)

PRINT NAME _____ CUSTOMER'S SIGNATURE OR AUTHORIZED AGENT _____
 POSITION _____ DATE SIGNED _____