

DRAYTON VALLEY TRUCK AND TRL
 7-1631 HAMMOND CRES
 Edmonton, AB. T6M0T2
 Phone: 780-881-5888

D40-1
 JUN

INVOICE

80

Org. Est. # 000085

Invoice from History

Printed Date: 07/09/2023

Work Completed: 07/09/2023

Kenworth - W900B - Cummins 444

Lic # :

Odometer In : 1

Odometer Out : 1

VIN # : 2XKWD29X2 LM921107

Part Description	Number	Qty	Sale	Ext	Labor Description	Ext
FLAT GLASS DL4717-30		2.00	48.86	97.72	STEERING SHAFT - R&I - Installed steering shaft. waiting on boot	112.51
CLAMP-EXHAUST EC50PLS		5.00	20.34	101.70	RADIATOR TIE ROD BRACKET - R&I - One Installed radiator rod bushings. nuts where seized good. ordered new rod will contact customer when new one comes in.	180.01
SPRING PIN BUSHING KIT SP700100S53UC		2.00	308.40	616.80	Cut bolts on fifthwheel mounting struggled to remove cut bolts as the were seized and hardened. tried to knock them out but they wouldn't move. tried to drill them out with a mag drill but they wouldn't even cut.	1,050.04
-Y-PIPE-EXHUAST K180-14766		1.00	434.14	434.14	had to burnt them out	
SWAYBAR-BUSHING K066-449		4.00	81.74	326.96	Install fenders	549.88
BUSHING 70 DURO M500-70NR		2.00	33.27	66.54	Installed quarter fenders. ha to cut and knock out old bolts that were seized in the mounting holes	
BUSHING 70 DURO M501-70NR		2.00	39.50	79.00	Remove PTO Removed PTO and drive shaft. filled up with new oil	300.48
BUSHING 60 DURO RUBBER CA368-6		4.00	38.64	154.56	INSTALL STEER DUST SHIELDS installed dust sheilds	105.00
SPACER-RAD-TIE-ROD K221-4210		2.00	42.03	84.06	CAB SUPPORT - R&I - Front or Rear, One Had to lift sleeper all round to change bushing.	700.00
SHAFT-STEERING 916657-227SX		1.00	945.00	945.00	SHOCK ABSORBER - R&I - One Tried to loosen bolts but would not move. ended up cutting bolts with zip disks. Removed and installed new ones.	298.88
CROSS-TUBE-ASSY 463DS55710		1.00	575.16	575.16	***HOURS ARE NOT SPECIFICALLY CORRECT TO THE JOB BUT TOTAL HOURS OF REPAIRS ARE CORRECT. THIS IS DUE TO THE RUSH TO COMPLETE THE JOB.***	
SHOCK-REAR 85310		4.00	99.30	397.20		
DUST-SHIELD A3264S227		2.00	231.54	463.08	CYLINDER HEAD ASSEMBLY - R&I - All - [Includes draining and refilling of cooling system, disconnecting and connecting of batteries, R&I of all related parts to access cylinder head, clean and inspect all removed parts, measuring liner projection, inspecti	7,833.88
BUSHING MOUNTS M17405		2.00	79.90	159.80		
HEAD-GASKET-KIT 4024918N		1.00	318.88	318.88		
CYLINDERHEAD 3053346		3.00	1,980.88	5,942.64		
AM, TEMP CNTRL, MECH, 205 DEG, NO 8037034P		1.00	158.00	158.00		
BUSHING INSTALL BUSHING INSTALL		1.00	120.00	120.00		
GASKET - JAKE-BRAKE 3042551N		3.00	28.78	86.34		
MOBIL DELVAC SUPER 13 122887		2.50	120.00	300.00		
FLEXTUBE 5IDX10FT GAL		4.00	18.49	73.96		

Visit us on the web: www.dvttts.ca

Email Address: malcolm@dvttts.ca

DRAYTON VALLEY TRUCK AND TRL
 7-1631 HAMMOND CRES
 Edmonton, AB. T6M0T2
 Phone: 780-881-5888

INVOICE

80

Org. Est. # 000085

Invoice from History

Printed Date: 07/09/2023

Work Completed: 07/09/2023

1990 Kenworth - W900B - Cummins N 14 Celect 6 CYL

Lic # :

Odometer In : 1

Odometer Out : 1

VIN # : 2XKWD29X2 LM921107

Part Description	/ Number	Qty	Sale	Ext	Labor Description	Ext
------------------	----------	-----	------	-----	-------------------	-----

Org. Estimate	0.00	Revisions	0.00	Current Estimate	0.00
---------------	------	-----------	------	------------------	------

Labor:	18,130.68
Parts:	12,886.94
HazMat:	30.00
SubTotal:	31,047.62
Tax:	1,552.38
Total:	32,600.00
Bal Due:	\$0.00

[Payments - Cheque - \$32,000.00, E-Transfer - \$600.00]

Vehicle Received: 2023-05-19

Customer Number : 27

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. All repairs or part sales will be paid upon completion of requested tasks. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts are based on the manufacturer's policy and are processed by Drayton Valley Truck and Trailer Service inc. (DVTTS) only if supplied by DVTTS, and labor is one year or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____

Visit us on the web: www.dvttts.ca

Email Address: malcolm@dvttts.ca

Service Advisor : Tshuma, Malcolm, Tech : Tshuma, Malcolm