

408-4
JUN



FROM:
BASKEL MECHANICAL LTD.
P.O. BOX 27061 - RPO HENDERSON
LAKE
LETHBRIDGE, AB
T1K 6Z8
baskelmechanical@gmail.com
P: 403-360-1294
GST#: 712490135RT0001

BILL TO:
ROSSCO'S TREE SERVICE
401 Clark Rd
Lethbridge County, AB

P: 4036346513

Invoice Date: 12 Jan, 2023
Due Date: 12 Jan, 2023
Invoice #: 6235

59 422

Customer Concerns:

Diagnosis:

Corrective Action:



Parts	Parts Description	QTY	Rate	Amount	Sales Tax
	GLOW PLUG	3.00	\$48.09	\$144.27	\$7.21
	RAIN CAP	1.00	\$10.26	\$10.26	\$0.51
	HOSE	1.00	\$13.22	\$13.22	\$0.66
Labour	Labour Description	Actual Hours	Rate	Amount	Sales Tax
	ADJUST THROTTLE CABLE SO THAT IT FUNCTIONS PROPERLY. REPLACE RAIN CAP ON EXHAUST. DIAGNOSE HARD START, 2 OUT OF 3 GLOW PLUGS NOT WORKING. REPLACE ALL GLOW PLUGS. REPLACE HOSE FOR BLOW BY TUBE AS IT CAME UNHOOKED.	3.00	\$100.00	\$300.00	\$15.00

Vehicle Info
Vehicle Year: 0
Vehicle Make: Vermeer
Vehicle Model: SC 352
VIN:
Color: ** ODOMETER READING IS IN HOURS **
Odometer Reading: 436 km
Engine Size:
Drive:
If wheels have been removed tires must be retorqued within 50km.

	Amt	Sales Tax
Shop Supplies	\$15.00	\$0.75
Subtotal	\$482.75	
Tax 5%	\$24.13	
Total	\$506.88	
Balance Due	\$506.88	