

A22-2
JUN

1962 Ford Galaxie 500 Convertible
VIN : 476A62L758507

16-Nov-21	Integra Tire	Inspection & Service	\$ 305.93
25-Feb-22	Integra Tire	Wiring, wheel bearings, new radiator	\$ 4,967.82
		Rear pinion & axle shaft, power steering lines stabilizer bar bushings, intake manifold valve cover gaskets	
10-Mar-22	Vibe Audio	600W stereo - 4 speakers, 2-10" subs	\$ 6,604.51
21-Mar-22	Integra Tire	Tires & Rims	\$ 2,554.36
30-Apr-22	Carriage Upholstery	New seats, carpet, interior, new convertible top	\$ 7,085.00
15-Aug-22	Integra Tire	New fuel pump, power steering pump	\$ 1,227.00

Total : \$ 22,744.62

Integra Tire Red Deer

Bay 3, 7450 49 Avenue Crescent

Red Deer, AB. T4P 1X8

Phone: (403) 356-1178 ~ Fax: 1-888-754-6408

integratire@gmail.com

GST # 842182305RT0001

Invoice

Bill To

Plate AB CKJ5871
Description Red 1962 Ford Galaxie 500 Base V8 5.8L
5769CC 352CID
VIN 758507476A62L
Odometer 78,184

Cell
Cell
Email

Invoice # 34519
Work Order # 44792
Service Advisor Deidra Bennett
Technician Blake Howes

Invoice Date 7/14/2023 4:47 PM
Appointment 7/12/2023 2:39 PM
Promised 7/12/2023 5:00 PM

Concern

Engine Concern - Check running hot, temp gauge going to hot

Technician Notes: Vehicle did not over heat on test drive, suspect the thermostat is sticking closed, recommend replacement.

Labor	0 Hour	\$136.00 / Hour	\$0.00 *G
Service Advisor: Deidra Bennett			
			Sub <u> </u> \$0.00

Inspection

Oil Change Courtesy Inspection

Labor	0 Hour	\$136.00 / Hour	\$0.00 *G
Service Advisor: Deidra Bennett			
			Sub <u> </u> \$0.00

Brake System Inspection

Labor	0 Hour	\$136.00 / Hour	\$0.00 *G
Service Advisor: Jaime Robertson			
			Sub <u> </u> \$0.00

Service

Lube, Oil & Filter Service - Regular Oil

performed lof, installed stop leak in the power steering, engine, and transmission fluid.

10W30 Hot Rod Oil 5L	1 Unit	\$74.48 / Unit	\$74.48 G
Oil Filter	1 Unit	\$8.20 / Unit	\$8.20 G
Brake Cleaner	1 Unit	\$5.95 / Unit	\$5.95 G
ATP Re-Seal	1 Unit	\$35.95 / Unit	\$35.95 G
Labor			\$40.00 *G
Service Advisor: Deidra Bennett			
			Sub <u> </u> \$164.58

Thermostat

Technician Notes: Replaced thermostat and gasket road tested to make sure vehicle not over heating.

OE TSTAT	1 Unit	\$7.47 / Unit	\$7.47 G
TSTAT GSKT	1 Unit	\$2.97 / Unit	\$2.97 G
Antifreeze (Concentrate)	2 Unit	\$10.95 / Unit	\$21.90 G
Labor	1 Hour	\$136.00 / Hour	\$136.00 *G
Service Advisor: Deidra Bennett			
			Sub <u> </u> \$168.34

Integra Tire Red Deer
 Bay 3, 7450 49 Avenue Crescent
 Red Deer, AB. T4P 1X8
 Phone: (403) 356-1178 ~ Fax: 1-888-754-6408
 integratire@gmail.com
 GST # 842182305RT0001

Invoice

Bill To

Plate AB CKJ5871
 Description Red 1962 Ford Galaxie 500 Base V8 5.8L
 5769CC 352CID
 VIN 758507476A62L
 Odometer 78,435

Cell
 Cell
 Email

Invoice # 49234
 Work Order # 63333
 Service Advisor Deidra Bennett
 Technician Sean Robertson

Invoice Date 7/9/2025 11:56 AM
 Appointment 7/7/2025 4:39 PM
 Promised 7/8/2025 5:00 PM

Concern

Steering System Noise - power steering whir noise thinks pump might be going needs car drivable by the 16th for parade
 Technician Notes: Confirmed slight noise. Found power steering to be slightly low. Topped up power steering and cleaned off residue underneath. Ram and lines underneath had fluid on them. Would recommend replacing.

Labor	0.5 Hour	\$152.00 / Hour	\$76.00 *G
Sub			\$76.00

Service Advisor: Deidra Bennett

Service

Cash / Counter Sale

The following is a list of material items you purchased which are not associated with services or repairs.

Hot Rod Oil 10W30	6 Unit	\$18.43 / Unit	\$110.58 G
Sub			\$110.58

Total Parts	\$110.58
Total Labor	\$76.00
Total Before Taxes & Miscellaneous Charges	\$186.58
(*) Shop Supplies	\$4.94 G
(G) Canadian Goods and Services Tax (GST)	5 %
Grand Total	\$201.10

Zaparniuk Holdings Ltd. paid \$201.10 by MasterCard
 7/9/2025 11:56 AM Card #: XXXXXXXXXXXXX5726 Entry Method: Chip Type: Sale Amount: 201.1
 Terminal: 75503 Transaction: d3c1964e-feb8-48e0-9c35-264fe8b2b050 Authorization: 00997J Result: Approved
 AID: A000000041010 TC: ARQC: C065DA02A880EB27 TVR: 0000008000 TSI: E800

Buyer agrees to pay total amount above according to cardholder's agreement with issuer.

Integra Tire Red Deer would like to thank you for your patronage and we look forward to serving you in your future automotive needs.

Integra Tire Red Deer

Bay 3, 7450 49 Avenue Crescent
Red Deer, AB. T4P 1X8
Phone: (403) 356-1178 ~ Fax: 1-888-754-6408
integratire@gmail.com
GST # 842182305RT0001

Invoice

Bill To	Plate AB CKJ5871
	Description Red 1962 Ford Galaxie Base V8 5.8L 5769CC
	352CID VIN X
Cell	VIN 758507476A62L
Cell	Odometer 78,093
Email	
Invoice # 28016	Invoice Date 8/29/2022 10:38 AM
Work Order # 36793	Appointment 8/15/2022 8:28 AM
Service Advisor Deidra Bennett	Promised 8/15/2022 5:00 PM
Technician Miloš Martić	

Concern

Fuel System Concern - Leaking fuel at the pump - leaking from housing

Service

Belts General Service - Check belts
Both drive belts in good working condition

Perform AVR Test

load tested battery. Battery good. 300A load at 9.9V Alternator charging at 13.8V

Labor	0.5 Hour	\$136.00 / Hour	\$68.00 *G
Service Advisor: Deidra Bennett			
		Sub	\$68.00

Replace Fuel Pump

Replaced fuel pump assembly

Fuel Pump	1 Unit	\$110.90 / Unit	\$110.90 G
Valve Cover Set	1 Unit	\$32.98 / Unit	\$32.98 G
Diagnose And Repair	1.5 Hour	\$136.00 / Hour	\$204.00 *G
Service Advisor: Deidra Bennett			
		Sub	\$347.88

Replace Power Steering Pump

Replaced power steering pump

Power Steering Pump	1 Unit	\$554.43 / Unit	\$554.43 G
Amsoil Gasoline Stabilizer	2 Unit	\$21.95 / Unit	\$43.90 G
Diagnose And Repair	1 Hour	\$136.00 / Hour	\$136.00 *G
Service Advisor: Deidra Bennett			
		Sub	\$734.33

Total Parts	\$742.21
Total Labor	\$408.00
Total Before Taxes & Miscellaneous Charges	\$1,150.21

(*) Shop Supplies	\$18.36 G
(G) Canadian Goods and Services Tax (GST) 5 %	\$58.43
Grand Total	\$1,227.00

Corvet Construction Ltd. paid \$1,227.00 by Visa Card

Integra Tire Red Deer would like to thank you for your patronage and we look forward to serving you in your future automotive needs.

Carriage Upholstery Ltd.

Mailing Address: 34 Livingston

Close, Lacombe AB, T4L 2J3.

Shop: 27017 TWP RD 405.5

Lacombe County AB

+1 4033468985

service@carriageupholstery.com

GST/HST Registration No.:

731898474RT0001



Invoice

BILL TO

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
2305	30/04/2022	\$7,085.00	30/04/2022	Due on receipt	

SIGNATURE

*

PMT METHOD

Credit Card

DATE	ACTIVITY	DESCRIPTION	TAX	QTY	RATE	AMOUNT
30/04/2022	Labour & Materials	Supply and Install Carpet	GST	1	750.00	750.00
06/07/2022	Labour & Materials	1962 Ford Galaxie-White Vinyl top, with plastic window. New seat covers and foam and fix springs. white and red. New door panels, white and red.	GST	1	6,300.00	6,300.00
06/07/2022	Labour & Materials	Extras;All new tack strips were installed for the convertible top. A new well liner was made.	GST	1	650.00	650.00

We appreciate your business. Payment is due as per due date above. Please be aware that we will charge 2.0% interest per month on late invoices.

We accept all major credit cards, cheques, cash and e-transfers (Service@carriageupholstery.com)

SUBTOTAL	7,700.00
GST @ 5%	385.00
TOTAL	8,085.00
DEPOSIT	1,000.00
BALANCE DUE	\$7,085.00

TAX SUMMARY

RATE	TAX	NET
GST @ 5%	385.00	7,700.00

Integra Tire Red Deer
 Bay 3, 7450 49 Avenue Crescent
 Red Deer, AB. T4P 1X8
 Phone: (403) 356-1178 ~ Fax: 1-888-754-6408
 integratire@gmail.com
 GST # 842182305RT0001

Estimate

Bill To Cell Cell Email Estimate # 33202 Service Advisor Jessie Shields Technician NA	Plate AB CKJ5871 Description Red 1962 Ford Galaxie Base V8 5.8L 5769CC 352CID VIN X VIN 758507476A62L Odometer 77,589 Appointment 3/18/2022 1:32 PM Promised 3/19/2022 5:00 PM
---	--

Service

Tire/Wheel Package - 4 Tires *Wheel ETA 4-6 Weeks*****

Install tire and new valve stem where applicable, clean and seal tire to wheel seat, set tire pressure to proper inflation. Mount and torque wheel lug nuts to manufacturers torque specifications. Perform final road test as required.

Pirelli Cinturato P7 All Season Plus 2 225/55R17 BW 97V	2 Unit	\$208.64 / Unit	\$417.28 GPT1
Pirelli Cinturato P7 All Season Plus 2 245/45R18XL BW 100V	2 Unit	\$242.56 / Unit	\$485.12 GPT1
17x7 US Mags U110 Rambler Chrome 5x4.5 CB72.56 +01	2 Unit	\$382.00 / Unit	\$764.00 G
18x8 US Mags U110 Rambler Chrome 5x4.5 CB72.56 +01	2 Unit	\$418.00 / Unit	\$836.00 G
Freight (Price May Vary)	1 Unit	\$125.00 / Unit	\$125.00 G
1/2 Chrome Acorn Lug Nut Kit	1 Unit	\$79.00 / Unit	\$79.00 G
Hub Centric Ring Set	1 Unit	\$19.95 / Unit	\$19.95 G
Valve Stem	4 Unit	\$3.95 / Unit	\$15.80 G
Labor			\$120.00 *G
Service Advisor: Jessie Shields			

Sub \$2,862.15

Please Note

Some wheels require lug nut re-torque. Ask your Service Consultant for details.
 Keeping your tires properly inflated and rotated will assist in maximizing tire wear life and vehicle handling.

Total Parts	\$2,742.15
Total Labor	\$120.00
Total Before Taxes & Miscellaneous Charges	\$2,862.15

(*) Shop Supplies		\$5.40 G
(P) Extended Protection Plan	\$10.00 Each	\$40.00 G
(G) Canadian Goods and Services Tax (GST)	5 %	\$146.18
(T1) Tire Recycling Fee	\$4.00 Each	\$16.00 G
Grand Total		\$3,069.73

All estimates are good for a 30 day period from date of Estimate.



VIBE CAR AUDIO INC.
 #2,5125-76A STREET CLOSE
 Red Deer, AB.
 T4P 3M2
 (403)309-3535

Date: 03/15/22	Page: 1
Invoice Number: 000 - 309734	Invoice

Sold To: COR00F

Ship To:

() -

Salesperson: RH

Purchase Order:

Code	Description	Qty/Ord	Qty/Shp	Unit/Price	Amount
POA	**PAYMENT ON ACCOUNT - THANK YOU ! **	1.00	1.00	6,604.510	6,604.51

PAID BY Mastercard 6604.51

Invoice Total 6,604.51
 G.S.T.# 860694678 0.00

**EXTENDED WARRANTY DOES NOT COVER PHYSICAL OR LIQUID DAMAGE. **
 ** WARRANTY DOES NOT COVER SPEAKERS IF BLOWN / COIL DAMAGE. **

Total Amount 6,604.51
 Amount Paid 6,604.51

Balance Due 0.00

X Customer Signature



VIBE CAR AUDIO INC.
 #2,5125-76A STREET CLOSE
 Red Deer, AB.
 T4P 3M2
 (403)309-3535

Date: 03/10/22	Page: 1
Invoice Number: 000 - 309703	Invoice (r)

Sold To: COR00F

Ship To:

() -

Salesperson: RH

Purchase Order:

Code	Description	Qty/Ord	Qty/Shp	Unit/Price	Amount
KMMX704	KENWOOD EXCELON MECHLESS 2020 MODEL	1.00	1.00	150.000	150.00
SCOTTINSTALL	CUSTOM GLOVE BOX DECK INSTALLATION	4.00	4.00	125.000	500.00
SHOP SUPPLIES	SHOP SUPPLIES	4.00	4.00	10.000	40.00
AXUSBE6	AXXESS 6" FLUSH USB EXTENSION	1.00	1.00	20.000	20.00
RCX165	FOCAL AUDITOR 6.5" COAX	2.00	2.00	130.000	260.00
CORYINSTALL	FRONT SPEAKER INSTALL	3.50	3.50	125.000	437.50
SHOP SUPPLIES	SHOP SUPPLIES	3.50	3.50	10.000	35.00
SCOTTINSTALL	REAR SPEAKER INSTALL	1.50	1.50	125.000	187.50
SHOP SUPPLIES	SHOP SUPPLIES	1.50	1.50	10.000	15.00
10TW3-D8	JL AUDIO 10" THIN LINE SUBWOOFER 8.ohm	2.00	2.00	500.000	1,000.00
CORYINSTALL	CUSTOM ENCLOSURE	5.00	5.00	125.000	625.00
SHOP SUPPLIES	ENCLOSURE MATERIALS	1.00	1.00	150.000	150.00
XD600/1V2	JL AUDIO 600 WATT x 1 CHANNEL AMPLIFIER	1.00	1.00	650.000	650.00
SCOTTINSTALL	AMP BRACKET & INSTALL	2.00	2.00	125.000	250.00
SHOP SUPPLIES	SHOP SUPPLIES	2.00	2.00	10.000	20.00
CORYINSTALL	AMP WIRE INSTALLATION	2.00	2.00	125.000	250.00
SHOP SUPPLIES	SHOP SUPPLIES	2.00	2.00	10.000	20.00
AKTP4	WIREZ TECH PLUS 4 AWG AMP KIT	1.00	1.00	100.000	100.00
SSD1	SOUNDSHIELD SOUND DEADENING TUBE	3.00	3.00	125.000	375.00
CORYINSTALL	SOUND MAT TRUNK/CUSTOM PANELS/CARPET	9.00	9.00	125.000	1,125.00
SHOP SUPPLIES	TRUNK MATERIALS	1.00	1.00	80.000	80.00

ON A/R ACCOUNT 6604.51

Invoice Total 6,290.00
 G.S.T.# 860694678 314.51

EXTENDED WARRANTY DOES NOT COVER PHYSICAL OR LIQUID DAMAGE.
 WARRANTY DOES NOT COVER SPEAKERS IF BLOWN / COIL DAMAGE.

Total Amount 6,604.51
 Amount Paid 0.00

Balance Due 6,604.51

X Customer Signature

Integra Tire Red Deer
 Bay 3, 7450 49 Avenue Crescent
 Red Deer, AB. T4P 1X8
 Phone: (403) 356-1178 ~ Fax: 1-888-754-6408
 integratire@gmail.com
 GST # 42182305RT0001

Invoice

Bill To Cell Cell Email Invoice # 24262 Work Order # 32164 Service Advisor Sean Robertson Technician Tim Wiebe	Plate AB CKJ5871 Description Red 1962 Ford Galaxie Base V8 5.8L 5769CC 352CID VIN X VIN 758507476A62L Odometer 77,589 Invoice Date 2/25/2022 2:15 PM Appointment 1/25/2022 10:42 AM Promised 2/28/2022 5:00 PM
---	---

Service

Inspect & Repair All Lights & Wiring

Inspect and repair wiring to all lights, 2 Hour estimate time only.
 Inspect and found brake lights and revers light are inoperative. Test for voltage at brake switch, ok. Inspect brake pressure switch with brakes applied and found no out put voltage. Supply voltage to output to confirm rear light are operational, ok. Replace defective brake pressure switch and confirm repair, brake lights are working now. Inspect for reverse lights inoperative. Test reverse switch, ok 0.3 Ohms. Inspect and found no voltage supply to switch. Jump voltage to rear lights to confirm operation, ok. Need to find open in supply voltage to reverse switch. Inspect and found supply wire has fallen out of fuse box. Reinstall wire and confirm reverse light are working. License plate light housing is broken. Remove old licence plate assembly and install new light in custom plate.

Stoplight Switch	1 Unit	\$15.82 / Unit	\$15.82 G
LED License Plate Lamp	1 Unit	\$22.50 / Unit	\$22.50 G
Labor	2.5 Hour	\$136.00 / Hour	\$340.00 *G
		Sub	\$378.32

Wheel Bearings, Clean & Repack Front

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Wheel Seal - Front	2 Unit	\$7.27 / Unit	\$14.54 G
Brake Cleaner	1 Unit	\$3.95 / Unit	\$3.95 G
Labor	1.5 Hour	\$136.00 / Hour	\$204.00 *G
		Sub	\$222.49

Radiator Assembly -

Remove and send out radiator out to be repaired. Reinstall radiator and fill with coolant.

Radiator Repair	1 Unit	\$690.13 / Unit	\$690.13 G
Antifreeze	12 Unit	\$6.50 / Unit	\$78.00 G
Labor	1.2 Hour	\$136.00 / Hour	\$163.20 *G
		Sub	\$931.33

Rear Differential Pinion Seal

Replace leaking pinion seal. Pinion preload set to 35"lb. service rear differential.

Pinion Seal (w/8.75" or 9" Ring Gear)	1 Unit	\$22.88 / Unit	\$22.88 G
80W90 Conventional Gear Oil	2 Unit	\$9.68 / Unit	\$19.36 FG
Brake Cleaner	1 Unit	\$3.95 / Unit	\$3.95 G
Labor	1.1 Hour	\$136.00 / Hour	\$149.60 *G
		Sub	\$195.79

Rear Axle Shaft Seal, Left And Right

Remove both rear axle shafts to replace seals. Inspect and found rear differential vent is plugged. Clean out vent and install a new vent hose. NOTE: LH shoes have slight cracking in the lining.

Rear Wheel Seal (w/HD Axle 9" Ring Gear)	2 Unit	\$19.00 / Unit	\$38.00 G
Vent Assembly	1 Unit	\$5.12 / Unit	\$5.12 G
3/8 Hose	5 Unit	\$6.00 / Unit	\$30.00 G

Brake Cleaner	1 Unit	\$3.95 / Unit	\$3.95 G
Labor	3 Hour	\$136.00 / Hour	\$408.00 *G
		Sub	<u>\$485.07</u>
Engine Shampoo - Has oil leak			
Shampoo undercarriage and inspect for leaks. Intake is leaking. Drain plug is leaking, tighten plug.			
Engine Shampoo	3 Unit	\$10.05 / Unit	\$30.15 G
Brake Cleaner	2 Unit	\$3.95 / Unit	\$7.90 G
Labor	0.6 Hour	\$136.00 / Hour	\$81.60 *G
		Sub	<u>\$119.65</u>
Stabilizer Bar Link(s)			
Remove and replace front sway bar links.			
Sway Bar Link - Front	2 Unit	\$13.67 / Unit	\$27.34 G
Labor	0.5 Hour	\$136.00 / Hour	\$68.00 *G
		Sub	<u>\$95.34</u>
Power Steering Pump Seal Kit			
Remove and replace all external power steering pump seals.			
Power Steering Pump Seal Kit	1 Unit	\$35.00 / Unit	\$35.00 G
Power Steering Fluid	1 Unit	\$12.95 / Unit	\$12.95 G
Labor	2.3 Hour	\$136.00 / Hour	\$312.80 *G
		Sub	<u>\$360.75</u>
Suspension Stabilizer Bar Bushings ***Stabilizer (Sway) Bar Diameter 5/8ths***			
Remove and inspect sway bar bushings. Found proper factory sway bar mount is not available. Inspect and modify frame ant the front of the sway bar to accept different design mount.			
Stabilizer Bar Bushing - Front to Frame 5/8" Bar	1 Unit	\$14.04 / Unit	\$14.04 G
Freight	1 Unit	\$20.51 / Unit	\$20.51 G
Labor	2 Hour	\$136.00 / Hour	\$272.00 *G
		Sub	<u>\$306.55</u>
Power Steering Pressure Line And Return Line			
Remove and replace leaking power steering return line. Fill with fluid and confirm no more power steering leaks.			
Power Steering Hose - Return	36 Unit	\$0.52 / Unit	\$18.72 G
Power Steering Fluid	1 Unit	\$12.95 / Unit	\$12.95 G
Labor	0.7 Hour	\$136.00 / Hour	\$95.20 *G
		Sub	<u>\$126.87</u>
Battery Hold Down ***Confirm Hold Down Style and Bolt Length Prior to Ordering***			
Modify and install battery hold down.			
Battery Hold Down Sets Adjustable Mount Crossbar	1 Unit	\$14.05 / Unit	\$14.05 G
Battery Hold Down Sets J Bolt	1 Unit	\$9.67 / Unit	\$9.67 G
Labor	0.5 Hour	\$136.00 / Hour	\$68.00 *G
		Sub	<u>\$91.72</u>
Four Wheel Alignment			
Inspect steering and suspension system components. Connect alignment equipment to verify and adjust front and rear wheel alignment settings for caster, camber, and toe in/out settings, thrust angle where applicable and center steering wheel. Some vehicles may require installation of alignment shims at additional charges. Adjust to meet manufacturers' specifications. Perform final road test where applicable.			
Labor			\$131.00 *G
		Sub	<u>\$131.00</u>
Maintenance Tune Up, 8 Cylinder Engines			
Replace spark plugs, ignition wires, cap and rotor. Set timing.			
Spark Plug - Resistor Plug - .035" Gap; OE Style; Copper	8 Unit	\$4.11 / Unit	\$32.88 G
Tailored Resistor Ignition Wire Set	1 Unit	\$52.85 / Unit	\$52.85 G
Wire Separator Set	1 Unit	\$11.00 / Unit	\$11.00 G
Distributor Cap	1 Unit	\$53.56 / Unit	\$53.56 G
Distributor Rotor	1 Unit	\$19.65 / Unit	\$19.65 G
ATP Re-Seal	1 Unit	\$35.95 / Unit	\$35.95 G
Labor	1 Hour	\$136.00 / Hour	\$136.00 *G

Sub \$341.89

Intake Manifold Gasket Set

Remove intake manifold and install an inline PCV system to remove draft tube. Reinstall intake.

Manifold Gasket Set - Intake	1 Unit	\$57.18 / Unit	\$57.18 G
10W30 Motor Oil (5L)	1 Unit	\$38.75 / Unit	\$38.75 FG
Gloss Black Engine Paint	1 Unit	\$17.07 / Unit	\$17.07 G
PCV Valve	1 Unit	\$11.17 / Unit	\$11.17 G
Hose-Heater	1 Unit	\$1.27 / Unit	\$1.27 G
Fuel Line	1 Unit	\$1.60 / Unit	\$1.60 G
Fuel Line	1 Unit	\$2.32 / Unit	\$2.32 G
Engine Oil Filter	1 Unit	\$9.95 / Unit	\$9.95 EG
Gasket	1 Unit	\$16.27 / Unit	\$16.27 G
Hose Clamp	1 Unit	\$1.70 / Unit	\$1.70 G
195°F Engine Coolant Thermostat	1 Unit	\$9.53 / Unit	\$9.53 G
Thermostat Housing Gasket	1 Unit	\$2.25 / Unit	\$2.25 G
Labor	4 Hour	\$136.00 / Hour	\$544.00 *G
		Sub	\$713.06

Valve Cover Gasket(s)

Replace both valve cover gaskets.

Valve Cover Gasket Set	1 Unit	\$57.98 / Unit	\$57.98 G
Labor	1 Hour	\$136.00 / Hour	\$136.00 *G
		Sub	\$193.98

Total Parts	\$1,584.41
Total Labor	\$3,109.40
Total Before Taxes & Miscellaneous Charges	<u>\$4,693.81</u>

(*) Shop Supplies		\$35.95 G
(E) Environmental Disposal Charge		\$1.20 G
(F) Fluid Disposal	\$0.10 Each	\$0.30 G
(G) Canadian Goods and Services Tax (GST)	5 %	<u>\$236.56</u>
Grand Total		\$4,967.82

Corvet Construction Ltd. paid \$4,967.82 by Master Card

Integra Tire Red Deer would like to thank you for your patronage and we look forward to serving you in your future automotive needs.

Integra Tire

Customer:	Date: 2/25/2022 9:47 AM
Company:	VIN
License No: CKJ5871	Technician: Joseph
Odometer: 77589	Order No.:

VEHICLE ALIGNMENT REPORT

,, 0

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	1.75°	----	----	3.49°
		Right	2.35°	----	----	4.21°
	Camber	Left	0.61°	----	----	0.16°
		Right	-0.89°	----	----	-0.09°
	Toe	Left	0.93°	----	----	0.01°
		Right	-0.81°	----	----	0.01°
Total		0.12°	----	----	0.02°	
Rear	Camber	Left	13.28°	----	----	13.28°
		Right	-13.62°	----	----	-13.62°
	Toe	Left	1.15°	----	----	1.15°
		Right	-0.96°	----	----	-0.96°
		Total	0.19°	----	----	0.19°
	Thrust Angle		----	----	----	----
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left	5.75°	----	----	8.92°	
	Right	8.42°	----	----	8.26°	
Included Angle	Left	6.36°	----	----	9.08°	
	Right	7.53°	----	----	8.17°	
Toe Out On Turns	Left	----	----	----	----	
	Right	----	----	----	----	
Maximum Turns	Left	----	----	----	----	
	Right	----	----	----	----	
Toe Curve Change	Left	----	----	----	----	
	Right	----	----	----	----	
Setback	Front	0.00"	----	----	-0.02"	
	Rear	----	----	----	----	
Track Width Diff.		0.00"	----	----	-0.08"	
Wheel Base Diff.		----	----	----	----	
Front Ride Height	Left	----	----	----	----	
	Right	----	----	----	----	
Rear Ride Height	Left	----	----	----	----	
	Right	----	----	----	----	
Frame Angle		----	----	----	----	

Integra Tire Red Deer
 Bay 3, 7450 49 Avenue Crescent
 Red Deer, AB. T4P 1X8
 Phone: (403) 356-1178 ~ Fax: 1-888-754-6408
 integratire@gmail.com
 GST # 842182305RT0001

Authorization

Bill To Cell Cell Email Work Order # 30601 Service Advisor Deidra Bennett Technician Miloš Martić	Plate AB CKJ5871 Description Red 1962 Ford Galaxie Base V8 5.8L 5769CC 352CID VIN X VIN 758507476A62L Odometer 77,541 In / 0 Out Appointment 11/16/2021 1:08 PM Promised 11/17/2021 5:00 PM
---	---

Inspection

Mechanical Inspection 1 hour			
Performed mechanical inspection. See Form			
Labor	1 Hour	\$136.00 / Hour	\$136.00 *G
		Sub	\$136.00
Oil Change Courtesy Inspection			
Labor	0 Hour	\$136.00 / Hour	\$0.00 *G
		Sub	\$0.00

Service

Lube, Oil & Filter Service - Regular Oil - Check all fluids, frt & rear diff, trans fluid etc.			
LOF performed. Front steering and suspension greased. Transmission fluid topped up.			
FILTER,OIL	1 Unit	\$9.95 / Unit	\$9.95 EG
10W30 Hot Rod Oil	6 Unit	\$12.32 / Unit	\$73.92 EG
OE Synthetic Multi-Vehicle ATF	1 Unit	\$12.00 / Unit	\$12.00 FG
Brake Cleaner	1 Unit	\$3.95 / Unit	\$3.95 G
Labor			\$40.00 *G
		Sub	\$139.82

Total Parts		\$99.82
Total Labor		\$176.00
Total Before Taxes & Miscellaneous Charges		<u>\$275.82</u>
(*) Shop Supplies		\$7.04 G
(E) Environmental Disposal Charge		\$8.40 G
(F) Fluid Disposal	\$0.10 Each	\$0.10 G
(G) Canadian Goods and Services Tax (GST)	5 %	\$14.57
Grand Total		<u>\$305.93</u>
Total Deposit & Payment		\$305.93
Total Outstanding		\$0.00

I hereby authorize the repair of the above vehicle as describe in the attached estimate/repair order.

Customer Signature: _____