

CUSTOMER #:

260790



LEDUC CHRYSLER JEEP

6102 46A Street

Leduc, Alberta T9E 7A7

Telephone (780) 986-2051

Facsimile (780) 986-1486

Toll Free: 1-800-355-8933

service@leduchrysler.com

www.leduchrysler.com



INVOICE

PAGE 2

HOME: CONT: SERVICE ADVISOR: 135 CHUCK
BUS: CELL:

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER-IN/ OUT	TAG	
	09	JEEP LIBERTY	1J8GN58K69W509001		125579/125588	T131	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
26JUN09 DD			16:30 15MAR24		0.00	CHG	21MAR24
R.O. OPENED	READY	OPTIONS: DLR:C3834 ENG:3.7_Liter_MPI					
17:17 06MAR24	15:48 21MAR24						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
D**					drivers rear loch actuator install (SUPPLIED/DIAGED BY CUSTOMER		
					REP drivers rear loch actuator install (SUPPLIED/DIAGED BY CUSTOMER		
					9238 WEIR, EVAN LIC#: 9238		
					C	338.00	338.00
PARTS:					0.00 LABOR: 338.00 OTHER: 0.00 TOTAL LINE D:		338.00
					125588 2.00 replace drivers rear door lock.		

VIP					VIP discount	C	-579.41

ESTIMATE: 3,706.24 11MAR24 10:41 SA: 135
CONTACT:

Shop supplies 95.00

****CAUTION!**** Failure to perform required maintenance items may result in damage to your vehicle and could VOID the warranty coverage. Please refer to your OWNERS MANUAL maintenance schedules. After ANY repair involving the removal of tires, re-torque wheel nuts within 100 km

CUSTOMER GST	(#: R103027447)	120.63	
AT YOUR SERVICE MON TO FRI: 7:30 AM TO 5:30 PM	INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. NO WARRANTY ON AFTERMARKET PARTS INSTALLED	DESCRIPTION	TOTALS
		LABOUR AMOUNT	2028.00
THANK YOU FOR ALLOWING US TO SERVICE YOUR VEHICLE	SIGNATURE _____ DATE _____	PARTS AMOUNT	869.04
		GAS, OIL, LUBE	0.00
		SUBLET AMOUNT	0.00
		MISC. CHARGES	95.00
		TOTAL CHARGES	2992.04
		LESS INSURANCE	579.41
		SALES TAX	120.63
	CUSTOMER SIGNATURE X	PLEASE PAY THIS AMOUNT	2533.26

CUSTOMER #:

255779

INVOICE

PAGE 1



LEDUC CHRYSLER JEEP

6102 46A Street

Leduc, Alberta T9E 7A7

Telephone (780) 986-2051

Facsimile (780) 986-1486

Toll Free 1-800-355-8933

service@leduchrysler.com

www.leduchrysler.com



HOME: CONT:
BUS: CELL:

SERVICE ADVISOR: 260 DAWN

Table with columns: COLOUR, YEAR, MAKE/MODEL, VIN, LICENSE, ODOMETER IN/ OUT, TAG. Values: 09, JEEP LIBERTY, 1J8GN58K69W509001, 118244/118244, T7116

Table with columns: IN SVC. DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., CUST. PAY LABOUR RATE, PAYMENT, INV. DATE. Values: 26JUN09 DD, 16:30 15AUG23, 0.00, CHG, 16AUG23

Table with columns: R.O. OPENED, READY, OPTIONS. Values: 07:39 15AUG23, 08:42 16AUG23, DLR:C3834 ENG:3.7_Liter_MPI

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL

A NO HEAT AGAIN - RECENT WORK ON PREV RO IN DECEMBER - TECH 194 - DIAG & ADVISE

24 NO HEAT AGAIN - RECENT WORK ON PREV RO IN DECEMBER - TECH 194 - DIAG & ADVISE
194 KEEGAN LIC#: 194

C 159.50 159.50
PARTS: 0.00 LABOR: 159.50 OTHER: 0.00 TOTAL LINE A: 159.50

118244 1.00 Road tested vehicle and got up to operating temp and set the HVAC to full hot. Found the heat was poor. Inspected for coolant leaks and found none at this time. Found the wrong coolant is in the system and found there is sediment build up in the radiator. Suspect the wrong coolant type is causing sediment build up. Suspect the heater core is filled with sediment now causing poor heat. Recommend removing the plugs on the side of the block and flushing the system to try and remove all the sediment and then re fill with proper coolant. Recommend back flushing the heater core as well.

B** Recommend removing plugs on side of block and flushing the entire cooling system to remove sediment

CS001 Recommend removing plugs on side of block and flushing the entire cooling system to remove sediment

194 KEEGAN LIC#: 194
C 450.00 450.00

1 VU01524AC \$COOLANT-ANTIFREEZE 21.51 21.51 21.51
PARTS: 21.51 LABOR: 450.00 OTHER: 0.00 TOTAL LINE B: 471.51

118244 3.00 Removed the heater hoses from the heater core and flushed the heater core out with water and air. Filled the heater core with CLR and let sit over night to break up any debris in the heater core. Lifted vehicle on hoist and removed the coolant plugs on the sides of the engine block. Flushed water through the entire cooling system for over an hour. Found lots of rust and sand like material to come out of the engine. Flushed until no more debris is coming out and then re installed the plugs into the block. Flushed out the CLR and

Form with sections: AT YOUR SERVICE, THANK YOU FOR ALLOWING US TO SERVICE YOUR VEHICLE, INDEBTEDNESS IS HEREBY ACKNOWLEDGED, SIGNATURE, DATE, CUSTOMER SIGNATURE, PLEASE PAY THIS AMOUNT



LEDUC CHRYSLER JEEP

CUSTOMER #:

255779

6102 46A Street
Leduc, Alberta T9E 7A7
Telephone (780) 986-2051
Facsimile (780) 986-1486
Toll Free 1-800-355-8933
service@leduchrysler.com
www.leduchrysler.com



INVOICE



PAGE 2

HOME: CONT:
BUS: CELL: SERVICE ADVISOR: 260 DAWN

Table with columns: COLOUR, YEAR, MAKE/MODEL, VIN, LICENSE, ODOMETER IN/ OUT, TAG. Values: 09, JEEP LIBERTY, 1J8GN58K69W509001, 118244/118244, T7116

Table with columns: IN SVC. DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., CUST. PAY LABOUR RATE, PAYMENT, INV. DATE. Values: 26JUN09 DD, 16:30 15AUG23, 0.00, CHG, 16AUG23

Table with columns: R.O. OPENED, READY, OPTIONS. Values: 07:39 15AUG23, 08:42 16AUG23, DLR:C3834 ENG:3.7_Liter_MPI

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL

filled and bled the cooling system with proper coolant. Found the vehicle now blows good heat evenly through all vents. All okay now

Table with columns: Description, Amount. Row: VIP discount, C, -126.20, -126.20

ESTIMATE: 521.52 15AUG23 11:07 SA: 260
CONTACT:

Table with columns: Description, Amount. Row: Shop supplies, 53.63

CAUTION! Failure to perform required maintenance items may result in damage to your vehicle and could VOID the warranty coverage. Please refer to your OWNERS MANUAL maintenance schedules. After ANY repair involving the removal of tires, re-torque wheel nuts within 100 km

Table with columns: Description, Amount. Includes sections for AT YOUR SERVICE, THANK YOU, and INDEBTEDNESS IS HEREBY ACKNOWLEDGED. Totals: 586.36

CUSTOMER #:

249342

CUSTOMER CALLED

INVOICE



LEDUC CHRYSLER JEEP



6102 46A Street
Leduc, Alberta T9E 7A7
Telephone (780) 986-2051
Facsimile (780) 986-1486
Toll Free 1-800-355-8933
service@leducchrysler.com
www.leducchrysler.com



PAGE 1

HOME: CONT:
BUS: CELL: SERVICE ADVISOR: 135 CHUCK

Table with columns: COLOUR, YEAR, MAKE/MODEL, VIN, LICENSE, ODOMETER IN/ OUT, TAG. Includes details for 09 JEEP LIBERTY with VIN 1J8GN58K69W509001.

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL.

A Inspect for no heat in cab of vehicle. Temp gauge reads good. Sometimes will make heat when shop. Flushed heater core. Replaced rad, water pump thermostat. Blower fan blowing at all speeds. Filters changed. StArts blowing cold air as soon as start driving vehicle. Ac would kick on so client disconnected. Pls advise

24 Inspect for no heat in cab of vehicle. Temp gauge reads good. Sometimes will make heat when shop. Flushed heater core. Replaced rad, water pump thermostat. Blower fan blowing at all speeds. Filters changed. StArts blowing cold air as soon as start driving vehicle. Ac would kick on so client disconnected. Pls advise

194 KEEGAN LIC#: 194

C

149.50 149.50

PARTS: 0.00 LABOR: 149.50 OTHER: 0.00 TOTAL LINE A: 149.50

100701 1.00 Road tested vehicle to get up to operating temperature. Found vehicle to get to operating temp and maintain operating temp. Found there to be no heat coming from the vents. Checked for codes and found no related codes. Performed an HVAC actuator calibration test and found all actuators to pass testing. Inspected for coolant leaks and found none. Inspected the serp belt for proper installation and found okay. Vacuum bled the cooling system and re tested. Found there to be a miniscule amount of heat now. Found the hose going into the heater core is hot and the return line is luke warm. Found the heater core is plugged. Recommend replacing the heater core.

B INSPECT FOR NO SUNROOF OPERATION. PLS ADVISE

08 INSPECT FOR NO SUNROOF OPERATION. PLS ADVISE

194 KEEGAN LIC#: 194

C

149.50 149.50

PARTS: 0.00 LABOR: 149.50 OTHER: 0.00 TOTAL LINE B: 149.50

100701 1.00 Found the sunroof does not operate from the switch.

Table with columns: AT YOUR SERVICE, THANK YOU, INDEBTEDNESS IS HEREBY ACKNOWLEDGED, DESCRIPTION, TOTALS. Includes signature and date lines.

G.S.T. REG. NO.: R103027447 "Your No Hassles, No Nonsense Dealer"

CUSTOMER COPY

CUSTOMER #:

249342

INVOICE



LEDUC CHRYSLER JEEP

6102 46A Street
Leduc, Alberta T9E 7A7
Telephone (780) 986-2051
Facsimile (780) 986-1486
Toll Free 1-800-355-8933
service@leduchrysler.com
www.leduchrysler.com



PAGE 2

HOME: CONT:
BUS: CELL: SERVICE ADVISOR: 135 CHUCK

Table with columns: COLOUR, YEAR, MAKE/MODEL, VIN, LICENSE, ODOMETER IN/ OUT, TAG. Values: 09, JEEP LIBERTY, 1J8GN58K69W509001, 100701/100719, T3005

Table with columns: IN SVC. DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., CUST. PAY LABOUR RATE, PAYMENT, INV. DATE. Values: 26JUN09, 16:00, 09DEC22, 0.00, CHG, 13DEC22

R.O. OPENED READY OPTIONS: DLR:C3834 ENG:3.7 Liter MPI

09:01 07DEC22 14:25 13DEC22

Table with columns: LINE OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL

Checked for codes and found no codes related. Found there to be a flash available for the sunroof module for the concern of sunroof not opening when commanded. Attempted to flash the module and found the flash to fail and code B227E ECU overtemp code to set. Attempted to flash the module again and found to fail flash again. Tried a different scan tool and found the same thing to happen again. Followed diag for code and tested the operation of the ambient temp sensor and found okay. Found the ambient temp data to be correct in the sunroof module as well. Found the sunroof module has failed and will need to be replaced.

C** Heater Core - Replace

CS40 Heater Core - Replace

194 KEEGAN LIC#: 194

C

1 98008 CORE-HEATER

308.20 308.20 308.20

1 VU01507-1 REFRIG

25.30 25.30 25.30

PARTS: 333.50 LABOR: 1495.00 OTHER: 0.00 TOTAL LINE C: 1828.50

100719 10.00 Removed the instrument panel from the vehicle. Removed the HVAC housing from the vehicle. Separated the HVAC housing and removed the old heater core. Installed the new heater core and re installed the HVAC housing. Installed the HVAC housing back into the vehicle and then re installed the instrument panel. Filled and bled the cooling system. Recharged the AC after repair. Road tested vehicle and found the cab to now have good sufficient heat. Re checked for leaks and found no leaks at this time. All okay now.

D** A/C Evaporator Core - Recommend replacing while HVAC housing is removed

AC13 A/C Evaporator Core - Recommend replacing while HVAC housing is removed

194 KEEGAN LIC#: 194

C

1 44084 CORE-EVAPORTOR

242.05 242.05 242.05

PARTS: 242.05 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D: 242.05

Table with columns: AT YOUR SERVICE, MON TO FRI: 7:30 AM TO 5:30 PM, THANK YOU FOR ALLOWING US TO SERVICE YOUR VEHICLE, INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$, BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. NO WARRANTY ON AFTERMARKET PARTS INSTALLED, SIGNATURE, DATE, CUSTOMER SIGNATURE, X, DESCRIPTION, LABOUR AMOUNT, PARTS AMOUNT, GAS, OIL, LUBE, SUBLET AMOUNT, MISC. CHARGES, TOTAL CHARGES, LESS INSURANCE, SALES TAX, PLEASE PAY THIS AMOUNT, TOTALS

CUSTOMER #:

249342

INVOICE

PAGE 3



LEDUC CHRYSLER JEEP

6102 46A Street
Leduc, Alberta T9E 7A7
Telephone (780) 986-2051
Facsimile (780) 986-1486
Toll Free 1-800-355-8933
service@leducchrysler.com
www.leducchrysler.com



HOME: CONT:
BUS: CELL: SERVICE ADVISOR: 135 CHUCK

Table with columns: COLOUR, YEAR, MAKE/MODEL, VIN, LICENSE, ODOMETER IN/ OUT, TAG. Values: 09, JEEP LIBERTY, 1J8GN58K69W509001, 100701/100719, T3005

Table with columns: IN SVC. DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., CUST. PAY LABOUR RATE, PAYMENT, INV. DATE. Values: 26JUN09 DD, 16:00 09DEC22, 0.00, CHG, 13DEC22

R.O. OPENED READY OPTIONS: DLR:C3834 ENG:3.7_Liter_MPI

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL

100719 Replaced the evaporator while the HVAC housing was removed.

VIP15 15 Percent off parts and laboUr
C -355.43 -355.43

ESTIMATE: 2,140.25 08DEC22 08:31 SA: 135
CONTACT:

Shop supplies 95.00

CAUTION! Failure to perform required maintenance items may result in damage to your vehicle and could VOID the warranty coverage. Please refer to your OWNERS MANUAL maintenance schedules. After ANY repair involving the removal of tires, re-torque wheel nuts within 100 km

Table with columns: CUSTOMER GST, INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$, DESCRIPTION, TOTALS. Includes 'AT YOUR SERVICE' and 'THANK YOU' sections.



Invoice #251

17 May 2022

BILL TO

FROM

Doug,s Auto Repair
4814-46 Ave
Wetaskiwin, AB T9A 0H3
dougautorepair1@gmail.com
+1 7803622632

INVOICE ITEMS	AMOUNT
2018 ford f150 front hub 1 unit x \$625.51/unit	\$625.51
f150 labor 1.50 hrs x \$100.00/hr	\$150.00
2008 jeep 2 hrs x \$100.00/hr	\$200.00
CV axle 1 unit x \$210.00/unit	\$210.00


Subtotal (excl. GST) \$1,185.51
5% GST \$59.28

\$1,244.79

PAYMENT DUE 21 MAY 2022

MESSAGE

Thanks for your business.



COPY

CUSTOMER #:

241755

INVOICE

PAGE 1



LEDUC CHRYSLER JEEP

6102 46A Street
Leduc, Alberta T9E 7A7
Telephone (780) 986-2051
Facsimile (780) 986-1486
Toll Free 1-800-355-8933
service@leducchrysler.com
www.leducchrysler.com



HOME: CONT:
BUS: CELL: SERVICE ADVISOR: 228 FRED

Table with columns: COLOUR, YEAR, MAKE/MODEL, VIN, LICENSE, ODOMETER IN/ OUT, TAG. Values: 09, JEEP LIBERTY, 1J8GN58K69W509001, 83314/83314, T001

Table with columns: IN SVC. DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., CUST. PAY LABOUR RATE, PAYMENT, INV. DATE. Values: 26JUN09 DD, 17:00 10FEB22, 0.00, CHG, 10FEB22

Table with columns: R.O. OPENED, READY, OPTIONS. Values: 12:02 10FEB22, 12:49 10FEB22, DLR:C3834 ENG:3.7_Liter_MPI

Table with columns: LINE OPCODE, TECH TYPE, HOURS, LIST, NET, TOTAL. Includes line 08 ELECTRICAL with 80.00 net and 196.65 net for parts.

Shop supplies 8.80

CAUTION! Failure to perform required maintenance items may result in damage to your vehicle and could VOID the warranty coverage. Please refer to your OWNERS MANUAL maintenance schedules. After ANY repair involving the removal of tires, re-torque wheel nuts within 100 km



Table with columns: CUSTOMER GST, INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$, DESCRIPTION, TOTALS. Includes 'AT YOUR SERVICE' and 'THANK YOU' sections.

Quote - Shop Copy

RO Number	241755
Tag	T001

LEDUC CHRYSLER LTD.
6102-46A ST
LEDUC AB T9E 7A7
Phone # (403)986-2051

Customer Information			Vehicle Information			
Customer #	Customer Name	Quote Date/Time	Year	Make	Model	Odometer
		02/10/2022 12:43 PM	2009	JEEP	LIBERTY	83314
Address			VIN		Last Service Date	
			1J8GN58K69W509001			
Phone #	Email Address		Advisor	Appt Promised: Date/Time		
(825)995-2708			Fred	No	02/10/2022	05:00 PM

SERVICE REQUEST

Technician Number: 268		Status: SUBMITTED			
B	Recommend vehicle inspection - found engine oil leaks and torn CV shaft boot (drivers front).				
Additional Recommendation	Qty	LT	Hrs	Unit Price	Price
Labor					
Recommend vehicle inspection - found engine oil leaks and torn CV shaft boot (drivers front).	C		1.50		224.25

Pricing Summary

	Labor	Parts	M/L/S	Tax	Line Total
Estimate	224.25	0.00	24.67	12.44	261.36

SERVICE REQUEST

Technician Number: 268		Status: SUBMITTED			
C	Perform diagnostic for PENDING code P0455 Evap large leak				
Additional Recommendation	Qty	LT	Hrs	Unit Price	Price
Labor					
Perform diagnostic for PENDING code P0455 Evap large leak	C		1.00		149.50

Pricing Summary

	Labor	Parts	M/L/S	Tax	Line Total
Estimate	149.50	0.00	16.45	8.30	174.25

Authorized Estimate	
Labor	
Parts	
Misc.	
Lube	
Sublet	
Subtotal	
Tax	
Total	

+

Additional Recommendations	
Labor	\$373.75
Parts	\$0.00
Misc.	\$41.12
Lube	\$0.00
Sublet	\$0.00
Subtotal	\$414.87
Tax	\$20.74
Total	\$435.61

=

Revised Estimate	
Labor	\$373.75
Parts	\$0.00
Misc.	\$41.12
Lube	\$0.00
Sublet	\$0.00
Subtotal	\$414.87
Tax	\$20.74
Total	\$435.61