



1787, HEKLA AVENUE87
WINNIPEG, MB R2R 0KR
PHONE: 204-952-4696, 416-576-1231, 204-800-1108
EMAIL: REESSETTRUCK@GMAIL.COM

DATE	INVOICE
08/07/2025	25432

INVOICE TO
SURSINGHIA TRANSPORT LTD.:UNIT 5911 / VIN 444519 UNIT 5911 / VIN 444519 2526 16A AVE NW EDMONTON AB T6T 2H6

VIN	CAB CARD/EXP	LIC PLATE	ODOMETER	MAKE/YEAR	UNIT
1XP5DB9X4WD444519	N/A		1972718 KM		5911

ITEM	DESCRIPTION	QTY	RATE	TAX	AMOUNT
1R0749 M L	FUEL FILTER	1	53.84	S	53.84
1R1808 FILTER L	OIL FILTER	1	72.26	S	72.26
15W40 L	15W40 ROTELLA ENGINE OIL	45	5.95	S	267.75
31S-930 L	BATTERY	4	110.00	S	440.00
PARKING	PARKING CHARGES	10	150.00	S	1,500.00
TOWING	2 TIME TOWING CHARGES	2	200.00	S	400.00
LK1352837-FPD	CYLINDER KIT	1	716.28	S	716.28
9Y6054-HAW	CONNECTING ROD	1	237.54	S	237.54
9Y7735G-IPD	CONECTING ROD BRG GROOVED	1	41.60	S	41.60
7E4195-MCB	BOLT CONNECTING ROD	2	20.65	S	41.30
FREIGHT	FREIGHT CHARGES	1	125.00	S	125.00
1663650	ARTICULATED PISTON	1	256.10	S	256.10
3J1907	SEAL	3	3.08	S	9.24
9S4191	PLUG	4	11.80	S	47.20
8T6765	PLUG	1	6.02	S	6.02
72915-20-10	MALE JIC 90 ELBOW	1	9.85	S	9.85
EX630956-DEL	INJECTOR	1	750.00	S	750.00
1070583	BOLT	3	0.75	S	2.25
1195-08-10	MALE ADAPTER	1	4.15	S	4.15
2818261 P	SLEEVE ASSEMBLY	6	63.40	S	380.40
8S9191	INJECTOR BOLT	2	3.65	S	7.30
1061792P	STUD TAPER EXHAUST MANIFOLD	11	29.91	S	329.01
1061793 P	TAPER EXHAUST MANIFOLD STUD	1	26.21	S	26.21
2N2766 P	EXHAUST LOCKNUT	12	15.33	S	183.96
9L8925	BOLT	5	0.92	S	4.60
5P5846	SEAL-O RING	1	32.92	S	32.92
5P8068	SEAL-O RING	1	34.51	S	34.51
4N1151	OIL PAN GASKET	1	45.77	S	45.77

23-14153-000 L	UNION 5/8	1	27.63	S	27.63
HS3046	BLUE HOOD SPRING	1	31.15	S	31.15
L92-6000-0718P	HOOD CABLE	2	25.71	S	51.42
13-03511	CABLE SAFETY SHORT	1	80.75	S	80.75
BRAKE CLEANER KFT/313 L	BRAKE CLEANER	30	4.86	S	145.80
CHO NF55/45 (550062567) L	ANTI FREEZE COOLANT	14	11.97	S	167.58
					Subtotal: 6,529.39
LABOUR.	CHECK ENGINE PROBLEM, REMOVE HEAD, REMOVE OIL PAN, CHECK PISTON, CONNECTING ROD	1	4,500.00	S	4,500.00
LABOUR.	REPLACE BATTERIES AND CLEAN CABLE	2	80.00	S	160.00
LABOUR.	REPLACE HEAD, CONNECTING ROD	0	80.00	S	0.00
LABOUR.	REPLACE INJECTOR AND BOLT	0	80.00	S	0.00
LABOUR.	REPLACE HOOD CABLE	0	80.00	S	0.00
LABOUR.	REPLACE OIL PAN GASKET	0	80.00	S	0.00
LABOUR.	REMOVE RADIATOR AND SIZED BOLT FRONT, PLATE BACK, INSTALL RADIATOR AND REPLACE HOSE	6	80.00	S	480.00
					Subtotal: 5,140.00
SHOP SUPPLY5%	SHOP SUPPLY	5,140	0.05	S	257.00

No Warranty on Labour

NOTE: Not responsible for broken nuts, bolts, and loose wheels and No refunds will give, if any. Wheels should be re-torque after 150km.
 PAYMENT TERMS: Due on receipt of Invoice, 2% per week interest will be charged on overdue accounts.
 NO WARRANTY ON LABOUR

TOTAL	13,357.57
S	1,431.18
BALANCE DUE	\$13,357.57