

#155 A02-50
SEPCUSTOMER #:
UNIT# 155

110605

PETERBILT MEDICINE HAT2250 South Highway Dr SE
Redcliff, AB. T0J 2P0
Tel: 403-526-4460
Fax: 403-525-5299
Toll-Free: 1- 844-526-4460

INVOICE

RONCO OILFIELD HAULING LTD.
BOX 338

MEDICINE HAT, AB T1A 7G1

PAGE 1

HOME: CONT:403-526-4873

BUS: 403-526-4873 CELL:

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR	YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/ OUT		TAG
	13	KENWORTH T800		1NKDX4EX6DR962894	J62724	800553/800553		179561
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE	
01JAN13 DD			09:16 14JUN25	155-0630	192.00	CHG	30JUN25	
R.O. OPENED		READY		OPTIONS: DLR:M068 ENG:79598047				

10:25 27MAY25 13:30 30JUN25

LINE OPCODE TECH TYPE HOURS

LIST NET TOTAL

A ENGINE HOURS 17136

EH ENGINE HOURS 17136

7005	C				0.00	0.00	
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE A:	0.00
800553							

B Peterbilt Platinum Courtesy Inspection

PPCI Peterbilt Platinum Courtesy Inspection

7001 C

7005 C

					0.00	0.00	
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE B:	0.00

800553 7001-PERFROM COURTESY INSPECTION FOUND MIDDLE DRIVE AXLE
LEFT SIDE WHEEL SEAL LEAKING, REAR DRIVE AXLE UPPER WISHBONE TORQUE ARM
BUSHINGS FAILED AND LOOSE BOLT. PTO LEAKING, UPPER LEFT COUNTERSHAFT
BEARING COVER LEAKING ON TRANS. FRONT LEFT DRIVE AXLE DUST SHIELD HALF
GON AND REMAINDER IS LOOSE. RIGHT FRONT HOOD SIGNAL INOP. LEFT REAR
REVERSE SIDE INOP. D SIGN AIR LEAK ON CYLINDER.

C CELCUM Inspect & Repair For Check Engine Light On - Cummins Engine

CELCUM CONNECT WITH INSITE ANF ANAYLYZE CODES

7001 CL

7018 CL

		155.00	155.00
1 4963857CUM INIJ GASKET	32.55	27.76	27.76
1 5292265CUM ISOLATOR	8.65	7.38	7.38
2 5579417PXCUM KIT, INJECTOR	2553.71	2035.17	4070.34
CORE CHARGE C		550.00	550.00
1 2866337CUM GASKET 5"	25.68	21.90	21.90
1 2871960CUM SENSOR-PRESSURE	328.39	280.05	280.05
2 M84-6044-005 STRAP ASSY	109.35	74.36	148.72
1 90-0013 (WH)CLAMP-V BAND 5"	33.18	20.01	20.01
1 2880213CUM CLAMP-V	109.79	93.63	93.63
1 FREIGHT CHARGE	130.00	130.00	130.00

OUT
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE.
\$
ALL WARRANTY SUBJECT TO FACTORY ACCEPTANCE.
SIGNATURE
DATE RELEASED

**CALGARY PETERBILT LTD**11550 44th Street S.E.
Calgary, AB T2Z 4A2
Phone: (403) 235-2550
Fax: (403) 235-1322
Toll Free: 1-800-332-1296**PETERBILT LETHBRIDGE PETERBILT RED DEER**4110 - 18th Avenue North
Lethbridge, AB T1H 6N7
Phone: (403) 328-0500
Fax: (403) 328-0225
Toll Free: 1-888-777-311227 Burnt Lake Crescent
Red Deer County, AB T4S 2L4
Phone: (403) 342-5100
Fax: (403) 342-5153
Toll Free: 1-877-348-5100

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
G.S.T.	
PLEASE PAY THIS AMOUNT	

GST # R100731918

CUSTOMER COPY

CUSTOMER #:
UNIT# 155

RONCO OILFIELD HAULING LTD.
BOX 338

MEDICINE HAT, AB T1A 7G1

HOME: CONT:403-526-4873

BUS: 403-526-4873 CELL:

110605

INVOICE

PAGE 2



PETERBILT MEDICINE HAT

2250 South Highway Dr SE

Redcliff, AB. T0J 2P0

Tel: 403-526-4460

Fax: 403-525-5299

Toll-Free: 1-844-526-4460

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
	13	KENWORTH T800	1NKDX4EX6DR962894	J62724	800553/800553	179561	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST PAY LABOUR RATE	PAYMENT	INV. DATE
01JAN13 DD			09:16 14JUN25	155-0630	192.00	CHG	30JUN25
R.O. OPENED		READY	OPTIONS: DLR:M068 ENG:79598047				

10:25 27MAY25 13:30 30JUN25

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
1					5068.14	3970.00	3970.00
1					33.35	28.44	28.44
2					256.16	256.16	512.32
1					0.14	0.14	0.14
1					0.05	0.05	0.05
3					0.04	0.04	0.12
-2					35.00	35.00	-70.00
COUPON: M25JUN7944 AUTH: 060625-PEABR							
-2					35.00	35.00	-70.00
COUPON: N25APRJUN7711 AUTH: 060625-PEABR							
-1					35.00	35.00	-35.00
COUPON: M25JUN7942 AUT: 060625-PEABR							
-1					50.00	50.00	-50.00
COUPON: N25APRJUN7717 AUTH: 060625-PEABR							
2					0.68	0.68	1.36
1					0.14	0.14	0.14
2					0.07	0.07	0.14
1					0.07	0.07	0.07
1					22.57	17.60	17.60
4					2553.71	2035.17	8140.68
CORE CHARGE C						1100.00	1100.00
-4					2553.71	275.00	-1100.00
1					20.00	20.00	20.00
-4					35.00	35.00	-140.00
COUPON: M25JUN7944 AUTH: 062725-GJQDN							
-4					35.00	35.00	-140.00
COUPON: N25APRJUN7711 AUTH: 062725-GJQDN							
-1					30.00	30.00	-30.00
COUPON: 30REWARD2025Q2 AUTH: 062725-PAG4J							
DIAG1 PERFORM INJECTOR PERFORMANCE TEST							
7001			CL			116.25	116.25
SVCH/CDOSER SERVICE AND OR REPLACE HYDRO CARBON							
DOSER							
7001			CL			310.00	310.00

OUT		DESCRIPTION	TOTALS
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE. \$ ALL WARRANTY SUBJECT TO FACTORY ACCEPTANCE.	 CALGARY PETERBILT LTD 11550 44th Street S.E. Calgary, AB T2Z 4A2 Phone: (403) 235-2550 Fax: (403) 235-1322 Toll Free: 1-800-332-1296	LABOUR AMOUNT	
		PARTS AMOUNT	
		GAS, OIL, LUBE	
		SUBLET AMOUNT	
		MISC. CHARGES	
SIGNATURE	PETERBILT LETHBRIDGE 4110 - 18th Avenue North Lethbridge, AB T1H 6N7 Phone: (403) 328-0500 Fax: (403) 328-0225 Toll Free: 1-888-777-3112	TOTAL CHARGES	
		LESS INSURANCE	
		G.S.T.	
DATE RELEASED	PETERBILT RED DEER 27 Burnt Lake Crescent Red Deer County, AB T4S 2L4 Phone: (403) 342-5100 Fax: (403) 342-5153 Toll Free: 1-877-348-5100	PLEASE PAY THIS AMOUNT	

GST # R100731918

CUSTOMER COPY

CUSTOMER #:
UNIT# 155

110605

INVOICE



PETERBILT MEDICINE HAT

2250 South Highway Dr SE
Redcliff, AB. T0J 2P0
Tel: 403-526-4460
Fax: 403-525-5299
Toll-Free: 1- 844-526-4460

RONCO OILFIELD HAULING LTD.
BOX 338

MEDICINE HAT, AB T1A 7G1

HOME: CONT:403-526-4873

BUS: 403-526-4873 CELL:

PAGE 3

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
	13	KENWORTH T800	1NKDX4EX6DR962894	J62724	800553/800553	179561	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST PAY LABOUR RATE	PAYMENT	INV. DATE
01JAN13 DD			09:16 14JUN25	155-0630	192.00	CHG	30JUN25
R.O. OPENED		READY	OPTIONS: DLR:M068 ENG:79598047				

10:25 27MAY25 13:30 30JUN25

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
04-124	REMOVE & REPLACE DPF ASSEMBLY						
	7001	CL				620.00	620.00
SEIZED	EXTRACTION OF SEIZED MOUNTING BOLTS						
	7001	CL				155.00	155.00
ASH-REGEN	PERFORM REGEN & DATA LOG						
	7001	CL				155.00	155.00
CELCUM	TSHOOT FOR CODES FOR TEMP SENSORS SHORTED TO HIGH						
	7001	CL				310.00	310.00
032-112	REPAIR DPF HARNESS						
	7001	CL				155.00	155.00
RT ROAD	TEST FOR DIAGNOSE OR REPAIR VERIFICATION.						
	7001	CL				155.00	155.00
CELCUM	PERFORM DIGNOSTICS FOR FREQUENT/INCOMPLETE REGENS						
	7001	CL				775.00	775.00
04-139	REPLACE 4 FAILED INJECTORS						
	7001	CL				0.00	0.00
RT REGEN	AND ROAD TEST UNIT						
	7001	CL				193.75	193.75
PARTS:	17505.85	LABOR:	3100.00	OTHER:	0.00	TOTAL LINE C:	20605.85

800553

7001- CONNECT TO ECM CHECK CODES FOUND 1981 AND 5383 RUN IPT TEST
FOUND INJECTOR #2 AND 6 HAVE FAILED. FOUND 5383 DIRECT THAT DPF ASH
LOAD IS ABOVE SPECIFICATION UNIT WILL NEED DPF CLEANING. DRAIN COOLANT
AND REMOVE FUEL DOSER AND INSPECT FOUND NOZZLE LOOKS CARBONED OFF.
CLEAN AND LEAK TEST AND FLOW TEST FOUND 290ML OF FUEL ALL OK.
RE-INSTALL DOSER FILL COOLANT. RESET AFTERTREATMENT DATA. CLEAR CODES.
REMOVE DPF STEP COVER, REMOVE LOWER STEP. REMOVE DPF DP SENSOR AND
MOUNT REMOVE TEMP SENSORS AND TEMP SENSOR MODULE. REMOVE MOUNTS CLAMPS
HAS TO CUT ONE OFF DUE TO UNABLE TO GET THE NUT OFF. RMEOVE INLET AND
OUTLET CLAMPS ONE BROKE AND THE OTHER HAD TO BE CUT OFF. REMOVE
DPF/DOC/ ASSEMBLY. FOUND DPF IS BREACHED CLEAN UP OUTLET HOUSING AND
INLET AND OUTLET PIPES. REMOVE STUCK CLAMP FROM LOWER SKID PLATE AND

OUT		DESCRIPTION	TOTALS
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE. \$ ALL WARRANTY SUBJECT TO FACTORY ACCEPTANCE. SIGNATURE DATE RELEASED	 CALGARY PETERBILT LTD 11550 44th Street S.E. Calgary, AB T2Z 4A2 Phone: (403) 235-2550 Fax: (403) 235-1322 Toll Free: 1-800-332-1296 PETERBILT LETHBRIDGE 4110 - 18th Avenue North Lethbridge, AB T1H 6N7 Phone: (403) 328-0500 Fax: (403) 328-0225 Toll Free: 1-888-777-3112 PETERBILT RED DEER 27 Burnt Lake Crescent Red Deer County, AB T4S 2L4 Phone: (403) 342-5100 Fax: (403) 342-5153 Toll Free: 1-877-348-5100	LABOUR AMOUNT	
		PARTS AMOUNT	
		GAS, OIL, LUBE	
		SUBLET AMOUNT	
		MISC. CHARGES	
		TOTAL CHARGES	
		LESS INSURANCE	
		G.S.T.	
		PLEASE PAY THIS AMOUNT	

GST # R100731918

CUSTOMER COPY

CUSTOMER #:
UNIT# 155

110605

INVOICE

RONCO OILFIELD HAULING LTD.
BOX 338

MEDICINE HAT, AB T1A 7G1

HOME: CONT:403-526-4873

BUS: 403-526-4873 CELL:

PAGE 4



PETERBILT MEDICINE HAT

2250 South Highway Dr SE

Redcliff, AB. T0J 2P0

Tel: 403-526-4460

Fax: 403-525-5299


Toll-Free: 1-844-526-4460

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR	YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/ OUT		TAG
	13	KENWORTH T800		1NKDX4EX6DR962894	J62724	800553/800553		179561
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE	
01JAN13 DD			09:16 14JUN25	155-0630	192.00	CHG	30JUN25	
R.O. OPENED		READY	OPTIONS: DLR:M068 ENG:79598047					

10:25 27MAY25 13:30 30JUN25

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
CLEAN OUT ROCKS AND DEBRIS. CLEAN DOC IN THE FSX MACHINE. ASSEMBLE DPF/DOC INSTALL TO UNIT. CONNECT OUTLET PIPE TO DECOMP TUBE, ROTATE HOUSING TO LINE UP THE INLET CONNECTION INSTALL INLET CONNECTION INSTALL MOUNT CLAMPS. INSTALL DOC INLET TEMP SENSOR FOUND THE OTHER 2 SENSORS THREAD ARE VERY DAMAGED AND SHOULD BE REPLACED TO PREVENT DAMAGE TO THE NEW DPF. HEAT AND FREE UP NUTS ON DPF DP SENSOR TUBES. INSTALL TUBES, INSTALL DPF STEP. INSTALL NEW TEMP SENSORS AND CONNECT SENSOR MODULE. INSTALL DPF DP SENSOR MOUNT AND CONNECT LINES. 7018 ROAD TEST AND CHECKED AFTER FOR ISSUES. 7018 CEL ON. HOOKED UP INSITE. FAULT CODES ARE 1921 ACTIVE, INACTIVE 2765,0195,1881,3134,3314,3317,3319 AND 1117. MOST CODES ARE RELATED TO AFTER TREATMENT HARNESS. TROUBLESHOOT HARNESS. REMOVED HARNESS FROM DIFFERENTIAL PRESSURE SENSOR AND TEMP SENSOR MODULE ON DPF. CHECKED HARNESS FOR ISSUES. DID NOT SEE ANY. TRACED HARNESS OUT. FOUND ON OEM HARNESS BEFORE CONNECTOR PLUG EXPOSED HARNESS. CHECKED FOR DAMAGE IN HARNESS. FOUND 2 WIRES WITH SCRUBS ON THEM. REPAIRED HARNESS WITH BUTT CONNECTORS. LOAD TEST HARNESS. ALL TESTES OUT GOOD. REASSEMBLE, RUN AND TEST. TIE UP AND PROTECT HARNESS ON RIGHT SIDE BY TRANS. CLEARED CODES. PUT OUTSIDE AND PERFORMED REGEN FOR FAULT CODE 1921. TIGHTENED UP LOOSE BATTERY CABLES ON BATTERIES. 7018 HOOKED UP TO TRUCK WITH CUMMINS INSITE. CREATE WARRANTY REPORT. PERFORMED SNAP SHOT. PERFORMED IPT. CREATED GUIDENAZ CASE. CASE FILE # 0141779. FOLLOWED TROUBLESHOOTING FOR 3375. CHECKED FOR RELATED FAULT CODES. NONE. CHECKED FOR RESTRICTED AIR INTAKE. NONE. CHECKED FOR RESTRICTED EGR DIFFERENTIAL PRESSURE TUBES. NON ISSUE FOUND. CHECKED FOR DAMAGED DIFFERENTIAL PRESSURE TUBES ON DPF. NO ISSUES FOUND. CHECKED FOR DIFFERENTIAL PRESSURE SESNOR STUCK IN RANGE. NO FAULT FOUND. CHECKED FOR LEAKS IN CHARGE AIR SYSTEM. NONE FOUND. CHECKED FOR MALFUNCTIONING DPF/DOC TEMP SENSORS. NO ISSUES FOUND. CHECKED HARNESS AND CONNECTORS FOR SENSORS. NO ISSUES FOUND. NEW DPF HAD BEEN INSTALLED. NOT PLUGGED. REGEN ANALYZER HAD PASSED. DOC WAS INSPECTED AND NO ISSUES WERE FOUND. UPDATED THE GUIDENAZ CASE. ATTACHED							

OUT			CALGARY PETERBILT LTD 11550 44th Street S.E. Calgary, AB T2Z 4A2 Phone: (403) 235-2550 Fax: (403) 235-1322 Toll Free: 1-800-332-1296	DESCRIPTION	TOTALS
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE.				LABOUR AMOUNT	
\$		 <td rowspan="2">PETERBILT LETHBRIDGE PETERBILT RED DEER 4110 - 18th Avenue North Lethbridge, AB T1H 6N7 Phone: (403) 328-0500 Fax: (403) 328-0225 Toll Free: 1-888-777-3112</td> <td>PARTS AMOUNT</td> <td></td>	PETERBILT LETHBRIDGE PETERBILT RED DEER 4110 - 18th Avenue North Lethbridge, AB T1H 6N7 Phone: (403) 328-0500 Fax: (403) 328-0225 Toll Free: 1-888-777-3112	PARTS AMOUNT	
ALL WARRANTY SUBJECT TO FACTORY ACCEPTANCE.				GAS, OIL, LUBE	
SIGNATURE		 <td rowspan="2">PETERBILT LETHBRIDGE PETERBILT RED DEER 27 Burnt Lake Crescent Red Deer County, AB T4S 2L4 Phone: (403) 342-5100 Fax: (403) 342-5153 Toll Free: 1-877-348-5100</td> <td>SUBLET AMOUNT</td> <td></td>	PETERBILT LETHBRIDGE PETERBILT RED DEER 27 Burnt Lake Crescent Red Deer County, AB T4S 2L4 Phone: (403) 342-5100 Fax: (403) 342-5153 Toll Free: 1-877-348-5100	SUBLET AMOUNT	
DATE RELEASED				MISC. CHARGES	
GST # R100731918		<td rowspan="2"></td> <td>TOTAL CHARGES</td> <td></td>		TOTAL CHARGES	
				LESS INSURANCE	
		<td rowspan="2"></td> <td>G.S.T.</td> <td></td>		G.S.T.	
				PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

CUSTOMER #:
UNIT# 155

110605



PETERBILT MEDICINE HAT

2250 South Highway Dr SE
Redcliff, AB. T0J 2P0
Tel: 403-526-4460
Fax: 403-525-5299
Toll-Free: 1- 844-526-4460

INVOICE

RONCO OILFIELD HAULING LTD.
BOX 338

MEDICINE HAT, AB T1A 7G1

HOME: CONT:403-526-4873

BUS: 403-526-4873 CELL:

PAGE 5

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR	YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/ OUT		TAG
	13	KENWORTH T800		1NKDX4EX6DR962894	J62724	800553/800553		179561
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE	
01JAN13 DD			09:16 14JUN25	155-0630	192.00	CHG	30JUN25	
R.O. OPENED		READY		OPTIONS: DLR:M068 ENG:79598047				

10:25 27MAY25 13:30 30JUN25

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

SNAPSHOTS . TALK TO CUMMINS TECH SUPPORT. CASE FILE
04736092. ATTACHED NEW ECM IMAGE. GO OVER WHAT HAS BEEN DO
WITH UNIT. RECOMMENDED TO PERFORM REGEN WITH SNAP SHOT AND
30 MIN ROAD TEST. ALSO PERFORM AFTERTREATMENT RESET.
PERFORMED RESET. IT IS NOT SHOWING UP IN HISTORY. REFLASHED
ECM ATTEMPTED RESET AGAIN. STILL NOT SHOWING UP IN HISTORY.
CUMMINS CARE RECOMMENDS REPLACEMENT OF OTHER 4 INJECTORS.
7001- REMOVE EGR CROSSOVER TUBE, VALVE COVER, REMOVE
INJECTOR FUEL LINES FROM #1,3,4,5. REMOVE INJECTOR HARNESS
FROM INJECTORS, REMOVE HOLD DOWN BOLTS AND HPCS. REMOVE INJECTOR,
INSTALL NEW INJECTORS TO #4 AND #5 CYLINDER.
TORQUE INJECTORS AND HPCS. INSTALL FUEL LINES. INSTALL NEW
INJECTORS 1 AND 3 INSTALL HPCS AND TORQUE. INSTALL HARNESS
AND ELECTRICAL CONNECTORS INSTALL FUEL LINES AND VALVE COVER
INSTALL EGR CROSSOVER TUBE. PROGRAM INJECTOR TRIM CODES AND
RUN REGENERATION ANALYZER.

D DIAGNOSE TACH READING 1500 AND HAS NO POWER, BETWEEN 1300 AND 1400
ITS OK

DIAG2 DIAGNOSE TACH READING 1500 AND HAS NO
POWER, BETWEEN 1300 AND 1400 ITS OK

7001 C 0.00 0.00
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D: 0.00
800553 7001 TAKE UNIT FOR TEST DRIVE ON BUMPY ROADS UNABLE TO
DUPLICATE THE COMPLAINT.

E** DRIVERS SIDE REVERSE LIGHT OUT
032-110 DRIVERS SIDE REVERSE LIGHT OUT
7001 CL
7014 CL

310.00 310.00

13 555*51621 14-16 HTSHRNK CRIMP BUTT BLUE
250P

0.70 0.70 9.10
3.38 3.38 10.14

3 555*5714* CONNECTOR HY/LINK

OUT		CALGARY PETERBILT LTD		DESCRIPTION	TOTALS
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE.			11550 44th Street S.E. Calgary, AB T2Z 4A2 Phone: (403) 235-2550 Fax: (403) 235-1322 Toll Free: 1-800-332-1296	LABOUR AMOUNT	
				PARTS AMOUNT	
\$				GAS, OIL, LUBE	
				SUBLET AMOUNT	
ALL WARRANTY SUBJECT TO FACTORY ACCEPTANCE.				MISC. CHARGES	
				TOTAL CHARGES	
SIGNATURE		PETERBILT LETHBRIDGE	PETERBILT RED DEER	LESS INSURANCE	
				G.S.T.	
DATE RELEASED		4110 - 18th Avenue North Lethbridge, AB T1H 6N7 Phone: (403) 328-0500 Fax: (403) 328-0225 Toll Free: 1-888-777-3112	27 Burnt Lake Crescent Red Deer County, AB T4S 2L4 Phone: (403) 342-5100 Fax: (403) 342-5153 Toll Free: 1-877-348-5100	PLEASE PAY THIS AMOUNT	

GST # R100731918

CUSTOMER COPY

CUSTOMER #:
UNIT# 155

110605



PETERBILT MEDICINE HAT

2250 South Highway Dr SE
Redcliff, AB. T0J 2P0
Tel: 403-526-4460
Fax: 403-525-5299
Toll-Free: 1- 844-526-4460

INVOICE

RONCO OILFIELD HAULING LTD.
BOX 338

MEDICINE HAT, AB T1A 7G1

HOME: CONT:403-526-4873

BUS: 403-526-4873 CELL:

PAGE 6

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR	YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/ OUT		TAG
	13	KENWORTH T800		1NKDX4EX6DR962894	J62724	800553/800553		179561
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE	
01JAN13 DD			09:16 14JUN25	155-0630	192.00	CHG	30JUN25	
R.O. OPENED		READY		OPTIONS: DLR:M068 ENG:79598047				

10:25 27MAY25 13:30 30JUN25

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
4	555*5161*	18-22	HTSHRNK CRIMP BUTT CONN RED		0.68	0.68	2.72
2	555*9092*	14-16	HTSHRNK RING TERM BLUE #10		0.93	0.93	1.86
PARTS: 23.82 LABOR: 310.00 OTHER: 0.00				TOTAL LINE E:		333.82	

800553

7014-REMOVE LIGHT, CHECK FOR ANY POWER OR GROUND AT THE LIGHT, FOUND NO POWER, ALSO FOUND NO POWER AT LEFT REAR SIGNAL LIGHT, CHECK WIRING, FOUND NO OBVIOUS ISSUES,
7001- TAKE OVER FOR 7014- RMEOVE REAR GRATE FROM BACK OF TRUCK. PULL WIRES UP THRU OPENING TO INSPECT FOUND SEVERAL WIRES PULLED FROM CONNECTIONS SPLICE WIRES BACK TOGETHER ADD WIRES SECTIONS WERE APPLICABLE. CHECK LIGHTS FOUND WORKING INSTALL LIGHTS AND INSTALL CONNECTIONS FOUND LEFT SIDE LIGHTS STOPPED WORKING PULL WIRES BACK UP THRU OPENING AND FOUND NO GROUND FOLLOW WIRES AND CHECK ALONG WIRE FOR GROUND PULL TEST WIRES FOUND GROUND WIRE WAS BROKEN INSIDE THE INSULATION AND HAD TO PULL QUITE HARD ON WIRE TO FIND THIS. REPAIR SECTION TAPE HARNESS BACK TOGETHER AND INSTALL LIGHT CONNECTIONS ONCE AGAIN CHECK OPERATION ALL OK.

F** FRONT RIGHT HOOD SIGNAL INOP

032-110 FRONT RIGHT HOOD SIGNAL INOP

7005 CL

3 555*51621 14-16 HTSHRNK CRIMP BUTT BLUE 250P 0.70 116.25 116.25

PARTS: 2.10 LABOR: 116.25 OTHER: 0.00 TOTAL LINE F: 118.35

800553 7005. INSPECT WIRING AND TRACE CIRCUIT. REMOVE ZIP TIES AND LOOM. INSPECT AND FOUND CORRODED AND BROKEN WIRING. REPAIR WIRING AS NEEDED AND RECHECK. CHECKS OK. LIGHTS NOW OPERATE NORMALLY. REINSTALL LOOM AND TIE UP WIRING.

G** P/S D SIGNS CYLINDER LEAKING AIR

013-416A P/S D SIGNS CYLINDER LEAKING AIR

7014 C

1 562*HK20SP PTO SNAPPER PIN ASST 20PCS 0.91 96.00 96.00

PARTS: 0.68 LABOR: 96.00 OTHER: 0.00 TOTAL LINE G: 96.68

800553 7014-CHECK OVER D-SIGN AIR LINES, FOUND TOP AIR LINE (BLUE)

OUT		DESCRIPTION	TOTALS
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE.	 CALGARY PETERBILT LTD. 11550 44th Street S.E. Calgary, AB T2Z 4A2 Phone: (403) 235-2550 Fax: (403) 235-1322 Toll Free: 1-800-332-1296 PETERBILT LETHBRIDGE PETERBILT RED DEER 4110 - 18th Avenue North Lethbridge, AB T1H 6N7 Phone: (403) 328-0500 Fax: (403) 328-0225 Toll Free: 1-888-777-3112	LABOUR AMOUNT	
\$		PARTS AMOUNT	
ALL WARRANTY SUBJECT TO FACTORY ACCEPTANCE.		GAS, OIL, LUBE	
		SUBLET AMOUNT	
		MISC. CHARGES	
		TOTAL CHARGES	
		LESS INSURANCE	
SIGNATURE		G.S.T.	
DATE RELEASED		PLEASE PAY THIS AMOUNT	

GST # R100731918

CUSTOMER COPY

CUSTOMER #:
UNIT# 155

110605

INVOICE



PETERBILT MEDICINE HAT

2250 South Highway Dr SE
Redcliff, AB. T0J 2P0
Tel: 403-526-4460
Fax: 403-525-5299
Toll-Free: 1-844-526-4460

RONCO OILFIELD HAULING LTD.
BOX 338

MEDICINE HAT, AB T1A 7G1

HOME: CONT:403-526-4873

BUS: 403-526-4873 CELL:

PAGE 7

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR	YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/ OUT		TAG
	13	KENWORTH T800		1NKDX4EX6DR962894	J62724	800553/800553		179561
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE	
01JAN13 DD			09:16 14JUN25	155-0630	192.00	CHG	30JUN25	
R.O. OPENED		READY		OPTIONS: DLR:M068 ENG:79598047				

10:25 27MAY25 13:30 30JUN25

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

HAD COME SLIGHTLY OUT OF THE FITTING, PUSH LINE BACK INTO FITTING AND
CHECK FOR LEAKS, ALL OK. NOTICED CYLINDER LOWER MOUNTING CLIP HAD
FALLEN OUT, REPLACED CLIP.

H** PTO LEAKING TRANSMISSION FLUID

TOIL DIAG OIL LEAK AT TRANS

7005 CL		124.00	124.00
1 35P15-2 20TH SHIM	5.44	3.26	3.26
1 35P15-1 10TH SHIM	4.18	2.51	2.51
1 28P216LP OIL SEAL	22.65	22.65	22.65
1 35P8LP SHIFTER COVER GASKET	2.46	2.46	2.46
1 22P127-1 GASKET 0.010	1.30	1.30	1.30
2 22P127-2 GASKET 0.020	1.30	1.30	2.60

023-104 REMOVE AND RESEAL PTO AND REINSTALL

7005 CL		620.00	620.00
---------	--	--------	--------

PARTS: 34.78 LABOR: 744.00 OTHER: 0.00 TOTAL LINE H: 778.78

800553 7005. INSPECT AND FOUND TRANS OIL LEAK IN THE PTO AREA AND
ON THE PTO. FURTHER INSPECT AND FOUND SEVERAL LEAKS. THE PTO TO TRANS
GASKET IS LEAKING; THE PTO OUTPUT SHAFT IS LEAKING. THE REAR PTO OUTPUT
COVER GASKET IS LEAKING AND THE FRONT COVER GASKET IS STARTING TO LEAK.
THE PTO NEEDS TO BE RESEALED. DRAIN TRANS OIL. DISCONNECT AIR LINE AND
DETENT SWITCH WIRING. REMOVE HYDRAULIC PUMP. REMOVE PTO ASSEMBLY. PLACE
PTO ONTO A CLEAN SURFACE WORK AREA. REMOVE FRONT COVER AND GASKETS.
REMOVE REAR OUTPUT COVER AND GASKETS. REMOVE SHIFT COVER AND GASKET.
MEASURE THE SELECTIVE SHIM GASKET THICKNESS FOR THE FRONT AND REAR
COVERS AND MEASURE THE SELECTIVE SHIM PTO TO TRANS GASKET. CLEAN PTO
HOUSING GASKET SURFACE AREAS. CLEAN FRONT COVER. CLEAN REAR OUTPUT
COVER AND SHIFT COVER ASSEMBLY. REINSTALL FRONT COVER WITH THE
SELECTIVE SHIM GASKET. REINSTALL THE REAR OUTPUT COVER WITH THE
SELECTIVE SHIM GASKETS. CHECK BEARING PRELOAD. CHECKS OK. INSTALL NEW
OUTPUT SEAL. CLEAN TRANSMISSION GASKET SURFACE AREA. INSTALL PTO WITH
THE SELECTIVE SHIM PTO TO TRANS GASKETS. MEASURE PTO GEAR BACKLASH.
CHECKS OK. INSTALL SHIFT COVER WITH NEW GASKET. RECONNECT AIR LINE AND
DETENT SWITCH CONNECTOR. REINSTALL HYDRAULIC PUMP. FILL TRANS OIL.

OUT		DESCRIPTION	TOTALS
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE. \$ ALL WARRANTY SUBJECT TO FACTORY ACCEPTANCE.	 CALGARY PETERBILT LTD. 11550 44th Street S.E. Calgary, AB T2Z 4A2 Phone: (403) 235-2550 Fax: (403) 235-1322 Toll Free: 1-800-332-1296	LABOUR AMOUNT	
		PARTS AMOUNT	
		GAS, OIL, LUBE	
		SUBLET AMOUNT	
		MISC. CHARGES	
SIGNATURE	PETERBILT LETHBRIDGE 4110 - 18th Avenue North Lethbridge, AB T1H 6N7 Phone: (403) 328-0500 Fax: (403) 328-0225 Toll Free: 1-888-777-3112	TOTAL CHARGES	
		LESS INSURANCE	
		G.S.T.	
DATE RELEASED	PETERBILT RED DEER 27 Burnt Lake Crescent Red Deer County, AB T4S 2L4 Phone: (403) 342-5100 Fax: (403) 342-5153 Toll Free: 1-877-348-5100	PLEASE PAY THIS AMOUNT	

GST # R100731918

CUSTOMER COPY

CUSTOMER #:
UNIT# 155

110605



PETERBILT MEDICINE HAT

2250 South Highway Dr SE
Redcliff, AB. T0J 2P0
Tel: 403-526-4460
Fax: 403-525-5299
Toll-Free: 1-844-526-4460

INVOICE

RONCO OILFIELD HAULING LTD.
BOX 338

MEDICINE HAT, AB T1A 7G1

HOME: CONT:403-526-4873

BUS: 403-526-4873 CELL:

PAGE 8

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR	YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/ OUT		TAG
	13	KENWORTH T800		1NKDX4EX6DR962894	J62724	800553/800553		179561
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE	
01JAN13 DD			09:16 14JUN25	155-0630	192.00	CHG	30JUN25	
R.O. OPENED		READY		OPTIONS: DLR:M068 ENG:79598047				

10:25 27MAY25 13:30 30JUN25

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
CLEAN UP TOOLS AND AREA							

I** LEFT REAR UPPER COUNTERSHAFT COVER LEAKING TRANSMISSION FLUID
TOIL LEFT REAR UPPER COUNTERSHAFT COVER LEAKING
TRANSMISSION FLUID

	7005	CL		155.00	155.00
	1	4307247	GASKET	19.77	11.27
	1	PC1469-5/32	PUSH TO CONNECT-5/32 90 DEG	11.94	11.94
PARTS:	23.21	LABOR:	155.00	OTHER:	0.00
				TOTAL LINE I:	178.21
800553 7005. CLEAN AREA. REMOVE LEFT UPPER COUNTERSHAFT COVER.					
CLEAN TRANS HOUSING AREA. CLEAN COVER GASKET SURFACE AREA. REINSTALL					
COVER WITH NEW GASKET.					

J** LEFT MIDDLE DRIVE AXLE WHEEL SEAL LEAKING
018-303 LEFT MIDDLE DRIVE AXLE WHEEL SEAL LEAKING

7005 CL		387.50	387.50
1 03-01568 AXLE GSKT	8.46	6.93	6.93
2 10047LUC OIL-GEAR LUC HVOL	27.04	20.68	41.36
2 1LEHC EHCC	0.17	0.17	0.34
1 SW47691 SEAL-WHEEL R DRIVE AXLE HVOL (WH)	48.27	29.54	29.54
1 BWSET430 SET-BEARING 580/572PS	99.20	89.28	89.28
1 BWSET429 SET-BEARING 594A/592APS	117.37	105.63	105.63
1 RK4709E2STD23M REMAN SHOE KIT HVOL	96.31	77.77	77.77
CORE CHARGE C		46.00	46.00
-1 RK4709E2STD23M CORE RETURN	96.31	46.00	-46.00
-1 REBATE TRP WHEEL SEALS	4.00	4.00	-4.00
COUPON: M25APRJUN7580 AUTH: 060625-PEABR			
-1 REBATE TRP REMAN BRAKE SHOE KIT	11.00	11.00	-11.00
COUPON: M25JUN7926 AUTH: 060625-PEABR			
018-305 REPLACE FAILED BEARINGS AND RACES			

7005	CL	232.50	232.50
PARTS:	335.51	LABOR:	620.00
		OTHER:	0.34
		TOTAL LINE J:	955.85
800553 7005. LIFT UP AXLE AND PLACE ON STANDS. REMOVE WHEELS. BACK			
OFF BRAKE AND REMOVE DRUM REMOVE AXLE SHAFT. REMOVE HUB ASSEMBLY AND			

OUT	DESCRIPTION	TOTALS
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE. \$ ALL WARRANTY SUBJECT TO FACTORY ACCEPTANCE.	LABOUR AMOUNT	
	PARTS AMOUNT	
	GAS, OIL, LUBE	
	SUBLET AMOUNT	
	MISC. CHARGES	
SIGNATURE	TOTAL CHARGES	
	LESS INSURANCE	
	G.S.T.	
DATE RELEASED	PLEASE PAY THIS AMOUNT	

GST # R100731918



CALGARY PETERBILT LTD.
11550 44th Street S.E.
Calgary, AB T2Z 4A2
Phone: (403) 235-2550
Fax: (403) 235-1322
Toll Free: 1-800-332-1296

PETERBILT LETHBRIDGE PETERBILT RED DEER
4110 - 18th Avenue North 27 Burnt Lake Crescent
Lethbridge, AB T1H 6N7 Red Deer County, AB T4S 2L4
Phone: (403) 328-0500 Phone: (403) 342-5100
Fax: (403) 328-0225 Fax: (403) 342-5153
Toll Free: 1-888-777-3112 Toll Free: 1-877-348-5100

CUSTOMER COPY

CUSTOMER #:
UNIT# 155

110605



PETERBILT MEDICINE HAT

2250 South Highway Dr SE
Redcliff, AB. T0J 2P0
Tel: 403-526-4460
Fax: 403-525-5299
Toll-Free: 1-844-526-4460

INVOICE

RONCO OILFIELD HAULING LTD.
BOX 338

MEDICINE HAT, AB T1A 7G1

HOME: CONT:403-526-4873

BUS: 403-526-4873 CELL:

PAGE 9

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
	13	KENWORTH T800	1NKDX4EX6DR962894	J62724	800553/800553	179561	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
01JAN13 DD			09:16 14JUN25	155-0630	192.00	CHG	30JUN25
R.O. OPENED		READY	OPTIONS: DLR:M068 ENG:79598047				

10:25 27MAY25 13:30 30JUN25

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

BEARINGS. INSPECT AND FOUND THE INNER BEARING IS DAMAGED AND SHOULD BE REPLACED. REMOVE OIL SOAKED BRAKE SHOES. CLEAN UP AXLE END. INSTALL NEW BRAKE SHOES WITH NEW HARDWARE. REMOVE BEARING RACES FROM HUB. INSTALL NEW BEARING RACES INTO HUB. INSTALL HUB WITH NEW SEAL AND NEW BEARINGS. SETUP BEARING PRELOAD. CLEAN AXLE FLANGE AND REINSTALL AXLE WITH NEW GASKET. FILL HUB OIL. INSTALL BRAKE DRUM. INSTALL WHEELS. SETUP BRAKE. TORQUE WHEELS. CHECK DIFF OIL LEVEL. CHECKS OK. CLEAN UP TOOLS AND AREA.

K** DRIVERS SIDE FRONT DRIVE AXLE DUST SHIELD LOOSE AND HALF IS MISSING
018-316 DRIVERS SIDE FRONT DRIVE AXLE DUST SHIELD
LOOSE AND HALF IS MISSING

7005	C		48.00	48.00
1	325148ETN KIT-DUSTSHIELD	215.96	128.50	128.50
PARTS:	128.50	LABOR:	48.00	OTHER: 0.00
TOTAL LINE K:		176.50		

800553 7005. REMOVE DAMAGED DUST SHIELD. CLEAN UP BOLT HOLES.
INSTALL NEW DUST SHIELD.

L** REAR DRIVE AXLE WISHBONE TORQUE ARM BOLT LOOSE AND BUSHINGS ARE
FAILED

016-511 R&R HEIGHT CONTROL VALVE AND ADJUST RIDE
HEIGHT
7005 CL
7018 CL

1	90549992 V-ROD ASSY	797.92	116.25	116.25
4	335*58* STOVER NUT 5/8	0.46	0.46	1.84
8	422*58 5/8 FLAT WASHER373012	0.29	0.29	2.32
4	H8C58*334LP 5/8 X 3 3/4 GR 8	9.89	9.36	37.44
1	H8C1*6 1 X 6 GR 8 BOLT	12.56	12.56	12.56
2	FW81 FLAT WASHER 1"	1.65	1.65	3.30
1	SLC1 1-8 STOVER LOCK NUT	3.24	3.24	3.24
1	HV9990 VALVE-HEIGHT CONTROL WITH DUMP (WH)			
HVOL		169.28	121.88	121.88

OUT
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE.
\$
ALL WARRANTY SUBJECT TO FACTORY ACCEPTANCE.
SIGNATURE
DATE RELEASED



CALGARY PETERBILT LTD.
11550 44th Street S.E.
Calgary, AB T2Z 4A2
Phone: (403) 235-2550
Fax: (403) 235-1322
Toll Free: 1-800-332-1296

PETERBILT LETHBRIDGE PETERBILT RED DEER
4110 - 18th Avenue North
Lethbridge, AB T1H 6N7
Phone: (403) 328-0500
Fax: (403) 328-0225
Toll Free: 1-888-777-3112

27 Burnt Lake Crescent
Red Deer County, AB T4S 2L4
Phone: (403) 342-5100
Fax: (403) 342-5153
Toll Free: 1-877-348-5100

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
G.S.T.	
PLEASE PAY THIS AMOUNT	

GST # R100731918

CUSTOMER COPY

CUSTOMER #:
UNIT# 155

110605



PETERBILT MEDICINE HAT

2250 South Highway Dr SE
Redcliff, AB. T0J 2P0
Tel: 403-526-4460
Fax: 403-525-5299
Toll-Free: 1-844-526-4460

INVOICE

RONCO OILFIELD HAULING LTD.
BOX 338

MEDICINE HAT, AB T1A 7G1

HOME: CONT:403-526-4873

BUS: 403-526-4873 CELL:

PAGE 10

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
	13	KENWORTH T800	1NKDX4EX6DR962894	J62724	800553/800553	179561	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
01JAN13 DD			09:16 14JUN25	155-0630	192.00	CHG	30JUN25
R.O. OPENED		READY	OPTIONS: DLR:M068 ENG:79598047				

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
1	884	*1469-6B	1469-6B AIR BRAKE	90ELBOW NYLON	5.30	5.30	5.30
1	93600561LP	WASHER-SPACER			15.95	15.10	15.10
BOLT R&R DECK PLATING FOR ACCESS							
	7018	CL				155.00	155.00
016-510 R&R TORQUE ARM							
	7018	CL				387.50	387.50
SEIZED EXTRACTION OF SEIZED MOUNTING BOLTS							
	7018	C				192.00	192.00
PARTS:	961.00	LABOR:	850.75	OTHER:	0.00	TOTAL LINE L:	1811.75

800553

7018 CHANGED OUT AIR RIDE VALVE.(WORN OUT AND LOOSE). SET RIDE HEIGHT. REMOVE DECK PLATING TO ACCESS WORN OUT TORQUE ARM. EVEN WITH DECK PLATE REMOVED IT WAS VERY DIFFICULT TO ACCESS AND ALL BOLTS WERE SEIZED. FINISHED REMOVING REAR DRIVE AXLE WISHBONE TORQUE ARM. HAD TO CUT TORQUE ARM TO ACCESS SEIZED BOLT IN TORQUE ARM. CUT OFF SEIZED BOLT. INSTALLED NEW TORQUE ARM. INSTALLED NEW BOLTS. INSTALLED REMOVED COVER OVER REAR HALF OF FRAME. RUN AND TEST. NO AIR LEAKS AT BACK OF TRUCK.

RECHECK RIDE HEIGHT AFTER ROAD TEST.

M** 04-132 Replace Camshaft (Cat-Cummins)

04-132 04-132 Replace Camshaft (Cat-Cummins)

7005	CL		3100.00	3100.00
1	890*108742	PER L BRAKE CLEAN	11.01	11.01 11.01
1	068*12*50	M12X50MM BOLT	1.07	1.07 1.07
2	402*12	M12 F WASHER	0.24	0.24 0.48
2	221854-483C	ATF HVOL	8.52	8.15 16.30
2	1LEHC	EHCC	0.17	0.17 0.34
2	AC11100	#10 ORING	0.97	0.68 1.36
3	AC10650	#6 ORING	1.01	0.71 2.13
1	R134A	30 LBS FREON	19.76	19.76 19.76
48 257000-990C CHV DELO400XLE SYNBLN 10W30BULK				
(DS) BULK OIL			7.53	6.54 313.92
48 OIL EHCC			0.06	0.06 2.88

OUT		 CALGARY PETERBILT LTD 11550 44th Street S.E. Calgary, AB T2Z 4A2 Phone: (403) 235-2550 Fax: (403) 235-1322 Toll Free: 1-800-332-1296 PETERBILT LETHBRIDGE 4110 - 18th Avenue North Lethbridge, AB T1H 6N7 Phone: (403) 328-0500 Fax: (403) 328-0225 Toll Free: 1-888-777-3112 PETERBILT RED DEER 27 Burnt Lake Crescent Red Deer County, AB T4S 2L4 Phone: (403) 342-5100 Fax: (403) 342-5153 Toll Free: 1-877-348-5100	DESCRIPTION		TOTALS	
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE.			LABOUR AMOUNT			
			PARTS AMOUNT			
\$			GAS, OIL, LUBE			
ALL WARRANTY SUBJECT TO FACTORY ACCEPTANCE.			SUBLET AMOUNT			
			MISC. CHARGES			
SIGNATURE			TOTAL CHARGES			
			LESS INSURANCE			
DATE RELEASED			G.S.T.			
			PLEASE PAY THIS AMOUNT			

GST # R100731918

CUSTOMER COPY

CUSTOMER #:
UNIT# 155

110605



PETERBILT MEDICINE HAT

2250 South Highway Dr SE
Redcliff, AB. T0J 2P0
Tel: 403-526-4460
Fax: 403-525-5299
Toll-Free: 1- 844-526-4460

INVOICE

RONCO OILFIELD HAULING LTD.
BOX 338

MEDICINE HAT, AB T1A 7G1

HOME: CONT:403-526-4873

BUS: 403-526-4873 CELL:

PAGE 11

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
	13	KENWORTH T800	1NKDX4EX6DR962894	J62724	800553/800553	179561	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
01JAN13 DD			09:16 14JUN25	155-0630	192.00	CHG	30JUN25

R.O. OPENED READY OPTIONS: DLR:M068 ENG:79598047

10:25 27MAY25 13:30 30JUN25

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
1	227811-487C	CHEVRON	50/50	MIX HVOL (DS)	19.04	13.69	13.69
-2	5579417PXCUM	CORE	RETURN		2553.71	275.00	-550.00
1	VH11600 (WH)	KIT- O-RING- HVAC	SERVICE- RUBBER/HNB		8.89	6.22	6.22
1	4298629CUM	CAMSHAFT			4327.38	3432.57	3432.57
1	5719778CUM	GASKET, CAMSHAFT	COVER		18.46	15.74	15.74
1	4299125CUM	SEAL - REAR O RING			30.04	25.62	25.62
1	3687007CUM	TIMING GASKET			79.84	68.09	68.09
1	5658175CUM	SEAL			21.29	18.15	18.15
1	4299124CUM	SEAL, ORING			22.74	19.40	19.40
1	LF14000NNFLG	FILTER			115.80	88.01	88.01
					1.25	1.25	1.25
1	3104392CUM	GASKET-VA			116.75	99.57	99.57
-1	REBATE CUMMINS	GENUINE CAMSHAFTS			55.00	55.00	-55.00
COUPON: M25JUN7948 AUTH: 060625-PEABR							
1	3689630CUM	GEAR, IDLER			964.77	807.31	807.31
1	5484229CUM	LEVER, ROCKER			240.42	205.03	205.03
2	5484230CUM	LEVER			264.93	225.94	451.88
1	5484231CUM	LEVER, ROCKER			255.73	218.08	218.08

PARTS: 5230.39 LABOR: 3100.00 OTHER: 4.47 TOTAL LINE M: 8334.86

800553 7005. REMOVE EGR CROSS OVER TUBE. REMOVE VALVE COVER.
INSPECT AND FOUND THE CAMSHAFT AND SOME ROCKERS ARE DAMAGED. DISCONNECT
INJECTOR WIRING HARNESS AND SET ASIDE. REMOVE FUEL HARD LINE ON
CYLINDERS 2 AND 6. REMOVE FUEL SUPPLY TUBE ON CYLINDERS 2 AND 6. REMOVE
INJECTORS 2 AND 6. CLEAN INJECTOR HOLE AND VACUUM OUT CYLINDERS.
INSTALL NEW INJECTORS AND FUEL SUPPLY TUBES. TORQUE TO SPEC AND
PROCEDURE. REINSTALL FUEL HARD LINES AND TORQUE TO SPEC. REMOVE ROCKER
ARM ASSEMBLIES. DRAIN RADIATOR. REMOVE UPPER AND LOWER RAD HOSES.
CONNECT AC MACHINE AND RECOVER REFRIGERANT. REMOVE RAD SUPPORT STRUT
RODS. DISCONNECT COOLANT TANK CONNECTOR. REMOVE TURBO TO CHARGE AIR
COOLER AIR PIPING. REMOVE CHARGE AIR COOLER TO INTAKE AIR PIPING.
DISCONNECT AC LINES. CAP AND PLUG LINES. SETUP OVERHEAD CRANE. REMOVE
LOWER RAD MOUNT NUTS. REMOVE RADIATOR/CHARGE AIR COOLER ASSEMBLY.
REMOVE FAN AND HALO SHROUD. REMOVE DRIVE BELTS. REMOVE FAN HUB. REMOVE

OUT		DESCRIPTION	TOTALS
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE.		LABOUR AMOUNT	
\$	CALGARY PETERBILT LTD. 11550 44th Street S.E. Calgary, AB T2Z 4A2 Phone: (403) 235-2550 Fax: (403) 235-1322 Toll Free: 1-800-332-1296	PARTS AMOUNT	
ALL WARRANTY SUBJECT TO FACTORY ACCEPTANCE.	PETERBILT LETHBRIDGE PETERBILT RED DEER 4110 - 18th Avenue North Lethbridge, AB T1H 6N7 Phone: (403) 328-0500 Fax: (403) 328-0225 Toll Free: 1-888-777-3112	GAS, OIL, LUBE	
SIGNATURE		SUBLET AMOUNT	
DATE RELEASED		MISC. CHARGES	
		TOTAL CHARGES	
		LESS INSURANCE	
		G.S.T.	
		PLEASE PAY THIS AMOUNT	

GST # R100731918

CUSTOMER COPY

CUSTOMER #:
UNIT# 155

110605



PETERBILT MEDICINE HAT

2250 South Highway Dr SE
Redcliff, AB. T0J 2P0
Tel: 403-526-4460
Fax: 403-525-5299
Toll-Free: 1- 844-526-4460

INVOICE

RONCO OILFIELD HAULING LTD.
BOX 338

MEDICINE HAT, AB T1A 7G1

HOME: CONT:403-526-4873

BUS: 403-526-4873 CELL:

PAGE 12

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR	YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/ OUT		TAG
	13	KENWORTH T800		1NKDX4EX6DR962894	J62724	800553/800553		179561
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE	
01JAN13 DD			09:16 14JUN25	155-0630	192.00	CHG	30JUN25	
R.O. OPENED		READY		OPTIONS: DLR:M068 ENG:79598047				

10:25 27MAY25 13:30 30JUN25

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

FRONT TIMING COVER. REMOVE CAM AND CAM IDLER GEAR. REMOVE UPPER IDLER GEAR. REMOVE CAM AND IDLER THRUST PLATES. REMOVE CAMSHAFT. INSPECT AND FOUND WORN BUSHING ON UPPER IDLER GEAR. INSTALL NEW UPPER IDLER GEAR AND TOQUE TO SPEC AND PROCEDURE. CLEAN FRONT OF HEAD AREA. PRELUBE AND INSTALL NEW CAMSHAFT. CLEAN AND INSTALL CAM AND IDLER THRUST PLATES WITH NEW O RING SEALS. INSTALL CAM AND CRANK WEDGE AND PIN TOOLING. CLEAN, PRELUBE AND INSTALL CAM IDLER GEAR AND CAM GEAR. SETUP GEAR LASH. TORQUE CAM AND IDLER GEARS TO SPEC AND PROCEDURE. REMOVE CAM WEDGE AND CRANK TOOLING. CLEAN AND INSTALL FRONT TIMING COVER WITH NEW STRING SEAL. REINSTALL CRANK DAMPER AND CRANK PULLEY. REINSTALL FAN HUB. REINSTALL DRIVE BELTS. REINSTALL FAN HALO SHROUD. SETUP OVERHEAD CRANE AND REINSTALL RADIATOR/CHARGE AIR COOLER ASSEMBLY. RECONNECT UPPER AND LOWER RAD HOSES. REINSTALL AC LINES TO CONDENSER WITH NEW O RINGS. RECHARGE AC SYSTEM, FOUND HIGH SIDE SCHRADER VALVE IS LEAKING. RECOVER REFRIGERANT AND REPLACE SCHRADER VALVE. RECHARGE AC SYSTEM AND RECHECK FOR LEAK, CHECKS OK. RECONNECT POWER STEERING COOLING LINES AND FILL POWER STEERING. REINSTALL HOOD SPRINGS. REINSTALL TURBO TO CHARGE AIR COOLER AIR PIPING. REINSTALL CHARGE AIR COOLER TO INTAKE AIR PIPING. REINSTALL UPPER FRONT HARNESS MOUNTING BRACKET. REPLACE DAMAGED ROCKER ARMS AND INSTALL ROCKER ARM ASSEMBLIES. TORQUE MOUNTING BOLTS TO SPEC AND PROCEDURE. RECONNECT AND INSTALL INJECTOR WIRING HARNESS. PERFORM A OVERHEAD VALVE AND ENGINE BRAKE ADJUSTMENT. REINSTALL VALVE COVER WITH NEW GASKET. REINSTALL EGR CROSS OVER TUBE. VACUUM FILL COOLING SYSTEM. DRAIN ENGINE OIL AND REPLACE FILTER. FILL ENGINE WITH NEW ENGINE OIL. CONNECT COMPUTER AND ENTER INJECTOR TRIM CODES FOR THE NEW INJECTORS IN CYLINDERS 2 AND 6. START AND RUN ENGINE AND CHECK FOR LEAKS AND OPERATION.

N** ASHDOCM Diesel Oxidation Catalyst Cleaning Using FSX Equipment (Med Hat)

ASHDOCM ASHDOCM Diesel Oxidation Catalyst
Cleaning Using FSX Equipment (Med Hat)
9999 C

PARTS: 0.00 LABOR: 150.00 OTHER: 0.00 TOTAL LINE N: 150.00 150.00

OUT	DESCRIPTION	TOTALS
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE.	LABOUR AMOUNT	
	PARTS AMOUNT	
	GAS, OIL, LUBE	
	SUBLET AMOUNT	
	MISC. CHARGES	
	TOTAL CHARGES	
	LESS INSURANCE	
	G.S.T.	
	PLEASE PAY THIS AMOUNT	
\$		
ALL WARRANTY SUBJECT TO FACTORY ACCEPTANCE.		
SIGNATURE		
DATE RELEASED		



CALGARY PETERBILT LTD.

11550 44th Street S.E.
Calgary, AB T2Z 4A2
Phone: (403) 235-2550
Fax: (403) 235-1322
Toll Free: 1-800-332-1296

PETERBILT LETHBRIDGE PETERBILT RED DEER

4110 - 18th Avenue North
Lethbridge, AB T1H 6N7
Phone: (403) 328-0500
Fax: (403) 328-0225
Toll Free: 1-888-777-3112

27 Burnt Lake Crescent
Red Deer County, AB T4S 2L4
Phone: (403) 342-5100
Fax: (403) 342-5153
Toll Free: 1-877-348-5100

GST # R100731918

CUSTOMER COPY

CUSTOMER #:
UNIT# 155

110605



PETERBILT MEDICINE HAT

2250 South Highway Dr SE
Redcliff, AB. T0J 2P0
Tel: 403-526-4460
Fax: 403-525-5299
Toll-Free: 1-844-526-4460

INVOICE

RONCO OILFIELD HAULING LTD.
BOX 338

MEDICINE HAT, AB T1A 7G1

HOME: CONT:403-526-4873

BUS: 403-526-4873 CELL:

PAGE 13

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR	YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/ OUT		TAG
	13	KENWORTH T800		1NKDX4EX6DR962894	J62724	800553/800553		179561
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE	
01JAN13 DD			09:16 14JUN25	155-0630	192.00	CHG	30JUN25	
R.O. OPENED		READY		OPTIONS: DLR:M068 ENG:79598047				

10:25 27MAY25 13:30 30JUN25

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

800553 7001-PUT DOC ON TRAP TESTER AND CHECK RESTRICTION ACROSS
DOC. DOC HAD 1.75 INCHES OF RESTRICTION. PUT DOC IN MACHINE AND CLEAN
FOR 60 MIN. RETEST FOR RESTRICTION AND DOC NOW HAS 1 INCHES OF
RESTRICTION ALL OK TO PUT BACK INTO UNIT

O Moved to: 110605X Line: A

9996 Moved to: 110605X Line: A

7000 C

0.00

0.00

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE O: 0.00

P** 013-407 Diagnose ABS Problem Hook to PC

013-407 DIAG ABS LIGHT ON AND REPLACE FAILED

WHEEL SPEED SENSOR

7005 CL

7018 CL

310.00

310.00

10 0502*550314 WIRE TIE COLD TEMP UV BLK

4.6X371M TIE5

0.20

0.20

2.00

1 4410309092 SENSOR ABS KIT IHJ

170.19

95.30

95.30

RT ROAD TEST FOR DIAGNOSE OR REPAIR VERIFICATION.

7005 CL

77.50

77.50

PARTS: 97.30 LABOR: 387.50 OTHER: 0.00 TOTAL LINE P: 484.80

800553

7005. CONNECT COMPUTER AND CHECK FOR CODES. ACTIVE CODE ADDITIONAL
AXLE OUTPUT LOW AT DRIVE OFF CODE IS PRESENT. CHECK WIRING. CHECKS OK.
REMOVE WHEELS ON LEFT ADDITIONAL AXLE AND CHECK SENSOR. CHECKS OK.
MEASURE SENSOR RESISTANCE. RESISTANCE IS OUT OF RANGE AND SPEC. REPLACE
SENSOR. REINSTALL AND TORQUE WHEELS. CLEAR CODES AND RECHECK. CHECKS
OK.

7018 ROAD TEST. NO FAULTS AFTER ROAD TEST.

*** THE FOLLOWING WORK NOT DONE-TRANSFERRED TO RO#110605X ***

O Moved to: 110605X Line: A

OUT		DESCRIPTION	TOTALS
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE.		LABOUR AMOUNT	
\$	CALGARY PETERBILT LTD 11550 44th Street S.E. Calgary, AB T2Z 4A2 Phone: (403) 235-2550 Fax: (403) 235-1322 Toll Free: 1-800-332-1296	PARTS AMOUNT	
ALL WARRANTY SUBJECT TO FACTORY ACCEPTANCE.	PETERBILT LETHBRIDGE 4110 - 18th Avenue North Lethbridge, AB T1H 6N7 Phone: (403) 328-0500 Fax: (403) 328-0225 Toll Free: 1-888-777-3112	GAS, OIL, LUBE	
SIGNATURE	PETERBILT RED DEER 27 Burnt Lake Crescent Red Deer County, AB T4S 2L4 Phone: (403) 342-5100 Fax: (403) 342-5153 Toll Free: 1-877-348-5100	SUBLET AMOUNT	
DATE RELEASED		MISC. CHARGES	
GST # R100731918		TOTAL CHARGES	
		LESS INSURANCE	
		G.S.T.	
		PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

CUSTOMER #:
UNIT# 155

110605

INVOICE

RONCO OILFIELD HAULING LTD.
BOX 338

MEDICINE HAT, AB T1A 7G1

HOME: CONT:403-526-4873

BUS: 403-526-4873 CELL:

PAGE 14



PETERBILT MEDICINE HAT

2250 South Highway Dr SE

Redcliff, AB. T0J 2P0

Tel: 403-526-4460

Fax: 403-525-5299

Toll-Free: 1-844-526-4460

SERVICE ADVISOR: 94 HEATHER THOMPSON

COLOUR	YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/ OUT		TAG
	13	KENWORTH T800		1NKDX4EX6DR962894	J62724	800553/800553		179561
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE	
01JAN13 DD			09:16 14JUN25	155-0630	192.00	CHG	30JUN25	
R.O. OPENED		READY		OPTIONS: DLR:M068 ENG:79598047				

10:25 27MAY25 13:30 30JUN25

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

ESTIMATE: 0.00 13JUN25 08:10 SA: 94

CONTACT:

ESTIMATE: 40.00 05JUN25 08:45 SA: 94

CONTACT:

ESTIMATE: 0.00 27MAY25 10:25 SA: 94

CONTACT:

THANK YOU FOR YOUR CONTINUED
BUSINESS !!!

** ANY DENIED WARRANTY OR PORTION THEREOF
WILL BE THE RESPONSIBILITY OF THE CUSTOMER **

NOTE: AS A MAINTENANCE REQUIREMENT, CUSTOMERS
MUST RETORQUE ALL WHEEL NUTS 100-150KM AFTER
WHEELS HAVE BEEN REINSTALLED.

GST (#: R100731918)

(#: 100731918RT0001)

1701.28

OUT	DESCRIPTION	TOTALS
I HEREBY ACKNOWLEDGE MY INDEBTEDNESS FOR THIS INVOICE.	LABOUR AMOUNT	9677.50
	PARTS AMOUNT	24343.14
	GAS, OIL, LUBE	0.00
	SUBLET AMOUNT	0.00
	MISC. CHARGES	4.81
	TOTAL CHARGES	34025.45
	LESS INSURANCE	0.00
	G.S.T.	1701.28
	PLEASE PAY THIS AMOUNT	35726.73

GST # R100731918

CUSTOMER COPY