

F02-2
SEP

Mid Plains Diesel Ltd.
1014 - 8 Avenue West
Box 1123
Kindersley, SK S0L 1S0, CA
ar@midplainsdiesel.ca
(306) 463-6469



Invoice: 1046294
Date: 11/14/2024

Bill To
TKC Trucking
Box 2337
Kindersley, SK S0L 1S0, CA
P:

Remit Payment To
Primary
1014 - 8 Avenue West
Box 1123
Kindersley, SK S0L 1S0, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Unit #
4792	Net 30	12/14/2024		TT061	TT061

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

Complaint: Heat isnt working

Cause: Heat isnt working

Labor	Correction: Chassis / Chassis / Let truck warm up and found no circulation through heater core. Tested valve and and it was moving externally but had no flow through it. Removed valve and found rubber seal swelled all the way shut. Changed valve and tested. Functioned properly so parked it in their yard. - Completed: 11/8/2024	1.75000	\$169.00	\$295.75
Parts	Water Valve - SR2000013	1.00000	\$306.93	\$306.93
Parts	Brass Connector 3/8" Push Connect Tube x 1/4" NPT - PC1468-6B	3.00000	\$9.00	\$27.00
Parts	Hex Head Cap Screw 1/2-13 x 2-1/2 UNC GR8 - MP39110	2.00000	\$1.91	\$3.82
Parts	Lock Washer 1/2 GR8 - 39729	2.00000	\$0.22	\$0.44

Unit: TT061 **VIN:** 1NKCL40X87R998170
2007 Kenworth C500
Chassis: 850,585 Kilometres
Engine: 22,404 Hours

Shop Supplies	\$17.75
Pre-Charge Subtotal	\$651.69
GST (5% of \$651.69)	\$32.58
Total	\$684.27
Payments & Credits	\$0.00
Balance Due	\$684.27

This is the only itemized account rendered. This company does not assume any responsibility whatever for vehicles or equipment left for repairs, storage or other purposes or for articles left in same. Vehicles driven by our employees at owners risk. 2% per month/24% per annum on all past due accounts. Accounts due upon receipt. PST exemption must be provided at the time of sale. Price shown does not prejudice the company's right to charge tax at a future date if assessed by the taxing authorities.

Mid Plains Diesel Ltd.

1014 - 8 Avenue West
Box 1123
Kindersley, SK S0L 1S0, CA
ar@midplainsdiesel.ca
(306) 463-6469

Invoice: 1046160

Date: 10/31/2024

Bill To
TKC Trucking
Box 2337
Kindersley, SK S0L 1S0, CA
P:

Remit Payment To
Primary
1014 - 8 Avenue West
Box 1123
Kindersley, SK S0L 1S0, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Unit #
4756	Net 30	11/30/2024		TT061	TT061

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

Complaint: No Start - Cranks but will not fire

Cause: No Start - Cranks but will not fire

Labor	Correction: Chassis / Chassis / Went outside to work on truck, key switch was left in the on position and batteries were completely dead. Strung out extension cords and battery charger. Left batteries to charge all morning and went onto other jobs. Went back outside work on truck. Brought out lap top. Checked to see first if ECM was powered up, ECM is powered up. Checked engine codes. Has code for low fuel rail pressure. Used data monitor to check fuel pressure while cranking, fuel pressure does not go above 0. Checked cam sensor while cranking and engine rpm, sensors read proper. Listened to electric fuel pump to see if it is running after turning key on, no noise at all from pump. Disconnected electrical connector, checked resistance at pump as well as power and ground on connector, power and ground test good with multi meter and pump resistance is good. Hooked up jumper wire from positive battery cable and ground directly to pump, pump runs now. Let pump run for a while to prime fuel system then started engine. Brought truck inside. Load tested fuel pump wires in engine harness. Ground side tests good. Power side no good. Load tested power at fuel pump fuse and relay, still not good. load tested power connector near ECM plug, has proper power and ground there. Retested at fuse holder and it tests good now. Corroded connectors at fuse was the problem. Replaced fuse and retested. Fuel pump runs now and engine starts good now. Fuel pump sounds like it is about to fail, recommend replacing pump soon as well as check valve above fuel pump. Engine has a fuel drain back issue or else it would be able to start without the electric lift pump. - Completed: 10/31/2024	4.00000	\$169.00	\$676.00
Parts	Locking Hex Nut - 4985492	1.00000	\$19.52	\$19.52

Mid Plains Diesel Ltd.

1014 - 8 Avenue West
Box 1123
Kindersley, SK S0L 1S0, CA
ar@midplainsdiesel.ca
(306) 463-6469



Invoice: 1043132

Date: 7/30/2024

Bill To
TKC Trucking
Box 2337
Kindersley, SK S0L 1S0, CA
P:

Remit Payment To
Primary
1014 - 8 Avenue West
Box 1123
Kindersley, SK S0L 1S0, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Unit #
4418	Net 30	8/29/2024		061	TT061

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

Complaint: Check for contamination in coolant, possibly oil

Cause: Customer request

(Inspection)

Labor	Correction: Chassis / Chassis / Truck was leaking diesel from fuel filter, changed filter. Drain coolant, remove air intake pipe, air to air pipe, turbo, EGR and oil cooler, Disassemble oil cooler, clean and reassemble with new gasket kit, install cooler, EGR, turbo, air to air pipe and air intake, new engine oil filter, fill coolant system with water, run up to temp and drain, fill with water again, run up to temp and add coolant flush and run for ten mins, drain coolant system, fill with water again and run up temp and drain, fill with coolant, install coolant filter, run truck and check for leaks - Completed: 7/22/2024	22.50000	\$169.00	\$3,802.50
Parts	Oil Cooler Core Gasket - 4973532CUM	6.00000	\$18.99	\$113.94
Parts	Gasket Set - 4955592CUM	1.00000	\$150.42	\$150.42
Parts	O Ring Seal - 3089025	1.00000	\$26.48	\$26.48
Parts	Thermostat - 4952629	1.00000	\$242.82	\$242.82
Parts	Screw 12 Point - 4101867	4.00000	\$16.23	\$64.92
Parts	Screw 12 Point - 4101868	4.00000	\$19.70	\$78.80
Parts	Seal O-Ring - 109080	2.00000	\$5.19	\$10.38
Parts	Turbo Gasket - 3102314	1.00000	\$35.19	\$35.19
Parts	Oil Filter - LF14000NN	1.00000	\$68.03	\$68.03
Parts	Water Filter - WF2127	1.00000	\$50.95	\$50.95
Parts	Fuel Filter - ISX - FF2200	1.00000	\$34.60	\$34.60
Parts	O-Ring - 3682076CUM	2.00000	\$3.87	\$7.74
Parts	O-Ring - 6V5048	2.00000	\$10.76	\$21.52
Parts	O Ring - 8L-2777	1.00000	\$9.95	\$9.95

Item	Description	Quantity	Rate	Amount
Parts	Flange Gasket - 3101268	1.00000	\$12.29	\$12.29
Parts	Flex Pipe 4 Inch Heavy Wall - 40011	1.00000	\$19.06	\$19.06
Parts	Lap Clamp 4' - TTA400	2.00000	\$16.88	\$33.76
Parts	Rad Flush - 911216	1.00000	\$22.92	\$22.92
Parts	Hex Head Cap Screw 1/2-13 x 1-3/4 UNC GR8 - MP39107	1.00000	\$1.38	\$1.38
Parts	Antifreeze 50/50 4L - AEAFFZ0010	13.00000	\$14.19	\$184.47
Parts	Extended Life Antifreeze 4 L - AEAFFZ0011	2.00000	\$25.26	\$50.52
Freight		1.00	\$68.00	\$68.00

Unit: TT061 VIN: 1NKCL40X87R998170
 2007 Kenworth C500
 Chassis: 0 Kilometres
 Engine: 0 Hours

Shop Supplies \$232.23
 Pre-Charge Subtotal \$5,274.87
 Freight \$68.00
 GST
 (5% of \$5,342.87) \$267.14
 Total \$5,610.01
 Payments & Credits \$0.00
 Balance Due \$5,610.01

ENTERED

This is the only itemized account rendered. This company does not assume any responsibility whatever for vehicles or equipment left for repairs, storage or other purposes or for articles left in same. Vehicles driven by our employees at owners risk. 2% per month/24% per annum on all past due accounts. Accounts due upon receipt. PST exemption must be provided at the time of sale. Price shown does not prejudice the company's right to charge tax at a future date if assessed by the taxing authorities. Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. Cores must be returned within 3 months of date of purchase or credit will not be issued. GST#124535048RP001

Customer Signature: _____

Printed Name: _____ Date: _____

Big Sky Steel Fabricators (2002) Ltd.

Box 1705
Kindersley, Saskatchewan S0L 1S0
Canada

INVOICE

Invoice No.: 68601
Date: Jun 30, 2022
Ship Date:
Page: 1
Re: Order No.

Sold to:

TKC TRUCKING
Box 2337
Kindersley, SK S0L 1S1

Ship to:

TKC TRUCKING
Box 2337
Kindersley, SK S0L 1S1

Business No.: 862087087RC0001

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
			UNIT# TT061			
			REPLACE RECT TUBING PERIMETER			
			ON TRUCK AND FAB TOOL BOXES			
	HRS	27.5	LABOUR	GP	110.00	3,025.00
	FT	20.0	2" X 4" X .125" RECT TUBE	GP	11.64	232.80
	FT	6.0	2" X 1/4" FLAT IRON	GP	3.40	20.40
	FT	5.0	1" X 1" X 1/8" ANGLE IRON	GP	1.44	7.20
	FT	1.0	5/8" CR SQUARE	GP	6.38	6.38
	SQ FT	10.0	12 GA	GP	8.86	88.60
	SQ FT	6.0	3/4" X 9GA FLAT EXPANDED METAL	GP	7.00	42.00
		6.0	4" WELD ON GREASABLE HINGES	GP	18.76	112.56
			Subtotal:			3,534.94
			GP - GST 5.00%, PST 0.00%			
			GST			176.75
			PST Exempt: #CABCARD AB-7729-1			
Shipped By: Tracking Number:				Total Amount		3,711.69
Comment:				Amount Paid		0.00
Sold By:				Amount Owing		3,711.69



Torque & Throttle 44 Mechanics Ltd.
 PO Box 1181
 Warman SK S0K 4S0
 tnt44@sasktel.net
 GST/HST Registration No.:
 760794545RC0001

Invoice 0174

BILL TO

TKC Trucking & Picker Service
 Ltd
 1019 9 Ave W, Kindersley, SK
 S0L 1S0

DATE
 20/06/2022

PLEASE PAY
\$4,172.87

DUE DATE
 20/07/2022

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
7/06/2022	Labour	Condition 1: Check & Repair unit throttle kicking in & out.	4	110.00	440.00
		Correction: Took unit for test drive found throttle pedal to respond then not respond. Hooked up diagnostic tool found code 187. Trouble shoot code found exhaust gas pressure sensor faulty. R&R sensor. Cleared codes, test drove unit, all good.			
	Sensor Pressure Exhaust Gas	4928594CUM	1	207.44	207.44
	Labour	Condition 2: Check & Repair drivers muffler split on bottom.	3	110.00	330.00
		Correction: R&I exhaust stack. R&R muffler. R&R upper stack bushing & pin.			
	Parts	EMM10682TRP - Muffler	1	116.58	116.58
	Parts	M13-1011 - Bushing Exhaust	1	31.53	31.53
	Parts	HWC04847 - Bolt Hex Locking	1	24.22	24.22
	Parts	M05-1003 - Shaft Exhaust	1	49.16	49.16
	Exhaust Stainless Steel Step Clamp 5"	X007785	1	15.31	15.31

We appreciate your business and look forward to helping you again soon.

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
	Labour	Condition 3: Check & Repair drivers window n/w.	3	110.00	330.00
		Correction: R&R drivers door panel, checked power at switch, all good. Checked power at window regulator, all good. Faulty window regulator. R&R window regulator.			
	Parts	WNR011000L - Window Regulator	1	204.98	204.98
	Parts	S67-1014 - Map Plug	1	14.32	14.32
	Labour	Condition 4: Check & repair drivers seat torn.	3	110.00	330.00
		Correction; R&R seat. Installed seat cover.			
	Parts	188900MW65 - Seat legacy silver	1	1,025.77	1,025.77
	Parts	181704XN1165 - Coveralls high back	1	72.24	72.24
	Labour	Condition 5: Check & Repair fuel tank caps leaking.	0.30	110.00	33.00
		Correction: R&R both fuel tank cap seals.			
	Labour	Labour adjustment	0.30	-110.00	-33.00
	Parts	12105GTD - Gasket	2	17.95	35.90
	Labour	Supplied customer with parts	1	0.00	0.00
	Parts	U12-6002-006 - Mattress	1	629.66	629.66
	Consumables				117.04

PO#:	SUBTOTAL	3,974.15
Unit#: TT061	GST @ 5%	198.72
License#: A30466	TOTAL	4,172.87
Vin#: 998170		
Year/Make/Model: 2007 Kenworth C-500B	TOTAL DUE	\$4,172.87
KMs: 733,076		
HRs: 19,564		
Engine: Cummins CM870		
ESN#: 79191126		
PST Exempt #: AB7729-1		

THANK YOU.

AX SUMMARY

RATE	TAX	NET
GST @ 5%	198.72	3,974.15

We appreciate your business and look forward to helping you again soon.