



KEN SARGENT
GMC BUICK

H02-8
SEP

12308 100 Street, Grande Prairie, AB T8V 4H7

Phone: (780) 532-8865 | Fax: (780) 539-7510 | Toll Free: (888) 532-8865

Parts Direct Line: (780) 539-3745 | Parts Fax: (780) 830-4220

Service Direct Line: (780) 830-4200

SMALL TRUCK

INVOICE

SERVICE ORDER

CUSTOMER COPY

UNIT #623



SO # S114291

Status

Printed 02/25/2026 10:28:47 AM

User KendraH Page 1

Customer No

Brothers HDD
2002 23 Ave
Wainwright, AB T9W 0B8

Home (780) 214-7771 Bus
Cell Today
Email

Type
Term Cash

Advisor Kendra Hare
Shop S1

Promised 02/24/2026 5:00 PM
Opened 02/23/2026 9:50 AM
Cashiered

Tag# 7784
Location
PO #

License	Odom In	Odom Out	In Service Date	Stock No
	175994	175996		
Year	Make	Model	Model Number	Colour
2022	CHEVROLET	SILVERADO 3500HD	CK30943	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1GC4YTEYXNF229591				
Engine	DURAMAX 6.6L TURBO-DIESEL V8, Fleet # Unit# 623			

Request	Description	Job	CSR	Severity	Status
MISC	Customer concern of service engine lamp is on, please advise	1	0442	Low	Original
Labour	Description				Amount
MISC	Customer concern of service engine lamp is on, stumbles at times while driving				105.00
Rate	210.00				Est Parts 0.00
Cause	Scanned for codes, P2635 Fuel Pump Flow Performance set current. Inspected fuel pump command, reading at 7000RPM.				Est Labour 0.00
Correction	Quoted				Labour Total 105.00
					Request Sub-total 105.00

Request	Description	Job	CSR	Severity	Status
DIAG	Customer concerned the emissions system message is on, please advise	2	0442	Low	Original
Labour	Description				Amount
DIAG	Customer concerned the emissions system message is on, please advise				0.00
Rate	210.00				Est Parts 0.00
Cause	May be related to case 1				Est Labour 0.00
Correction	Will require to replace fuel pump first and diagnose other light if needed.				

Request	Description	Job	CSR	Severity	Status
DIAG	Customer concerned the vehicle is stumbling while driving, almost like the brakes ae stuck on, please advise	3	0442	Low	Original
Labour	Description				Amount
DIAG	Customer concerned the vehicle is stumbling while driving, almost like the brakes ae stuck on, please advise				0.00
Rate	210.00				Est Parts 0.00
Cause	May be related to case 6				Est Labour 0.00
Correction	Will require to repair harness and sensor to perform further diagnosis if needed.				

Request	Description	Job	CSR	Severity	Status				
RECALL	N232426400 - Tailgate May Open Unexpectedly	4	0442	Low	Original				
Labour	Description				Amount				
RECALL	N232426400 - Tailgate May Open Unexpectedly								
Part	Description	Shp	OH	AOH	SL	Bin	Retail	Price	Amount
85877553	SWITCH	1	51	44		050FLR			
Cause	Tailgate May Open Unexpectedly					Est Parts			0.00
Correction	Removed and replaced main tailgate switch. Verified operation.					Est Labour			0.00

Request	Description	Job	CSR	Severity	Status
RECALL	N222371151 - Heated Steering Wheel Retrofit - Steering Wheel Replacement Only - Expires January 31, 2027	5	0442	Low	Original

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that to the extent permitted by law, you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets highways or elsewhere for the purpose of testing and/or inspection. Until payment in full of the within account. I hereby acknowledge the existence of a repair lien in favor of the within dealer on the vehicle described herein in respect of the material supplied and services rendered under this work order for the full amount charged therefor I further acknowledge that the said lien shall continue in force at all times, whether the vehicle is in my possession or possession of the dealer, until the within account is paid in full. While the vehicle is in my possession it shas at all times be subject to repossession on demand by the dealer until the within account is paid in full

Date: _____

Signature: _____



KEN SARGENT
GMC BUICK

12308 100 Street, Grande Prairie, AB T8V 4H7
Phone: (780) 532-8865 | Fax: (780) 539-7510 | Toll Free: (888) 532-8865
Parts Direct Line: (780) 539-3745 | Parts Fax: (780) 830-4220
Service Direct Line: (780) 830-4200

SO # S114291

Status
Printed 02/25/2026 10:28:48 AM

**SERVICE ORDER
CUSTOMER COPY**

User KendraH Page 2



Customer No

Brothers HDD
2002 23 Ave
Wainwright, AB T9W 0B8

Home (780) 214-7771 Bus
Cell Today
Email

Type
Term Cash

Advisor Kendra Hare Promised 02/24/2026 5:00 PM Tag# 7784
Shop S1 Opened 02/23/2026 9:50 AM Location
Cashiered PO #

License	Odom In	Odom Out	In Service Date	Stock No
	175994	175996		
Year	Make	Model	Model Number	Colour
2022	CHEVROLET	SILVERADO 3500HD	CK30943	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1GC4YTEYXNF229591				
Engine	DURAMAX 6.6L TURBO-DIESEL V8,	Fleet #	Unit# 623	

Labour	Description								Amount
RECALL	N222371151 - Heated Steering Wheel Retrofit – Steering Wheel Replacement Only - Expires January 31, 2027								
Part	Description	Shp	OH	AOH	SL	BIn	Retail	Price	Amount
84946341	WHEEL	1	0	0		M16WAL			
Cause	Steering wheel retrofit					Est Parts			0.00
Correction	Removed and replaced steering wheel per si bulletin. Torqued fasteners to specs. Verified operation of steering wheel controls.					Est Labour			0.00

Request	Description	Job	CSR	Severity	Status
DIAG	Customer concerned the service brake pad message is on, please advise	6	0442	Low	Approved
Labour	Description				Amount
DIAG	Customer concerned the service brake pad message is on, please advise				63.00
Rate	210.00	Est Parts			0.00
Cause	Scanned for codes C116B Rear brake pad sensor wear signal circuit set current.	Est Labour			0.00
	Removed LR brake sensor and inspected, terminals are broken/corroded on male and female sides. Will require new sensor and harness	Labour Total			63.00
		Request Sub-total			63.00
Correction	Quoted				

780-897-6427 dan
noticed during drop off the service brake pad message is on

Labour	168.00
Parts	0.00
Fees	0.00
Supplies	22.18
Sub-Total	190.18
GST	9.51
Total Invoice	199.69

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that to the extent permitted by law, you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets highways or elsewhere for the purpose of testing and/or inspection. Until payment in full of the within account. I hereby acknowledge the existence of a repair lien in favor of the within dealer on the vehicle described herein in respect of the material supplied and services rendered under this work order for the full amount charged therefor I further acknowledge that the said lien shall continue in force at all times, whether the vehicle is in my possession or possession of the dealer, until the within account is paid in full. While the vehicle is in my possession it shall at all times be subject to repossession on demand by the dealer until the within account is paid in full

Date: _____ Signature: _____