

D40-55
Aug

CUSTOMER #:

260790

CUSTOMER CALLED

INVOICE

PAGE 1

CHRYSLER

LEDUC CHRYSLER JEEP



6102 46A Street
Leduc, Alberta T9E 7A7
Telephone (780) 986-2051
Facsimile (780) 986-1486
Toll Free 1-800-355-8933
service@leducchrysler.com
www.leducchrysler.com

HOME:
BUS:

CONT:
CELL:

SERVICE ADVISOR: 135 CHUCK

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
	09	JEEP LIBERTY	1J8GN58K69W509001		125579/125588	T131	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
26JUN09 DD			16:30 15MAR24		0.00	CHG	21MAR24
R.O. OPENED		READY	OPTIONS: DLR:C3834 ENG:3.7_Liter_MPI				

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A INSPECT FOR CLIENT REPORTS OF STRONG SMELL OF COOLANT IN CAB OF VEHICLE AND FLOOR UNDER GLOVE BOX SOAKED WITH WHAT APPEARS TO BE ANTI FREEZE. PLS ADVISE. HEATER CORE REPLACED ON RO#249342

24 INSPECT FOR CLIENT REPORTS OF STRONG SMELL OF COOLANT IN CAB OF VEHICLE AND FLOOR UNDER GLOVE BOX SOAKED WITH WHAT APPEARS TO BE ANTI FREEZE. PLS ADVISE. HEATER CORE REPLACED ON RO#249342

9238 WEIR, EVAN LIC#: 9238

C

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

125579 found heater core leaking will need to replace and retest

B QUOTE TO INSTALL DRIVERS REAR DOOR LOCK ACTUATOR

08 QUOTE TO INSTALL DRIVERS REAR DOOR LOCK ACTUATOR

9238 WEIR, EVAN LIC#: 9238

C

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

125579 quoted

C** heater core replace, 1 heater core, 1 coolant

REP heater core replace, 1 heater core, 1 coolant

9238 WEIR, EVAN LIC#: 9238

C

1 VU01524AC \$COOLANT-ANTIFREEZE 22.44 22.44 22.44

1 68003993AA CORE-HEATER 394.80 394.80 394.80

1 68004022AA HOUSING-DISTRIBUTION 502.00 451.80 451.80

PARTS: 869.04 LABOR: 1690.00 OTHER: 0.00 TOTAL LINE C: 2559.04

125588 10.00 replaced leaking heater core found heater housing melted wile apart replace heater housing and heater core. reassembled then verified heat is good (NOTE BEFORE REPAIR WAS COMPLETED AIR BAG AND TIRE LIGHT ON ALSO FOUND HEADLINER DIRTY AND SUNROOF WHISTLES)

AT YOUR SERVICE MON TO FRI: 7:30 AM TO 5:30 PM	O U T	INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. NO WARRANTY ON AFTERMARKET PARTS INSTALLED	DESCRIPTION	TOTALS
			LABOUR AMOUNT	
THANK YOU FOR ALLOWING US TO SERVICE YOUR VEHICLE		SIGNATURE _____ DATE _____	PARTS AMOUNT	
			GAS, OIL, LUBE	
			SUBLET AMOUNT	
			MISC. CHARGES	
			TOTAL CHARGES	
			LESS INSURANCE	
		CUSTOMER SIGNATURE X	SALES TAX	
			PLEASE PAY THIS AMOUNT	

CUSTOMER #:

260790

INVOICE

PAGE 2

CHRYSLER

LEDUC CHRYSLER JEEP

6102 46A Street
 Leduc, Alberta T9E 7A7
 Telephone (780) 986-2051
 Facsimile (780) 986-1486
 Toll Free 1-800-355-8933
 service@leduchrysler.com
 www.leduchrysler.com

HOME:

CONT:

BUS:

CELL:

SERVICE ADVISOR: 135 CHUCK

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
	09	JEEP LIBERTY	1J8GN58K69W509001		125579/125588	T131	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
26JUN09 DL			16:30 15MAR24		0.00	CHG	21MAR24
R.O. OPENED		READY	OPTIONS: DLR:C3834 ENG:3.7 Liter MPI				

17:17 06MAR24 15:48 21MAR24

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

D** drivers rear lock actuator install (SUPPLIED/DIAGED BY CUSTOMER

REP drivers rear lock actuator install

(SUPPLIED/DIAGED BY CUSTOMER

9238 WEIR, EVAN LIC#: 9238

C

338.00 338.00

PARTS: 0.00 LABOR: 338.00 OTHER: 0.00 TOTAL LINE D: 338.00

125588 2.00 replace drivers rear door lock.

VIP VIP discount

C

-579.41 -579.41

ESTIMATE: 3,706.24 11MAR24 10:41 SA: 135

CONTACT:

Shop supplies

95.00

****CAUTION!**** Failure to perform required maintenance items may result in damage to your vehicle and could VOID the warranty coverage. Please refer to your OWNERS MANUAL maintenance schedules.
 After ANY repair involving the removal of tires, re-torque wheel nuts within 100 km

CUSTOMER GST

(#: R103027447)

120.63

AT YOUR SERVICE MON TO FRI: 7:30 AM TO 5:30 PM THANK YOU FOR ALLOWING US TO SERVICE YOUR VEHICLE	O U T	INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$	DESCRIPTION	TOTALS
		BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. NO WARRANTY ON AFTERMARKET PARTS INSTALLED	LABOUR AMOUNT	2028.00
SIGNATURE	DATE	CUSTOMER SIGNATURE X	PARTS AMOUNT	869.04
			GAS, OIL, LUBE	0.00
			SUBLET AMOUNT	0.00
			MISC. CHARGES	95.00
			TOTAL CHARGES	2992.04
			LESS INSURANCE	579.41
PLEASE PAY THIS AMOUNT			SALES TAX	120.63
				2533.26

G.S.T. REG. NO.: R103027447 "Your No Hassles, No Nonsense Dealer"

CUSTOMER COPY

CUSTOMER #:

255779

INVOICE

PAGE 1

CHRYSLER

LEDUC CHRYSLER JEEP

6102 46A Street

Leduc, Alberta T9E 7A7

Telephone (780) 986-2051

Facsimile (780) 986-1486

Toll Free 1-800-355-8933

service@leduchrysler.com

www.leduchrysler.com

HOME:

CONT:

BUS:

CELL:

SERVICE ADVISOR: 260 DAWN

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
	09	JEEP LIBERTY	1J8GN58K69W509001		118244/118244	T7116	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY / ACQUIT. DATE	PAYMENT	INV. DATE
26JUN09 DD			16:30 15AUG23		0.00	CHG	16AUG23

R.O. OPENED READY OPTIONS: DLR:C3834 ENG:3.7_Liter_MPI

07:39 15AUG23 08:42 16AUG23

LINE OPCODE TECH TYPE HOURS LIST NET TOTAL

A NO HEAT AGAIN - RECENT WORK ON PREV RO IN DECEMBER - TECH 194 - DIAG
& ADVISE24 NO HEAT AGAIN - RECENT WORK ON PREV RO IN
DECEMBER - TECH 194 - DIAG & ADVISE

194 KEEGAN LIC#: 194

C

159.50 159.50

PARTS: 0.00 LABOR: 159.50 OTHER: 0.00 TOTAL LINE A: 159.50

118244 1.00 Road tested vehicle and got up to operating temp and set the HVAC to full hot. Found the heat was poor. Inspected for coolant leaks and found none at this time. Found the wrong coolant is in the system and found there is sediment build up in the radiator. Suspect the wrong coolant type is causing sediment build up. Suspect the heater core is filled with sediment now causing poor heat. Recommend removing the plugs on the side of the block and flushing the system to try and remove all the sediment and then re fill with proper coolant. Recommend back flushing the heater core as well.

B** Recommend removing plugs on side of block and flushing the entire cooling system to remove sediment

CS001 Recommend removing plugs on side of block
and flushing the entire cooling system to
remove sediment

194 KEEGAN LIC#: 194

C

450.00 450.00

1 VU01524AC \$COOLANT-ANTIFREEZE

21.51 21.51 21.51

PARTS: 21.51 LABOR: 450.00 OTHER: 0.00 TOTAL LINE B: 471.51

118244 3.00 Removed the heater hoses from the heater core and flushed the heater core out with water and air. Filled the heater core with CLR and let sit over night to break up any debris in the heater core. Lifted vehicle on hoist and removed the coolant plugs on the sides of the engine block. Flushed water through the entire cooling system for over an hour. Found lots of rust and sand like material to come out of the engine. Flushed until no more debris is coming out and then re installed the plugs into the block. Flushed out the CLR and

AT YOUR SERVICE		INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE		DESCRIPTION	TOTALS
MON TO FRI: 7:30 AM TO 5:30 PM		SUM OF \$		LABOUR AMOUNT	
		BEING ALL OR THE BALANCE OWING FOR REPAIRS,		PARTS AMOUNT	
		PARTS & ACCESSORIES DESCRIBED IN THIS		GAS, OIL, LUBE	
		INVOICE. NO WARRANTY ON AFTERMARKET		SUBLET AMOUNT	
		PARTS INSTALLED		MISC. CHARGES	
				TOTAL CHARGES	
				LESS INSURANCE	
				SALES TAX	
				PLEASE PAY THIS AMOUNT	

THANK YOU
FOR ALLOWING US TO
SERVICE YOUR VEHICLE

SIGNATURE

DATE

CUSTOMER SIGNATURE

X

G.S.T. REG. NO.: R103027447 "Your No Hassles, No Nonsense Dealer"
CUSTOMER COPY

CUSTOMER #:

255779

INVOICE

PAGE 2

CHRYSLER

LEDUC CHRYSLER JEEP

6102 46A Street

Leduc, Alberta T9E 7A7

Telephone (780) 986-2051

Facsimile (780) 986-1486

Toll Free 1-800-355-8933

service@leducchrysler.com

www.leducchrysler.com

HOME:

CONT:

BUS:

CELL:

SERVICE ADVISOR: 260 DAWN

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
	09	JEEP LIBERTY	1J8GN58K69W509001		118244/118244	T7116	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
26JUN09 DD			16:30 15AUG23		0.00	CHG	16AUG23
R.O. OPENED		READY	OPTIONS: DLR:C3834 ENG:3.7_Liter_MPI				
07:39 15AUG23		08:42 16AUG23					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

filled and bled the cooling system with proper coolant. Found the vehicle now blows good heat evenly through all vents. All okay now

VIP VIP discount

C

-126.20 -126.20

ESTIMATE: 521.52

15AUG23 11:07 SA: 260

CONTACT:

Shop supplies

53.63

****CAUTION!**** Failure to perform required maintenance items may result in damage to your vehicle and could VOID the warranty coverage. Please refer to your OWNERS MANUAL maintenance schedules.

After ANY repair involving the removal of tires, re-torque wheel nuts within 100 km

CUSTOMER GST

(#: R103027447)

27.92

AT YOUR SERVICE MON TO FRI: 7:30 AM TO 5:30 PM	O U T	INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. NO WARRANTY ON AFTERMARKET PARTS INSTALLED	DESCRIPTION	TOTALS
			LABOUR AMOUNT	609.50
THANK YOU FOR ALLOWING US TO SERVICE YOUR VEHICLE		SIGNATURE _____ DATE _____ CUSTOMER SIGNATURE X	PARTS AMOUNT	21.51
			GAS, OIL, LUBE	0.00
			SUBLET AMOUNT	0.00
			MISC. CHARGES	53.63
			TOTAL CHARGES	684.64
			LESS INSURANCE	126.20
			SALES TAX	27.92
			PLEASE PAY THIS AMOUNT	586.36

G.S.T. REG. NO.: R103027447 "Your No Hassles, No Nonsense Dealer"
 CUSTOMER COPY

CUSTOMER #:

CUSTOMER CALLED

249342

INVOICE

PAGE 1



LEDUC CHRYSLER JEEP

6102 46A Street

Leduc, Alberta T9E 7A7

Telephone (780) 986-2051

Facsimile (780) 986-1486

Toll Free 1-800-355-8933

service@leducchrysler.com

www.leducchrysler.com



DODGE

HOME:

CONT:

BUS:

CELL:

SERVICE ADVISOR: 135 CHUCK

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
	09	JEEP LIBERTY	1J8GN58K69W509001		100701/100719	T3005	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
26JUN09 DD			16:00 09DEC22		0.00	CHG	13DEC22
R.O. OPENED		READY	OPTIONS: DLR:C3834 ENG:3.7 Liter MPI				

09:01 07DEC22 14:25 13DEC22

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A Inspect for no heat in cab of vehicle. Temp gauge reads good.

Sometimes will make heat when shop. Flushed heater core.

Replaced rad, water pump thermostat. Blower fan blowing at all speeds. Filters changed. StArts blowing cold air as soon as start driving vehicle. Ac would kick on so client disconnected. Pls advise

24 Inspect for no heat in cab of vehicle. Temp gauge reads good. Sometimes will make heat when shop. Flushed heater core. Replaced rad, water pump thermostat. Blower fan blowing at all speeds. Filters changed. StArts blowing cold air as soon as start driving vehicle. Ac would kick on so client disconnected. Pls advise

194 KEEGAN LIC#: 194

C

149.50 149.50

PARTS: 0.00 LABOR: 149.50 OTHER: 0.00 TOTAL LINE A: 149.50

100701 1.00 Road tested vehicle to get up to operating temperature. Found vehicle to get to operating temp and maintain operating temp. Found there to be no heat coming from the vents. Checked for codes and found no related codes. Performed an HVAC actuator calibration test and found all actuators to pass testing. Inspected for coolant leaks and found none. Inspected the serp belt for proper installation and found okay. Vacuum bled the cooling system and re tested. Found there to be a miniscule amount of heat now. Found the hose going into the heater core is hot and the return line is luke warm. Found the heater core is plugged. Recommend replacing the heater core.

B INSPECT FOR NO SUNROOF OPERATION. PLS ADVISE

08 INSPECT FOR NO SUNROOF OPERATION. PLS ADVISE

194 KEEGAN LIC#: 194

C

149.50 149.50

PARTS: 0.00 LABOR: 149.50 OTHER: 0.00 TOTAL LINE B: 149.50

100701 1.00 Found the sunroof does not operate from the switch.

100701 1-800-1-	
---	--

G.S.T. REG. NO.: R103027447 "Your No Hassles, No Nonsense Dealer"
 CUSTOMER COPY

CUSTOMER #:

249342

INVOICE



LEDUC CHRYSLER JEEP

6102 46A Street

Leduc, Alberta T9E 7A7

Telephone (780) 986-2051

Facsimile (780) 986-1486

Toll Free 1-800-355-8933

service@leducchrysler.com

www.leducchrysler.com



PAGE 2

HOME:

CONT:

BUS:

CELL:

SERVICE ADVISOR: 135 CHUCK

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT		TAG
	09	JEEP LIBERTY	1J8GN58K69W509001		100701/100719		T3005
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
26JUN09 DI			16:00 09DEC22		0.00	CHG	13DEC22
R.O. OPENED		READY	OPTIONS: DLR:C3834 ENG:3.7 Liter MPI				

09:01 07DEC22 14:25 13DEC22

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

Checked for codes and found no codes related. Found there to be a flash available for the sunroof module for the concern of sunroof not opening when commanded. Attempted to flash the module and found the flash to fail and code B227E ECU overtemp code to set. Attempted to flash the module again and found to fail flash again. Tried a different scan tool and found the same thing to happen again. Followed diag for code and tested the operation of the ambient temp sensor and found okay. Found the ambient temp data to be correct in the sunroof module as well. Found the sunroof module has failed and will need to be replaced.

C** Heater Core - Replace

CS40 Heater Core - Replace

194 KEEGAN LIC#: 194

C

1 98008 CORE-HEATER

1495.00 1495.00

1 VU01507-1 REFRIG

308.20 308.20 308.20

25.30 25.30 25.30

PARTS: 333.50 LABOR: 1495.00 OTHER: 0.00 TOTAL LINE C: 1828.50

100719 10.00 Removed the instrument panel from the vehicle. Removed the HVAC housing from the vehicle. Separated the HVAC housing and removed the old heater core. Installed the new heater core and re installed the HVAC housing. Installed the HVAC housing back into the vehicle and then re installed the instrument panel. Filled and bled the cooling system. Recharged the AC after repair. Road tested vehicle and found the cab to now have good sufficient heat. Re checked for leaks and found no leaks at this time. All okay now.

D** A/C Evaporator Core - Recommend replacing while HVAC housing is removed

AC13 A/C Evaporator Core - Recommend replacing while HVAC housing is removed

194 KEEGAN LIC#: 194

C

1 44084 CORE-EVAPORTOR

0.00 0.00

242.05 242.05 242.05

PARTS: 242.05 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D: 242.05

AT YOUR SERVICE MON TO FRI: 7:30 AM TO 5:30 PM THANK YOU FOR ALLOWING US TO SERVICE YOUR VEHICLE	O U T	INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. NO WARRANTY ON AFTERMARKET PARTS INSTALLED	DESCRIPTION	TOTALS
			LABOUR AMOUNT	
			PARTS AMOUNT	
			GAS, OIL, LUBE	
			SUBLET AMOUNT	
			MISC. CHARGES	
			TOTAL CHARGES	
			LESS INSURANCE	
			SALES TAX	
			PLEASE PAY THIS AMOUNT	

SIGNATURE

DATE

CUSTOMER SIGNATURE

X

G.S.T. REG. NO.: R103027447 "Your No Hassles, No Nonsense Dealer"

CUSTOMER COPY

CUSTOMER #:

249342

INVOICE

PAGE 3



LEDUC CHRYSLER JEEP

6102 46A Street

Leduc, Alberta T9E 7A7

Telephone (780) 986-2051

Facsimile (780) 986-1486

Toll Free 1-800-355-8933

service@leducchrysler.com

www.leducchrysler.com



HOME:

CONT:

BUS:

CELL:

SERVICE ADVISOR: 135 CHUCK

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG
	09	JEEP LIBERTY	1J8GN58K69W509001		100701/100719	T3005

IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
26JUN09 DD			16:00 09DEC22		0.00	CHG	13DEC22

R.O. OPENED READY OPTIONS: DLR:C3834 ENG:3.7_Liter_MPI

09:01 07DEC22 14:25 13DEC22

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
100719	Replaced the evaporator while the HVAC housing was removed.						

VIP15	15 Percent off parts and laboUr						
						-355.43	-355.43

VIP15 15 Percent off parts and laboUr

C

-355.43 -355.43

ESTIMATE: 2,140.25 08DEC22 08:31 SA: 135

CONTACT:

Shop supplies

95.00

****CAUTION!**** Failure to perform required maintenance items may result in damage to your vehicle and could VOID the warranty coverage. Please refer to your OWNERS MANUAL maintenance schedules.

After ANY repair involving the removal of tires, re-torque wheel nuts within 100 km

CUSTOMER GST

(#: R103027447)

105.45

AT YOUR SERVICE MON TO FRI: 7:30 AM TO 5:30 PM THANK YOU FOR ALLOWING US TO SERVICE YOUR VEHICLE	O U T	INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. NO WARRANTY ON AFTERMARKET PARTS INSTALLED SIGNATURE _____ DATE _____ CUSTOMER SIGNATURE X	DESCRIPTION	TOTALS
			LABOUR AMOUNT	1794.00
			PARTS AMOUNT	575.55
			GAS, OIL, LUBE	0.00
			SUBLET AMOUNT	0.00
			MISC. CHARGES	95.00
			TOTAL CHARGES	2464.55
			LESS INSURANCE	355.43
			SALES TAX	105.45
			PLEASE PAY THIS AMOUNT	2214.57

G.S.T. REG. NO.: R103027447 **"Your No Hassles, No Nonsense Dealer"**
 CUSTOMER COPY



Invoice #251

17 May 2022

BILL TO

FROM

Doug,s Auto Repair
4814-46 Ave
Wetaskiwin, AB T9A 0H3
dougautorepair1@gmail.com
+1 7803622632

INVOICE ITEMS

AMOUNT

~~2018 ford f150 front hub~~

~~\$625.51~~

1 unit x \$625.51/unit

~~f150 labor~~

~~\$150.00~~

1.50 hrs x \$100.00/hr

2008 jeep

\$200.00

2 hrs x \$100.00/hr

CV axle

\$210.00

1 unit x \$210.00/unit

Subtotal (excl. GST) \$1,185.51

5% GST \$59.28

\$1,244.79

PAYMENT DUE 21 MAY 2022

MESSAGE

Thanks for your business.



COPY

CUSTOMER #:

241755

INVOICE

PAGE 1



LEDUC CHRYSLER JEEP

6102 46A Street

Leduc, Alberta T9E 7A7

Telephone (780) 986-2051

Facsimile (780) 986-1486

Toll Free 1-800-355-8933

service@leduchrysler.com

www.leduchrysler.com



DODGE

HOME:

CONT:

BUS:

CELL:

SERVICE ADVISOR: 228 FRED

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG
	09	JEEP LIBERTY	1J8GN58K69W509001		83314 / 83314	T001

IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
26JUN09 DD			17:00 10FEB22		0.00	CHG	10FEB22

R.O. OPENED READY OPTIONS: DLR:C3834 ENG:3.7_Liter_MPI

12:02 10FEB22 12:49 10FEB22

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A ELECTRICAL. PROGRAM NEW OE KEY FOB

08 ELECTRICAL

268 JARED LIC#: 268

C

1 68029834AC KEY-BLANK WITH TRANSMITTER

PARTS: 196.65 LABOR: 80.00 OTHER: 0.00 TOTAL LINE A: 276.65

83314 VEHICLE PROGRAMMED NEW KEY

Shop supplies

8.80

****CAUTION!**** Failure to perform required maintenance items may result in damage to your vehicle and could VOID the warranty coverage. Please refer to your OWNERS MANUAL maintenance schedules.
After ANY repair involving the removal of tires, re-torque wheel nuts within 100 km

CUSTOMER GST

(#: R103027447)

14.27

AT YOUR SERVICE MON TO FRI: 7:30 AM TO 5:30 PM THANK YOU FOR ALLOWING US TO SERVICE YOUR VEHICLE	O U T	INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$	DESCRIPTION	TOTALS
		BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. NO WARRANTY ON AFTERMARKET PARTS INSTALLED	LABOUR AMOUNT	80.00
			PARTS AMOUNT	196.65
			GAS, OIL, LUBE	0.00
			SUBLET AMOUNT	0.00
			MISC. CHARGES	8.80
			TOTAL CHARGES	285.45
			LESS INSURANCE	0.00
			SALES TAX	14.27
			PLEASE PAY THIS AMOUNT	299.72

G.S.T. REG. NO.: R103027447 **"Your No Hassles, No Nonsense Dealer"**
CUSTOMER COPY

Quote - Shop Copy

RO Number	241755
Tag	T001

LEDUC CHRYSLER LTD.
6102-46A ST
LEDUC AB T9E 7A7
Phone # (403)986-2051

Customer Information			Vehicle Information			
Customer #	Customer Name	Quote Date/Time	Year	Make	Model	Odometer
		02/10/2022 12:43 PM	2009	JEEP	LIBERTY	83314
Address			VIN		Last Service Date	
			1J8GN58K69W509001			
Phone #	Email Address		Advisor	Appt Promised: Date/Time		
(825)995-2708			Fred	No 02/10/2022 05:00 PM		

SERVICE REQUEST

Technician Number: 268		Status: SUBMITTED			
B	Recommend vehicle inspection - found engine oil leaks and torn CV shaft boot (drivers front).				
Additional Recommendation		Qty LT	Hrs	Unit Price	Price
Labor					
	Recommend vehicle inspection - found engine oil leaks and torn CV shaft boot (drivers front).	C	1.50		224.25

Pricing Summary

	Labor	Parts	M/L/S	Tax	Line Total
Estimate	224.25	0.00	24.67	12.44	261.36

SERVICE REQUEST

Technician Number: 268		Status: SUBMITTED			
C	Perform diagnostic for PENDING code P0455 Evap large leak				
Additional Recommendation		Qty LT	Hrs	Unit Price	Price
Labor					
	Perform diagnostic for PENDING code P0455 Evap large leak	C	1.00		149.50

Pricing Summary

	Labor	Parts	M/L/S	Tax	Line Total
Estimate	149.50	0.00	16.45	8.30	174.25

Authorized Estimate	
Labor	
Parts	
Misc.	
Lube	
Sublet	
Subtotal	
Tax	
Total	

+

Additional Recommendations	
Labor	\$373.75
Parts	\$0.00
Misc.	\$41.12
Lube	\$0.00
Sublet	\$0.00
Subtotal	\$414.87
Tax	\$20.74
Total	\$435.61

=

Revised Estimate	
Labor	\$373.75
Parts	\$0.00
Misc.	\$41.12
Lube	\$0.00
Sublet	\$0.00
Subtotal	\$414.87
Tax	\$20.74
Total	\$435.61