

013-6
SEP

JBS Mechanical Inc
 Whitecourt Alberta T7S 1N5
 Whitecourt, AB T7S 1N5
 Box 353
 jbsmechanical.service@gmail.com

GST/HST No. 828463240

Invoice



JBS Mechanical Inc.
 1-780-779-6759

Invoice #	Date
47761	7/8/2026

P.O. No.	Terms
	Due on receipt

Invoice To

AWG Ventures LTD

Location	Work Order #	Make/Model	Unit Number
Shop	19247	Kenworth	Blue

Item	Description of Item	Bin	Qty	Rate	Amount
Regular Time	Disassembled multiple front end components and removed broken front frame horn. Waiting for new leaf springs to rebuild.		5	160.00	800.00
Regular Time	Installed front horn and all components, Removed and replace worn out leaf springs, and change rear spring hanger bushings.		8	160.00	1,280.00
Regular Time	Diagnose why truck had shake after new front leafs installed, Checked caster checked out steer tires. Checked toe found unit toed out, Tried adjusting toe was unable to move bar, Replaced tie rod bar assembly and set toe, Tested front shocks found them to be no good, Replaced front shocks, Checked rear shocks, found them to be good, Checked rear suspension found, Newway pivot bushings failed, Replace pivot bushings on Axle 2-3 LH/RH, Removed tires inspected drums and cleaned rims, Reinstalled and torqued tires, Checked oil in differentials		8	160.00	1,280.00
5707	Front Axle Spring Hanger (P/N: B11-6078 - Cast Steel)		1	2,400.00	2,400.00
Freight	Freight Parts		1	80.00	80.00
59-574	KENWORTH HD FRONT SPRING ASSEMBLY	CB	2	1,105.00	2,210.00
N-5000	7/8 X 3 X 12 R/TOP U-BOLTS W DN/FW	CB	4	49.00	196.00
Freight	Freight Parts		1	100.00	100.00
MR894	K/W SILENT BLOCK 5-7/16IN CT	BIN 3 K	2	63.34	126.68
Freight	Freight Parts		1	50.00	50.00
7715-0002	HOT CAC 4.00" IDX6.00"OAL	S 17 C	2	41.78	83.56
HC19-425	CONSTANT TORQUE CLAMP	BIN 3 H	4	14.64	58.56
M17412UB	RAD/MOTOR MOUNT	BIN 1 I	1	15.78	15.78
QT108SB	QWIKTIE TIE ROD ASSY 1.25" red	End 2	1	506.68	506.68
65101	SHOCK ABSORBER B71-6011 B71-6009	Shock ...	2	91.89	183.78
48100509	KIT-BUSHING FRONT PIVOT	CB	1	479.98	479.98
48100509	KIT-BUSHING FRONT PIVOT	CB	1	479.98	479.98
Shop Supplies	8% of Base Labour		21	13.20	277.20
Customer Signature _____		2% Interest charged on overdue invoices			

Subtotal

GST/HST

Total

Payment

Balance Due

JBS Mechanical Inc
 Whitecourt Alberta T7S 1N5
 Whitecourt, AB T7S 1N5
 Box 353
 jbsmechanical.service@gmail.com
 GST/HST No. 828463240

Invoice



JBS Mechanical Inc.
 1-780-779-6759

Invoice #	Date
47761	7/8/2026

P.O. No.	Terms
	Due on receipt

Invoice To

AWG Ventures LTD

Location	Work Order #	Make/Model	Unit Number
Shop	19247	Kenworth	Blue

Item	Description of Item	Bin	Qty	Rate	Amount
	Year 03/2020 VIN 1XK-WD40X-0-MR968625 592083 Kms 13898 Hrs				
Customer Signature _____		2% Interest charged on overdue invoices			

If we have had your wheels off re-tourque within 100 km's.
 Flat rate charges may be subjected to a 75% increase for siezed or aftermarket parts.
 A 25% increase in flat rate labor charge may occur due to excessive mud or snow on units.
 Parts warranty subject to manufactures approval.
 If customer does not request old parts back they will be disposed of by JBS Mechanical.
 No return on electrical components or special order parts.
UNAUTHORIZED ENGINE MODIFICATIONS OR DPF DELETES DO NOT QUALIFY FOR WARRANTY

Subtotal	\$10,608.20
GST/HST	\$530.41
Total	\$11,138.61
Payment	\$0.00
Balance Due	\$11,138.61

JBS Mechanical Inc
 Whitecourt Alberta T7S 1N5
 Whitecourt, AB T7S 1N5
 Box 353
 jbsmechanical.service@gmail.com
 GST/HST No. 828463240

Invoice



JBS Mechanical Inc.
1-780-779-6759

Invoice #	Date
46760	3/31/2026

P.O. No.	Terms
	Due on receipt

Invoice To

AWG Ventures LTD

Location	Work Order #	Make/Model	Unit Number
ST-07	18329		

Item	Description of Item	Bin	Qty	Rate	Amount
	slave lake - Blair. 2021 Kenworth W900B. VIN: 1xkwd40x0mr968625. L/P: 0-du941. 576,553 km. 13,451 hr.				
CVIP Truck - 3 ...	CVIP - 3 Axle		1	325.00	325.00
Regular Time	March 23, 2026.		3	140.00	420.00
	- perform cvip inspection on unit and make repair list.				
Regular Time	March 24, 2026.		5	140.00	700.00
	- source parts, find correct air dryer ad get ordered. - remove drive line, several stripped u-joint strap bolts had to extracted, drain diff. replace trans output u-joint. clean and inspect yokes in driveline and tap out holes for straps.				
Regular Time	March 25.		8	140.00	1,120.00
	- remove front drive axle shafts. had issues getting cone locks out of axles. - remove brakes, slack adjuster, s-cam and brake pot from A2 right side to get clearance to remove diff. un bolt and remove diff from truck(bolts all rusted in, took extra time to heat and get bolts loose). replace diff lock piston seal and cap. clean and prep diff housing and diff carrier. - seal and install diff in housing.				
Customer Signature _____		2% Interest charged on overdue invoices			

Subtotal

GST/HST

Total

Payment

Balance Due

JBS Mechanical Inc
 Whitecourt Alberta T7S 1N5
 Whitecourt, AB T7S 1N5
 Box 353
 jbsmechanical.service@gmail.com

GST/HST No. 828463240

Invoice



JBS Mechanical Inc.
1-780-779-6759

Invoice #	Date
46760	3/31/2026

P.O. No.	Terms
	Due on receipt

Invoice To

AWG Ventures LTD

Location	Work Order #	Make/Model	Unit Number
ST-07	18329		

Item	Description of Item	Bin	Qty	Rate	Amount
Regular Time	March 26. - clean hubs and axles, install axles with new gaskets. - fill diff and hubs with oil. - install brake pot, s-cam, slack adjuster on A2 right. - install drive line with new strap kits and torque to spec.		7	140.00	980.00
Regular Time	March 26. - drain coolant, remove pipes and hoses and brackets as needed. remove power steering pump from compressor, remove steering shaft from box for clearance. remove power steering reservoir/bracket. - remove air compressor. - clean surfaces, swap fittings to new compressor. install compressor on truck with new gasket. re assemble unit as required. - fill coolant. - replace compressor discharge line from hard line to dryer and secure as needed.		7	140.00	980.00
Customer Signature _____		2% Interest charged on overdue invoices			

Subtotal

GST/HST

Total

Payment

Balance Due

JBS Mechanical Inc
 Whitecourt Alberta T7S 1N5
 Whitecourt, AB T7S 1N5
 Box 353
 jbsmechanical.service@gmail.com

GST/HST No. 828463240

Invoice



JBS Mechanical Inc.
 1-780-779-6759

Invoice #	Date
46760	3/31/2026

P.O. No.	Terms
	Due on receipt

Invoice To

AWG Ventures LTD

Location	Work Order #	Make/Model	Unit Number
ST-07	18329		

Item	Description of Item	Bin	Qty	Rate	Amount
Regular Time	March 30. - replace A3 v-bar to frame mounting bolts. bolts were seized, had to carefully heat and remove due to air lines and harness' close by. - replace air dryer cartridge due to oil bypass from old compressor. - diag for signal/brake lights not working on headache rack and rear of truck. find junction box at rear rusted out, wiring hooked up wrong causing backfeeding to chassis node. - trace wiring to get correct functions hooked up and hard wire chassis harness to rear light and headache rack. repair replace wiring and pigtails as needed in rear light harness. cover and secure as needed to prevent damage. still no left signal power. confirm output from chassis node is good. trace wiring along frame and find a section that had been cut apart previously and wiring has been cut or poked with a test light. repair or replace sections of wiring as needed. cover and secure as required. test and all lights work now. noticed entire harness was not secured. bundle and secure as needed to prevent further damage.		9	140.00	1,260.00
Regular Time	March 31, 2026. - install and torque wheels. - fill out cvip forms on line.		2	140.00	280.00
250-70-18X	SPL250 STRAP KIT	Unassi...	3	35.18	105.54
SPL250-3X	SPL250 U-JOINT	Unassi...	1	301.24	301.24
180.10613	GASKET,DRIVE FLANGE	Unassi...	2	3.39	6.78
512892	D155/156/170/190 L/O REPAIR KIT	Unassi...	2	47.00	94.00
50190-18.9L	75W90 GL-5 FULLY SYNTHETIC - GEAR OIL 18.9L W/ ENVIRONMENTAL FEE	Unassi...	1	258.42	258.42
9111530270SX	WABCO AIR COMPRESSOR - CUM ISX15, 1 1/4" INTAKE	Unassi...	1	1,338.60	1,338.60
Freight	Freight Parts		1	80.00	80.00
1250E473	DRAIN PLUG MAGNETIC	Unassi...	1	7.70	7.70
30076	300ML BLK R/STUFF GASKET	Unassi...	1	68.27	68.27
5440813	GASKET, ACC DRIVE SUPPORT	Unassi...	1	44.46	44.46

2% Interest charged on overdue invoices

Subtotal

GST/HST

Total

Payment

Balance Due

JBS Mechanical Inc
 Whitecourt Alberta T7S 1N5
 Whitecourt, AB T7S 1N5
 Box 353
 jbsmechanical.service@gmail.com
 GST/HST No. 828463240

Invoice



JBS Mechanical Inc.
1-780-779-6759

Invoice #	Date
46760	3/31/2026

P.O. No.	Terms
	Due on receipt

Invoice To

AWG Ventures LTD

Location	Work Order #	Make/Model	Unit Number
ST-07	18329		

Item	Description of Item	Bin	Qty	Rate	Amount
Out Going Sub ... 5008414 Shop Supplies	Hose build at Heavy Tech AD-SP/AD-IS DESICCANT CARTRIDGE 8% of Base Labour	Main Bin	1 1 43	210.23 130.07 13.20	210.23 130.07 567.60
Customer Signature _____ 2% Interest charged on overdue invoices					

If we have had your wheels off re-torque within 100 km's.
 Flat rate charges may be subjected to a 75% increase for siezed or aftermarket parts.
 A 25% increase in flat rate labor charge may occur due to excessive mud or snow on units.
 Parts warranty subject to manufactures approval.
 If customer does not request old parts back they will be disposed of by JBS Mechanical.
 No return on electrical components or special order parts.
UNAUTHORIZED ENGINE MODIFICATIONS OR DPF DELETES DO NOT QUALIFY FOR WARRANTY

Subtotal	\$9,277.91
GST/HST	\$463.90
Total	\$9,741.81
Payment	\$0.00
Balance Due	\$9,741.81