

Kinked Wrench Mechanical Ltd.
 RR1 Site 2 Box 7
 Eckville, AB T0M 0X0, CA
 hollyweaver@kinkedwrenchmechanical.com
 403-429-0320



C15-25
SEP

Page: 1 of 3

Invoice: **INV-1406**

Date: **6/29/2023**



Bill To
 Raven Rentals 2022 LTD

P: (403) 350-7816

Remit Payment To
 Kinked Wrench Mechanical
 RR1 Site 2 Box 7
 Eckville, AB T0M 0X0, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Unit #
SO-1882	Net 30	7/29/2023	Richard Turner		Pup

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

Complaint: CVIP - Trailer

Cause: Customer request **Type:** Customer Requested Repair

Labor	Correction: Chassis / Chassis / Perform CVIP on trailer. Check all brakes, air leaks, check all lights, measure and record all items needed for CVIP inspection, make list of all repairs needed, get parts quote, contact customer for approval. Fill out CVIP paperwork, install new sticker, return unit to customer, clean up all tools and bay. - Completed: 6/29/2023	1.53846	\$130.00	\$200.00	
				Subtotal	\$200.00

Complaint: CVIP - Wheels Off - 2 Axles

Cause: Customer request **Type:** Customer Requested Repair

Labor	Correction: Chassis / Chassis / Perform wheels off CVIP Jack up all axles, remove all wheels and rims, fully inspect braking components, measure brake drums and brake pads, reinstall all drums and tires, torque all wheels to spec. Customer to retorque wheels within 150km of CVIP. Fill out CVIP paperwork, install new sticker, return unit to customer, clean up all tools and bay. - Completed: 6/29/2023	1.53846	\$130.00	\$200.00	
				Subtotal	\$200.00

Complaint: REPLACE WORN BRAKE DRUMS

Cause: Customer request **Type:** CVIP Repair

(Inspection)

Labor	Trailer / Wheels / REPLACE WORN BRAKE DRUMS - Completed: 6/29/2023	0.80000	\$130.00	\$104.00
-------	--	---------	----------	----------

Item	Description	Quantity	Rate	Amount
Parts	3600A Brake Drum - FLT4400B	2.00000	\$182.2365	\$364.47
Subtotal				\$468.47

Complaint: INSTALL BRAKE STROKE INDICATORS AND WHEEL NUT INDICATORS

Cause: Customer request **Type:** CVIP Repair

(Inspection)

Labor	Correction: Trailer / Wheels / Installed missing brake stroke indicators and wheel nut indicators. - Completed: 6/29/2023	0.95000	\$130.00	\$123.50
Parts	Green wheel nut indicator - WLCHB	40.00000	\$2.0385	\$81.54
Parts	Red Brake pot stroke indicators, stop signs - S-100	4.00000	\$1.89	\$7.56
Subtotal				\$212.60

Complaint: REPLACE SHOCK

Cause: Customer request **Type:** CVIP Repair

(Inspection)

Labor	Correction: Trailer / Suspension / Removed old shock with impact and wrench and then grabbed new bolts and shock and installed shock with anti cease on the bolts tightened with impact and wrench. Cleaned up finished. - Completed: 6/29/2023	1.00000	\$130.00	\$130.00
Parts	Shock absorber 1-5/8" bore - 85000	1.00000	\$70.875	\$70.88
Parts	3/4"x 5-1/2" Grade 8 Bolt - 3/4X5.5	1.00000	\$6.345	\$6.35
Parts	3/4"x 3-1/2" Grade 8 Bolt - 3/4X3.5	1.00000	\$4.32	\$4.32
Parts	3/4" Bolt Nylock and Washers - 3/4HDWR	2.00000	\$2.2275	\$4.46
Subtotal				\$216.01

Unit: Pup **VIN:** 2LDPF32329J049158

License Plate: (AB) 5PE682

2009 Lode King PFJ28-2

Chassis: 0 Kilometres

Labor	\$757.50
Parts	\$539.58
Shop Supplies	\$44.85
Pre-Charge Subtotal	\$1,341.93
GST (5% of \$1,341.93)	\$67.10
Total	\$1,409.03
Payments & Credits	\$0.00
Balance Due	\$1,409.03

I hereby authorize the above work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways or elsewhere to the purpose of testing and/or inspection. Any amounts charged over the approved limit will