

**CG Truck and Equipment Repair
Inc**

5312 114 Avenue Southeast
Calgary, AB T2C 4T9, CA
service@cgter.ca
4032796200

Invoice: **INV-202512133**Date: **1/16/2025**

*X33-13
SEP*

Bill To
ATLAS AGGREGATES
CA
P: 403-438-7706

Remit Payment To
Billing
5312 114 Avenue Southeast
Calgary, AB T2C 4T9, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Unit #
SO-4460	Net 30	2/15/2025			T01

Item	Description	Quantity	Rate	Amount	Taxable
Labor	Chassis / Chassis / Annual Commercial Vehicle Inspection - Truck: Annual Commercial Vehicle Inspection - Truck - Completed: 1/16/2025	2.50000	\$100.00	\$250.00	Y
				Subtotal	\$250.00
Labor	Chassis / Chassis / Annual Commercial Vehicle Inspection - Tire Removal (x3): Annual Commercial Vehicle Inspection - Tire Removal \$80 / Axle x3 - Completed: 1/16/2025	2.18182	\$110.00	\$240.00	Y
				Subtotal	\$240.00
Labor	Engine / Lubrication / 'B' Full Wet Service (Lube, Oil & Filters): 'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters(Fuel&Oil) -Greased unit - Completed: 1/16/2025	1.20000	\$100.00	\$120.00	Y
Parts	Oil filter	1.00000	\$30.48	\$30.48	Y
Parts	15W40 Extreme CK4	39.00000	\$4.60	\$179.43	Y
Parts	Cat fuel filter	1.00000	\$35.87	\$35.87	Y
Parts	Fuel separator	1.00000	\$28.61	\$28.61	Y
				Subtotal	\$394.39
Labor	Exhaust / Exhaust Pipe / repair loose right side exhaust stack. -removed stack, cut off damaged section. Reinstalled. - Completed: 1/16/2025	0.80000	\$100.00	\$80.00	Y
				Subtotal	\$80.00
Labor	Electrical System / Battery / Replace batteries and broken cables -Replaced batteries. -Repaired broken ground to frame. - Completed: 1/16/2025	1.00000	\$100.00	\$100.00	Y

Item	Description	Quantity	Rate	Amount	Taxable
Parts	COPPER SPLICE TIN 4GA	1.00000	\$7.22	\$7.22	Y
Parts	BATTERY, GRP	3.00000	\$108.20	\$324.61	Y
			Subtotal	\$431.83	
Labor	Brakes / Brake Shoes & Drums / Replace second axle brake shoes. -Replaced both sides. - Completed: 1/16/2025	1.00000	\$100.00	\$100.00	Y
Parts	Brake shoes 4707 Q plus Meritor lining 23K	2.00000	\$67.71	\$135.43	Y
			Subtotal	\$235.43	
Labor	Rear Axle/Final Drives / Wheel Seals / Third axle right side wheel seal is leaking. -Removed axle, removed hub assembly. Cleaned bearings and inspected. -Reinstalled bearings with new wheel seal. Installed hub assembly and set bearings. Topped up oil. - Completed: 1/16/2025	1.50000	\$100.00	\$150.00	Y
Parts	Seal (drive axle)	1.00000	\$30.62	\$30.62	Y
Parts	Synthetic gear oil	1.00000	\$13.16	\$13.16	Y
			Subtotal	\$193.78	
Labor	Rear Axle/Final Drives / Springs / Replace all rear spring pin bushings. -Cut off seized bolts. Pressed out old bushings. Installed new bushings. -Aligned axles with hangers and installed with new bolts. - Completed: 1/16/2025	6.00000	\$100.00	\$600.00	Y
Parts	POLY AIRLINER BUSHING	4.00000	\$116.00	\$463.99	Y
			Subtotal	\$1,063.99	
Labor	Rear Axle/Final Drives / Torque Rods / Third axle torque rod bushings have shifted. -Removed torque rod to get re-bushed. -Installed new torque rod. - Completed: 1/16/2025	0.50000	\$100.00	\$50.00	Y
Parts	16-18972-000 Torq Rod TMR536 / 345-916	1.00000	\$143.91	\$143.91	Y
			Subtotal	\$193.91	
Labor	Chassis / Air Conditioning & Heating / Operator said that the blow motor still does not have every speed. -confirmed issue. Checked connections from the resistor to the motor. They are good. Checked wiring from the resistor to the switch found one wire had come off at the switch. Reattached. Tested, all good now. - Completed: 1/16/2025	1.10000	\$100.00	\$110.00	Y
			Subtotal	\$110.00	
Labor	Brakes / Air Compressor / Air system is only building to 100psi. -Adjusted governor. Tested, it is over 120 now. - Completed: 1/16/2025	0.50000	\$100.00	\$50.00	Y

Item	Description	Quantity	Rate	Amount	Taxable
			Subtotal	\$50.00	
Labor	Chassis / Lighting & Electrical / Repair rear marker lights on box. -Replaced one left light and one right rear one. DONE - Completed: 1/16/2025	0.75000	\$100.00	\$75.00	Y
Parts	Lamp 2in LED red	1.00000	\$12.34	\$12.34	Y
Parts	2in sealed marker lamp red	1.00000	\$4.26	\$4.26	Y
			Subtotal	\$91.60	
Labor	Chassis / Chassis / Tailgate has a large gap. -Added material to the locks. The tailgate is tight to the box now. - Completed: 1/16/2025	0.60000	\$100.00	\$60.00	Y
			Subtotal	\$60.00	
Labor	Transmission / Drive Shaft / First diff u joint has play. -Had to remove the whole shaft to get the u joint off. -Installed new u joint and then the drive shaft. Used new strap kits. -Tightened loose yoke nut at steady bearing and transmission yoke. - Completed: 1/16/2025	2.00000	\$100.00	\$200.00	Y
Parts	SPL170 U-JOINT	1.00000	\$158.82	\$158.82	Y
Parts	U-joint strap kit	2.00000	\$34.28	\$68.57	Y
			Subtotal	\$427.39	
Labor	Engine / Electrical / Replace ECM. -removed old ECM, repaired some rubbed through wires. -Installed new ECM. Tested, everything is working now. - Completed: 1/16/2025	2.50000	\$100.00	\$250.00	Y
Parts	CONT GP -E	1.00000	\$3,838.01	\$3,838.01	Y
Parts	TEST AND PROGRAM ECM	1.00000	\$298.90	\$298.90	Y
			Subtotal	\$4,386.91	

Unit: T01 VIN: 5KJJALAV37PY22308

License Plate: (AB) 31-N056

2007 Western Star 4900

Chassis: 5,593 Kilometers

Labor	\$2,435.00	
Parts	\$5,774.23	
Shop Supplies	\$170.45	Y
Pre-Charge Subtotal	\$8,379.68	
GST (5% of \$8,379.68)	\$418.98	
Total	\$8,798.66	
Payments & Credits	\$0.00	
Balance Due	\$8,798.66	

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work.

You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice. **Please** have wheels nuts retorqued within 100-150 KM after repairs have been completed.

GST: 77787 9008 RT 0001

Customer Signature: _____

Printed Name: _____ Date: _____