

JBS Mechanical Inc
 Whitecourt Alberta T7S 1N5
 Whitecourt, AB T7S 1N5
 Box 353
 jbsmechanical.service@gmail.com

GST/HST No. 828463240

Invoice



JBS Mechanical Inc.
1-780-779-6759

W48-8
SEP

Invoice #	Date
48411	9/15/2026

P.O. No.	Terms
	Net 30

Invoice To

Philip Lewis Contracting

Location	Work Order #	Make/Model	Unit Number
Shop	19865	WESTERN STAR	010

Item	Description of Item	Bin	Qty	Rate	Amount
Regular Time	Remove and replace starter (Customer supplied starter), Mounting bolts extremely tight had to disassembled old starter in unit to get bolts out		4	160.00	640.00
Shop Supplies	8% of Base Labour		4	13.20	52.80
	Year 2018 VIN5KKPALFG4KPKC2014 334985MILES 12963HR Plate A-88674				
Customer Signature _____		2% Interest charged on overdue invoices			

If we have had your wheels off re-tourque within 100 km's.
 Flat rate charges may be subjected to a 75% increase for siezed or aftermarket parts.
 A 25% increase in flat rate labor charge may occur due to excessive mud or snow on units.
 Parts warranty subject to manufactures approval.
 If customer does not request old parts back they will be disposed of by JBS Mechanical.
 No return on electrical components or special order parts.
UNAUTHORIZED ENGINE MODIFICATIONS OR DPF DELETES DO NOT QUALIFY FOR WARRANTY

Subtotal	\$692.80
GST/HST	\$34.64
Total	\$727.44
Payment	\$0.00
Balance Due	\$727.44

Posted.

JBS Mechanical Inc
Whitecourt Alberta T7S 1N5
Whitecourt, AB T7S 1N5
Box 353
jbsmechanical.service@gmail.com

GST/HST No. 828463240

Invoice



JBS Mechanical Inc.
1-780-779-8239

Invoice #	Date
47934	7.30/2026

P.O. No.	Terms
	Net 30

Invoice To

Philip Lewis Contracting

Location	Work Order #	Make/Model	Unit Number
Shop	19306	Western star	010

Item	Description of Item	Bin	Qty	Rate	Amount
Regular Time	Wash down engine by air compressor to find source of oil leak. Found crank case filter drain line leaking, tapped up plastic line for temporary fix and ordered new line		0.5	160.00	80.00
Regular Time	Diagnose reverse lights always on found failed ball switch on transmission replaced ball switch and tested		0.5	160.00	80.00
Regular Time	Noticed major oil leak under unit when unit was pulled into shop. Inspected and found oil coming out of differential filter on Axle 2, Replaced filter and checked level		0.5	160.00	80.00
B233	MERITOR DIFFERENTIAL FILTER ENV INCLUDED IN PRICE LF689	PR 1 C	1	7.91	7.91
75W90	DELO SYN GEAR XDM 75W90 ENV INC. IN PRICE PER L	Bulk Oil	2	21.82	43.64
3691032	TUBE, LUBE OIL DRAIN	Unassi...	1	77.63	77.63
Freight	Freight Parts		1	50.00	50.00
577.55525	METRI-PACK REV SW 9/16-18 NO W/HARNESS	Bin 3 A	1	22.86	22.86
Shop Supplies	8% of Base Labour		1.5	13.20	19.80
	Year 2018 VIN 5KKPALFG4KPKC2014 905604KM 12774HR				
	NOTE CRANKCASE OIL DRIAN LINE IS HERE AND CAN BE INSTALLED NEXT TIME UNIT IS BACK AT SHOP				
Customer Signature _____		2% Interest charged on overdue invoices			

If we have had your wheels off re-tourque within 100 km's.
Flat rate charges may be subjected to a 75% increase for siezed or aftermarket parts.
A 25% increase in flat rate labor charge may occur due to excessive mud or snow on units.
Parts warranty subject to manufactures approval.
If customer does not request old parts back they will be disposed of by JBS Mechanical.
No return on electrical components or special order parts.
UNAUTHORIZED ENGINE MODIFICATIONS OR DPF DELETES DO NOT QUALIFY FOR WARRANTY

Subtotal	\$461.84
GST/HST	\$23.09
Total	\$484.93
Payment	\$0.00
Balance Due	\$484.93

NOTHE NUMBER 618746
OUR NUMBER
DATE MAY 20/26
COMMANDED BY CLIENT
CUSTOMER ORDER

PHILIP LEWIS
CONTRACTING

NAME _____
SHIP TO _____
ADDRESS _____
ADDRESS _____

100-443887-100 100-443887-100	100-443887-100 100-443887-100
----------------------------------	----------------------------------

PAGES 1
 FOR 1

[illegible]

BlueLine DCB37

© Blümel & 2010

email or text messages carry the notice while the financial institutions securely transfer the money using existing payment networks.

This email was sent to you by Interac Corp., the owner of the Interac e-Transfer service, on behalf of ATB Financial

Posted

JBS Mechanical Inc
Whitecourt Alberta T7S 1N5
Whitecourt, AB T7S 1N5
Box 353
jbsmechanical.service@gmail.com

GST/HST No. 828463240

Invoice



JBS Mechanical Inc.
1-780-779-6759

Invoice #	Date
46261	2/26/2026

P.O. No.	Terms
	Net 30

Invoice To

Philip Lewis Contracting

Location	Work Order #	Make/Model	Unit Number
ST-13	18014	Western Star	010

Item	Description of Item	Bin	Qty	Rate	Amount
Mobile Time	Diagnose no power steering. Find that the crank shaft in air compressor has broke. Remove power steering pump from rear of air compressor. Disconnect coolant lines from air compressor and cap. Remove air compressor discharge line from compressor. Remove compressor from engine. Inspect drive gears for any damage. No visible damage found on gears at this time. Swap all fitting over from old air compressor on to new customer supplied air compressor. Replace all sealing Orings on fittings. Clean mounting surface on engine and install new air compressor with new gasket. Reconnect air compressor discharge line and reconnect coolant lines. Reinstall power steering pump with new gasket. Start and run unit. Unit now builds air and has power steering again. Return to base.		5	170.00	850.00
4988280	GASKET, HYDRAULIC PUMP	End 1	1	8.24	8.24
Shop Supplies	8% of Base Labour		5	13.60	68.00
	Make : Western Star Model : 4900SB VIN : 5KKPALFG4KPKC2014 Mileage : 508092km Hours : 12202				
Customer Signature _____		2% Interest charged on overdue invoices			

If we have had your wheels off re-tourque within 100 km's.

Flat rate charges may be subjected to a 75% increase for siezed or aftermarket parts.
A 25% increase in flat rate labor charge may occur due to excessive mud or snow on units.

Parts warranty subject to manufactures approval.

If customer does not request old parts back they will be disposed of by JBS Mechanical.

No return on electrical components or special order parts.

UNAUTHORIZED ENGINE MODIFICATIONS OR DPF DELETES DO NOT QUALIFY FOR WARRANTY

Subtotal \$926.24

GST/HST \$46.31

Total \$972.55

Payment \$0.00

Balance Due \$972.55