

Date	Equipment	Activity	BLOCK_CODE	Service Meter	Hours	Work Code 1	Work Code 2	Type
12/13/2023	FB12	MAINT	ZMAINTENAN	1.00	1.50	MOVE	MACH	Employee
5/11/2023	FB12	MAINT	ZMAINTENAN	0.00	1.00	SRV REG	TANKS	Employee
5/11/2023	FB12	MAINT	ZMAINTENAN	0.00	3.00	REPAIR	ELEC	Employee
11/22/2022	FB12	MAINT	ZMAINTENAN	0.00	0.50	INSTL	HOSES	Employee
11/17/2022	FB12	MAINT	ZMAINTENAN	0.00	0.50	RE+RE	HOSES	Employee
11/17/2022	FB12	MAINT	ZMAINTENAN	0.00	1.00	REPAIR	HOSES	Employee
8/24/2022	FB12	MAINT	ZMAINTENAN	0.00	2.50	SRV REG	MACH	Employee
8/23/2022	FB12	MAINT	ZMAINTENAN	0.00	7.50	SRV REG	MACH	Employee
8/23/2022	FB12	MAINT	ZMAINTENAN	0.00	1.00	RE+RE	ELEC	Employee
8/20/2022	FB12	MAINT	ZMAINTENAN	0.00	1.50	RE+RE	ELEC	Employee
8/19/2022	FB12	MAINT	ZMAINTENAN	0.00	1.00	PARTS	PARTS	Employee
	FB12				21.00			

Grand Totals **21.00**

Date: 5/1/2021 - 5/30/2024

5/30/2024 9:53:27 PM

EMPLOYEE _CODE	Description
WIE001	check machine over for start up and moved across yard for snow removal
MAC001	drained some fuel from tank it was good
MAC001	got hood working enough to close it something wrong with valve in power pac
LAT001	1. INSTALLED NEW HYDRAULIC HOSE ON MACHINE
LAT001	1. REMOVED HYDRAULIC HOSE FROM BOOM TO REPAIR
WIE001	pulled bad hydro hose with hannah
WIE001	RUN THREW HOLE MACHINE MADE A DETAILED LISTS OF REPAIRS THAT WILL NEED TO BE DONE INSPECTED INTIRE MACHINE ENGINE OIL HIGH DRAINED DEALT AND FOUGHT WITH HOOD ISSUES
WIE001	FOR MORE INFORMATION PLEASE SPEAK TO ART
WIE001	INSTALLED BATTERIES
WIE001	INSTALL NEW BATTERY AS PER UNTI REQUIRES BUT BATTERY BOX HAD BEEN MODIFIED 4 A SMALLER SET
WIE001	SIZE AND ORDER BATTERIES FOR FB03,FB12,RE11