

Maintenance History Detail

927

2026

Date	Entity	Entity Type	Service Type	Service Name	Notes	Cost	Fleet Manager	Odometer	Engine Hours
2026-03-30	927	vehicle			install new left drive hub cap. install new front right side marker light. install used outer drive tire. hubcap mount broke on the road, which caused the inner drive to lose air. 1 x light 993113nb a503n9		Jeanette Hrechka	871173	17314

Date	Entity	Entity Type	Service Type	Service Name	Notes	Cost	Fleet Manager	Odometer	Engine Hours
2026-05-07	927	vehicle	Tires	Tire Inspection - drivcs	Dismount or mount loose commercial 18" and up Commercial Truck Valve Stem yard-Service call Courtesy inspection shop Supplies Dismount 4 tires, Mount 2 Tires set @ 110 PSI	296.6	Susan Agland	875222	17400
2026-04-27	927	vehicle	180 day inspection	Mo Safety inspection	Gov't Safety 1. One license plate light out 2. Roar right side marker light out 3. Air lines rubbing on right drive brake pot 4. one battery post corroded 5. Battery door rear latch has broken bolt 6/ Right drive tires worn to specs 7. Rear engine hatch lock mech missing bolt 8. All luggage doors upper cowings loose 9. Condenser door front lock mech, not working 10. Rear right docking light out 11. Drivers windshield has stone marks 12. Ex. pipe cracked to muffler 1-amber marker light- 993113NBAS03N9 1- docking light - 10985542 labor 8 hrs/8 hrs		Susan Agland	875222	17400
2026-04-23	927	vehicle			check A/c, cleaned all coach air filters. A/C light came on. 2 hours.		Jeanette Hrechka	875122	17394
2026-04-07	927	vehicle	Tires,Oil Change	Tire Inspection - Tags,oil change	Install 2 new tag tires from denray (recaps) Oil change and filter. Install new A/C clutch and pulley. Evacuate and fill system. Install 2 new latches for rear left side engine door, 1 x latch 660170420 1 x latch 660170421 1 x oil filter 7907 44 l - 10w30 oil 2 tag tires 1 A/c clutch assy.		Jeanette Hrechka	871204	17316

927 -
2024

Date	Entity	Entity Type	Service Type	Service Name	Notes	Cost	Fleet Manager	Odometer	Engine Hours
2024-12-18	927	vehicle			M Install new pro heater fuel filter. Reinstall shelf front in bathroom vanity. Split apart S-Bar harness connection and clean corrosion of f. Run and test. Better than ever. 1- F. filter 33361 Labor 4 hrs		Jeanette Hrechka	776962	15372
2024-11-13	927	vehicle	Oil Change, Tires, Tires	oil change, Tire Inspection Required - steers, Tire Inspection - drives, Tire Inspection - Tags	Oil and filter change. tire pressure's checked - 110 on drives, 115 on tags and steers 45 L 10w30 oil filter - P55100 5 - Napa fuel filter kit - P550954 - not installed Fog light bulb changed - still no fog light - wiring issue possibly - Fog bulb - H7 RH low beam replaced		Jeanette Hrechka	769384	15189
2024-11-06	927	vehicle			Install new air belt tensioner on A/C compressor 1 belt 10635845 ABC Labor 2 hrs		Jeanette Hrechka	768055	15154
2024-11-04	927	vehicle			Repair marker light above driver on left side of bus. Repair wiring and install new light. Repair fender, lose on mounting bolts Labor 2 hrs 1- light- 993113N BAS03N9		Jeanette Hrechka	766844	15153
2024-10-19	927	vehicle	Tires	Tire Inspection - Tags	Quality Tire Moosejaw, Sask- MRT Z Multi T-SA retread MRT 315/80R22.5, casing Medium Truck Tire c/Over up to 11R24.5 Left rear tag, Medium Truck Tire Balance Bead Balance, Valve Stem Euro Bras Stem		Jeanette Hrechka	762691	15048
2024-10-18	927	vehicle	Tires	Tire Inspection - Tags	Quality Tire Whitewood Sask - COMS C commercial service call Oct 18, 2024, serlabour service truck labour removed Blown Tire/ Wheel assembly and installed spare tire, Left hand tag		Jeanette Hrechka	762507	15043
2024-10-02	927	vehicle			install used coolant pump beside evelasto change out coolant pipe from air compressor to block. Drained coolant and refilled. Run + test. Parts: Coolant pipe A4712007552/ 26L coolant. labor 6 hrs/ 2 hrs		Jeanette Hrechka	762367	15041
2024-10-02	927	vehicle			parts purchased	95.69	Jeanette Hrechka	760464	14996
2024-09-05	927	vehicle			Install 1 new hose clamp on hose off intercooler. Install both new filters on hoses off coolant reservoir, @ X coolant filters 11662333		Jeanette Hrechka	752817	14839

2024-08-12	927	vehicle	180 day inspection	Mb Safety inspection	Fire extinguisher expired. Battery tray not latching on front right side. Rad door rear latch broken. Left low beam and right daytime running light out. Right tag tire worn below specs. While steers were off change up top grease nipple so greasing is much easier. Labor - 8 hrs		Shari Leshchyshyn (Deactivated)	745413	14703
2024-08-08	927	vehicle	Tires	Tire Inspection - Tags	CHANGE THE TAGS TIRE TAKEN FROM STOCK	47.25	Natalie Hrechka	744840	14127
2024-08-08	927	vehicle			tie change over	47.25	Natalie Hrechka		
2024-08-02	927	vehicle			Removal of coach filters and clean out . Labor - 1 hr		Shari Leshchyshyn (Deactivated)	745330	14688
2024-06-26	927	vehicle	Tires	Tire Inspection Required - steers	Left Steer Tire Change and Balance	112.0	Shari Leshchyshyn (Deactivated)	742348	14603
2024-06-20	927	vehicle			Tire Balance LF Inner shoulder wear	134.0	Shari Leshchyshyn (Deactivated)	741749	14594
2024-06-20	927	vehicle	Oil Change	oil change	oil and filter change - Brett Hassard		Jeanelle Hrechka	741815	14592
2024-06-20	927	vehicle	Oil Change	oil change	oil and filter change - Brett Hassard		Jeanelle Hrechka	741815	14592
2024-05-29	927	vehicle			Unit runs rough at idle, sometimes when starting; sometimes after running on the highway Freightliner had scanned the unit in the past and we were informed the wastegates are prone to seizing. On further inspection by Brett, wastegate not seized, EGR actuator is partially. Remove and Replace EGR Actuator Brett Hassard - 4 hours DDE/EA4701500994 \$1435.37 - Premier Truck		Jeanelle Hrechka	739697	
2024-05-11	927	vehicle			Change out front right tire from 920, Retorque on May 13th. Top up coolant and check oil. 4L Coolant Labor 2 hrs		Shari Leshchyshyn (Deactivated)	735424	14486
2024-04-11	927	vehicle			Install new bladder into toilet flush mechanism. Remove complete toilet from bus. Parts 1 diaphragm 1969767 1 Alt Belt 11204564ABC		Shari Leshchyshyn (Deactivated)	728616	14347
2024-03-05	927	vehicle			Install new alt#1. Had to reposition mount brackets and modify mounts. Front left high beam out. Parts 1 alt del star 160-60243-ABC 1 light H9 Labor 13 hrs / 1 hr		Shari Leshchyshyn (Deactivated)	724425	14267
2024-02-12	927	vehicle			Driver Brian, Boost in Wpg	123.9	Shari Leshchyshyn (Deactivated)	721383	14191
2024-01-29	927	vehicle	Oil Change. 180 day inspection	oil change, Mb Safety inspection	1 Fuel access door has broken brackets. Oil change and filter (Grease) L 15/40 oil 1 oil filter P551005		Jeanelle Hrechka	719152	14139

927

2025

Date	Entity	Entity Type	Service Type	Service Name	Notes	Cost	Fleet Manager	Odometer	Engine Hours
2025-03-31	927	vehicle	Oil Change	oil change	oil and filter change . 40 litres 10w30 oil filter -		Jeanette Hrechka	802100	15901
2025-03-08	927	vehicle	90 day inspection, Tires,Tires,180 day inspection	push out window lo g,Tire Inspection - drives,Tire Inspecti on Required - steer s,Tire Inspection - Tags,Mb Safety ins pection	793,908 M Gov't S afety inspection Fr ont left need flap missing, Battery bo x compartment, flo or croching through . One marker light out labor 5 hrs		Jeanette Hrechka	793908	15756
2025-03-04	927	vehicle			793,400 km 15,748 hrs Change engine air filter 1x Donalds on Filter p785426 (f rom ABC)		Jeanette Hrechka	793400	15748
2025-02-12	927	vehicle			787,864 kms 15,62 2 hrs adjust pax do or by moving catch brackets Change 6 belts and tensioner bottom bushing 2 i o A/C compressors (63960200) 2 to en gine fan (63960200 1) 1 to alternator (1 1204564) 1 siames e (11081176) 1 bus hing (11159064		Jeanette Hrechka	788170	15630
2025-02-04	927	vehicle	Tires,Tires,Tires	Tire Inspection Req uired - steers,Tire I nspection - drives, Tire Inspection - Ta gs	tire pressure check , found tag and inn er drives to be sligh tly low, reinflated ta g to 115 psi and dri ves to 110 psi steer s wore ok		Jeanette Hrechka	786676	15592
2025-02-04	927	vehicle	Tires,Tires,Tires	Tire Inspection Req uired - steers,Tire I nspection - drives, Tire Inspection - Ta gs	tire pressure check , found tag and inn er drives to be sligh tly low, reinflated ta g to 115 psi and dri ves to 110 psi steer s wore ok		Jeanette Hrechka	786676	15592
2025-01-28	927	vehicle	Oil Change	oil change	oil and filter change 40L 10W/30 1 x 790 9 Napa filter		Jeanette Hrechka	784411	15544
2025-01-20	927	vehicle			change rh low bea m 1 - H9 - 12V bulb		Jeanette Hrechka	780746	15472

Date	Entity	Entity Type	Service Type	Service Name	Notes	Cost	Fleet Manager	Odometer	Engine Hours
2025-06-26	927	vehicle			pull steer tires, grease king pins retorque completed.		Jeanette Hrechka	831339	16436
2025-06-03	927	vehicle			dENRAY TIRE CHANGED TIRE - SUPPLIED BY US		Natalie Hrechka	826320	16332
2025-05-26	927	vehicle	90 day inspection	push out window log	changed fuel filters A4700903151 (Premier)		Jeanette Hrechka	823434	16273
2025-05-16	927	vehicle	Oil Change	oil change	Oil and filter change grease 40 L 10/30 oil 1 X filter 57909		Jeanette Hrechka	818182	16183
2025-05-01	927	vehicle	Tires	Tire Inspection - Tags	drivers side tag tire has nail, fix at denray. (April 29) retorque required.... take off stoor tires to grease knuckles Rotorque required.... Brian took for test drive Retorque done		Jeanette Hrechka	809586	16041

Date	Entity	Entity Type	Service Type	Service Name	Notes	Cost	Fleet Manager	Odometer	Engine Hours
2025-09-19	927	vehicle			Install new water pump belt, tensioner and idler 1- belt 350485 1- idler - 354180 1- tensioner-442451 Engine failed to start! Remove floor boards to look for oil and coolant leaks. Found battery cable melted to block on right side. Separate and insulate from ground. Test starter for cranking from start button. Found 3 seconds of crank only. Check R521 and breakers in floor board. Found breaker tripped for ECM. Reset and start bus. labor-6 hrs/3 hrs		Susan Agland	845557	16724
2025-09-15	927	vehicle			miles remove steering shaft and level gear box to change out u-joint on steering box on axle. Test drovo and water pump belt snapped overheating engine. Top u with coolant and test bus with used belt. 1- u-joint - 11554251 labor 7 hrs		Susan Agland	845512	16722
2025-09-11	927	vehicle			Milos install drivers blind from parts bus labor 2 hrs		Susan Agland	844757	16704
2025-08-29	927	vehicle			Remove both front wheels to grease to top of icing pins. Reinstall wheels and require re-torque Check tail lights, top right tail light only half working. Loosen belts and tighten up shirt loose and rubbing on hanger. labor 6 hrs Front L 44.32R 11/16 P R 44.32 R 11/16 P		Jeanette Hrechka	843603	16675
2025-08-19	927	vehicle	90 day inspection, Tires, Tires, Tires	push out window log, Tire Inspection - Tags, Tire Inspection - drives, Tire Inspection Required - steers			Jeanette Hrechka	842552	16656
2025-08-18	927	vehicle			Steering a little stiff. Sounds like when Bearing making noises. Sound doesn't change when making brake App.		Jeanette Hrechka	841806	16647
2025-07-10	927	vehicle	Oil Change	oil change	oil and filter change tires to 110 psi 40 L 10W30 1 X 7909 filter (Napa)		Jeanette Hrechka	834909	16526

Date	Entity	Entity Type	Service Type	Service Name	Notes	Cost	Fleet Manager	Odometer	Engine Hours
2025-12-05	927	vehicle	Oil Change	oil change	oil and filter change . install upper brake light 1 X 7909 filler 42 I 10w30 1 1133 9234 bulb 3 hours labor		Jeanelle Hrechka	854572	16915
2025-11-12	927	vehicle			M change out drivers wiper blade. change out loose front left hub cap from parts bus. Install new steer tires		Susan Agland	848947	16805
2025-11-12	927	vehicle	Tires	Tire Inspection Required - steers	change steer tires by denray from stock	2771.24	Natalie Hrechka	848000	16700
2025-10-06	927	vehicle	180 day inspection	Mb Safety inspection	Gov't Safety M Exhaust pip off turbo broke off.		Susan Agland	845557	16725