



Pakenham Toyota

Service

33 Commercial Dr, Pakenham, Melbourne, VIC, 3810
PO Box 594, Berwick, VIC, 3806
T: (03) 5945 1755 F: (03) 5945 1785
E: service@pakenhamtoyota.com.au
W: pakenhamtoyota.com.au
HF Automotive Trust
ABN: 93626387876 DL: 51198
LMCT: 537 ARC: AU 39418 MVRB: LVT 9854

SERVICE TAX INVOICE

LR127

11/12

REPAIR ORDER No: J442022478	PAGE: 1
C1 Customer (Account)	

CUSTOMER: LINCROADS PTY LTD Unit 7/2-4 Purton Road Pakenham VIC 3810		DATE: 01/09/2023	TIME IN: 8:10 AM	TIME OUT: 1:30 PM	KILOMETERS: 10272	ADVISER: JW3
		VEHICLE: Hilux 4x2 Workmate 2.7L Petrol Automatic Single			MONTH/YEAR 08/2022	AIR:
		REG. No: 1WV7MS	STOCK No: 10730035	SELLING DEALER:		
CUSTOMER No: T104187	VIN: MR0CX3CB104336273			ENGINE No: 2TRB002097		
CONTACT NAME: MR Steve Fazzino		COLOUR/TRIM: Glacier White/Black Fabric			ORDER No:	
CONTACT NUMBERS: M:0418140661		WAR. EXP:	WAR. KM:	EXT. WAR. EXP:	EXT. WAR. KM:	RDR Date: 14/11/2022

		PRICE	QTY/HRS	AMOUNT
JOB DETAILS				
JOB 1	CARRY OUT 6 MONTHS/10,000KM SERVICE, TOYOTA SERVICE ADVANTAGE PLAN (TSA) FROM 01/05/2020 - (SDD)01/01/2022 TO 31/12/2022 Carried out 6 months/10,000km service, Toyota Service Advantage Plan. Includes:- Replaced engine oil & oil filter. Inspected drive belt. Inspected brake fluid. Inspected battery electrolyte, cleanliness & security. Checked power steering fluid. Inspected brake pads & discs. Lubricated propeller shaft & tightened bolts. Inspected towbar & bullbar mounts (if fitted). Checked condition & pressures of all tyres including spare. Rotated wheels. Balanced front wheels. Checked lights, wiper/washers, horn & electrical systems. Inspected all seat belts operation and condition. Inspected driver's floor mat for correct fitment and retention. Road tested vehicle & reported any defects.		126.00	
PRT	0888800001C ORD P/N 0888800001EP		1	.89
PRT	9043012031 GASKET		1	1.92
PRT	90915YZZD2 OIL FILTER 75*85		1	21.74
CON	Engine Oil 5w30			64.40
MIS	Sundry Materials			13.09
MIS	TSA Discount			28.04-
JOB 1 SUBTOTAL				200.00
RECOMMENDATIONS				
01/09/2023 TYRE AND BRAKE REPORT FRONT BRAKE PADS: 10.0mm of wear remaining				

32300
ENTERED
21/12 By NO.
9999.
SCANNED
NO.

***** CONTINUED *****

Vehicle Release:

☐ WORK EXPLAINED ☐ COST EXPLAINED ☐ VEHICLE WASHED ☐ ALL COURTSTY ITEMS REMOVED

Preferred Contact Method:

☐ LETTER ☐ EMAIL ☐ PHONE ☐ DO NOT CONTACT

☐ CASH ☐ MASTERCARD ☐ VISA CARD ☐ EFTPOS ☐ OTHER (DETAILS) _____

REF NO: _____ DELIVERED BY: _____

AMOUNT: _____ RECEIVED BY: _____





Pakenham Toyota

Service

33 Commercial Dr, Pakenham, Melbourne, VIC, 3810
PO Box 594, Berwick, VIC, 3806
T: (03) 5945 1755 F: (03) 5945 1785
E: service@pakenhamtoyota.com.au
W: pakenhamtoyota.com.au
HF Automotive Trust
ABN: 93626387876 DL: 51198
LMCT: 537 ARC: AU 39418 MVRB: LVT 9854

SERVICE TAX INVOICE

REPAIR ORDER No: J442022478	PAGE: 2
C1 Customer (Account)	

CUSTOMER: LINCROADS PTY LTD Unit 7/2-4 Purton Road Pakenham VIC 3810		DATE: 01/09/2023	TIME IN: 8:10 AM	TIME OUT: 1:30 PM	KILOMETERS: 10272	ADVISER: JW3
VEHICLE: Hilux 4x2 Workmate 2.7L Petrol Automatic Single					MONTH/YEAR: 08/2022	AIR:
REG. No: 1WV7MS	STOCK No: 10730035	SELLING DEALER:				
CUSTOMER No: T104187	VIN: MR0CX3CB104336273	ENGINE No: 2TRB002097				
CONTACT NAME: MR Steve Fazzino		COLOUR/TRIM: Glacier White/Black Fabric			ORDER No:	
CONTACT NUMBERS: M:0418140661		WAR. EXP:	WAR. KM:	EXT. WAR. EXP:	EXT. WAR. KM:	RDR Date: 14/11/2022

JOB DETAILS

PRICE

QTY/HRS

AMOUNT

REAR BRAKE PADS: 5.0mm of wear remaining
FRONT TYRES: 5.7mm from lowest point of tyre
REAR TYRES: 4.7mm from lowest point of tyre
SPARE TYRE: GOOD

**** Next service due: 14/11/2023 or odometer reading: 20000 whichever comes first.

LABOUR	\$126.00
CONSUMABLES	\$64.40
PARTS	\$24.55
MISCELLANEOUS	\$14.95-
SUBTOTAL	\$200.00
GST	\$20.00
TOTAL INCLUDES GST	\$220.00

Thank you for servicing with Pakenham Toyota! We hope to see you again soon. Please feel free to leave us a great review on our Google page!

PRINTED 20/12/23 15:05:44

Vehicle Release:

Preferred Contact Method:

☐ WORK EXPLAINED ☐ COST EXPLAINED ☐ VEHICLE WASHED ☐ ALL COURTSEY ITEMS REMOVED

☐ LETTER ☐ EMAIL ☐ PHONE ☐ DO NOT CONTACT

☐ CASH ☐ MASTERCARD ☐ VISA CARD ☐ EFTPOS ☐ OTHER (DETAILS)

REF NO: _____ DELIVERED BY: _____
AMOUNT: _____ RECEIVED BY: _____

Deposit To:
HF AUTO BERWICK
013542 - 837263216 (AUD)



Pakenham Toyota

Service

33 Commercial Dr, Pakenham, Melbourne, VIC, 3810
PO Box 594, Berwick, VIC, 3806
T: (03) 5945 1755 F: (03) 5945 1785
E: service@pakenhamtoyota.com.au
W: pakenhamtoyota.com.au
HF Automotive Trust
ABN: 93626387876 DL: 51198
LMCT: 537 ARC: AU 39418 MYRB: LVT 9854

SERVICE TAX INVOICE

LR127.

REPAIR ORDER No: J442028913	PAGE: 1
C1 Customer (Account)	

CUSTOMER: LINCROADS PTY LTD Unit 7/2-4 Purton Road Pakenham VIC 3810		DATE: 03/06/2024	TIME IN: 7:30 AM	TIME OUT: 4:00 PM	KILOMETERS: 20881	ADVISER: BS
		VEHICLE: Hilux 4x2 Workmate 2.7L Petrol Automatic Si			MONTH/YEAR 08/2022	AIR:
		REG. No: 1WV7MS	STOCK No: 10730035	SELLING DEALER:		
CUSTOMER No: T104187	VIN: MR0CX3CB104336273			ENGINE No: 2TRB002097		
CONTACT NAME: Lincroads Pty Ltd		COLOUR/TRIM Glacier White/Black Fabric			ORDER No:	
CONTACT NUMBERS: W:0359416244 M:0418140661		WAR. EXP:	WAR. KM:	EXT.WAR.EXP:	EXT.WAR.KM:	RDR Date: 14/11/2022

	PRICE	QTY/HRS	AMOUNT
JOB DETAILS			
JOB 1 DCM SOFTWARE TFAN-0017-20/ LFAN-007-2022			NO CHARGE
JOB 1 SUBTOTAL			NO CHARGE
JOB DETAILS			
JOB 2 Carry out 18 months/30,000km service, Toyota Service Advantage Plan (TSA) From 01/05/2020 - (SDD)01/01/2022 to 31/12/2022 Carried out 18 months/30,000km service, Toyota Service Advantage Plan. Includes:- Replaced engine oil & oil filter. Inspected drive belt. Inspected brake fluid. Inspected battery electrolyte, cleanliness & security. Checked power steering fluid. Inspected brake pads & discs. Lubricated propeller shaft & tightened bolts. Replaced air conditioning fresh air filter. Inspected towbar & bullbar mounts (if fitted). Checked condition & pressures of all tyres including spare. Rotated wheels. Balanced front wheels. Checked lights, wiper/washers, horn & electrical systems. Inspected all seat belts operation and condition. Inspected driver's floor mat for correct fitment and retention. Road tested vehicle & reported any defects.			142.76
PRT 0888800001C	ORD P/N 0888800001EP	1	.91
PRT 871390K070	ELEMENT AIR REFINER	1	76.00
PRT 9043012031	GASKET	1	1.97
PRT 90915YZZD2	OIL FILTER 75*85	1	22.28
CON Engine Oil 0w20			85.03
MIS Sundry Materials			13.41
MIS TSA Discount			142.36-

9999
34717
ENTERED
Date 6/6 By

SCANNED

***** CONTINUED *****

Vehicle Release:

[] WORK EXPLAINED [] COST EXPLAINED [] VEHICLE WASHED [] ALL COURTESY ITEMS REMOVED [] LETTER [] EMAIL [] PHONE [] DO NOT CONTACT

[] CASH [] MASTERCARD [] VISA CARD [] EFTPOS [] OTHER (DETAILS):

REF NO: DELIVERED BY:

AMOUNT: RECEIVED BY:

Pakenham%J442028913%03/06/2024%1WV7MS

Preferred Contact Method:



Pakenham Toyota

Service

33 Commercial Dr, Pakenham, Melbourne, VIC, 3810
PO Box 594, Berwick, VIC, 3806
T: (03) 5945 1755 F: (03) 5945 1785
E: service@pakenhamtoyota.com.au
W: pakenhamtoyota.com.au
HF Automotive Trust
ABN: 93626387876 DL: 51198
LMCT: 537 ARC, AU 39418 MVRB: LVT 9854

SERVICE TAX INVOICE

REPAIR ORDER No: J442028913	PAGE: 2
C1 Customer	(Account)

CUSTOMER: LINCROADS PTY LTD Unit 7/2-4 Purton Road Pakenham VIC 3810		DATE: 03/06/2024	TIME IN: 7:30 AM	TIME OUT: 4:00 PM	KILOMETERS: 20881	ADVISER: BS
		VEHICLE: Hilux 4x2 Workmate 2.7L Petrol Automatic Si			MONTH/YEAR 08/2022	AIR:
		REG. No: 1WV7MS	STOCK No: 10730035	SELLING DEALER:		
CUSTOMER No: T104187	VIN: MR0CX3CB104336273			ENGINE No: 2TRB002097		
CONTACT NAME: Lincroads Pty Ltd		COLOUR/TRIM Glacier White/Black Fabric			ORDER No:	
CONTACT NUMBERS: W:0359416244 M:0418140661		WAR. EXP:	WAR. KM:	EXT.WAR.EXP:	EXT.WAR.KM:	RDR Date: 14/11/2022

JOB DETAILS	PRICE	QTY/HRS	AMOUNT
JOB 2 SUBTOTAL			200.00

JOB DETAILS

JOB 4 vehicle has a flat battery, will need a jump start .
Tested battery - passed.

JOB 4 SUBTOTAL	NO CHARGE
----------------	-----------

RECOMMENDATIONS

03/06/2024 Tyre and Brake report

Front brake pads: 8.0mm remaining .
Rear brake pads: 4.5mm remaining .
Front tyres: 4.2mm of tread remaining .
Rear tyres: 4.0mm of tread remaining .
Spare tyre : Good .

Additional items

**** Next service due: 14/11/2024 or odometer reading: 40000 whichever comes first.

LABOUR	\$142.76
CONSUMABLES	\$85.03
PARTS	\$101.16
MISCELLANEOUS	\$128.95-
SUBTOTAL	\$200.00
GST	\$20.00
TOTAL INCLUDES GST	\$220.00

***** CONTINUED *****

Vehicle Release:

Preferred Contact Method:

☐ WORK EXPLAINED ☐ COST EXPLAINED ☐ VEHICLE WASHED ☐ ALL COURTESY ITEMS REMOVED ☐ LETTER ☐ EMAIL ☐ PHONE ☐ DO NOT CONTACT

☐ CASH ☐ MASTERCARD ☐ VISA CARD ☐ EFTPOS ☐ OTHER (DETAILS) _____

REF NO: _____ DELIVERED BY: _____

AMOUNT: _____ RECEIVED BY: _____



Pakenham Toyota

Service

33 Commercial Dr, Pakenham, Melbourne, VIC, 3810
PO Box 594, Berwick, VIC, 3806
T: (03) 5945 1755 F: (03) 5945 1785
E: service@pakenhamtoyota.com.au
W: pakenhamtoyota.com.au
HF Automotive Trust
ABN: 93626387876 DL: 51198
LMCT: 537 ARC, AU 39410 MVRB, LVT 9054

SERVICE TAX INVOICE

REPAIR ORDER No: J442028913	PAGE: 3
C1 Customer (Account)	

CUSTOMER: LINCROADS PTY LTD Unit 7/2-4 Purton Road Pakenham VIC 3810		DATE: 03/06/2024	TIME IN: 7:30 AM	TIME OUT: 4:00 PM	KILOMETERS: 20881	ADVISER: BS
VEHICLE: Hilux 4x2 Workmate 2.7L Petrol Automatic Si					MONTH/YEAR 08/2022	AIR:
REG. No: 1WV7MS	STOCK No: 10730035	SELLING DEALER:				
CUSTOMER No: T104187	VIN: MR0CX3CB104336273	ENGINE No: 2TRB002097				
CONTACT NAME: Lincroads Pty Ltd		COLOUR/TRIM Glacier White/Black Fabric			ORDER No:	
CONTACT NUMBERS: W:0359416244 M:0418140661		WAR. EXP:	WAR. KM:	EXT.WAR.EXP:	EXT.WAR.KM:	RDR Date: 14/11/2022

JOB DETAILS

PRICE

QTY/HRS

AMOUNT

Thank you for servicing with Pakenham Toyota! We hope to see you again soon. Please feel free to leave us a great review on our Google page!

PRINTED 03/06/24 12:28:29

Vehicle Release:

☐ WORK EXPLAINED ☐ COST EXPLAINED ☐ VEHICLE WASHED! ☐ ALL COURTESY ITEMS REMOVED ☐ LETTER ☐ EMAIL ☐ PHONE ☐ DO NOT CONTACT

☐ CASH ☐ MASTERCARD ☐ VISA CARD ☐ EFTPOS ☐ OTHER (DETAILS): _____

REF NO: _____ DELIVERED BY: _____

AMOUNT: _____ RECEIVED BY: _____

Preferred Contact Method:

Deposit To:
HF AUTO BERWICK
013542 - 837263216 (AUD)

WARRANTY

Pakenham Toyota may offer a limited warranty on some repairs or exchange units that are not covered by Toyota warranties.

This will not cover you for driver abuse or negligence in relation to proper servicing or operation of your vehicle.

We will state below the specific items covered and the limits that will apply.

This, at all times will be in accordance with the guarantees that cannot be excluded under the Australian Consumer law, where you are entitled to a replacement or refund for a major failure and for compensation for any other reasonable foreseeable loss or damage.

You are also entitled to have the goods repaired or replaced if the goods fail to be acceptable quality and the failure does not amount to a major failure.

AFTERMARKET ACCESSORIES AND NON-GENUINE PARTS STATEMENT

- I have been made aware that my vehicle is modified with the fitment of non-genuine parts or accessories.
- Pakenham Toyota takes no responsibility or liability for any failure or consequential damage that may occur to this vehicle or other property as a result of these non-genuine parts or accessories that are fitted to this vehicle.
- I am aware that some non-genuine parts or accessories can render my vehicle to be un-roadworthy and accept that it is my responsibility to comply with the current laws that apply.

PRIVACY STATEMENT

Your personal information is being collected by Pakenham Toyota and will be shared with Toyota Australia and its related bodies corporate and maybe disclosed to third parties to facilitate your purchase of a vehicle and to meet the requirements of the legislation associated with the supply of a motor vehicle and related goods and services. Your information may be transferred out of Australia for these purposes.

From time to time we would like to send you service information and reminders and let you know about our products and services, including special offers.

If you do not wish to receive any of this information, please let us know by phone:

(03) 5945 1777 or email: service@pakenhamtoyota.com.au. Your consent will remain current until you advise us otherwise.

If you do not provide us with your personal information, we may not be able to consider any offer made by you or provide products and services to you. If you would like to access the information we hold about you (although an administration fee may apply) or more information on our privacy policy, please contact us on

(03) 5945 1777 or via www.pakenhamtoyota.com.au/privacy-policy.

Please note that Toyota Motor Corporation Australia (TMCA) is a separate organization to Pakenham Toyota. If you do not wish to receive information from TMCA, please contact TCMA directly on 1800 252 097 (You will still receive safety related messages).

By signing these terms and conditions, I consent to the use and disclosure of my personal information as set out in the above contract.

The purchaser acknowledges that he/she has read and understood the terms and conditions above and on each page of the contract and agrees to be bound by them.